

Report No.: J094099
Nature of Work: Demolition Survey
Issue Date: 11/06/2018
Client Name: WYG Engineering Ltd
Geneva Building, Lake View Drive, Sherwood Business Park,
Annesley, Nottingham, NG15 0ED
Site Address: Dawson building, Former City North Campus, Birmingham City
University, Perry Barr, B42 2US



Order Placed By: Reg 13(1)
Site Contact: Reg 13(1)
Date(s) of Work: 26/04/2018 to 01/05/2018
Technical Manager: Reg 13(1) (Asbestos)
Assistant Surveyor(s): Reg 13(1)

Lead Surveyor:

Reg 13(1)

Authorised Signatory:

Reg 13(1)

Reg 13(1)

Asbestos Consultant

Reg 13(1)

Technical Review Officer

11 Jun 2018

*Non-accredited tests are present within this report.

Head Office:

20 Stourbridge Road,
Halesowen, West Midlands
B63 3US

Tel: 0121 550 0224 Fax: 0121 550 0641

Email: sales@bradley-enviro.co.uk



1155



291



Contents

1.0 Introduction & Scope of Work

- 1.1 Aims & Objectives
- 1.2 Caveats, Restrictions & Inaccessible Areas
- 1.3 Pre-agreed Caveats
- 1.4 Surveyor Imposed Caveats
- 1.5 UKAS Accreditation
- 1.6 'Licensable' Abatement
- 1.7 Extent of ACM Identified
- 1.8 Presumption or Identification of ACMs

2.0 Recommendations

3.0 Executive Summary

- 3.1 Asbestos Containing Materials (ACMs) ranked by Risk
- 3.2 Non-Asbestos Materials

4.0 Item Register & Management Report

5.0 Annotated Building Plans

6.0 Room Description Report

7.0 Room Access Report

8.0 Bulk Analysis Results

9.0 Intrusion Photographs

10.0 Risk Assessment Algorithms

- 10.1 Material Assessment
- 10.2 Likelihood of Disturbance Assessment
- 10.3 Overall Risk Category

1.0 Introduction & Scope of Work

A demolition survey in line with HSG264 Asbestos: The Survey Guide was carried out internally and externally to the property. While this document is considered to be a comprehensive account of ACMs located throughout the site. We strongly recommend (in line with Regulation 10 of the Control of Asbestos Regulations 2012) that all persons who are involved with the demolition process be in possession of valid/recognised asbestos awareness certification to prevent accidental disturbance or spread should suspect material be uncovered during the various processes associated with demolition.

1.1 Aims & Objectives

The purpose of the survey was to locate, as far as reasonably practicable, the presence and extent of all suspect ACMs prior to demolition.

This survey was conducted for the specific project(s) stated above. Additional or alternative tasks over and above that mentioned will require a supplementary investigation to identify further ACMs that could potentially be disturbed by the task(s) at hand.

1.2 Caveats, Restrictions & Inaccessible Areas

The value and usefulness of a survey can be seriously undermined where either the client or the surveyor imposes restrictions on the survey scope (HSG264).

If any rooms were not accessed during the inspection, they will be indicated on the building plans (in yellow block) in section 5.

Where a room was accessed but specific elements within the room could not be inspected, caveats and their justification will be detailed in section 7.

It is strongly recommended that the client reviews the (general) caveats noted in sections 1.3 and/or 1.4 below, as well as the (room-specific) caveats cited in sections 5 and 7 as soon as possible upon receipt of the report. If the extent of access is less than required, the client should advise the Technical Management Team to arrange additional inspection work as necessary.

1.3 Pre-agreed Caveats:

No safe access was available internally to items of electrically connected plant and equipment. The presence of ACMs internally to such items may therefore have been presumed at the surveyor's discretion.

No access was required beyond ACMs (i.e. into voids or cavities etc) where the services of a licensed asbestos removal contractor would be required to provide safe access.

All land associated with the building such as surrounding grassed verges etc. are not included within the scope of these works and therefore remain unsurveyed.

All incoming services to the building were only investigated above ground level once they had entered the building therefore all sub ground water, gas and electric connections remain un-surveyed.

All outgoing services such as drainage routes were not included within the scope of these works and therefore remain un-surveyed.

All lift shafts will not be accessed as agreed with the client during the pre start period. therefore they will remain unsurveyed at this time

Please note that, although a thorough and methodical survey strategy was adopted, it is possible that further ACMs may be present, and are unreported in this survey. HSG264 Asbestos: the survey guide states that "It is now recognised that even with 'complete' access demolition surveys, all ACMs may not be identified and this only becomes apparent during demolition itself."

1.4 Surveyor Imposed Caveats:

No surveyor imposed caveats were noted during the survey.

1.5 UKAS Accreditation

Bradley Environmental are accredited by UKAS to both ISO17025 (testing) and ISO17020 (inspections). Please note that the following are outside the scope of UKAS Accreditation:

- Opinions & interpretations;
- Likelihood of disturbance risk assessment;
- Recommendations;
- The sample references cited in section 8.0.

1.6 'Licensable' Abatement

Where an asbestos-containing material is stated as being licensable within section 4 of this report, this is merely a qualified opinion and may not in practice be an absolute fact.

1.7 Extent of ACM Identified

Please note that the extents cited within this report are an approximation only and should not be used for the purposes of quoting asbestos removal works.

1.8 Presumption or Identification of ACMs

Where suspect materials have been located during this investigation, their asbestos content (or otherwise) will have been determined as follows:

A sample of the material will have been taken by the surveyor during the survey. This sample will then have been **analysed using polarised light microscopy** (PLM) to determine its asbestos content.

A material's asbestos content will have been **strongly presumed** where a visual inspection by the lead surveyor indicates the material is visually similar to other items present within the building which have been confirmed to contain asbestos (or otherwise) using PLM.

A material's asbestos content will have been **presumed** where it cannot be accessed or inspected.

2.0 Recommendations

Please note that where a management survey was carried out, individual recommendations related to safe management of each ACM has been cited by the surveyor in section 4.0.

Where a refurbishment or demolition survey was carried out, the recommendation for each item has been defaulted to 'program removal' in line with Regulation 7 of CAR2012.

Report No.: J094099
Issue Date: 11/06/2018



3.0 Executive Summary

As required by HSG264 Asbestos: The survey guide, the following sections contain an executive summary of the survey findings.

3.1 Executive Summary of Asbestos Containing Materials (ACMs) by Risk

The following pages show an executive summary of the ACMs located during these works ranked in order of risk (i.e. the highest risk item will be at the top of the page).

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001429	1st Floor	University	2.11	Asbestos Insulating board debris within riser	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B13	Program removal
DU001465	2nd Floor	University	3.09	Asbestos Insulating board debris within riser	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B13	Program removal
DU001358	Ground Floor	University	1.99	Asbestos Insulating board debris within riser	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B13	Program removal
DU001370	Ground Floor	University	1.25	Asbestos Insulating board debris to base of riser	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B13	Program removal
DU001389	Ground Floor	University	1.13A	Asbestos Insulating board debris to base of riser	Amosite	Analysis of sample using PLM	1 m ²	B13	Program removal
DU001445	2nd Floor	University	3.31	Asbestos Insulating board panel to ceiling of riser	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B12	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001361	Ground Floor	University	1.05	Asbestos Insulating board door header panel	Amosite	Analysis of sample using PLM	1 m ²	B12	Program removal
DU001395	1st Floor	University	2.04	Asbestos Insulating board panels	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B11	Program removal
DU001397	1st Floor	University	2.05	Asbestos Insulating board door header panel	Chrysotile Amosite	Analysis of sample using PLM	2 m ²	B11	Program removal
DU001435	2nd Floor	University	3.05	Asbestos Insulating board door header panel	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B11	Program removal
DU001468	3rd Floor	University	4.05	Asbestos Insulating board door header panel	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B11	Program removal
DU001470	3rd Floor	University	4.00	Asbestos Insulating board door header panel	Chrysotile Amosite	Analysis of sample using PLM	4 m ²	B11	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001472	3rd Floor	University	4.99	Asbestos Insulating board door header panel	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B11	Program removal
DU001363	Ground Floor	University	1.00	Asbestos Insulating board door header panel	Chrysotile Amosite	Analysis of sample using PLM	4 m ²	B11	Program removal
DU001502	L - Loft	University	R.01	Asbestos Insulating board panel to rear of timber boxing	Chrysotile Amosite	Analysis of sample using PLM	4 linear metres	B11	Program removal
DU001444	2nd Floor	University	3.31	Asbestos Cement shuttering	Chrysotile Amosite	Analysis of sample using PLM	15 m ²	C10	Program removal
As DU001453	2nd Floor	University	3.23	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	16 m ²	C10	Program removal
As DU001453	2nd Floor	University	3.18	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	10 m ²	C10	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001461	2nd Floor	University	3.10	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	12 m ²	C10	Program removal
DU001467	3rd Floor	University	4.03	Asbestos Insulating board door header panel	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	C10	Program removal
As DU001496	3rd Floor	University	4.11	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	10 m ²	C10	Program removal
DU001365	Ground Floor	University	1.27	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	10 m ²	C10	Program removal
DU001503	L - Loft	University	R.01	Asbestos Insulating board lining to door	Chrysotile	Analysis of sample using PLM	2 m ²	C10	Program removal
As DU001399	1st Floor	University	2.26	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	80 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001399	1st Floor	University	2.25	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	64 m ²	C9	Program removal
DU001416	1st Floor	University	2.22B	Asbestos Thermoplastic floor tile debris within riser	Chrysotile	Analysis of sample using PLM	<1 m ²	C9	Program removal
As DU001410	1st Floor	University	2.21	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	90 m ²	C9	Program removal
As DU001412	1st Floor	University	2.21	Asbestos Cement window sill	Chrysotile	Strongly presumed	15 linear metres	C9	Program removal
As DU001413	1st Floor	University	2.21	Asbestos Cement shuttering	Chrysotile	Strongly presumed	15 m ²	C9	Program removal
As DU001423	1st Floor	University	2.11	Asbestos Cement window sill	Chrysotile	Strongly presumed	12 linear metres	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001425	1st Floor	University	2.11	Asbestos Cement shuttering	Chrysotile	Strongly presumed	12 m ²	C9	Program removal
As DU001439	2nd Floor	University	3.31	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	60 m ²	C9	Program removal
DU001442	2nd Floor	University	3.31	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	15 linear metres	C9	Program removal
DU001446	2nd Floor	University	3.31	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	60 m ²	C9	Program removal
As DU001439	2nd Floor	University	3.30	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	60 m ²	C9	Program removal
As DU001444	2nd Floor	University	3.30	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	6 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001439	2nd Floor	University	3.27	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	50 m ²	C9	Program removal
As DU001444	2nd Floor	University	3.27	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	6 m ²	C9	Program removal
As DU001439	2nd Floor	University	3.26	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	54 m ²	C9	Program removal
As DU001444	2nd Floor	University	3.26	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	9 m ²	C9	Program removal
DU001453	2nd Floor	University	3.24	Asbestos Cement shuttering	Chrysotile Amosite	Analysis of sample using PLM	4 m ²	C9	Program removal
As DU001449	2nd Floor	University	3.23	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	60 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001450	2nd Floor	University	3.23	Asbestos Cement window sill	Chrysotile	Strongly presumed	16 linear metres	C9	Program removal
As DU001452	2nd Floor	University	3.23	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	60 m ²	C9	Program removal
As DU001453	2nd Floor	University	3.20	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	4 m ²	C9	Program removal
As DU001453	2nd Floor	University	3.19	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	4 m ²	C9	Program removal
As DU001450	2nd Floor	University	3.18	Asbestos Cement window sill	Chrysotile	Strongly presumed	10 linear metres	C9	Program removal
As DU001453	2nd Floor	University	3.17	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	3 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001453	2nd Floor	University	3.16	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	2 m ²	C9	Program removal
As DU001453	2nd Floor	University	3.15A	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	2 m ²	C9	Program removal
As DU001453	2nd Floor	University	3.15	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	3 m ²	C9	Program removal
As DU001453	2nd Floor	University	3.14A	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	3 m ²	C9	Program removal
As DU001453	2nd Floor	University	3.14	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	2 m ²	C9	Program removal
As DU001453	2nd Floor	University	3.13A	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	2 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001461	2nd Floor	University	3.13	Asbestos Cement shuttering	Chrysotile Amosite	Analysis of sample using PLM	6 m ²	C9	Program removal
As DU001461	2nd Floor	University	3.11	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	2 m ²	C9	Program removal
As DU001461	2nd Floor	University	3.12	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	3 m ²	C9	Program removal
As DU001461	2nd Floor	University	3.10A	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	3 m ²	C9	Program removal
As DU001460	2nd Floor	University	3.10	Asbestos Cement window sill	Chrysotile	Strongly presumed	12 linear metres	C9	Program removal
As DU001461	2nd Floor	University	3.09	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	2 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001477	3rd Floor	University	4.38A	Asbestos Cement shuttering	Chrysotile Amosite	Analysis of sample using PLM	4 m ²	C9	Program removal
As DU001477	3rd Floor	University	4.38B	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	2 m ²	C9	Program removal
As DU001477	3rd Floor	University	4.38C	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	8 m ²	C9	Program removal
As DU001474	3rd Floor	University	4.34	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	70 m ²	C9	Program removal
As DU001477	3rd Floor	University	4.34	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	7 m ²	C9	Program removal
As DU001475	3rd Floor	University	4.34	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	70 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001477	3rd Floor	University	4.37	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	3 m ²	C9	Program removal
As DU001474	3rd Floor	University	4.34A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	50 m ²	C9	Program removal
As DU001477	3rd Floor	University	4.34A	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	6 m ²	C9	Program removal
As DU001475	3rd Floor	University	4.34A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	50 m ²	C9	Program removal
As DU001477	3rd Floor	University	4.27	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	8 m ²	C9	Program removal
DU001488	3rd Floor	University	4.33A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	8 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001496	3rd Floor	University	4.14	Asbestos Cement shuttering	Chrysotile Amosite	Analysis of sample using PLM	4 m ²	C9	Program removal
As DU001494	3rd Floor	University	4.13	Asbestos Textured coating to concrete	Chrysotile	Strongly presumed	50 m ²	C9	Program removal
As DU001496	3rd Floor	University	4.13	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	8 m ²	C9	Program removal
As DU001496	3rd Floor	University	4.12	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	3 m ²	C9	Program removal
As DU001496	3rd Floor	University	4.12A	Asbestos Cement shuttering	Chrysotile Amosite	Strongly presumed	2 m ²	C9	Program removal
As DU001495	3rd Floor	University	4.11	Asbestos Cement window sill	Chrysotile	Strongly presumed	10 linear metres	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001366	Ground Floor	University	1.25	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	56 m ²	C9	Program removal
DU001368	Ground Floor	University	1.25	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	16 linear metres	C9	Program removal
DU001369	Ground Floor	University	1.25	Asbestos Cement shuttering	Chrysotile	Analysis of sample using PLM	20 linear metres	C9	Program removal
As DU001366	Ground Floor	University	1.24	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	88 m ²	C9	Program removal
As DU001366	Ground Floor	University	1.23	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	80 m ²	C9	Program removal
As DU001366	Ground Floor	University	1.22	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	50 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001366	Ground Floor	University	1.21	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	64 m ²	C9	Program removal
As DU001368	Ground Floor	University	1.21	Asbestos Cement window sill	Chrysotile	Strongly presumed	16 linear metres	C9	Program removal
As DU001369	Ground Floor	University	1.21	Asbestos Cement shuttering	Chrysotile	Strongly presumed	16 m ²	C9	Program removal
DU001382	Ground Floor	University	1.19	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	12 linear metres	C9	Program removal
As DU001380	Ground Floor	University	1.19	Asbestos Cement shuttering	Chrysotile	Strongly presumed	12 linear metres	C9	Program removal
DU001399	1st Floor	University	2.27C	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	10 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001401	1st Floor	University	2.27C	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal
DU001402	1st Floor	University	2.27C	Asbestos Cement shuttering	Chrysotile	Analysis of sample using PLM	4 m ²	C8	Program removal
As DU001399	1st Floor	University	2.27B	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	14 m ²	C8	Program removal
As DU001401	1st Floor	University	2.27B	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal
As DU001402	1st Floor	University	2.27B	Asbestos Cement shuttering	Chrysotile	Strongly presumed	8 m ²	C8	Program removal
As DU001399	1st Floor	University	2.27A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	16 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001401	1st Floor	University	2.27A	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001402	1st Floor	University	2.27A	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 m ²	C8	Program removal
As DU001399	1st Floor	University	2.27	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	16 m ²	C8	Program removal
As DU001401	1st Floor	University	2.26	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal
As DU001402	1st Floor	University	2.26	Asbestos Cement shuttering	Chrysotile	Strongly presumed	8 m ²	C8	Program removal
As DU001403	1st Floor	University	2.26	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	80 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001401	1st Floor	University	2.25	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal
As DU001402	1st Floor	University	2.25	Asbestos Cement shuttering	Chrysotile	Strongly presumed	8 m ²	C8	Program removal
DU001405	1st Floor	University	2.23C	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	15 m ²	C8	Program removal
DU001406	1st Floor	University	2.23C	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	2 linear metres	C8	Program removal
DU001407	1st Floor	University	2.23C	Asbestos Cement shuttering	Chrysotile	Analysis of sample using PLM	2 m ²	C8	Program removal
As DU001405	1st Floor	University	2.23B	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	15 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001406	1st Floor	University	2.23B	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001407	1st Floor	University	2.23B	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
As DU001405	1st Floor	University	2.23A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001406	1st Floor	University	2.23A	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001407	1st Floor	University	2.23A	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
As DU001405	1st Floor	University	2.23	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001406	1st Floor	University	2.23	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001407	1st Floor	University	2.23	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
DU001410	1st Floor	University	2.22	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	25 m ²	C8	Program removal
DU001412	1st Floor	University	2.22	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal
DU001413	1st Floor	University	2.22	Asbestos Cement shuttering	Chrysotile	Analysis of sample using PLM	5 m ²	C8	Program removal
As DU001410	1st Floor	University	2.22A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	16 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001412	1st Floor	University	2.22A	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal
As DU001413	1st Floor	University	2.22A	Asbestos Cement shuttering	Chrysotile	Strongly presumed	8 m ²	C8	Program removal
As DU001412	1st Floor	University	2.22B	Asbestos Cement window sill	Chrysotile	Strongly presumed	1 linear metres	C8	Program removal
As DU001413	1st Floor	University	2.22B	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
As DU001410	1st Floor	University	2.99A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	30 m ²	C8	Program removal
As DU001414	1st Floor	University	2.21	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	90 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001410	1st Floor	University	2.21B	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	10 m ²	C8	Program removal
As DU001413	1st Floor	University	2.21B	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
As DU001410	1st Floor	University	2.20	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001413	1st Floor	University	2.20	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 m ²	C8	Program removal
As DU001412	1st Floor	University	2.20	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001412	1st Floor	University	2.19	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001413	1st Floor	University	2.19	Asbestos Cement shuttering	Chrysotile	Strongly presumed	3 m ²	C8	Program removal
As DU001410	1st Floor	University	2.18	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001412	1st Floor	University	2.18	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001413	1st Floor	University	2.18	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001412	1st Floor	University	2.17	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal
As DU001413	1st Floor	University	2.17	Asbestos Cement shuttering	Chrysotile	Strongly presumed	3 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001412	1st Floor	University	2.16	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001413	1st Floor	University	2.16	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
As DU001410	1st Floor	University	2.24	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	18 m ²	C8	Program removal
As DU001412	1st Floor	University	2.15	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001413	1st Floor	University	2.15	Asbestos Cement shuttering	Chrysotile	Strongly presumed	3 m ²	C8	Program removal
DU001422	1st Floor	University	2.14B	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	14 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001423	1st Floor	University	2.14B	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	2 linear metres	C8	Program removal
DU001425	1st Floor	University	2.14B	Asbestos Cement shuttering	Chrysotile	Analysis of sample using PLM	3 m ²	C8	Program removal
As DU001422	1st Floor	University	2.14A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	10 m ²	C8	Program removal
As DU001423	1st Floor	University	2.14A	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001425	1st Floor	University	2.14A	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
As DU001422	1st Floor	University	2.13	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	24 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001423	1st Floor	University	2.13	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001425	1st Floor	University	2.13	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 m ²	C8	Program removal
As DU001422	1st Floor	University	2.12B	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	14 m ²	C8	Program removal
As DU001423	1st Floor	University	2.12B	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal
As DU001425	1st Floor	University	2.12B	Asbestos Cement shuttering	Chrysotile	Strongly presumed	3 m ²	C8	Program removal
As DU001422	1st Floor	University	2.12A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	10 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001423	1st Floor	University	2.12A	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001425	1st Floor	University	2.12A	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
As DU001422	1st Floor	University	2.11	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	28 m ²	C8	Program removal
As DU001442	2nd Floor	University	3.30	Asbestos Cement window sill	Chrysotile	Strongly presumed	6 linear metres	C8	Program removal
As DU001442	2nd Floor	University	3.27	Asbestos Cement window sill	Chrysotile	Strongly presumed	6 linear metres	C8	Program removal
DU001447	2nd Floor	University	3.27	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001442	2nd Floor	University	3.26	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal
DU001448	2nd Floor	University	3.26	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	54 m ²	C8	Program removal
As DU001448	2nd Floor	University	3.99A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	80 m ²	C8	Program removal
As DU001439	2nd Floor	University	3.99A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	20 m ²	C8	Program removal
DU001449	2nd Floor	University	3.24	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	25 m ²	C8	Program removal
DU001450	2nd Floor	University	3.24	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001452	2nd Floor	University	3.24	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	25 m ²	C8	Program removal
As DU001449	2nd Floor	University	3.20	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	24 m ²	C8	Program removal
As DU001450	2nd Floor	University	3.20	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001449	2nd Floor	University	3.19	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001450	2nd Floor	University	3.19	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal
As DU001449	2nd Floor	University	3.18	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	25 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001449	2nd Floor	University	3.17	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001450	2nd Floor	University	3.17	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001449	2nd Floor	University	3.16	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001450	2nd Floor	University	3.16	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001449	2nd Floor	University	3.15A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001450	2nd Floor	University	3.15A	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001449	2nd Floor	University	3.15	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	18 m ²	C8	Program removal
As DU001450	2nd Floor	University	3.15	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal
DU001456	2nd Floor	University	3.15	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	18 m ²	C8	Program removal
As DU001449	2nd Floor	University	3.14A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001450	2nd Floor	University	3.14A	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal
As DU001456	2nd Floor	University	3.14A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001449	2nd Floor	University	3.14	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001450	2nd Floor	University	3.14	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001456	2nd Floor	University	3.14	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001449	2nd Floor	University	3.13A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001450	2nd Floor	University	3.13A	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001456	2nd Floor	University	3.13A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001457	2nd Floor	University	3.28	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	12 m ²	C8	Program removal
DU001458	2nd Floor	University	3.28	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C8	Program removal
As DU001457	2nd Floor	University	3.13	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	40 m ²	C8	Program removal
DU001460	2nd Floor	University	3.13	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	6 linear metres	C8	Program removal
DU001463	2nd Floor	University	3.13	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	40 m ²	C8	Program removal
As DU001457	2nd Floor	University	3.11	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001460	2nd Floor	University	3.11	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
DU001464	2nd Floor	University	3.11	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C8	Program removal
As DU001457	2nd Floor	University	3.12	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001460	2nd Floor	University	3.12	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal
As DU001464	2nd Floor	University	3.12	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001457	2nd Floor	University	3.10A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001460	2nd Floor	University	3.10A	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001464	2nd Floor	University	3.10A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001457	2nd Floor	University	3.10	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	49 m ²	C8	Program removal
As DU001460	2nd Floor	University	3.09	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal
As DU001474	3rd Floor	University	4.38A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	20 m ²	C8	Program removal
DU001476	3rd Floor	University	4.38A	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001475	3rd Floor	University	4.38A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	20 m ²	C8	Program removal
As DU001474	3rd Floor	University	4.38B	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	20 m ²	C8	Program removal
As DU001476	3rd Floor	University	4.38B	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001475	3rd Floor	University	4.38B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	20 m ²	C8	Program removal
As DU001474	3rd Floor	University	4.38C	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	20 m ²	C8	Program removal
As DU001476	3rd Floor	University	4.38C	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001475	3rd Floor	University	4.38C	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	20 m ²	C8	Program removal
As DU001476	3rd Floor	University	4.34	Asbestos Cement window sill	Chrysotile	Strongly presumed	7 linear metres	C8	Program removal
As DU001474	3rd Floor	University	4.37	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	15 m ²	C8	Program removal
As DU001476	3rd Floor	University	4.37	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal
As DU001475	3rd Floor	University	4.37	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	15 m ²	C8	Program removal
As DU001476	3rd Floor	University	4.34A	Asbestos Cement window sill	Chrysotile	Strongly presumed	6 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001474	3rd Floor	University	4.27	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	48 m ²	C8	Program removal
As DU001476	3rd Floor	University	4.27	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal
DU001479	3rd Floor	University	4.27	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	48 m ²	C8	Program removal
DU001482	3rd Floor	University	4.26	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	2 linear metres	C8	Program removal
DU001483	3rd Floor	University	4.26	Asbestos Cement shuttering	Chrysotile	Analysis of sample using PLM	2 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.25	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001483	3rd Floor	University	4.25	Asbestos Cement shuttering	Chrysotile	Strongly presumed	3 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.24	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001483	3rd Floor	University	4.24	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.23	Asbestos Cement window sill	Chrysotile	Strongly presumed	7 linear metres	C8	Program removal
As DU001483	3rd Floor	University	4.23	Asbestos Cement shuttering	Chrysotile	Strongly presumed	7 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.22	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001483	3rd Floor	University	4.22	Asbestos Cement shuttering	Chrysotile	Strongly presumed	3 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.21	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001483	3rd Floor	University	4.21	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.20	Asbestos Cement window sill	Chrysotile	Strongly presumed	5 linear metres	C8	Program removal
As DU001483	3rd Floor	University	4.20	Asbestos Cement shuttering	Chrysotile	Strongly presumed	6 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.19	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001483	3rd Floor	University	4.19	Asbestos Cement shuttering	Chrysotile	Strongly presumed	8 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.18	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001483	3rd Floor	University	4.18	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.17	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001483	3rd Floor	University	4.17	Asbestos Cement shuttering	Chrysotile	Strongly presumed	3 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.16	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001483	3rd Floor	University	4.16	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.15A	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001483	3rd Floor	University	4.15A	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal
As DU001482	3rd Floor	University	4.15	Asbestos Cement window sill	Chrysotile	Strongly presumed	6 linear metres	C8	Program removal
As DU001483	3rd Floor	University	4.15	Asbestos Cement shuttering	Chrysotile	Strongly presumed	7 m ²	C8	Program removal
DU001490	3rd Floor	University	4.15	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001494	3rd Floor	University	4.14	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	24 m ²	C8	Program removal
DU001495	3rd Floor	University	4.14	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal
As DU001495	3rd Floor	University	4.13	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal
DU001499	3rd Floor	University	4.13	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
As DU001494	3rd Floor	University	4.12	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	16 m ²	C8	Program removal
As DU001495	3rd Floor	University	4.12	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001494	3rd Floor	University	4.12A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	14 m ²	C8	Program removal
As DU001495	3rd Floor	University	4.12A	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001494	3rd Floor	University	4.11	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	24 m ²	C8	Program removal
As DU001494	3rd Floor	University	4.99C	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	10 m ²	C8	Program removal
DU001362	Ground Floor	University	1.05	Asbestos Reinforced plastic cistern	Amosite	Analysis of sample using PLM	1 unit	C8	Program removal
DU001364	Ground Floor	University	1.27	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	10 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001366	Ground Floor	University	1.26	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	10 m ²	C8	Program removal
As DU001365	Ground Floor	University	1.26	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	C8	Program removal
As DU001368	Ground Floor	University	1.24	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal
As DU001369	Ground Floor	University	1.24	Asbestos Cement shuttering	Chrysotile	Strongly presumed	8 m ²	C8	Program removal
As DU001368	Ground Floor	University	1.23	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal
As DU001369	Ground Floor	University	1.23	Asbestos Cement shuttering	Chrysotile	Strongly presumed	8 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001371	Ground Floor	University	1.24	Asbestos Bitumen adhesive to concrete	Chrysotile	Analysis of sample using PLM	88 m ²	C8	Program removal
As DU001371	Ground Floor	University	1.23	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	80 m ²	C8	Program removal
As DU001368	Ground Floor	University	1.22	Asbestos Cement window sill	Chrysotile	Strongly presumed	6 linear metres	C8	Program removal
As DU001369	Ground Floor	University	1.22	Asbestos Cement shuttering	Chrysotile	Strongly presumed	6 m ²	C8	Program removal
DU001374	Ground Floor	University	1.22	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
DU001376	Ground Floor	University	1.21	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	64 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001377	Ground Floor	University	1.20B	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	25 m ²	C8	Program removal
DU001380	Ground Floor	University	1.20B	Asbestos Cement shuttering	Chrysotile	Analysis of sample using PLM	1 m ²	C8	Program removal
As DU001377	Ground Floor	University	1.19	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	36 m ²	C8	Program removal
As DU001377	Ground Floor	University	1.18B	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001382	Ground Floor	University	1.18B	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal
As DU001380	Ground Floor	University	1.18B	Asbestos Cement shuttering	Chrysotile	Strongly presumed	2 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001383	Ground Floor	University	1.18B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C8	Program removal
As DU001377	Ground Floor	University	1.18	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	24 m ²	C8	Program removal
As DU001382	Ground Floor	University	1.18	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001380	Ground Floor	University	1.18	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 m ²	C8	Program removal
As DU001383	Ground Floor	University	1.18	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	24 m ²	C8	Program removal
DU001384	Ground Floor	University	1.18A	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	18 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001386	Ground Floor	University	1.18A	Asbestos Cement shuttering	Chrysotile	Analysis of sample using PLM	3 m ²	C8	Program removal
DU001388	Ground Floor	University	1.18A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	18 m ²	C8	Program removal
DU001385	Ground Floor	University	1.18A	Asbestos Cement window sill	Chrysotile	Analysis of sample using PLM	2 linear metres	C8	Program removal
As DU001384	Ground Floor	University	1.17B	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	25 m ²	C8	Program removal
As DU001386	Ground Floor	University	1.17B	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 m ²	C8	Program removal
As DU001385	Ground Floor	University	1.17B	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001384	Ground Floor	University	1.17A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	24 m ²	C8	Program removal
As DU001386	Ground Floor	University	1.17A	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 m ²	C8	Program removal
As DU001385	Ground Floor	University	1.17A	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001384	Ground Floor	University	1.15	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	15 m ²	C8	Program removal
As DU001386	Ground Floor	University	1.15	Asbestos Cement shuttering	Chrysotile	Strongly presumed	3 m ²	C8	Program removal
As DU001385	Ground Floor	University	1.15	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001384	Ground Floor	University	1.14	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001386	Ground Floor	University	1.14	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 m ²	C8	Program removal
As DU001385	Ground Floor	University	1.14	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001384	Ground Floor	University	1.14A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU001386	Ground Floor	University	1.14A	Asbestos Cement shuttering	Chrysotile	Strongly presumed	3 m ²	C8	Program removal
As DU001385	Ground Floor	University	1.14A	Asbestos Cement window sill	Chrysotile	Strongly presumed	2 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001384	Ground Floor	University	1.12	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	10 m ²	C8	Program removal
As DU001386	Ground Floor	University	1.12	Asbestos Cement shuttering	Chrysotile	Strongly presumed	4 m ²	C8	Program removal
As DU001385	Ground Floor	University	1.12	Asbestos Cement window sill	Chrysotile	Strongly presumed	4 linear metres	C8	Program removal
As DU001384	Ground Floor	University	1.13	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	16 m ²	C8	Program removal
As DU001386	Ground Floor	University	1.13	Asbestos Cement shuttering	Chrysotile	Strongly presumed	8 m ²	C8	Program removal
As DU001385	Ground Floor	University	1.13	Asbestos Cement window sill	Chrysotile	Strongly presumed	8 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001384	Ground Floor	University	1.13A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	10 m ²	C8	Program removal
As DU001386	Ground Floor	University	1.13A	Asbestos Cement shuttering	Chrysotile	Strongly presumed	3 m ²	C8	Program removal
As DU001385	Ground Floor	University	1.13A	Asbestos Cement window sill	Chrysotile	Strongly presumed	3 linear metres	C8	Program removal
As DU001384	Ground Floor	University	1.99D	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	10 m ²	C8	Program removal
DU001509	L - Loft	University	R.03	Asbestos Compressed fibre gasket	Chrysotile	Analysis of sample using PLM	2 units	C8	Program removal
DU001398	1st Floor	University	2.05	Asbestos Reinforced plastic cistern	Amosite	Analysis of sample using PLM	1 unit	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001403	1st Floor	University	2.27C	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	10 m ²	C7	Program removal
As DU001403	1st Floor	University	2.27B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal
As DU001403	1st Floor	University	2.27A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C7	Program removal
As DU001403	1st Floor	University	2.27	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C7	Program removal
DU001409	1st Floor	University	2.23C	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	15 m ²	C7	Program removal
As DU001409	1st Floor	University	2.23B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	15 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001409	1st Floor	University	2.23A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
As DU001409	1st Floor	University	2.23	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
DU001414	1st Floor	University	2.22	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	25 m ²	C7	Program removal
As DU001414	1st Floor	University	2.22A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C7	Program removal
As DU001410	1st Floor	University	2.22B	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	6 m ²	C7	Program removal
As DU001414	1st Floor	University	2.21B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001410	1st Floor	University	2.19	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	8 m ²	C7	Program removal
As DU001410	1st Floor	University	2.24A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	8 m ²	C7	Program removal
As DU001410	1st Floor	University	2.17	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	9 m ²	C7	Program removal
As DU001410	1st Floor	University	2.16	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	6 m ²	C7	Program removal
As DU001419	1st Floor	University	2.24	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	18 m ²	C7	Program removal
As DU001410	1st Floor	University	2.15	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	8 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001426	1st Floor	University	2.14B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	14 m ²	C7	Program removal
As DU001426	1st Floor	University	2.14A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	C7	Program removal
As DU001426	1st Floor	University	2.13	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	24 m ²	C7	Program removal
DU001427	1st Floor	University	2.12B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	14 m ²	C7	Program removal
As DU001427	1st Floor	University	2.12A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	C7	Program removal
DU001428	1st Floor	University	2.11	Asbestos	Chrysotile	Analysis of	28 m ²	C7	Program removal

Thermoplastic
floor tiles with
bitumen
adhesive

sample using
PLM

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001422	1st Floor	University	2.99C	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	9 m ²	C7	Program removal
DU001433	1st Floor	University	2.99C	Asbestos Bitumen adhesive to concrete	Chrysotile	Analysis of sample using PLM	9 m ²	C7	Program removal
DU001436	2nd Floor	University	3.05	Asbestos Reinforced plastic cistern	Amosite	Analysis of sample using PLM	1 unit	C7	Program removal
DU001439	2nd Floor	University	3.32A	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	6 m ²	C7	Program removal
DU001440	2nd Floor	University	3.32A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	6 m ²	C7	Program removal
As DU001439	2nd Floor	University	3.32	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	6 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001440	2nd Floor	University	3.32	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	6 m ²	C7	Program removal
As DU001439	2nd Floor	University	3.32B	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	6 m ²	C7	Program removal
As DU001440	2nd Floor	University	3.32B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	6 m ²	C7	Program removal
As DU001449	2nd Floor	University	3.21	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	8 m ²	C7	Program removal
DU001455	2nd Floor	University	3.21	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	8 m ²	C7	Program removal
As DU001457	2nd Floor	University	3.99B	Asbestos Textured coating to concrete	Chrysotile	Strongly presumed	9 m ²	C7	Program removal

ceiling

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001469	3rd Floor	University	4.05	Asbestos Reinforced plastic cistern	Amosite	Analysis of sample using PLM	1 unit	C7	Program removal
DU001474	3rd Floor	University	4.39	Asbestos Textured coating to concrete ceiling	Chrysotile	Analysis of sample using PLM	6 m ²	C7	Program removal
DU001475	3rd Floor	University	4.39	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	6 m ²	C7	Program removal
As DU001474	3rd Floor	University	4.39A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	9 m ²	C7	Program removal
As DU001474	3rd Floor	University	4.31	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	20 m ²	C7	Program removal
As DU001488	3rd Floor	University	4.16	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001488	3rd Floor	University	4.15A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	C7	Program removal
DU001497	3rd Floor	University	4.14	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	24 m ²	C7	Program removal
As DU001499	3rd Floor	University	4.12	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C7	Program removal
As DU001499	3rd Floor	University	4.12A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal
As DU001499	3rd Floor	University	4.11	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	24 m ²	C7	Program removal
DU001514	E - External	University	External Balcony	Asbestos Cement shuttering	Chrysotile Amosite	Analysis of sample using PLM	7 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001377	Ground Floor	University	1.20A	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	4 m ²	C7	Program removal
As DU001377	Ground Floor	University	1.99C	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	6 m ²	C7	Program removal
As DU001384	Ground Floor	University	1.16	Asbestos Textured coating to concrete ceiling	Chrysotile	Strongly presumed	4 m ²	C7	Program removal
As DU001388	Ground Floor	University	1.16	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	4 m ²	C7	Program removal
As DU001414	1st Floor	University	2.22B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	6 m ²	D6	Program removal
As DU001414	1st Floor	University	2.99A	Asbestos Bitumen adhesive to concrete	Chrysotile	Strongly presumed	10 m ²	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001419	1st Floor	University	2.24A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	8 m ²	D6	Program removal
As DU001456	2nd Floor	University	3.99B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	9 m ²	D6	Program removal

Report No.: J094099
Issue Date: 11/06/2018



3.2 Executive Summary of Non-Asbestos Material

The following pages show a summary of non-asbestos materials located during these works.

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001354	Ground Floor	University	1.99	Insulating board fillet strip above sliding doors	No Asbestos Detected	Analysis of sample using PLM	6 linear metres	E0	Not applicable
DU001355	Ground Floor	University	1.99	Insulating board door header panels	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
DU001356	Ground Floor	University	1.99	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
DU001357	Ground Floor	University	1.99	Insulating board fillet above red sliding doors	No Asbestos Detected	Analysis of sample using PLM	6 linear metres	E0	Not applicable
DU001359	Ground Floor	University	1.01A	Compressed fibre gasket debris and to pipework	No Asbestos Detected	Analysis of sample using PLM	6 units	E0	Not applicable
DU001360	Ground Floor	University	1.03	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001367	Ground Floor	University	1.25	Insulating board panels to risers	No Asbestos Detected	Analysis of sample using PLM	8 m ²	E0	Not applicable
As DU001367	Ground Floor	University	1.24	Insulating board panels to risers	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
As DU001367	Ground Floor	University	1.23	Insulating board panels to risers	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
DU001372	Ground Floor	University	1.99B	Insulating board door headers	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
DU001373	Ground Floor	University	1.22A	Insulating board infill to concrete stairs	No Asbestos Detected	Analysis of sample using PLM	6 linear metres	E0	Not applicable
As DU001367	Ground Floor	University	1.22	Insulating board panels to risers	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001375	Ground Floor	University	1.22	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
As DU001367	Ground Floor	University	1.21	Insulating board panels to risers	No Asbestos Detected	Strongly presumed	5 m ²	E0	Not applicable
DU001378	Ground Floor	University	1.20B	Insulating board panel to riser	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
DU001379	Ground Floor	University	1.20B	Insulating board panel to door	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
DU001381	Ground Floor	University	1.20B	Bitumen damp proof course	No Asbestos Detected	Analysis of sample using PLM	250 linear metres	E0	Not applicable
As DU001378	Ground Floor	University	1.19	Insulating board panels to risers	No Asbestos Detected	Strongly presumed	6 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001387	Ground Floor	University	1.18A	Insulating board panel to riser	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
As DU001387	Ground Floor	University	1.17B	Insulating board panel to riser	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
As DU001387	Ground Floor	University	1.15	Insulating board panel to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
As DU001387	Ground Floor	University	1.14A	Insulating board panel to riser	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
As DU001387	Ground Floor	University	1.13	Insulating board panel to riser	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
As DU001387	Ground Floor	University	1.13A	Insulating board panel to riser	No Asbestos Detected	Strongly presumed	3 linear metres	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001390	Ground Floor	University	1.99D	Insulating board door header panels	No Asbestos Detected	Analysis of sample using PLM	10 m ²	E0	Not applicable
DU001393	1st Floor	University	2.99	Insulating board door header panels	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
DU001392	1st Floor	University	2.99	Insulating board door header panels	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
DU001391	1st Floor	University	2.99	Insulating board panel to room 2.11	No Asbestos Detected	Analysis of sample using PLM	3 linear metres	E0	Not applicable
DU001394	1st Floor	University	2.99	Bitumen damp proof course	No Asbestos Detected	Analysis of sample using PLM	7 linear metres	E0	Not applicable
DU001396	1st Floor	University	2.03	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001400	1st Floor	University	2.27C	Insulating board panels to risers	No Asbestos Detected	Analysis of sample using PLM	3 linear metres	E0	Not applicable
As DU001400	1st Floor	University	2.27B	Insulating board panels to risers	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
As DU001400	1st Floor	University	2.26	Insulating board panels to risers	No Asbestos Detected	Strongly presumed	6 m ²	E0	Not applicable
As DU001400	1st Floor	University	2.25	Insulating board panels to risers	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
DU001404	1st Floor	University	2.25	Bitumen damp proof course	No Asbestos Detected	Analysis of sample using PLM	250 linear metres	E0	Not applicable
DU001408	1st Floor	University	2.23C	Insulating board panel to riser	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001411	1st Floor	University	2.22	Insulating board panels to riser	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
As DU001411	1st Floor	University	2.22A	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
As DU001411	1st Floor	University	2.22B	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
DU001415	1st Floor	University	2.22B	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable
DU001417	1st Floor	University	2.99A	Thermoplastic floor tiles	No Asbestos Detected	Analysis of sample using PLM	18 m ²	E0	Not applicable
As DU001417	1st Floor	University	2.21C	Thermoplastic floor tiles	No Asbestos Detected	Strongly presumed	8 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001411	1st Floor	University	2.21	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	7 m ²	E0	Not applicable
As DU001411	1st Floor	University	2.21B	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
As DU001411	1st Floor	University	2.19	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
DU001418	1st Floor	University	2.00A	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
As DU001411	1st Floor	University	2.17	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
DU001420	1st Floor	University	2.99B	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	7 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001421	1st Floor	University	2.99B	Insulating board door header panels	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
DU001424	1st Floor	University	2.14B	Insulating board panels to riser	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
As DU001424	1st Floor	University	2.12B	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
As DU001424	1st Floor	University	2.11	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	5 m ²	E0	Not applicable
DU001430	1st Floor	University	2.11	Insulating board panel above window	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
DU001431	1st Floor	University	2.99C	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	6 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001432	1st Floor	University	2.99C	Insulating board door header panels	No Asbestos Detected	Analysis of sample using PLM	5 m ²	E0	Not applicable
DU001434	2nd Floor	University	3.03	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable
DU001437	2nd Floor	University	3.99	Insulating board door header panels	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
DU001438	2nd Floor	University	3.99	Bitumen damp proof course	No Asbestos Detected	Analysis of sample using PLM	10 linear metres	E0	Not applicable
DU001441	2nd Floor	University	3.32A	Thermoplastic floor tile debris within wall void	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
DU001443	2nd Floor	University	3.31	Insulating board panels to riser	No Asbestos Detected	Analysis of sample using PLM	6 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001443	2nd Floor	University	3.30	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
As DU001443	2nd Floor	University	3.27	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
As DU001443	2nd Floor	University	3.26	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	5 m ²	E0	Not applicable
DU001451	2nd Floor	University	3.24	Insulating board panels to riser	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
As DU001451	2nd Floor	University	3.23	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	6 m ²	E0	Not applicable
DU001454	2nd Floor	University	3.23	Bitumen damp proof course	No Asbestos Detected	Analysis of sample using PLM	250 linear metres	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001451	2nd Floor	University	3.19	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
As DU001451	2nd Floor	University	3.18	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
As DU001451	2nd Floor	University	3.17	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
As DU001451	2nd Floor	University	3.15	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
As DU001451	2nd Floor	University	3.14A	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	3 linear metres	E0	Not applicable
DU001459	2nd Floor	University	3.00A	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001462	2nd Floor	University	3.13	Insulating board panels to riser	No Asbestos Detected	Analysis of sample using PLM	6 m ²	E0	Not applicable
As DU001462	2nd Floor	University	3.10	Insulating board panels to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
DU001466	3rd Floor	University	4.06	Reinforced plastic cistern	No Asbestos Detected	Analysis of sample using PLM	1 unit	E0	Not applicable
DU001471	3rd Floor	University	4.99	Insulating board door header panels	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
DU001473	3rd Floor	University	4.99	Bitumen damp proof course	No Asbestos Detected	Analysis of sample using PLM	10 linear metres	E0	Not applicable
DU001478	3rd Floor	University	4.38A	Insulating board panels to riser	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001480	3rd Floor	University	4.27	Bitumen damp proof course	No Asbestos Detected	Analysis of sample using PLM	250 linear metres	E0	Not applicable
DU001481	3rd Floor	University	4.26	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	14 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.25	Textured coating to concrete	No Asbestos Detected	Strongly presumed	8 m ²	E0	Not applicable
DU001484	3rd Floor	University	4.25	Insulating board panel to riser	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.24	Textured coating to concrete	No Asbestos Detected	Strongly presumed	6 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.23	Textured coating to concrete	No Asbestos Detected	Strongly presumed	12 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001481	3rd Floor	University	4.22	Textured coating to concrete	No Asbestos Detected	Strongly presumed	10 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.21	Textured coating to concrete ceiling	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable
DU001485	3rd Floor	University	4.99A	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
DU001486	3rd Floor	University	4.99A	Insulating board door header panels	No Asbestos Detected	Analysis of sample using PLM	7 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.20	Textured coating to concrete ceiling	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.19	Textured coating to concrete ceiling	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001487	3rd Floor	University	4.19	Insulating board panel to riser	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.18	Textured coating to concrete ceiling	No Asbestos Detected	Strongly presumed	12 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.17	Textured coating to concrete ceiling	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable
As DU001487	3rd Floor	University	4.17	Insulating board panel to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.33	Textured coating to concrete ceiling	No Asbestos Detected	Strongly presumed	12 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.33A	Textured coating to concrete ceiling	No Asbestos Detected	Strongly presumed	8 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU001481	3rd Floor	University	4.16	Textured coating to concrete ceiling	No Asbestos Detected	Strongly presumed	12 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.15A	Textured coating to concrete ceiling	No Asbestos Detected	Strongly presumed	10 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.15	Textured coating to concrete	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable
DU001489	3rd Floor	University	4.15	Insulating board panels to risers	No Asbestos Detected	Analysis of sample using PLM	6 m ²	E0	Not applicable
DU001491	3rd Floor	University	4.00A	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
As DU001481	3rd Floor	University	4.00A	Textured coating to concrete ceiling	No Asbestos Detected	Strongly presumed	30 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001492	3rd Floor	University	4.99B	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	7 m ²	E0	Not applicable
DU001493	3rd Floor	University	4.99B	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
DU001498	3rd Floor	University	4.13	Insulating board panel to riser	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
As DU001498	3rd Floor	University	4.12	Insulating board panel to riser	No Asbestos Detected	Strongly presumed	3 m ²	E0	Not applicable
As DU001498	3rd Floor	University	4.11	Insulating board panel to riser	No Asbestos Detected	Strongly presumed	5 m ²	E0	Not applicable
DU001500	3rd Floor	University	4.99C	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	6 m ²	E0	Not applicable


Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001501	L - Loft	University	R.01	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
DU001504	L - Loft	University	R.03	Insulation to pipework	No Asbestos Detected	Analysis of sample using PLM	6 linear metres	E0	Not applicable
DU001505	L - Loft	University	R.03	Insulation to pipework	No Asbestos Detected	Analysis of sample using PLM	6 linear metres	E0	Not applicable
DU001506	L - Loft	University	R.03	Insulation to pipework	No Asbestos Detected	Analysis of sample using PLM	6 linear metres	E0	Not applicable
DU001507	L - Loft	University	R.03	Insulation to pipework	No Asbestos Detected	Analysis of sample using PLM	6 linear metres	E0	Not applicable
DU001508	L - Loft	University	R.03	Insulation to pipework	No Asbestos Detected	Analysis of sample using PLM	6 linear metres	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU001510	L - Loft	University	R.03	Compressed fibre gasket	No Asbestos Detected	Analysis of sample using PLM	8 units	E0	Not applicable
DU001511	L - Loft	University	R.03	Textile seal to flue pipe	No Asbestos Detected	Analysis of sample using PLM	2 linear metres	E0	Not applicable
DU001512	E - External	University	External Balcony	Insulating board canopy	No Asbestos Detected	Analysis of sample using PLM	250 m ²	E0	Not applicable
DU001513	E - External	University	External Balcony	Insulating board panels to riser	No Asbestos Detected	Analysis of sample using PLM	21 m ²	E0	Not applicable
DU001515	E - External	University	External	Insulating board canopy	No Asbestos Detected	Analysis of sample using PLM	100 m ²	E0	Not applicable
DU001516	E - External	University	External	Insulating board canopy over front entrance	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable

4.0 Item Register & Management Report


The following pages show a register of all suspect materials located during this investigation, which includes a photographic record of each item along with individual risk assessment scores.

The section entitled 'Portal Ref No' relates to a corresponding number assigned to each sample for the purpose of identification within the TEAMS online Portal.

Location:	1.99	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001354	Portal Ref No.:	1	27/04/2018 08:48:34
Item:	Insulating board fillet strip above sliding doors			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	6 linear metres		
Comments: Both sliding doors parallel to Cox building entrance				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.99	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001355	Portal Ref No.:	3	
Item:	Insulating board door header panels			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 m ²	
Comments: Leading to rooms 1.02, 1.03 and 1.04				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.99	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001356	Portal Ref No.:	5	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 m ²	
Comments: Above door to room 1.01				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.99	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001357	Portal Ref No.:	6	
Item:	Insulating board fillet above red sliding doors			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 linear metres	
Comments: Both entrances to dawson building red sliding doors				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.99	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001358	Portal Ref No.:	7	
Item:	Asbestos Insulating board debris within riser			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: Evidence of removal work taking place previously, potential for more insulating board to be present within the riser				


Material Assessment Total Score: 9		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B13
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	3 (Significant damage)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.01A	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001359	Portal Ref No.:	14	
Item:	Compressed fibre gasket debris and to pipework			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 units	
Comments: To gas pipework only				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.03	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001360	Portal Ref No.:	19	
Item:	Bitumen sink pad			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.05	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001361	Portal Ref No.:	20	
Item:	Asbestos Insulating board door header panel			
Asbestos Content:	Result Based on:			
Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: Board is loose				


Material Assessment Total Score: 7		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B12
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	2 (Easily disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.05	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001362	Portal Ref No.:	21	
Item:	Asbestos Reinforced plastic cistern			
Asbestos Content:	Result Based on:			
Amosite	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	1 unit	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	2 (Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.00	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001363	Portal Ref No.:	23	
Item:	Asbestos Insulating board door header panel			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 m ²		
Comments: Double skin, to fire exit door				

Material Assessment Total Score: 7		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B11
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.27	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001364	Portal Ref No.:	24	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	10 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.27	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001365	Portal Ref No.:	25	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	10 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 7		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	3 (Routinely disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.26	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001366	Portal Ref No.:	27	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	10 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.26	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001365	Portal Ref No.:	28	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.25	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001366	Portal Ref No.:	29	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	56 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	1.25	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001367	Portal Ref No.:	30	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	8 m ²	
Comments: 3 x risers				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.25	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001368	Portal Ref No.:	31	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	16 linear metres		
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.25	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001369	Portal Ref No.:	32	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	20 linear metres		
Comments: Continues into room 1.27, to ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.25	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001370	Portal Ref No.:	33	
Item:	Asbestos Insulating board debris to base of riser			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: The whole riser area should be presumed to be contaminated.				


Material Assessment Total Score: 9		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B13
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	3 (Significant damage)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.24	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001366	Portal Ref No.:	34	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	88 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	1.24	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001367	Portal Ref No.:	35	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: 1 x riser				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.24	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001368	Portal Ref No.:	36	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.24	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001369	Portal Ref No.:	37	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.23	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001366	Portal Ref No.:	38	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	80 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	1.23	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001367	Portal Ref No.:	39	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: 1 x riser				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.23	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001368	Portal Ref No.:	40	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.23	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001369	Portal Ref No.:	41	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.24	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001371	Portal Ref No.:	42	
Item:	Asbestos Bitumen adhesive to concrete			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	88 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	1.23	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001371	Portal Ref No.:	43	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	80 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	1.99B	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001372	Portal Ref No.:	44	
Item:	Insulating board door headers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 m ²	
Comments: Above double doors leading to room 1.99D and 1.22				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.22A	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001373	Portal Ref No.:	45	
Item:	Insulating board infill to concrete stairs			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 linear metres	
Comments: Both sides of stairs				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.22	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001366	Portal Ref No.:	46	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	1.22	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001367	Portal Ref No.:	47	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: 1 x riser				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.22	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001368	Portal Ref No.:	48	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.22	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001369	Portal Ref No.:	49	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.22	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001374	Portal Ref No.:	50	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	50 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	1.22	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001375	Portal Ref No.:	51	
Item:	Insulating board door header panel			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.21	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001366	Portal Ref No.:	53	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	64 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	1.21	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001367	Portal Ref No.:	54	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	5 m ²	
Comments: 2 x risers				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.21	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001368	Portal Ref No.:	55	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.21	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001369	Portal Ref No.:	56	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.21	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001376	Portal Ref No.:	57	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	64 m ²		
Comments: Present beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	1.20B	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001377	Portal Ref No.:	61	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.20B	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001378	Portal Ref No.:	62	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 m ²	
Comments: Top panel only				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.20B	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001379	Portal Ref No.:	63	
Item:	Insulating board panel to door			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments: Presume door leads to external, currently pad locked shut				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.20B	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001380	Portal Ref No.:	64	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: Present within wall heater void				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.20B	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001381	Portal Ref No.:	65	
Item:	Bitumen damp proof course			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	250 linear metres	
Comments: One sample representing the entire perimeter of the floor level, dpc present to the external wall of the wall void				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.20A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001377	Portal Ref No.:	67	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: Present above suspended ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.19	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001377	Portal Ref No.:	73	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	36 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.19	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001378	Portal Ref No.:	74	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: 2 x risers				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.19	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001382	Portal Ref No.:	75	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	12 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.19	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001380	Portal Ref No.:	76	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 linear metres	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.18B	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001377	Portal Ref No.:	81	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present above suspended ceiling				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.18B	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001382	Portal Ref No.:	82	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.18B	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001380	Portal Ref No.:	83	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.18B	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001383	Portal Ref No.:	84	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	12 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.18	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001377	Portal Ref No.:	85	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	24 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.18	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001382	Portal Ref No.:	86	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.18	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001380	Portal Ref No.:	87	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.18	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001383	Portal Ref No.:	88	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	24 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.99C	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001377	Portal Ref No.:	89	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: Present to small section of ceiling, above suspended ceiling tiles				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.18A	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001384	Portal Ref No.:	90	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	18 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.18A	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001386	Portal Ref No.:	92	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	3 m ²		
Comments: To ceiling of wall void behind polystyrene				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.18A	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001388	Portal Ref No.:	93	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	18 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.18A	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001385	Portal Ref No.:	94	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 linear metres		
Comments: Present within the wall heater void				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.18A	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001387	Portal Ref No.:	95	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments: 1 x riser top 2 panels				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.17B	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001384	Portal Ref No.:	97	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.17B	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001386	Portal Ref No.:	98	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.17B	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001385	Portal Ref No.:	100	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.17B	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001387	Portal Ref No.:	101	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: 1 x riser top 2 panels				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.17A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001384	Portal Ref No.:	102	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	24 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.17A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001386	Portal Ref No.:	103	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.17A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001385	Portal Ref No.:	104	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.16	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001384	Portal Ref No.:	105	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.16	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001388	Portal Ref No.:	107	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.15	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001384	Portal Ref No.:	108	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	15 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.15	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001386	Portal Ref No.:	109	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.15	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001385	Portal Ref No.:	110	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.15	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001387	Portal Ref No.:	111	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: 1 x riser				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.14	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001384	Portal Ref No.:	113	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.14	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001386	Portal Ref No.:	114	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.14	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001385	Portal Ref No.:	115	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.14A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001384	Portal Ref No.:	117	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present above suspended ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.14A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001386	Portal Ref No.:	118	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.14A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001385	Portal Ref No.:	119	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.14A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001387	Portal Ref No.:	120	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: Top two panels				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.12	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001384	Portal Ref No.:	121	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Above suspended ceiling tiles				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.12	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001386	Portal Ref No.:	122	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.12	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001385	Portal Ref No.:	123	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.13	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001384	Portal Ref No.:	125	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.13	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001386	Portal Ref No.:	126	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.13	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001385	Portal Ref No.:	127	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.13	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001387	Portal Ref No.:	128	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: Top two panels				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.13A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001384	Portal Ref No.:	129	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.13A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001386	Portal Ref No.:	130	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.13A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001385	Portal Ref No.:	131	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.13A	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001387	Portal Ref No.:	132	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	1.13A	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001389	Portal Ref No.:	133	
Item:	Asbestos Insulating board debris to base of riser			
Asbestos Content:	Result Based on:			
Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
<p>Comments: The whole riser area should be presumed to be contaminated. Evidence of previous asbestos removal work remain within the riser.</p>				


Material Assessment Total Score: 9		Likelihood of Disturbance Assessment Total Score: 4		<p>Management Assessment</p> <p>Licensable: Yes</p> <p>Recommendations: Program removal</p> <p>Reinspection Interval: Not Applicable</p> <p>Overall Risk Category: B13</p>
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	3 (Significant damage)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	1.99D	Block:	University	Floor Level: Ground Floor
Sample No.:	As DU001384	Portal Ref No.:	134	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Small section of ceiling, above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	1.99D	Block:	University	Floor Level: Ground Floor
Sample No.:	DU001390	Portal Ref No.:	135	
Item:	Insulating board door header panels			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	10 m ²		
Comments: Above doors leading to rooms 1.25, 1.24A, 1.24, 1.23, 1.17B, 1.18A, 1.14 and 1.15. The board is labelled PE Board				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.99	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001393	Portal Ref No.:	138	
Item:	Insulating board door header panels			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments: Leading to corridor				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.99	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001392	Portal Ref No.:	140	
Item:	Insulating board door header panels			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 m ²		
Comments: Above doors to room 2.01, 2.02, 2.03 and 2.04				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.99	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001391	Portal Ref No.:	141	
Item:	Insulating board panel to room 2.11			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 linear metres	
Comments: Above sliding doors leading to the balcony				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.99	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001394	Portal Ref No.:	142	
Item:	Bitumen damp proof course			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	7 linear metres	
Comments: To ceiling concrete level drops				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.04	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001395	Portal Ref No.:	143	
Item:	Asbestos Insulating board panels			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: Also visible packed in brickwork				


Material Assessment Total Score: 7		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B11
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.03	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001396	Portal Ref No.:	149	
Item:	Bitumen sink pad			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.05	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001397	Portal Ref No.:	150	
Item:	Asbestos Insulating board door header panel			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 7		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B11
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.05	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001398	Portal Ref No.:	151	
Item:	Asbestos Reinforced plastic cistern			
Asbestos Content:	Result Based on:			
Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 unit		
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	2 (Amosite)	Extent Score:	0 (Small amounts or items)	

Management Detail

Location:	2.27C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001399	Portal Ref No.:	154	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	10 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.27C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001400	Portal Ref No.:	155	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 linear metres	
Comments: 1 x riser				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.27C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001401	Portal Ref No.:	156	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 linear metres		
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.27C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001402	Portal Ref No.:	157	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 m ²		
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail


Location:	2.27C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001403	Portal Ref No.:	158	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	10 m ²	
Comments: Present beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail


Location:	2.27B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001399	Portal Ref No.:	159	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	
Management Detail				

Location:	2.27B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001400	Portal Ref No.:	160	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: 1 x riser				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.27B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001401	Portal Ref No.:	161	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.27B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001402	Portal Ref No.:	162	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.27B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001403	Portal Ref No.:	163	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.27A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001399	Portal Ref No.:	164	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.27A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001401	Portal Ref No.:	166	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.27A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001402	Portal Ref No.:	167	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.27A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001403	Portal Ref No.:	168	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: Present beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.27	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001399	Portal Ref No.:	169	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.27	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001403	Portal Ref No.:	172	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.26	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001399	Portal Ref No.:	173	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	80 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	2.26	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001400	Portal Ref No.:	174	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: 2 x riser				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.26	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001401	Portal Ref No.:	175	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.26	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001402	Portal Ref No.:	176	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.26	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001403	Portal Ref No.:	177	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	80 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	2.25	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001399	Portal Ref No.:	178	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	64 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	2.25	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001400	Portal Ref No.:	179	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: Top two panels				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.25	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001401	Portal Ref No.:	180	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.25	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001402	Portal Ref No.:	181	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.25	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001404	Portal Ref No.:	182	
Item:	Bitumen damp proof course			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	250 linear metres	
Comments: To entire perimeter of floor level external wall of heater void				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.23C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001405	Portal Ref No.:	184	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	15 m ²	
Comments: Above suspended tiles				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.23C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001406	Portal Ref No.:	186	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 linear metres		
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.23C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001407	Portal Ref No.:	187	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Chrysotile			
Result Based on:	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.23C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001409	Portal Ref No.:	188	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	15 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.23C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001408	Portal Ref No.:	189	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.23B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001405	Portal Ref No.:	190	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	15 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.23B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001406	Portal Ref No.:	191	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.23B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001407	Portal Ref No.:	192	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.23B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001409	Portal Ref No.:	193	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	15 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.23A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001405	Portal Ref No.:	194	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.23A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001406	Portal Ref No.:	195	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.23A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001407	Portal Ref No.:	196	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.23A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001409	Portal Ref No.:	197	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.23	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001405	Portal Ref No.:	198	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.23	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001406	Portal Ref No.:	199	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.23	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001407	Portal Ref No.:	200	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Chrysotile			
Result Based on:	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.23	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001409	Portal Ref No.:	201	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.22	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001410	Portal Ref No.:	202	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	25 m ²		
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.22	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001412	Portal Ref No.:	203	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	4 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.22	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001413	Portal Ref No.:	204	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	5 m ²		
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.22	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001414	Portal Ref No.:	205	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	25 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.22	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001411	Portal Ref No.:	206	
Item:	Insulating board panels to riser			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	3 m ²		
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.22A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	207	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.22A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001412	Portal Ref No.:	208	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.22A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001413	Portal Ref No.:	209	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.22A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001414	Portal Ref No.:	210	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: Present beneath carpet.				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.22A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001411	Portal Ref No.:	211	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.22B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	213	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.22B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001412	Portal Ref No.:	214	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.22B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001413	Portal Ref No.:	215	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.22B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001414	Portal Ref No.:	216	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: Present beneath modern vinyl				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.22B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001411	Portal Ref No.:	217	 <p>30/04/2018 08:47:19</p>
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.22B	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001415	Portal Ref No.:	218	
Item:	Bitumen sink pad			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.22B	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001416	Portal Ref No.:	219	
Item:	Asbestos Thermoplastic floor tile debris within riser			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	<1 m ²		
Comments: One small piece				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	3 (Significant damage)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.99A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	220	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments: Above suspended tiles				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.99A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001414	Portal Ref No.:	221	
Item:	Asbestos Bitumen adhesive to concrete			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Present to section of the floor, beneath carpet.				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.99A	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001417	Portal Ref No.:	222	
Item:	Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	18 m ²		
Comments: Section of the corridor floor				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.21C	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001417	Portal Ref No.:	223	
Item:	Thermoplastic floor tiles			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: Section of the corridor floor				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.21	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	224	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	90 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	2.21	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001412	Portal Ref No.:	225	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	15 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.21	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001413	Portal Ref No.:	226	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	15 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.21	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001414	Portal Ref No.:	227	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	90 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	2.21	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001411	Portal Ref No.:	228	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	7 m ²	
Comments: 3 x risers				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.21B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	229	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.21B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001413	Portal Ref No.:	231	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.21B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001414	Portal Ref No.:	232	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.21B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001411	Portal Ref No.:	233	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: bottom and top section				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.20	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	234	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.20	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001413	Portal Ref No.:	235	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.20	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001412	Portal Ref No.:	238	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.19	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	239	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.19	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001412	Portal Ref No.:	240	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.19	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001413	Portal Ref No.:	241	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.19	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001411	Portal Ref No.:	243	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.18	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	244	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.18	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001412	Portal Ref No.:	245	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.18	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001413	Portal Ref No.:	246	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Chrysotile			
Result Based on:	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.00A	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001418	Portal Ref No.:	247	
Item:	Insulating board door header panel			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Double skin				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.24A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	248	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.24A	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001419	Portal Ref No.:	249	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	8 m ²		
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.17	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	250	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	9 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.17	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001412	Portal Ref No.:	251	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.17	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001413	Portal Ref No.:	252	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.17	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001411	Portal Ref No.:	253	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.16	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	254	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.16	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001412	Portal Ref No.:	255	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.16	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001413	Portal Ref No.:	256	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.24	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	257	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.24	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001419	Portal Ref No.:	258	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.15	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001410	Portal Ref No.:	259	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.15	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001412	Portal Ref No.:	260	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.15	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001413	Portal Ref No.:	261	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.99B	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001420	Portal Ref No.:	265	
Item:	Insulating board door header panel			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	7 m ²	
Comments: Visibly similar door header above doors to 2.15, 2.16, 2.17, 2.18, 2.20 and 2.21				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.99B	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001421	Portal Ref No.:	266	
Item:	Insulating board door header panels			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Visibly similar above doors to rooms 2.24A, 2.24 and leading to next corridor 2.99C				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.14B	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001422	Portal Ref No.:	268	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	14 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.14B	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001423	Portal Ref No.:	269	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 linear metres		
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.14B	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001425	Portal Ref No.:	270	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	3 m ²		
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.14B	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001424	Portal Ref No.:	271	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.14B	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001426	Portal Ref No.:	272	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	14 m ²		
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.14A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001422	Portal Ref No.:	273	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.14A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001423	Portal Ref No.:	274	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.14A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001425	Portal Ref No.:	275	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.14A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001426	Portal Ref No.:	277	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.13	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001422	Portal Ref No.:	278	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	24 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.13	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001423	Portal Ref No.:	279	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.13	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001425	Portal Ref No.:	280	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.13	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001426	Portal Ref No.:	281	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	24 m ²	
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.12B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001422	Portal Ref No.:	282	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.12B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001423	Portal Ref No.:	283	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.12B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001425	Portal Ref No.:	284	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.12B	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001424	Portal Ref No.:	285	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.12B	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001427	Portal Ref No.:	286	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	14 m ²		
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.12A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001422	Portal Ref No.:	287	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.12A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001423	Portal Ref No.:	288	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.12A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001425	Portal Ref No.:	289	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.12A	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001427	Portal Ref No.:	290	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.11	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001422	Portal Ref No.:	291	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	28 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.11	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001423	Portal Ref No.:	292	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.11	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001425	Portal Ref No.:	293	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.11	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001424	Portal Ref No.:	294	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	5 m ²	
Comments: 2 x risers				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.11	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001428	Portal Ref No.:	295	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	28 m ²		
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	2.11	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001429	Portal Ref No.:	296	
Item:	Asbestos Insulating board debris within riser			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: Whole riser area should be presumed to be contaminated.				


Material Assessment Total Score: 9		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B13
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	3 (Significant damage)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.11	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001430	Portal Ref No.:	297	
Item:	Insulating board panel above window			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.99C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001431	Portal Ref No.:	298	
Item:	Insulating board door header panel			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 m ²	
Comments: Visibly similar door header above doors to 2.25, 2.26, 2.14, 2.13, 2.12, 2.11 and 2.27				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.99C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001432	Portal Ref No.:	299	
Item:	Insulating board door header panels			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	5 m ²		
Comments: Visibly similar above doors to rooms 2.27B, 2.27A, 2.27C and upstand to suspended ceiling leading to this section				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	2.99C	Block:	University	Floor Level: 1st Floor
Sample No.:	As DU001422	Portal Ref No.:	301	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	9 m ²	
Comments: To recess sections of main corridor only				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	2.99C	Block:	University	Floor Level: 1st Floor
Sample No.:	DU001433	Portal Ref No.:	302	
Item:	Asbestos Bitumen adhesive to concrete			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	9 m ²		
Comments: To recess sections of main corridor only				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.03	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001434	Portal Ref No.:	305	
Item:	Bitumen sink pad			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.05	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001435	Portal Ref No.:	307	
Item:	Asbestos Insulating board door header panel			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments:				


Material Assessment Total Score: 7		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B11
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.05	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001436	Portal Ref No.:	308	
Item:	Asbestos Reinforced plastic cistern			
Asbestos Content:	Result Based on:			
Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 unit		
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	2 (Amosite)	Extent Score:	0 (Small amounts or items)	

Management Detail

Location:	3.99	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001437	Portal Ref No.:	309	
Item:	Insulating board door header panels			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Leading to corridor				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.99	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001438	Portal Ref No.:	312	
Item:	Bitumen damp proof course			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	10 linear metres	
Comments: To ceiling concrete where level drops				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.32A	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001439	Portal Ref No.:	313	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	6 m ²		
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.32A	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001440	Portal Ref No.:	314	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	6 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.32A	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001441	Portal Ref No.:	315	
Item:	Thermoplastic floor tile debris within wall void			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments: Within left hand opening to wall voids				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.32	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001439	Portal Ref No.:	317	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.32	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001440	Portal Ref No.:	318	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: Present beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.32B	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001439	Portal Ref No.:	319	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.32B	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001440	Portal Ref No.:	320	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.31	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001439	Portal Ref No.:	321	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	60 m ²	
Comments: Present above suspended ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	3.31	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001442	Portal Ref No.:	322	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	15 linear metres		
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.31	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001444	Portal Ref No.:	323	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	15 m ²		
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.31	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001443	Portal Ref No.:	324	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 m ²	
Comments: 2 x risers				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.31	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001446	Portal Ref No.:	325	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	60 m ²		
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	3.31	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001445	Portal Ref No.:	326	
Item:	Asbestos Insulating board panel to ceiling of riser			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments:				


Material Assessment Total Score: 8		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B12
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	2 (Local damage)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.30	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001439	Portal Ref No.:	327	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	60 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	3.30	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001442	Portal Ref No.:	328	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.30	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001444	Portal Ref No.:	329	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.30	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001443	Portal Ref No.:	330	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: 1 x riser top two panels				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.27	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001439	Portal Ref No.:	331	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	3.27	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001442	Portal Ref No.:	332	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.27	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001444	Portal Ref No.:	333	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.27	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001443	Portal Ref No.:	334	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.27	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001447	Portal Ref No.:	335	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	50 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	3.26	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001439	Portal Ref No.:	336	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	54 m ²	
Comments: Present above suspended ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	3.26	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001442	Portal Ref No.:	337	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.26	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001444	Portal Ref No.:	338	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	9 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.26	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001443	Portal Ref No.:	339	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	5 m ²	
Comments: 2 x risers				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.26	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001448	Portal Ref No.:	340	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	54 m ²		
Comments: Present beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	3.99A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001448	Portal Ref No.:	342	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	80 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	3.99A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001439	Portal Ref No.:	343	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.24	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001449	Portal Ref No.:	344	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.24	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001450	Portal Ref No.:	345	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.24	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001453	Portal Ref No.:	346	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 m ²		
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.24	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001451	Portal Ref No.:	347	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments: Top two panels				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.24	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001452	Portal Ref No.:	348	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	25 m ²		
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.23	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	349	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	60 m ²	
Comments: Above ceiling tiles painted black				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	3.23	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	350	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.23	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	351	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.23	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001451	Portal Ref No.:	352	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.23	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001452	Portal Ref No.:	353	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	60 m ²	
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	3.23	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001454	Portal Ref No.:	354	
Item:	Bitumen damp proof course			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	250 linear metres	
Comments: To entire perimeter of floor level to the external wall of the wall void				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.21	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	355	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.21	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001455	Portal Ref No.:	356	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	8 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.20	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	357	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	24 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.20	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	358	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.20	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	359	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.19	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	360	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.19	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	361	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.19	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	362	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.19	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001451	Portal Ref No.:	363	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.18	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	364	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.18	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	365	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.18	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	366	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.18	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001451	Portal Ref No.:	367	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.17	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	368	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.17	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	369	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.17	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	370	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.17	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001451	Portal Ref No.:	371	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: top 2 panels				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.16	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	372	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.16	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	373	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.16	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	374	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.15A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	375	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Above ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.15A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	376	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.15A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	377	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.15	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	378	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.15	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	379	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.15	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	380	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.15	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001451	Portal Ref No.:	381	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.15	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001456	Portal Ref No.:	382	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	18 m ²		
Comments: Present beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.14A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	383	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present above suspended ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.14A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	384	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.14A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	385	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.14A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001451	Portal Ref No.:	386	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments: Continuation from adjoining room				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.14A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001456	Portal Ref No.:	387	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.14	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	388	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present above suspended ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.14	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	389	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.14	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	390	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.14	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001456	Portal Ref No.:	392	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.13A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001449	Portal Ref No.:	393	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present above suspended ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.13A	Block:	University		Floor Level: 2nd Floor
Sample No.:	As DU001450	Portal Ref No.:	394		
Item:	Asbestos Cement window sill				
Asbestos Content:	Result Based on:				
Chrysotile	Strongly presumed				
Sample Analysed By:	Not applicable	Extent:	2 linear metres		
Comments:					


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.13A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001453	Portal Ref No.:	395	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.13A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001456	Portal Ref No.:	396	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.28	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001457	Portal Ref No.:	397	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.28	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001458	Portal Ref No.:	398	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	12 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.00A	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001459	Portal Ref No.:	399	
Item:	Insulating board door header panel			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Both doors leading to the stairwell				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.99B	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001456	Portal Ref No.:	401	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	9 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.99B	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001457	Portal Ref No.:	402	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	9 m ²	
Comments: Above suspended tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.13	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001457	Portal Ref No.:	403	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	40 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.13	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001460	Portal Ref No.:	404	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	6 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.13	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001461	Portal Ref No.:	405	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	6 m ²		
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.13	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001462	Portal Ref No.:	406	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 m ²	
Comments: 2 x risers				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.13	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001463	Portal Ref No.:	407	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	40 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.11	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001457	Portal Ref No.:	408	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present above suspended ceiling				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail


Location:	3.11	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001460	Portal Ref No.:	409	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail


Location:	3.11	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001461	Portal Ref No.:	410	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	
Management Detail				

Location:	3.11	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001464	Portal Ref No.:	412	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	12 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.12	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001457	Portal Ref No.:	413	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present above suspended ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.12	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001460	Portal Ref No.:	414	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.12	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001461	Portal Ref No.:	415	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.12	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001464	Portal Ref No.:	416	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.10A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001457	Portal Ref No.:	417	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present above suspended ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.10A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001460	Portal Ref No.:	418	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.10A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001461	Portal Ref No.:	419	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.10A	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001464	Portal Ref No.:	420	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.10	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001457	Portal Ref No.:	421	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	49 m ²	
Comments: Present above suspended ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.10	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001460	Portal Ref No.:	422	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.10	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001461	Portal Ref No.:	423	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	3.10	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001462	Portal Ref No.:	424	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	3.09	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001460	Portal Ref No.:	426	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.09	Block:	University	Floor Level: 2nd Floor
Sample No.:	As DU001461	Portal Ref No.:	427	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	3.09	Block:	University	Floor Level: 2nd Floor
Sample No.:	DU001465	Portal Ref No.:	429	
Item:	Asbestos Insulating board debris within riser			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: The riser area should be presumed to be contaminated.				


Material Assessment Total Score: 9		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B13
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	3 (Significant damage)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.06	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001466	Portal Ref No.:	431	
Item:	Reinforced plastic cistern			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 unit	
Comments: Present at high level behind door				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.03	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001467	Portal Ref No.:	433	
Item:	Asbestos Insulating board door header panel			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: Double skin				

Material Assessment Total Score: 6		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.05	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001468	Portal Ref No.:	434	
Item:	Asbestos Insulating board door header panel			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments:				


Material Assessment Total Score: 7		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B11
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.05	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001469	Portal Ref No.:	435	
Item:	Asbestos Reinforced plastic cistern			
Asbestos Content:	Result Based on:			
Amosite	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	1 unit	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	2 (Amosite)	Extent Score:	0 (Small amounts or items)	

Management Detail

Location:	4.00	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001470	Portal Ref No.:	437	
Item:	Asbestos Insulating board door header panel			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 m ²		
Comments: Double skin				


Material Assessment Total Score: 7		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B11
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.99	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001471	Portal Ref No.:	439	
Item:	Insulating board door header panels			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	3 m ²		
Comments: Above doors to rooms. 4.01, 4.02 and 4.04				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.99	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001473	Portal Ref No.:	440	
Item:	Bitumen damp proof course			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	10 linear metres	
Comments: To ceiling concrete where level drops				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.99	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001472	Portal Ref No.:	441	
Item:	Asbestos Insulating board door header panel			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: Opposite side to sample DU1467 above door to room 4.03				


Material Assessment Total Score: 7		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B11
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.39	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001474	Portal Ref No.:	442	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	6 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.39	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001475	Portal Ref No.:	443	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	6 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.39A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001474	Portal Ref No.:	444	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	9 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.38A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001474	Portal Ref No.:	445	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.38A	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001476	Portal Ref No.:	446	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.38A	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001477	Portal Ref No.:	447	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 m ²		
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.38A	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001478	Portal Ref No.:	448	
Item:	Insulating board panels to riser			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 m ²		
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.38A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001475	Portal Ref No.:	449	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.38B	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001474	Portal Ref No.:	450	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.38B	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001476	Portal Ref No.:	451	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.38B	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001477	Portal Ref No.:	452	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.38B	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001475	Portal Ref No.:	454	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.38C	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001474	Portal Ref No.:	455	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.38C	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001476	Portal Ref No.:	456	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.38C	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001477	Portal Ref No.:	457	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.38C	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001475	Portal Ref No.:	458	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.34	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001474	Portal Ref No.:	459	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	70 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	4.34	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001476	Portal Ref No.:	460	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	7 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.34	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001477	Portal Ref No.:	461	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	7 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.34	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001475	Portal Ref No.:	463	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	70 m ²	
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	4.37	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001474	Portal Ref No.:	464	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	15 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.37	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001476	Portal Ref No.:	465	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.37	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001477	Portal Ref No.:	466	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.37	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001475	Portal Ref No.:	467	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	15 m ²	
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.34A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001474	Portal Ref No.:	468	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	4.34A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001476	Portal Ref No.:	469	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.34A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001477	Portal Ref No.:	470	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.34A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001475	Portal Ref No.:	471	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	4.31	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001474	Portal Ref No.:	472	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.27	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001474	Portal Ref No.:	473	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	48 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.27	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001476	Portal Ref No.:	474	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.27	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001477	Portal Ref No.:	475	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.27	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001479	Portal Ref No.:	476	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	48 m ²		
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.27	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001480	Portal Ref No.:	477	
Item:	Bitumen damp proof course			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	250 linear metres	
Comments: One sample for the entire perimeter of the floor level, item is to the external wall of the wall void				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.26	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001481	Portal Ref No.:	478	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	14 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.26	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001482	Portal Ref No.:	479	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.26	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001483	Portal Ref No.:	480	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 m ²		
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.25	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	482	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.25	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	483	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.25	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	484	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.25	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001484	Portal Ref No.:	485	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.24	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	486	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.24	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	487	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.24	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	488	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.23	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	489	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.23	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	490	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	7 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.23	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	491	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	7 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.22	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	492	
Item:	Textured coating to concrete			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.22	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	493	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.22	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	494	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.21	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	496	
Item:	Textured coating to concrete ceiling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.21	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	497	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.21	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	498	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.99A	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001485	Portal Ref No.:	500	
Item:	Insulating board door header panel			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Double skin, double doors leading to adjoining corridor				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.99A	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001486	Portal Ref No.:	501	
Item:	Insulating board door header panels			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	7 m ²	
Comments: Above doors leading to rooms, 4.21,22,23,25,26 and 4.27 visually similar product throughout				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.20	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	502	
Item:	Textured coating to concrete ceiling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.20	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	503	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.20	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	504	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.19	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	505	
Item:	Textured coating to concrete ceiling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.19	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	506	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.19	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	507	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.19	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001487	Portal Ref No.:	508	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 m ²	
Comments: Non suspect sampled to prove negative				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.18	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	509	
Item:	Textured coating to concrete ceiling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.18	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	510	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.18	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	511	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.17	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	512	
Item:	Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.17	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	513	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.17	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	514	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.17	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001487	Portal Ref No.:	515	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: Non suspect sampled to prove negative				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.33	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	516	
Item:	Textured coating to concrete ceiling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.33A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	517	
Item:	Textured coating to concrete ceiling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.33A	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001488	Portal Ref No.:	518	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	8 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	3 (Routinely disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.16	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	519	
Item:	Textured coating to concrete ceiling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.16	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	520	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.16	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	521	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.16	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001488	Portal Ref No.:	522	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.15A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	523	
Item:	Textured coating to concrete ceiling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.15A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	524	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.15A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	525	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.15A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001488	Portal Ref No.:	526	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.15	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	527	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.15	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001482	Portal Ref No.:	528	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.15	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001483	Portal Ref No.:	529	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	7 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.15	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001490	Portal Ref No.:	530	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	50 m ²		
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	4.15	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001489	Portal Ref No.:	531	
Item:	Insulating board panels to risers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.00A	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001491	Portal Ref No.:	532	
Item:	Insulating board door header panel			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Double skin, both double doors either side of the stairwell				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.00A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001481	Portal Ref No.:	533	
Item:	Textured coating to concrete ceiling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.99B	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001492	Portal Ref No.:	534	
Item:	Insulating board door header panel			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	7 m ²	
Comments: Above doors leading to rooms, 4.20, 19,18, 17, 33, 33A, 16 and 4.15, visually similar product to all areas listed				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.99B	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001493	Portal Ref No.:	535	
Item:	Insulating board door header panel			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 m ²		
Comments: Above doors leading to adjoining corridor 4.99C, double skin				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.14	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001494	Portal Ref No.:	536	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	24 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.14	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001495	Portal Ref No.:	537	
Item:	Asbestos Cement window sill			
Asbestos Content:	Chrysotile			
Result Based on:	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.14	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001496	Portal Ref No.:	538	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 m ²		
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.14	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001497	Portal Ref No.:	539	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	24 m ²		
Comments: Present beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.13	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001494	Portal Ref No.:	540	
Item:	Asbestos Textured coating to concrete			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	4.13	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001495	Portal Ref No.:	541	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 linear metres	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.13	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001496	Portal Ref No.:	542	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.13	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001499	Portal Ref No.:	543	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	50 m ²		
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	4.13	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001498	Portal Ref No.:	544	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.12	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001494	Portal Ref No.:	545	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.12	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001495	Portal Ref No.:	546	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.12	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001496	Portal Ref No.:	547	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.12	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001499	Portal Ref No.:	548	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.12	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001498	Portal Ref No.:	549	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.12A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001494	Portal Ref No.:	550	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments: Above suspended ceiling tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.12A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001495	Portal Ref No.:	551	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.12A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001496	Portal Ref No.:	552	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				

Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	4.12A	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001499	Portal Ref No.:	553	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments: Beneath carpet				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.11	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001494	Portal Ref No.:	554	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	24 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	
Management Detail				

Location:	4.11	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001495	Portal Ref No.:	555	
Item:	Asbestos Cement window sill			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.11	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001496	Portal Ref No.:	556	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: To ceiling of wall void behind polystyrene sheets				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.11	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001499	Portal Ref No.:	557	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	24 m ²	
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	4.11	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001498	Portal Ref No.:	558	
Item:	Insulating board panel to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	5 m ²	
Comments: 2 x risers				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.99C	Block:	University	Floor Level: 3rd Floor
Sample No.:	DU001500	Portal Ref No.:	559	
Item:	Insulating board door header panel			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	6 m ²		
Comments: Above doors leading to rooms, 4.14, 4.13, 4.12, 4.11, 4.34 and 4.39A				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	4.99C	Block:	University	Floor Level: 3rd Floor
Sample No.:	As DU001494	Portal Ref No.:	560	
Item:	Asbestos Textured coating to concrete ceiling			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Above suspended ceiling tiles to recess section of corridor only				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos textured coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	R.01	Block:	University	Floor Level: L - Loft
Sample No.:	DU001501	Portal Ref No.:	561	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 m ²	
Comments: Double skin				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	R.01	Block:	University		Floor Level: L - Loft
Sample No.:	DU001502	Portal Ref No.:	562		
Item:	Asbestos Insulating board panel to rear of timber boxing				
Asbestos Content:	Result Based on:				
Chrysotile Amosite	Analysis of sample using PLM				
Sample Analysed By: Reg 13(1)	Extent:	4 linear metres			
Comments:					


Material Assessment Total Score: 7		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B11
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	R.01	Block:	University	Floor Level: L - Loft
Sample No.:	DU001503	Portal Ref No.:	564	
Item:	Asbestos Insulating board lining to door			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 m ²		
Comments:				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	2 (Easily disturbed)	
Surface Treatment:	1 (Enclosed asbestos insulating board)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	R.03	Block:	University	Floor Level: L - Loft
Sample No.:	DU001504	Portal Ref No.:	565	
Item:	Insulation to pipework			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 linear metres	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	R.03	Block:	University	Floor Level: L - Loft
Sample No.:	DU001505	Portal Ref No.:	566	
Item:	Insulation to pipework			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 linear metres	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	R.03	Block:	University	Floor Level: L - Loft
Sample No.:	DU001506	Portal Ref No.:	567	
Item:	Insulation to pipework			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 linear metres	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	R.03	Block:	University	Floor Level: L - Loft
Sample No.:	DU001507	Portal Ref No.:	568	
Item:	Insulation to pipework			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 linear metres	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	R.03	Block:	University	Floor Level: L - Loft
Sample No.:	DU001508	Portal Ref No.:	569	
Item:	Insulation to pipework			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 linear metres	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	R.03	Block:	University	Floor Level: L - Loft
Sample No.:	DU001509	Portal Ref No.:	570	
Item:	Asbestos Compressed fibre gasket			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 units		
Comments: To blue and black pipework located behind boilers				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	2 (Compressed asbestos fibre)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Enclosed textile/paper)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	0 (Small amounts or items)	

Management Detail

Location:	R.03	Block:	University	Floor Level: L - Loft
Sample No.:	DU001510	Portal Ref No.:	571	
Item:	Compressed fibre gasket			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	8 units	
Comments: To pipework flanges to rear of boilers				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	R.03	Block:	University	Floor Level: L - Loft
Sample No.:	DU001511	Portal Ref No.:	573	
Item:	Textile seal to flue pipe			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 linear metres	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	External Balcony	Block:	University	Floor Level: E - External
Sample No.:	DU001512	Portal Ref No.:	574	
Item:	Insulating board canopy			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	250 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	External Balcony	Block:	University	Floor Level: E - External
Sample No.:	DU001513	Portal Ref No.:	575	
Item:	Insulating board panels to riser			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	21 m ²	
Comments: 7 x risers				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	External Balcony	Block:	University	Floor Level: E - External
Sample No.:	DU001514	Portal Ref No.:	576	
Item:	Asbestos Cement shuttering			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	7 m ²		
Comments: Internally to each riser				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 2		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos cement)	Location:	0 (Outdoors)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	External	Block:	University	Floor Level: E - External
Sample No.:	DU001515	Portal Ref No.:	578	
Item:	Insulating board canopy			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	100 m ²	
Comments: To level 1 external				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	External	Block:	University	Floor Level: E - External
Sample No.:	DU001516	Portal Ref No.:	579	
Item:	Insulating board canopy over front entrance			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Report No.: J094099
Issue Date: 11/06/2018




5.0 Annotated Building Plans

Diagrams included:

Plan(s) drawn by Bradley Environmental Consultants Ltd.

- J094099/01 - Ground Floor Plan - Positive Item Location(s)
- J094099/02 - Ground Floor Plan - Negative Item Location(s)
- J094099/03 - Ground Floor Plan - Intrusion Location(s)
- J094099/04 - First Floor Plan - Positive Item Location(s)
- J094099/05 - First Floor Plan - Negative Item Location(s)
- J094099/06 - First Floor Plan - Intrusion Location(s)
- J094099/07 - Second Floor Plan - Positive Item Location(s)
- J094099/08 - Second Floor Plan - Negative Item Location(s)
- J094099/09 - Second Floor Plan - Intrusion Location(s)
- J094099/10 - Third Floor Plan - Positive Item Location(s)
- J094099/11 - Third Floor Plan - Negative Item Location(s)
- J094099/12 - Third Floor Plan - Intrusion Location(s)
- J094099/13 - Roof Floor Plan - Positive Item Location(s)
- J094099/14 - Roof Floor Plan - Negative Item Location(s)
- J094099/15 - Roof Floor Plan - Intrusion Location(s)



KEY
 ?????? ASBESTOS ITEM LOCATION
 ??? ROOM NO.
 AREA/FEATURES NOT ACCESSED

Additional information:
 This diagram is only to be reproduced in colour.

Plan Abbreviations:
 AC - Asbestos Cement
 AIB - Asbestos Insulating Board
 AT - Asbestos Textile
 AI - Asbestos Insulation
 ATC - Asbestos Textured Coating
 AB - Asbestos Bitumen
 ATP - Asbestos Thermoplastic
 ACF - Asbestos Compressed Fibre

Drawing title:
 Asbestos Survey Plan (J094099/01)

Site address:
 Dawson Building
 Former City North Campus
 Birmingham City University
 Perry Barr
 B42 2US

Floor level(s): Ground Floor

This drawing is to be read in conjunction with survey report number: J094099

Date of work: 26/04/18 - 01/05/18

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
 20 Stourbridge Road
 Halesowen, West Midlands B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 email: info@bradley-enviro.co.uk

KEY

- ?????? NON-ASBESTOS ITEM LOCATION
- ??? ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC - Asbestos Textured Coating
- AB - Asbestos Bitumen
- ATP - Asbestos Thermoplastic
- ACF - Asbestos Compressed Fibre

Drawing title:
Asbestos Survey Plan (J094099/02)

Site address:
Dawson Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Ground Floor

This drawing is to be read in conjunction with survey report number: J094099


Date of work: 26/04/18 - 01/05/18

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.




Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk



KEY

- ⊘??? INTRUSION LOCATIONS
- ??? ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
 This diagram is only to be reproduced in colour.



Drawing title:
Asbestos Survey Plan (J094099/03)

Site address:
 Dawson Building
 Former City North Campus
 Birmingham City University
 Perry Barr
 B42 2US

Floor level(s): Ground Floor

This drawing is to be read in conjunction with survey report number: J094099

Date of work: 26/04/18 – 01/05/18

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.




Bradley Environmental Consultants Limited
 20 Stourbridge Road
 Halesowen, West Midlands B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 email: info@bradley-enviro.co.uk

KEY

- ?????? NON-ASBESTOS ITEM LOCATION
- ??? ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
This diagram is only to be reproduced in colour.

- Plan Abbreviations:
- AC - Asbestos Cement
 - AIB - Asbestos Insulating Board
 - AT - Asbestos Textile
 - AI - Asbestos Insulation
 - ATC - Asbestos Textured Coating
 - AB - Asbestos Bitumen
 - ATP - Asbestos Thermoplastic
 - ACF - Asbestos Compressed Fibre



Drawing title:
Asbestos Survey Plan (J094099/05)

Site address:
Dawson Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): First Floor

This drawing is to be read in conjunction with survey report number: J094099

Date of work: 26/04/18 - 01/05/18

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.




Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk

KEY

- ⊘??? INTRUSION LOCATIONS
- ??? ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
 This diagram is only to be reproduced in colour.



Drawing title:
Asbestos Survey Plan (J094099/06)

Site address:
 Dawson Building
 Former City North Campus
 Birmingham City University
 Perry Barr
 B42 2US

Floor level(s): First Floor

This drawing is to be read in conjunction with survey report number: J094099

Date of work: 26/04/18 – 01/05/18

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.




Bradley Environmental Consultants Limited
 20 Stourbridge Road
 Halesowen, West Midlands B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 email: info@bradley-enviro.co.uk

KEY

- ?????? ASBESTOS ITEM LOCATION
- ??? ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
This diagram is only to be reproduced in colour.

- Plan Abbreviations:
- AC - Asbestos Cement
 - AIB - Asbestos Insulating Board
 - AT - Asbestos Textile
 - AI - Asbestos Insulation
 - ATC - Asbestos Textured Coating
 - AB - Asbestos Bitumen
 - ATP - Asbestos Thermoplastic
 - ACF - Asbestos Compressed Fibre



Drawing title:
Asbestos Survey Plan (J094099/07)

Site address:
Dawson Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Second Floor

This drawing is to be read in conjunction with survey report number: J094099

Date of work: 26/04/18 - 01/05/18

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.




Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk

KEY

- ⊘ INTRUSION LOCATIONS
- ?? ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
 This diagram is only to be reproduced in colour.



Drawing title:
Asbestos Survey Plan (J094099/09)

Site address:
 Dawson Building
 Former City North Campus
 Birmingham City University
 Perry Barr
 B42 2US

Floor level(s): Second Floor

This drawing is to be read in conjunction with survey report number: J094099

Date of work: 26/04/18 – 01/05/18

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
 20 Stourbridge Road
 Halesowen, West Midlands B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 email: info@bradley-enviro.co.uk

KEY

- ?????? NON-ASBESTOS ITEM LOCATION
- ??? ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC - Asbestos Textured Coating
- AB - Asbestos Bitumen
- ATP - Asbestos Thermoplastic
- ACF - Asbestos Compressed Fibre

Drawing title:
Asbestos Survey Plan (J094099/11)

Site address:
Dawson Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Third Floor

This drawing is to be read in conjunction with survey report number: J094099


Date of work: 26/04/18 - 01/05/18

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.




Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk



KEY

- ⊘??? INTRUSION LOCATIONS
- ??? ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
 This diagram is only to be reproduced in colour.



Drawing title:
Asbestos Survey Plan (J094099/12)

Site address:
 Dawson Building
 Former City North Campus
 Birmingham City University
 Perry Barr
 B42 2US

Floor level(s): Third Floor

This drawing is to be read in conjunction with survey report number: J094099


Date of work: 26/04/18 – 01/05/18

Lead surveyor: Reg 13(1)


Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
 20 Stourbridge Road
 Halesowen, West Midlands B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 email: info@bradley-enviro.co.uk



PLAN OVERVIEW



KEY

- ASBESTOS ITEM LOCATION
- ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
This diagram is only to be reproduced in colour.

- Plan Abbreviations:
- AC - Asbestos Cement
 - AIB - Asbestos Insulating Board
 - AT - Asbestos Textile
 - AI - Asbestos Insulation
 - ATC - Asbestos Textured Coating
 - AB - Asbestos Bitumen
 - ATP - Asbestos Thermoplastic
 - ACF - Asbestos Compressed Fibre

Drawing title:
Asbestos Survey Plan (J094099/13)

Site address:
Dawson Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Roof

This drawing is to be read in conjunction with survey report number: J094099

Date of work: 26/04/18 - 01/05/18

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk

KEY

- ?????? NON-ASBESTOS ITEM LOCATION
- ??? ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
 This diagram is only to be reproduced in colour.

- Plan Abbreviations:
- AC - Asbestos Cement
 - AIB - Asbestos Insulating Board
 - AT - Asbestos Textile
 - AI - Asbestos Insulation
 - ATC - Asbestos Textured Coating
 - AB - Asbestos Bitumen
 - ATP - Asbestos Thermoplastic
 - ACF - Asbestos Compressed Fibre

Drawing title:
 Asbestos Survey Plan (J094099/14)

Site address:
 Dawson Building
 Former City North Campus
 Birmingham City University
 Perry Barr
 B42 2US

Floor level(s): Roof

This drawing is to be read in conjunction with survey report number: J094099


Date of work: 26/04/18 - 01/05/18

Lead surveyor: Reg 13(1)


Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
 20 Stourbridge Road
 Halesowen, West Midlands B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 email: info@bradley-enviro.co.uk



PLAN OVERVIEW



KEY

- ⊘?? INTRUSION LOCATIONS
- ?? ROOM NO.
- AREA/FEATURES NOT ACCESSED

Additional information:
 This diagram is only to be reproduced in colour.

Drawing title:
 Asbestos Survey Plan (J094099/15)

Site address:
 Dawson Building
 Former City North Campus
 Birmingham City University
 Perry Barr
 B42 2US

Floor level(s): Roof

This drawing is to be read in conjunction with survey report number: J094099

Date of work: 26/04/18 – 01/05/18

Lead surveyor: Reg 13(1)


Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
 20 Stourbridge Road
 Halesowen, West Midlands B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 email: info@bradley-enviro.co.uk



PLAN OVERVIEW



6.0 Room Description Report

Please note that this section of the survey report documents the general building materials recorded on a room by room basis by the surveyor while undertaking the inspection in line with our ISO17020 UKAS Accreditation. It has not been designed to use as a register for asbestos materials. Please refer to the asbestos register and/or summary section of this report for details of the ACMs located during this investigation.

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.00	Ground Floor	Concrete	Brick	Modern vinyl to concrete	Insulating board door header panel, modern stair nosing, timber frame to internal windows, plasterboard door header above stairwell doors
University	1.01	Ground Floor	Foam fibre suspended ceiling tiles to concrete	Ceramic tile to plaster to block	Modern vinyl to concrete	Metal and plastic pipework, ceramic cistern, timber panels to original wall covering, quarry tile window
University	1.01A	Ground Floor	Concrete	Block, plasterboard partition	Concrete	Foam insulated metal pipework, plastic pipework, compressed fibre gasket debris and to pipework, plastic wall vent covers, plastic cisterns

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.02	Ground Floor	Timber slatted panels to concrete	Ceramic tile to plaster to block	Ceramic tile to concrete	Metal ducting, metal and plastic pipework
University	1.03	Ground Floor	Concrete	Block	Modern vinyl to concrete	Bitumen sink pad, timber boxing to metal pipework, plastic pipework, foam insulation to metal pipework
University	1.04	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Ceramic tile plaster to brick and block	Ceramic tile to concrete	Block built riser containing metal and plastic pipework, ceramic cisterns, timber panels to original wall finish, plastic conduit, foil faced glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.05	Ground Floor	Concrete	Block	Concrete	Insulating board door header panel, reinforced plastic cistern, metal and plastic pipework, metal ducting
University	1.12	Ground Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to concrete	Cement window sill, cement shuttering, plastic downpipe, metal pipework, timber boxing to cabling
University	1.13	Ground Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to concrete	Cement window sill, cement shuttering, insulating board panel to riser, plastic downpipe, metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.13A	Ground Floor	Textured coating to concrete	Block, plasterboard partition	Carpet tiles to concrete	Cement window sill, cement shuttering, insulating board panel to riser, plastic downpipe, metal pipework, insulating board debris to riser
University	1.14	Ground Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to concrete	Cement window sill, cement shuttering, plastic downpipe, metal pipework, timber boxing to cabling
University	1.14A	Ground Floor	Textured coating to concrete	Block, plasterboard partition	Carpet tiles to concrete	Cement window sill, cement shuttering, insulating board panel to riser, plastic downpipe, metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.15	Ground Floor	Textured coating to concrete	Block, plasterboard partition	Carpet tiles to concrete	Cement window sill, cement shuttering, insulating board panel to riser, plastic downpipe, metal pipework, timber boxing to cabling
University	1.16	Ground Floor	Textured coating to concrete	Block	Thermoplastic floor tiles to concrete	Metal conduit
University	1.17A	Ground Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Cement window sill, cement shuttering, plastic downpipe, metal pipework, timber boxing to cabling

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.17B	Ground Floor	Textured coating to concrete	Block, plasterboard partition	Carpet tiles to concrete	Cement window sill, cement shuttering, insulating board panel to riser, plastic downpipe, metal pipework, timber boxing to cabling
University	1.18	Ground Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Cement window sill, cement shuttering
University	1.18A	Ground Floor	Textured coating to concrete	Block, plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Cement window sill, cement shuttering, insulating board panel to riser, plastic downpipe, metal pipework, timber boxing to cabling

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.18B	Ground Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Cement window sill, cement shuttering
University	1.19	Ground Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, modern electrics, fibre board panel with glass fibre cavity insulation, raised timber stage, modern stair nosing
University	1.20A	Ground Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Plaster to plasterboard	Carpet tiles to modern vinyl to concrete	Modern electrics

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.20B	Ground Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to modern vinyl to concrete	Insulating board panel to riser, insulating board panel to door, cement shuttering to wall void, bitumen damp proof course to perimeter of floor level, plastic pipework, glass fibre insulation to metal pipework, metal trunking, timber boxing to metal ducting, modern electrics
University	1.21	Ground Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, modern electrics, fibre board panel with glass fibre cavity insulation
University	1.22	Ground Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, insulating board door header panel to internal door

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.22A	Ground Floor	Concrete	Block	Modern vinyl to concrete	Insulating board infill to concrete stairs
University	1.23	Ground Floor	Textured coating to concrete	Block	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	1.24	Ground Floor	Textured coating to concrete	Block	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.24A	Ground Floor	Concrete	Block	Carpet tiles to concrete	Plastic conduit
University	1.25	Ground Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, insulating board debris to riser, cloth wrap glass fibre insulation to metal pipework, plastic pipework, timber panel to fibreglass panel rear of riser, insulating board debris to riser floor
University	1.26	Ground Floor	Textured coating to concrete	Block	Carpet to thermoplastic floor tiles	Plastic conduit

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.27	Ground Floor	Textured coating to concrete	Block	Thermoplastic floor tiles to concrete	Timber access panel to wall void heater concrete ceiling to wall void, modern electrics fixed to timber, plastic and metal backboards, metal cable tray, foil faced glass fibre insulation to metal pipework
University	1.28	Ground Floor	Concrete	Block	Concrete	Modern ventilation units, plasterboard to rolled steel joists, glass fibre insulation to metal pipework
University	1.34	Ground Floor	Concrete	Block	Concrete	Modern ventilation units, plasterboard to rolled steel joists, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.99	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Brick, plaster to block	Carpet and modern vinyl to concrete	Insulating board door header panels, foil faced glass fibre insulation to metal pipework, plastic pipework, metal conduit, metal cable trays, timber boxing to concrete lintel, insulating board fillet strip above sliding doors, cloth wrap to glass fibre insulation to metal pipework, plasterboard door header, insulating board debris within riser, built in heating system
University	1.99B	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block	Modern vinyl to concrete	Insulating board door header panels
University	1.99C	Ground Floor	Compressed fibre suspended ceiling tiles to concrete and section of textured coating	Block, plasterboard partitions	Carpet tiles to concrete	Foam insulated metal pipework, metal cable tray

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	1.99D	Ground Floor	Compressed fibre suspended ceiling tiles to concrete and section of textured coating	Block, plasterboard partitions	Carpet tiles to concrete	Foam insulated metal pipework, metal cable tray, insulating board door header panels
University	2.00	1st Floor	Concrete	Brick	Modern vinyl to concrete	Modern stair nosing, timber frame to internal windows, plasterboard door header above stairwell doors
University	2.00A	1st Floor	Concrete	Block	Modern vinyl to concrete	Insulating board door header panels, modern stair nosing

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.01	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Ceramic tile to plaster to block	Ceramic tile to concrete	Metal and plastic pipework, ceramic cistern, timber panels to original wall covering, quarry tile window
University	2.01A	1st Floor	Concrete	Block, plasterboard partition	Concrete	Metal pipework, plastic pipework, plastic cisterns, foam insulated metal pipework
University	2.02	1st Floor	Timber slatted panels to concrete	Ceramic tile to plaster to block	Ceramic tile to concrete	Metal ducting, metal and plastic pipework, ceramic cistern

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.03	1st Floor	Concrete	Block	Concrete	Bitumen sink pad, timber boxing to modern electrics, plastic pipework, foam insulation to metal pipework
University	2.04	1st Floor	Timber slatted to concrete	Ceramic tile plaster to brick and block	Ceramic tile to concrete	Block built riser containing metal and plastic pipework, ceramic cisterns, timber panels to original wall finish, plastic conduit, foil faced glass fibre insulation to metal pipework, insulating board panels within riser
University	2.05	1st Floor	Concrete	Block	Concrete	Insulating board door header panel, reinforced plastic cistern, metal and plastic pipework, metal ducting

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.11	1st Floor	Textured coating to concrete	Block, plasterboard partitions	Carpet to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, insulating board debris within riser, insulating board panel above window
University	2.12A	1st Floor	Textured coating to concrete	Block, plasterboard partitions	Carpet to thermoplastic floor tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.12B	1st Floor	Textured coating to concrete	Block, plasterboard partitions	Carpet to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.13	1st Floor	Textured coating to concrete	Block, plasterboard partitions	Carpet to thermoplastic floor tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.14A	1st Floor	Textured coating to concrete	Block, plasterboard partitions	Carpet to thermoplastic floor tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.14B	1st Floor	Textured coating to concrete	Block, plasterboard partitions	Carpet to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.15	1st Floor	Textured coating to concrete	Block	Carpet to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.16	1st Floor	Textured coating to concrete	Block	Carpet to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.17	1st Floor	Textured coating to concrete	Block	Carpet to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.18	1st Floor	Textured coating to concrete	Block	Carpet to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.19	1st Floor	Textured coating to concrete	Block	Carpet to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.20	1st Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.21	1st Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.21B	1st Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.21C	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Block	Thermoplastic floor tiles to concrete	Timber panel to door header

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.22	1st Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.22A	1st Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.22B	1st Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Modern vinyl to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, thermoplastic floor tile debris, bitumen sink pad

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.23	1st Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.23A	1st Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.23B	1st Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.23C	1st Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.24	1st Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plasterboard	Carpet to thermoplastic floor tiles to concrete	Modern electrics, plastic trunking, foil faced glass fibre insulation to metal ducting
University	2.24A	1st Floor	Textured coating to concrete	Block, plasterboard	Carpet to thermoplastic floor tiles to concrete	Modern electrics, plastic trunking, foil faced glass fibre insulation to metal ducting

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.25	1st Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, plasterboard boxing to metal ducting
University	2.26	1st Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.27	1st Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles concrete	Plastic trunking

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.27A	1st Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles concrete	Cement window sill, cement shuttering to heater wall void, compressed fibre expansion board to external wall, metal pipework
University	2.27B	1st Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	2.27C	1st Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.99	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Brick, plaster to block	Carpet and modern vinyl to concrete	Insulating board door header panels, foil faced glass fibre insulation to metal pipework, plastic pipework, metal conduit, metal cable trays, cloth wrap to glass fibre insulation to metal pipework, plasterboard door header, built in heating system
University	2.99A	1st Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Plasterboard partitions, block	Carpet tiles to bitumen and thermoplastic floor tiles	Plasterboard door header, timber panels to door headers, modern electrics
University	2.99B	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plasterboard partitions, block	Carpet tiles to concrete	Insulating board door header panels, timber panels to door headers, modern electrics, metal cable tray

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	2.99C	1st Floor	Compressed fibre suspended ceiling tiles to concrete, textured coating to concrete	Plasterboard partitions, block	Carpet tiles to concrete, carpet tile to bitumen adhesive to concrete	Insulating board door header panels, timber panels to door headers, modern electrics, metal cable tray
University	3.00	2nd Floor	Concrete	Brick	Modern vinyl to concrete	Modern stair nosing, timber frame to internal windows, plasterboard door header above stairwell doors
University	3.00A	2nd Floor	Concrete	Block	Modern vinyl to concrete	Insulating board door header, modern stair nosing

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.01	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Ceramic tile to plaster to block	Ceramic tile to concrete	Metal and plastic pipework, ceramic cistern, quarry tile window
University	3.02	2nd Floor	Timber slatted panels to concrete	Ceramic tile to plaster to block	Ceramic tile to concrete	Metal ducting, metal and plastic pipework, ceramic cistern
University	3.03	2nd Floor	Concrete	Block	Concrete	Bitumen sink pad, modern electrics, plastic pipework, foam insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.03A	2nd Floor	Concrete	Block, plasterboard partition	Concrete	Metal pipework, plastic pipework, plastic cisterns, foam insulated metal pipework
University	3.04	2nd Floor	Timber slatted to concrete	Ceramic tile plaster to brick and block	Ceramic tile to concrete	Block built riser containing metal and plastic pipework, ceramic cisterns, timber panels to original wall finish, plastic conduit, foil faced glass fibre insulation to metal pipework
University	3.05	2nd Floor	Concrete	Block	Concrete	Insulating board door header panel, reinforced plastic cistern, metal and plastic pipework, metal ducting

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.09	2nd Floor	Compressed fibre tiles to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Timber panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, insulating board debris within riser
University	3.10	2nd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, bitumen damp proof course
University	3.10A	2nd Floor	Textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to bitumen adhesive to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.11	2nd Floor	Textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to bitumen adhesive to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	3.12	2nd Floor	Textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to bitumen adhesive to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	3.13	2nd Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, bitumen damp proof course

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.13A	2nd Floor	Compressed fibre suspended tiles to textured coating to concrete	Block	Carpet tiles to bitumen adhesive to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	3.14	2nd Floor	Textured coating to concrete	Block	Carpet tiles to bitumen adhesive to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	3.14A	2nd Floor	Textured coating to concrete	Block	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, bitumen damp proof course

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.15	2nd Floor	Textured coating to concrete	Block	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, bitumen damp proof course
University	3.15A	2nd Floor	Compressed fibre suspended tiles to textured coating to concrete	Block	Carpet tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	3.16	2nd Floor	Compressed fibre suspended tiles to textured coating to concrete	Block	Carpet tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.17	2nd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, bitumen damp proof course
University	3.18	2nd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, bitumen damp proof course
University	3.19	2nd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, bitumen damp proof course

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.20	2nd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	3.21	2nd Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Plasterboard door header
University	3.23	2nd Floor	Textured coating to concrete	Block	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, bitumen damp proof course

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.24	2nd Floor	Textured coating to concrete	Block	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	3.26	2nd Floor	Compressed fibre tiles to textured coating to concrete	Block	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	3.27	2nd Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.28	2nd Floor	Textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to thermoplastic floor tiles to concrete	Modern electrics, plasterboard door header
University	3.30	2nd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	3.31	2nd Floor	Compressed fibre tiles to textured coating to concrete	Block, plasterboard partitions	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, insulating board panel to ceiling of riser

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.32	2nd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Metal ductwork
University	3.32A	2nd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	In built heating system, thermoplastic floor tile debris within wall void, metal duct work
University	3.32B	2nd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Metal ductwork

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.33	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plasterboard to brick, block, plasterboard partition	Carpet tiles to concrete	Foil faced glass fibre insulation to metal pipework, plastic pipework, metal conduit, foam insulation to metal pipework
University	3.99	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Brick, plaster to block, plasterboard	Carpet and modern vinyl to concrete	Insulating board door header panels, foil faced glass fibre insulation to metal pipework, plastic pipework, metal conduit, metal cable trays, bcloth wrap to glass fibre insulation to metal pipework, plasterboard door header
University	3.99A	2nd Floor	Compressed fibre suspended ceiling tiles to concrete and sections of textured coating	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Plasterboard door headers, metal trunking, timber boxing

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	3.99B	2nd Floor	Compressed fibre suspended ceiling tiles to concrete and sections of textured coating	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Plasterboard door headers, metal trunking, timber boxing
University	4.00	3rd Floor	Compressed fibre suspended ceiling tiles to concrete	Brick	Modern vinyl to concrete	Insulating board door header panel, modern stair nosing
University	4.00A	3rd Floor	Textured coating to concrete	Block	Modern vinyl to concrete	Insulating board door header panels, modern stair nosing

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.01	3rd Floor	Compressed fibre suspended ceiling tiles to concrete	Ceramic tile to plaster to block	Ceramic tile to concrete	Metal and plastic pipework, ceramic cistern, quarry tile window
University	4.02	3rd Floor	Timber slatted panels to concrete	Ceramic tile to plaster to block	Ceramic tile to concrete	Metal ducting, metal and plastic pipework, ceramic cistern
University	4.03	3rd Floor	Concrete	Block	Concrete	Cloth wrap glass fibre insulation to metal pipework, no visible gaskets to pipework flanges, insulating board door header

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.04	3rd Floor	Timber slatted to concrete	Ceramic tile plaster to brick and block	Ceramic tile to concrete	Block built riser containing metal and plastic pipework, plastic conduit, foil faced glass fibre insulation to metal pipework, cloth wrap glass fibre insulation to metal pipework
University	4.04A	3rd Floor	Compressed fibre suspended ceiling tiles to concrete	Brick, block, plasterboard to glass fibre cavity	Carpet tiles to concrete	Metal pipework, concrete lintel
University	4.05	3rd Floor	Concrete	Block	Concrete	Insulating board door header panel, reinforced plastic cistern, metal and plastic pipework, metal ducting

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.05A	3rd Floor	Compressed fibre suspended ceiling tiles to concrete	Plasterboard to brick, plaster to plasterboard	Carpet tiles to concrete	Not Applicable
University	4.06	3rd Floor	Concrete	Block	Concrete	Reinforced plastic cistern, plastic cisterns, plastic pipework, cloth wrap glass fibre insulation to metal pipework
University	4.10	3rd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to plasterboard, plasterboard to brick	Carpet tiles to concrete	Metal pipework, no visible pipework flanges

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.11	3rd Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.12	3rd Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.12A	3rd Floor	Compressed fibre suspended tiles to textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.13	3rd Floor	Textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.14	3rd Floor	Textured coating to concrete	Block	Carpet tiles to bitumen adhesive to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.15	3rd Floor	Textured coating to concrete	Block, plaster to plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Insulating board panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.15A	3rd Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plaster to plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.16	3rd Floor	Compressed fibre suspended tiles to textured coating to concrete	Block, plaster to plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.17	3rd Floor	Compressed fibre suspended tiles to textured coating to concrete	Block	Carpet tiles to concrete	Insulating board panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.18	3rd Floor	Compressed fibre suspended tiles to textured coating to concrete	Block	Carpet tiles to concrete	Timber panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.19	3rd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Insulating board panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.20	3rd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Timber panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.21	3rd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.22	3rd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Timber panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.23	3rd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Timber panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.24	3rd Floor	Textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, timber packers
University	4.25	3rd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Insulating board panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, timber packers
University	4.26	3rd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Timber panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.27	3rd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block	Carpet tiles to thermoplastic floor tiles to concrete	Timber panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework, bitumen damp proof course
University	4.31	3rd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Metal trunking
University	4.33	3rd Floor	Textured coating to concrete	Block	Carpet tiles to concrete	Plastic and metal conduit

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.33A	3rd Floor	Textured coating to concrete	Block	Thermoplastic floor tiles to concrete	Plastic and metal conduit
University	4.34	3rd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to bitumen adhesive to concrete	Timber panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.34A	3rd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to bitumen adhesive to concrete	Timber panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.37	3rd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to bitumen adhesive to concrete	Timber panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.38A	3rd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Block, plaster to plasterboard	Carpet tiles to bitumen adhesive to concrete	Insulating board panels to riser, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.38B	3rd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Plaster to plasterboard	Carpet tiles to bitumen adhesive to concrete	Cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.38C	3rd Floor	Compressed fibre suspended ceiling tiles to textured coating to concrete	Plaster to plasterboard, block	Carpet tiles to bitumen adhesive to concrete	Timber panels to risers, cement window sill, cement shuttering to heater wall void, plastic pipework, timber panel to fibreglass panel rear of riser, compressed fibre expansion board to external wall, metal pipework, timber upstand to external window wall, glass fibre insulation to metal pipework
University	4.39	3rd Floor	Textured coating to concrete	Block, plasterboard partition	Carpet tiles to bitumen adhesive to concrete	In built heating system, metal duct work, concrete to ceiling of wall void, metal pipework, timber panel to low level wall void, timber header panel
University	4.39A	3rd Floor	Textured coating to concrete	Block, plasterboard partition	Carpet tiles to concrete	Metal pipework, metal trunking

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.99	3rd Floor	Compressed fibre suspended ceiling tiles to concrete	Brick, plaster to block, plasterboard	Carpet to concrete	Insulating board door header panels, foil faced glass fibre insulation to metal pipework, plastic pipework, metal conduit, metal cable trays, cloth wrap to glass fibre insulation to metal pipework, bitumen damp proof course to ceiling change in levels
University	4.99A	3rd Floor	Compressed fibre suspended ceiling tiles to concrete	Block, glazed partition	Carpet tiles to concrete	Insulating board door headers, metal trunking
University	4.99B	3rd Floor	Compressed fibre suspended ceiling tiles to concrete	Block, glazed partition	Carpet tiles to concrete	Insulating board door headers, metal trunking

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	4.99C	3rd Floor	Compressed fibre suspended ceiling tiles to concrete, and textured coating section	Block, plasterboard partitions	Carpet tiles to concrete	Insulating board door headers, metal trunking
University	R.01	L - Loft	Concrete	Block	Concrete, steel spiral staircase	Insulating board door header, timber boxing to insulating board, cloth wrap glass fibre insulation to metal pipework, metal cable tray, plastic pipework, metal conduit
University	R.03	L - Loft	Concrete	Block	Concrete	Insulation to metal pipework, compressed fibre gasket, textile wrap to metal flue pipe, modern cast iron boilers with modern rope seal, metal water tanks non suspect mastic, plastic pipework, metal trunking, modern electrics

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
University	R.04	L - Loft	Concrete	Block	Concrete	Non suspect lift motor, modern electrics, slate shuttering to air bricks
University	External	E - External	Modern bitumen roof felt	Brick	Not Applicable	Insulating board panels over front entrances ground floor, modern ventilation units to roof, plastic rainwater down pipes, perspex roof lights, metal capping to parapet wall to rooftop, metal flue pipes, modern putty seal to glazing, concrete soffits to each floor level, fibreglass panels to external of risers
University	External Balcony	E - External	Insulating board to concrete	Brick	Rubber matt tiles to concrete	Insulating board panels to risers, cement shuttering internally to risers, plastic pipework, cloth wrap glass fibre insulation to metal pipework, glass panels to glass fibre insulation to fibreglass panels

Report No.: J094099
Issue Date: 11/06/2018



7.0 Room Access Report

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	1.00	Ground Floor	Accessed	None	Not Applicable
University	1.01	Ground Floor	Accessed	None	Not Applicable
University	1.01A	Ground Floor	Accessed	None	Not Applicable
University	1.02	Ground Floor	Accessed	None	Not Applicable
University	1.03	Ground Floor	Accessed	None	Not Applicable
University	1.04	Ground Floor	Accessed	None	Not Applicable
University	1.05	Ground Floor	Accessed	None	Not Applicable
University	1.12	Ground Floor	Accessed	None	Not Applicable
University	1.13	Ground Floor	Accessed	None	Not Applicable
University	1.13A	Ground Floor	Accessed	None	Not Applicable
University	1.14	Ground Floor	Accessed	None	Not Applicable
University	1.14A	Ground Floor	Accessed	None	Not Applicable
University	1.15	Ground Floor	Accessed	None	Not Applicable
University	1.16	Ground Floor	Accessed	None	Not Applicable
University	1.17A	Ground Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	1.17B	Ground Floor	Accessed	None	Not Applicable
University	1.18	Ground Floor	Accessed	None	Not Applicable
University	1.18A	Ground Floor	Accessed	None	Not Applicable
University	1.18B	Ground Floor	Accessed	None	Not Applicable
University	1.19	Ground Floor	Accessed	None	Not Applicable
University	1.20A	Ground Floor	Accessed	None	Not Applicable
University	1.20B	Ground Floor	Accessed	None	Not Applicable
University	1.21	Ground Floor	Accessed	None	Not Applicable
University	1.22	Ground Floor	Accessed	None	Not Applicable
University	1.22A	Ground Floor	Accessed	None	Not Applicable
University	1.23	Ground Floor	Accessed	None	Not Applicable
University	1.24	Ground Floor	Accessed	None	Not Applicable
University	1.24A	Ground Floor	Accessed	None	Not Applicable
University	1.25	Ground Floor	Accessed	None	Not Applicable
University	1.26	Ground Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	1.27	Ground Floor	Accessed	None	Not Applicable
University	1.28	Ground Floor	Accessed	None	Not Applicable
University	1.34	Ground Floor	Accessed	None	Not Applicable
University	1.99	Ground Floor	Accessed	None	Not Applicable
University	1.99B	Ground Floor	Accessed	None	Not Applicable
University	1.99C	Ground Floor	Accessed	None	Not Applicable
University	1.99D	Ground Floor	Accessed	None	Not Applicable
University	2.00	1st Floor	Accessed	None	Not Applicable
University	2.00A	1st Floor	Accessed	None	Not Applicable
University	2.01	1st Floor	Accessed	None	Not Applicable
University	2.01A	1st Floor	Accessed	None	Not Applicable
University	2.02	1st Floor	Accessed	None	Not Applicable
University	2.03	1st Floor	Accessed	None	Not Applicable
University	2.04	1st Floor	Accessed	None	Not Applicable
University	2.05	1st Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	2.11	1st Floor	Accessed	None	Not Applicable
University	2.12A	1st Floor	Accessed	None	Not Applicable
University	2.12B	1st Floor	Accessed	None	Not Applicable
University	2.13	1st Floor	Accessed	None	Not Applicable
University	2.14A	1st Floor	Accessed	None	Not Applicable
University	2.14B	1st Floor	Accessed	None	Not Applicable
University	2.15	1st Floor	Accessed	None	Not Applicable
University	2.16	1st Floor	Accessed	None	Not Applicable
University	2.17	1st Floor	Accessed	None	Not Applicable
University	2.18	1st Floor	Accessed	None	Not Applicable
University	2.19	1st Floor	Accessed	None	Not Applicable
University	2.20	1st Floor	Accessed	None	Not Applicable
University	2.21	1st Floor	Accessed	None	Not Applicable
University	2.21B	1st Floor	Accessed	None	Not Applicable
University	2.21C	1st Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	2.22	1st Floor	Accessed	None	Not Applicable
University	2.22A	1st Floor	Accessed	None	Not Applicable
University	2.22B	1st Floor	Accessed	None	Not Applicable
University	2.23	1st Floor	Accessed	None	Not Applicable
University	2.23A	1st Floor	Accessed	None	Not Applicable
University	2.23B	1st Floor	Accessed	None	Not Applicable
University	2.23C	1st Floor	Accessed	None	Not Applicable
University	2.24	1st Floor	Accessed	None	Not Applicable
University	2.24A	1st Floor	Accessed	None	Not Applicable
University	2.25	1st Floor	Accessed	None	Not Applicable
University	2.26	1st Floor	Accessed	None	Not Applicable
University	2.27	1st Floor	Accessed	None	Not Applicable
University	2.27A	1st Floor	Accessed	None	Not Applicable
University	2.27B	1st Floor	Accessed	None	Not Applicable
University	2.27C	1st Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	2.99	1st Floor	Accessed	None	Not Applicable
University	2.99A	1st Floor	Accessed	None	Not Applicable
University	2.99B	1st Floor	Accessed	None	Not Applicable
University	2.99C	1st Floor	Accessed	None	Not Applicable
University	3.00	2nd Floor	Accessed	None	Not Applicable
University	3.00A	2nd Floor	Accessed	None	Not Applicable
University	3.01	2nd Floor	Accessed	None	Not Applicable
University	3.02	2nd Floor	Accessed	None	Not Applicable
University	3.03	2nd Floor	Accessed	None	Not Applicable
University	3.03A	2nd Floor	Accessed	None	Not Applicable
University	3.04	2nd Floor	Accessed	None	Not Applicable
University	3.05	2nd Floor	Accessed	None	Not Applicable
University	3.09	2nd Floor	Accessed	None	Not Applicable
University	3.10	2nd Floor	Accessed	None	Not Applicable
University	3.10A	2nd Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	3.11	2nd Floor	Accessed	None	Not Applicable
University	3.12	2nd Floor	Accessed	None	Not Applicable
University	3.13	2nd Floor	Accessed	None	Not Applicable
University	3.13A	2nd Floor	Accessed	None	Not Applicable
University	3.14	2nd Floor	Accessed	None	Not Applicable
University	3.14A	2nd Floor	Accessed	None	Not Applicable
University	3.15	2nd Floor	Accessed	None	Not Applicable
University	3.15A	2nd Floor	Accessed	None	Not Applicable
University	3.16	2nd Floor	Accessed	None	Not Applicable
University	3.17	2nd Floor	Accessed	None	Not Applicable
University	3.18	2nd Floor	Accessed	None	Not Applicable
University	3.19	2nd Floor	Accessed	None	Not Applicable
University	3.20	2nd Floor	Accessed	None	Not Applicable
University	3.21	2nd Floor	Accessed	None	Not Applicable
University	3.23	2nd Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	3.24	2nd Floor	Accessed	None	Not Applicable
University	3.26	2nd Floor	Accessed	None	Not Applicable
University	3.27	2nd Floor	Accessed	None	Not Applicable
University	3.28	2nd Floor	Accessed	None	Not Applicable
University	3.30	2nd Floor	Accessed	None	Not Applicable
University	3.31	2nd Floor	Accessed	None	Not Applicable
University	3.32	2nd Floor	Accessed	None	Not Applicable
University	3.32A	2nd Floor	Accessed	None	Not Applicable
University	3.32B	2nd Floor	Accessed	None	Not Applicable
University	3.33	2nd Floor	Accessed	None	Not Applicable
University	3.99	2nd Floor	Accessed	None	Not Applicable
University	3.99A	2nd Floor	Accessed	None	Not Applicable
University	3.99B	2nd Floor	Accessed	None	Not Applicable
University	4.00	3rd Floor	Accessed	None	Not Applicable
University	4.00A	3rd Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	4.01	3rd Floor	Accessed	None	Not Applicable
University	4.02	3rd Floor	Accessed	None	Not Applicable
University	4.03	3rd Floor	Accessed	None	Not Applicable
University	4.04	3rd Floor	Accessed	None	Not Applicable
University	4.04A	3rd Floor	Accessed	None	Not Applicable
University	4.05	3rd Floor	Accessed	None	Not Applicable
University	4.05A	3rd Floor	Accessed	None	Not Applicable
University	4.06	3rd Floor	Accessed	None	Not Applicable
University	4.10	3rd Floor	Accessed	None	Not Applicable
University	4.11	3rd Floor	Accessed	None	Not Applicable
University	4.12	3rd Floor	Accessed	None	Not Applicable
University	4.12A	3rd Floor	Accessed	None	Not Applicable
University	4.13	3rd Floor	Accessed	None	Not Applicable
University	4.14	3rd Floor	Accessed	None	Not Applicable
University	4.15	3rd Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	4.15A	3rd Floor	Accessed	None	Not Applicable
University	4.16	3rd Floor	Accessed	None	Not Applicable
University	4.17	3rd Floor	Accessed	None	Not Applicable
University	4.18	3rd Floor	Accessed	None	Not Applicable
University	4.19	3rd Floor	Accessed	None	Not Applicable
University	4.20	3rd Floor	Accessed	None	Not Applicable
University	4.21	3rd Floor	Accessed	None	Not Applicable
University	4.22	3rd Floor	Accessed	None	Not Applicable
University	4.23	3rd Floor	Accessed	None	Not Applicable
University	4.24	3rd Floor	Accessed	None	Not Applicable
University	4.25	3rd Floor	Accessed	None	Not Applicable
University	4.26	3rd Floor	Accessed	None	Not Applicable
University	4.27	3rd Floor	Accessed	None	Not Applicable
University	4.31	3rd Floor	Accessed	None	Not Applicable
University	4.33	3rd Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	4.33A	3rd Floor	Accessed	None	Not Applicable
University	4.34	3rd Floor	Accessed	None	Not Applicable
University	4.34A	3rd Floor	Accessed	None	Not Applicable
University	4.37	3rd Floor	Accessed	None	Not Applicable
University	4.38A	3rd Floor	Accessed	None	Not Applicable
University	4.38B	3rd Floor	Accessed	None	Not Applicable
University	4.38C	3rd Floor	Accessed	None	Not Applicable
University	4.39	3rd Floor	Accessed	None	Not Applicable
University	4.39A	3rd Floor	Accessed	None	Not Applicable
University	4.99	3rd Floor	Accessed	None	Not Applicable
University	4.99A	3rd Floor	Accessed	None	Not Applicable
University	4.99B	3rd Floor	Accessed	None	Not Applicable
University	4.99C	3rd Floor	Accessed	None	Not Applicable
University	R.01	L - Loft	Accessed	None	Not Applicable
University	R.03	L - Loft	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
University	R.04	L - Loft	Accessed	None	Not Applicable
University	External	E - External	Accessed	None	Not Applicable
University	External Balcony	E - External	Accessed	None	Not Applicable

8.0 Bulk Analysis Results

CERTIFICATE OF ANALYSIS

Asbestos Fibre Identification in Bulk Sample

Client WYG Engineering Ltd
Address: Geneva Building
 Lake View Drive
 Sherwood Business Park
 Annesley
 Nottingham
 NG15 0ED

Site Dawson building
Address: Former City North Campus
 Birmingham City University
 Perry Barr
 B42 2US

Samples Received: 01/05/2018

Issue Date: 23/05/2018

Order Placed By: Reg 13(1)

Sampled By: Reg [REDACTED]

Analysed on: 17/05/2018 –23/05/2018

Authorised Signatory: Reg 13(1) [REDACTED]

Job Title: Laboratory Analyst

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation					
Report No.: J094099					
Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001354	-	1.99	Insulating board fillet strip above sliding doors	No Asbestos Detected	Reg 13(1)
DU001355	-	1.99	Insulating board door header panels	No Asbestos Detected	Reg 13(1)
DU001356	-	1.99	Insulating board door header	No Asbestos Detected	Reg 13(1)
DU001357	-	1.99	Insulating board fillet above red sliding doors	No Asbestos Detected	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001358	-	1.99	Asbestos Insulating board debris within riser	Chrysotile + Amosite	Reg 13(1)
DU001359	-	1.01A	Compressed fibre gasket debris and to pipework	No Asbestos Detected	Reg 13(1)
DU001360	-	1.03	Bitumen sink pad	No Asbestos Detected	Reg 13(1)
DU001361	-	1.05	Asbestos Insulating board door header panel	Amosite	Reg 13(1)
DU001362	-	1.05	Asbestos Reinforced plastic cistern	Amosite	Reg 13(1)
DU001363	-	1.00	Asbestos Insulating board door header panel	Chrysotile + Amosite	Reg 13(1)
DU001364	-	1.27	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg 13(1)
DU001365	-	1.27	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg
DU001366	-	1.26	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg 13(1)
DU001367	-	1.25	Insulating board panels to risers	No Asbestos Detected	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001368	-	1.25	Asbestos Cement window sill	Chrysotile	Reg [REDACTED]
DU001369	-	1.25	Asbestos Cement shuttering	Chrysotile	Reg [REDACTED]
DU001370	-	1.25	Asbestos Insulating board debris to base of riser	Chrysotile + Amosite	Reg [REDACTED]
DU001371	-	1.24	Asbestos Bitumen adhesive to concrete	Chrysotile	Reg [REDACTED]
DU001372	-	1.99B	Insulating board door headers	No Asbestos Detected	Reg [REDACTED]
DU001373	-	1.22A	Insulating board infill to concrete stairs	No Asbestos Detected	Reg [REDACTED]
DU001374	-	1.22	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg [REDACTED]
DU001375	-	1.22	Insulating board door header panel	No Asbestos Detected	Reg [REDACTED]
DU001376	-	1.21	Asbestos Bitumen adhesive	Chrysotile	Reg [REDACTED]
DU001377	-	1.20B	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg [REDACTED]

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001378	-	1.20B	Insulating board panel to riser	No Asbestos Detected	Reg [REDACTED]
DU001379	-	1.20B	Insulating board panel to door	No Asbestos Detected	Reg [REDACTED]
DU001380	-	1.20B	Asbestos Cement shuttering	Chrysotile	Reg [REDACTED]
DU001381	-	1.20B	Bitumen damp proof course	No Asbestos Detected	Reg [REDACTED]
DU001382	-	1.19	Asbestos Cement window sill	Chrysotile	Reg [REDACTED]
DU001383	-	1.18B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg [REDACTED]
DU001384	-	1.18A	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg 13(1) [REDACTED]
DU001385	-	1.18A	Asbestos Cement window sill	Chrysotile	Reg 13(1) [REDACTED]
DU001386	-	1.18A	Asbestos Cement shuttering	Chrysotile	Reg 13(1) [REDACTED]
DU001387	-	1.18A	Insulating board panel to riser	No Asbestos Detected	Reg 13(1) [REDACTED]

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001388	-	1.18A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg 13(1)
DU001389	-	1.13A	Asbestos Insulating board debris to base of riser	Amosite	Reg 13(1)
DU001390	-	1.99D	Insulating board door header panels	No Asbestos Detected	Reg 13(1)
DU001391	-	2.99	Insulating board panel to room 2.11	No Asbestos Detected	Reg
DU001392	-	2.99	Insulating board door header panels	No Asbestos Detected	Reg
DU001393	-	2.99	Insulating board door header panels	No Asbestos Detected	Reg
DU001394	-	2.99	Bitumen damp proof course	No Asbestos Detected	Reg
DU001395	-	2.04	Asbestos Insulating board panels	Chrysotile + Amosite	Reg
DU001396	-	2.03	Bitumen sink pad	No Asbestos Detected	Reg
DU001397	-	2.05	Asbestos Insulating board door header panel	Chrysotile + Amosite	Reg

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001398	-	2.05	Asbestos Reinforced plastic cistern	Amosite	Reg [REDACTED]
DU001399	-	2.27C	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg 13(1)
DU001400	-	2.27C	Insulating board panels to risers	No Asbestos Detected	Reg 13(1)
DU001401	-	2.27C	Asbestos Cement window sill	Chrysotile	Reg 13(1)
DU001402	-	2.27C	Asbestos Cement shuttering	Chrysotile	Reg 13(1)
DU001403	-	2.27C	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg 13(1)
DU001404	-	2.25	Bitumen damp proof course	No Asbestos Detected	Reg 13(1)
DU001405	-	2.23C	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg 13(1)
DU001406	-	2.23C	Asbestos Cement window sill	Chrysotile	Reg 13(1)
DU001407	-	2.23C	Asbestos Cement shuttering	Chrysotile	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001408	-	2.23C	Insulating board panel to riser	No Asbestos Detected	Reg 13(1)
DU001409	-	2.23C	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU001410	-	2.22	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg 13(1)
DU001411	-	2.22	Insulating board panels to riser	No Asbestos Detected	Reg 13(1)
DU001412	-	2.22	Asbestos Cement window sill	Chrysotile	Reg 13(1)
DU001413	-	2.22	Asbestos Cement shuttering	Chrysotile	Reg 13(1)
DU001414	-	2.22	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU001415	-	2.22B	Bitumen sink pad	No Asbestos Detected	Reg 13(1)
DU001416	-	2.22B	Asbestos Thermoplastic floor tile debris within riser	Chrysotile in adhesive only	Reg 13(1)
DU001417	-	2.99A	Thermoplastic floor tiles	No Asbestos Detected	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001418	-	2.00A	Insulating board door header panel	No Asbestos Detected	Reg 13(1)
DU001419	-	2.24A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg 13(1)
DU001420	-	2.99B	Insulating board door header panel	No Asbestos Detected	Reg 13(1)
DU001421	-	2.99B	Insulating board door header panels	No Asbestos Detected	Reg 13(1)
DU001422	-	2.14B	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg 13(1)
DU001423	-	2.14B	Asbestos Cement window sill	Chrysotile	Reg 13(1)
DU001424	-	2.14B	Insulating board panels to riser	No Asbestos Detected	Reg 13(1)
DU001425	-	2.14B	Asbestos Cement shuttering	Chrysotile	Reg 13(1)
DU001426	-	2.14B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg 13(1)
DU001427	-	2.12B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
20 Stourbridge Road,
Halesowen, West Midlands
B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001428	-	2.11	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg 13(1)
DU001429	-	2.11	Asbestos Insulating board debris within riser	Chrysotile + Amosite	Reg
DU001430	-	2.11	Insulating board panel above window	No Asbestos Detected	Reg
DU001431	-	2.99C	Insulating board door header panel	No Asbestos Detected	Reg
DU001432	-	2.99C	Insulating board door header panels	No Asbestos Detected	Reg
DU001433	-	2.99C	Asbestos Bitumen adhesive to concrete	Chrysotile	Reg
DU001434	-	3.03	Bitumen sink pad	No Asbestos Detected	Reg
DU001435	-	3.05	Asbestos Insulating board door header panel	Chrysotile + Amosite	Reg
DU001436	-	3.05	Asbestos Reinforced plastic cistern	Amosite	Reg
DU001437	-	3.99	Insulating board door header panels	No Asbestos Detected	Reg

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
20 Stourbridge Road,
Halesowen, West Midlands
B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001438	-	3.99	Bitumen damp proof course	No Asbestos Detected	Reg [REDACTED]
DU001439	-	3.32A	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg [REDACTED]
DU001440	-	3.32A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Reg [REDACTED]
DU001441	-	3.32A	Thermoplastic floor tile debris within wall void	No Asbestos Detected	Reg [REDACTED]
DU001442	-	3.31	Asbestos Cement window sill	Chrysotile	Reg [REDACTED]
DU001443	-	3.31	Insulating board panels to riser	No Asbestos Detected	Reg [REDACTED]
DU001444	-	3.31	Asbestos Cement shuttering	Chrysotile + Amosite	Reg [REDACTED]
DU001445	-	3.31	Asbestos Insulating board panel to ceiling of riser	Chrysotile + Amosite	Reg [REDACTED]
DU001446	-	3.31	Asbestos Bitumen adhesive	Chrysotile	Reg [REDACTED]
DU001447	-	3.27	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Reg [REDACTED]

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001448	-	3.26	Asbestos Bitumen adhesive	Chrysotile	Reg [REDACTED]
DU001449	-	3.24	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg [REDACTED]
DU001450	-	3.24	Asbestos Cement window sill	Chrysotile	Reg [REDACTED]
DU001451	-	3.24	Insulating board panels to riser	No Asbestos Detected	Reg [REDACTED]
DU001452	-	3.24	Asbestos Bitumen adhesive	Chrysotile	Reg [REDACTED]
DU001453	-	3.24	Asbestos Cement shuttering	Chrysotile + Amosite	Reg [REDACTED]
DU001454	-	3.23	Bitumen damp proof course	No Asbestos Detected	Reg 13(1)
DU001455	-	3.21	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg 13(1)
DU001456	-	3.15	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU001457	-	3.28	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg [REDACTED]

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001458	-	3.28	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Reg 13(1)
DU001459	-	3.00A	Insulating board door header panel	No Asbestos Detected	Reg 13(1)
DU001460	-	3.13	Asbestos Cement window sill	Chrysotile	Reg 13(1)
DU001461	-	3.13	Asbestos Cement shuttering	Chrysotile + Amosite	Reg 13(1)
DU001462	-	3.13	Insulating board panels to riser	No Asbestos Detected	Reg 13(1)
DU001463	-	3.13	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Reg 13(1)
DU001464	-	3.11	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU001465	-	3.09	Asbestos Insulating board debris within riser	Chrysotile + Amosite	Reg 13(1)
DU001466	-	4.06	Reinforced plastic cistern	No Asbestos Detected	Reg 13(1)
DU001467	-	4.03	Asbestos Insulating board door header panel	Chrysotile + Amosite	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001468	-	4.05	Asbestos Insulating board door header panel	Chrysotile + Amosite	Reg 13(1)
DU001469	-	4.05	Asbestos Reinforced plastic cistern	Amosite	Reg 13(1)
DU001470	-	4.00	Asbestos Insulating board door header panel	Chrysotile + Amosite	Reg 13(1)
DU001471	-	4.99	Insulating board door header panels	No Asbestos Detected	Reg 13(1)
DU001472	-	4.99	Asbestos Insulating board door header panel	Chrysotile + Amosite	Reg 13(1)
DU001473	-	4.99	Bitumen damp proof course	No Asbestos Detected	Reg 13(1)
DU001474	-	4.39	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg 13(1)
DU001475	-	4.39	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU001476	-	4.38A	Asbestos Cement window sill	Chrysotile	Reg 13(1)
DU001477	-	4.38A	Asbestos Cement shuttering	Chrysotile + Amosite	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001478	-	4.38A	Insulating board panels to riser	No Asbestos Detected	Reg 13(1)
DU001479	-	4.27	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg 13(1)
DU001480	-	4.27	Bitumen damp proof course	No Asbestos Detected	Reg 13(1)
DU001481	-	4.26	Textured coating to concrete	No Asbestos Detected	Reg 13(1)
DU001482	-	4.26	Asbestos Cement window sill	Chrysotile	Reg 13(1)
DU001483	-	4.26	Asbestos Cement shuttering	Chrysotile	Reg 13(1)
DU001484	-	4.25	Insulating board panel to riser	No Asbestos Detected	Reg 13(1)
DU001485	-	4.99A	Insulating board door header panel	No Asbestos Detected	Reg 13(1)
DU001486	-	4.99A	Insulating board door header panels	No Asbestos Detected	Reg 13(1)
DU001487	-	4.19	Insulating board panel to riser	No Asbestos Detected	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001488	-	4.33A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg [REDACTED]
DU001489	-	4.15	Insulating board panels to risers	No Asbestos Detected	Reg [REDACTED]
DU001490	-	4.15	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg [REDACTED]
DU001491	-	4.00A	Insulating board door header panel	No Asbestos Detected	Reg [REDACTED]
DU001492	-	4.99B	Insulating board door header panel	No Asbestos Detected	Reg [REDACTED]
DU001493	-	4.99B	Insulating board door header panel	No Asbestos Detected	Reg [REDACTED]
DU001494	-	4.14	Asbestos Textured coating to concrete ceiling	Chrysotile	Reg [REDACTED]
DU001495	-	4.14	Asbestos Cement window sill	Chrysotile	Reg [REDACTED]
DU001496	-	4.14	Asbestos Cement shuttering	Chrysotile + Amosite	Reg [REDACTED]
DU001497	-	4.14	Asbestos Bitumen adhesive	Chrysotile	Reg [REDACTED]

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001498	-	4.13	Insulating board panel to riser	No Asbestos Detected	Reg [REDACTED]
DU001499	-	4.13	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Reg [REDACTED]
DU001500	-	4.99C	Insulating board door header panel	No Asbestos Detected	Reg [REDACTED]
DU001501	-	R.01	Insulating board door header	No Asbestos Detected	Reg [REDACTED]
DU001502	-	R.01	Asbestos Insulating board panel to rear of timber boxing	Chrysotile + Amosite	Reg [REDACTED]
DU001503	-	R.01	Asbestos Insulating board lining to door	Chrysotile	Reg [REDACTED]
DU001504	-	R.03	Insulation to pipework	No Asbestos Detected	Reg [REDACTED]
DU001505	-	R.03	Insulation to pipework	No Asbestos Detected	Reg [REDACTED]
DU001506	-	R.03	Insulation to pipework	No Asbestos Detected	Reg [REDACTED]
DU001507	-	R.03	Insulation to pipework	No Asbestos Detected	Reg [REDACTED]

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



1155

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J094099

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU001508	-	R.03	Insulation to pipework	No Asbestos Detected	Reg [REDACTED]
DU001509	-	R.03	Asbestos Compressed fibre gasket	Chrysotile	Reg [REDACTED]
DU001510	-	R.03	Compressed fibre gasket	No Asbestos Detected	Reg [REDACTED]
DU001511	-	R.03	Textile seal to flue pipe	No Asbestos Detected	Reg [REDACTED]
DU001512	-	External Balcony	Insulating board canopy	No Asbestos Detected	Reg [REDACTED]
DU001513	-	External Balcony	Insulating board panels to riser	No Asbestos Detected	Reg [REDACTED]
DU001514	-	External Balcony	Asbestos Cement shuttering	Chrysotile + Amosite	Reg [REDACTED]
DU001515	-	External	Insulating board canopy	No Asbestos Detected	Reg [REDACTED]
DU001516	-	External	Insulating board canopy over front entrance	No Asbestos Detected	Reg [REDACTED]

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
20 Stourbridge Road,
Halesowen, West Midlands
B63 3US

Tel: 0121 550 0224 Fax: 0121 550 0641

Email: sales@bradley-enviro.co.uk

END OF REPORT



1155

Report No.: J094099
Issue Date: 11/06/2018



9.0 Intrusion Photographs

Please note that the intrusion numbers in this section may not run consecutively.

Intrusion 01



Intrusion 02



Intrusion 03



Intrusion 04




Intrusion 05



Intrusion 06



Intrusion 07



Intrusion 08




Intrusion 09




Intrusion 10



Intrusion 11



Intrusion 12



Intrusion 13



Intrusion 14



Intrusion 15



Intrusion 16



Intrusion 17




Intrusion 18



Intrusion 19



Intrusion 20



Intrusion 21



Intrusion 22



Intrusion 23



Intrusion 24



Intrusion 25



Intrusion 26



Intrusion 27



Intrusion 28




Intrusion 29



Intrusion 30



Intrusion 31



Intrusion 32



Intrusion 33



Intrusion 34



Intrusion 35




Intrusion 36




Intrusion 37



Intrusion 38



Intrusion 39



Intrusion 40




Intrusion 41



Intrusion 42



Intrusion 43



Intrusion 44



Intrusion 45



Intrusion 46



10.0 Risk Assessment Algorithms

Once an asbestos item has been identified, Regulation 4 of CAR2012 requires that a risk assessment be undertaken on the material. The risk assessment contained within this report is based on the **material assessment algorithm**, as defined in HSG264, and the **likelihood of disturbance algorithm** which is *part* of the priority assessment as defined in HSG227.

The score for each assessment is added together to provide an **overall risk rating** based on the material's ability to release airborne fibre *and* the risk of it being disturbed. This overall risk category is shown in section 10.3.

10.1 Material Assessment

The material assessment algorithm provides a numerical indication of the ability of an ACM to release airborne asbestos fibre, if disturbed. A risk category score of between 2 and 12 is assigned to each ACM as shown below:

- < 5 Very low hazard
- 5 & 6 Low hazard
- 7 - 9 Medium hazard
- > 9 High hazard

The table below shows how the individual material assessment scores are calculated:

	SCORE 0	SCORE 1	SCORE 2	SCORE 3
Product type		Composite materials, reinforced plastics, felts, textured coating and asbestos cement (AC) products	Low density boards (i.e. AIB), gaskets, textiles	Sprays, insulation, loose asbestos, mattresses and packing
Extent of damage/deterioration	Good condition: no visible damage	Low damage: a few scratches or damaged edges	Medium damage: significant breakage of materials or several small areas of damage revealing loose fibres	High damage or delamination of materials, sprays and insulation. Visible asbestos debris
Surface treatment	Composite materials, reinforced plastics, textured coating, felts etc	Painted, encapsulated AIB & AC. Enclosed AIB, AC, sprays & lagging, Unencapsulated AC	Unencapsulated AIB. Encapsulated sprays and insulation	Unencapsulated sprays and insulation
Asbestos type		Chrysotile	Amphibole asbestos excluding crocidolite	Crocidolite

10.2 Likelihood of Disturbance Assessment

The likelihood of disturbance algorithm provides a numerical value which helps assess how likely an ACM is to be disturbed.

The following table has been extracted from HSG227 (A comprehensive guide to Managing Asbestos in premises):

SAMPLE VARIABLE	SCORE	EXAMPLES OF SCORES
LOCATION	0	Outdoors
	1	Large rooms or well ventilated areas
	2	Rooms up to 100 sq. m
	3	Confined spaces
ACCESSIBILITY	0	Usually inaccessible or unlikely to be disturbed
	1	Occasionally likely to be disturbed
	2	Easily disturbed
	3	Routinely disturbed
EXTENT/AMOUNT	0	Small amounts or items (i.e. strings, gaskets etc)
	1	<10 sq m or < 10 linear metre pipe run
	2	>10 - <50 sq m or >10m - <50 linear metre pipe run
	3	>50 sq m or >50 linear metre pipe run

10.3 Overall Risk Category

It is recommended that where practicable to do so, the Dutyholder aims to reduce the risk associated with all ACMs to a grade C (low) or D (very low).

Risk Category	Risk	Score Range	Comments and Recommendations
A	High	16+	<p>It is very likely that crumbly loose asbestos may be disturbed releasing a significant quantity of fibres.</p> <p>Plans for urgent remedial work, including possible removal, are required and access to the area should be limited to adequately trained personnel.</p>
B	Medium	11-15	<p>Fibres may be released if the material is further damaged or disturbed.</p> <p>A programme of remedial work (which may include removal) should be planned. Until then, some emergency repairs may be required.</p> <p>The material's condition should be monitored periodically.</p>
C	Low	7-10	<p>Little likelihood of fibres being released under normal conditions, either because of the location of the materials or because the type of material present will only release very low levels of fibres.</p> <p>Immediate work is not needed and any removal can be planned with a suitable timescale. The material should be inspected and assessed at suitable intervals (at least annually).</p>
D	Very Low	<7	<p>Little likelihood that fibres will be released. The material will only need removal if serious damage/deterioration is detected in the future.</p> <p>The material should be inspected and assessed at suitable intervals (at least annually).</p>
E	No asbestos detected	0	No asbestos detected

DISCLAIMER

Bradley Environmental Consultants Ltd have undertaken surveying, sampling and analysis following in-house documented methods, which involve systematic access, inspection and reporting. It is not possible to guarantee that all asbestos will be located within a specified site and we accept no financial or other responsibility for remedial works or disruption to programmes which may occur as a result of asbestos materials being located which are *outside the scope of this survey*.

The survey report should not be reproduced except in full without the approval of the client and Bradley Environmental Consultants Ltd.

Bradley Environmental - Additional Services

Since 1991, Bradley Environmental Consultants have provided a full range of asbestos management services to a wide range of clients including local authorities, hospital trusts and large commercial businesses. A summary of the asbestos related services we are able to offer include the following:

- Management asbestos surveys;
- Refurbishment & demolition asbestos surveys;
- Preparation of Asbestos Management Plans;
- Labelling programmes;
- Cost-effective remedial advice;
- Preparation of removal specifications;
- Evaluation & selection of licensed asbestos removal contractors;
- Preparation of tender documentation;
- Assessment and critical evaluation of method statements;
- Air monitoring during asbestos removal projects;
- Issuing certificates of re-occupation following asbestos removal works;
- Annual re-inspection of ACMs to update the asbestos register.

If you would like any further information regarding your survey, the implementation of a suitable management plan, or any other asbestos-related issue, please do not hesitate to contact us.

Birmingham: (Head Office)	0121 550 0224	Reg 13(1)
Wakefield: (Northern Office)	01924 274 777	Reg 13(1)
Blackpool: (North West Office)	01253 405 396	Reg 13(1)
St Asaph: (North Wales Office)	01745 585 587	Reg 13(1)