

Report No.: J102748
Nature of Work: Demolition Survey
Issue Date: 31/10/2018
Client Name: WYG Engineering Ltd
Geneva Building, Lake View Drive, Sherwood Business Park,
Annesley, Nottingham, NG15 0ED
Site Address: Baker Building, Former City North Campus, Birmingham City
University, Perry Barr, B42 2US



Order Placed By: Reg 13(1)
Site Contact: Reg 13(1)
Date(s) of Work: 31/08/2018 to 03/10/2018
Technical Manager: Reg 13(1) (Asbestos)
Assistant Surveyor(s): Reg 13(1)

Lead Surveyor:

Reg 13(1)

Authorised Signatory:

Reg 13(1)

Reg 13(1)

Asbestos Consultant

Reg 13(1)

Technical Review Officer and Deputy Lab Supervisor

31 Oct 2018

*Non-accredited tests are present within this report.

Head Office:
20 Stourbridge Road,
Halesowen, West Midlands
B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
Email: sales@bradley-enviro.co.uk



Contents

1.0 Introduction & Scope of Work

- 1.1 Aims & Objectives
- 1.2 Caveats, Restrictions & Inaccessible Areas
- 1.3 Pre-agreed Caveats
- 1.4 Surveyor Imposed Caveats
- 1.5 UKAS Accreditation
- 1.6 'Licensable' Abatement
- 1.7 Extent of ACM Identified
- 1.8 Presumption or Identification of ACMs

2.0 Recommendations

3.0 Executive Summary

- 3.1 Asbestos Containing Materials (ACMs) ranked by Risk
- 3.2 Non-Asbestos Materials

4.0 Item Register & Management Report

5.0 Annotated Building Plans

6.0 Room Description Report

7.0 Room Access Report

8.0 Bulk Analysis Results

9.0 Intrusion Photographs

10.0 Risk Assessment Algorithms

- 10.1 Material Assessment
- 10.2 Likelihood of Disturbance Assessment
- 10.3 Overall Risk Category

1.0 Introduction & Scope of Work

A demolition survey in line with HSG264 Asbestos: The Survey Guide was carried out internally and externally to the property.

1.1 Aims & Objectives

The purpose of the survey was to locate, as far as reasonably practicable, the presence and extent of all suspect ACMs prior to demolition.

This survey was conducted for the specific project(s) stated above. Additional or alternative tasks over and above that mentioned will require a supplementary investigation to identify further ACMs that could potentially be disturbed by the task(s) at hand.

1.2 Caveats, Restrictions & Inaccessible Areas

The value and usefulness of a survey can be seriously undermined where either the client or the surveyor imposes restrictions on the survey scope (HSG264).

If any rooms were not accessed during the inspection, they will be indicated on the building plans (in yellow block) in section 5.

Where a room was accessed but specific elements within the room could not be inspected, caveats and their justification will be detailed in section 7.

It is strongly recommended that the client reviews the (general) caveats noted in sections 1.3 and/or 1.4 below, as well as the (room-specific) caveats cited in sections 5 and 7 as soon as possible upon receipt of the report. If the extent of access is less than required, the client should advise the Technical Management Team to arrange additional inspection work as necessary.

1.3 Pre-agreed Caveats:

No safe access was available internally to items of electrically connected plant and equipment. The presence of ACMs internally to such items may therefore have been presumed at the surveyor's discretion.

No access was required beyond ACMs (i.e. into voids or cavities etc) where the services of a licensed asbestos removal contractor would be required to provide safe access.

All land associated with the building such as surrounding grassed verges etc. are not included within the scope of these works and therefore remain unsurveyed.

All incoming services to the building were only investigated above ground level once they had entered the building therefore all sub ground water, gas and electric connections remain un-surveyed.

All outgoing services such as drainage routes were not included within the scope of these works and therefore remain un-surveyed.

All lift shafts will not be accessed as agreed with the client during the pre start period. therefore they will remain unsurveyed at this time

Please note that, although a thorough and methodical survey strategy was adopted, it is possible that further ACMs may be present, and are unreported in this survey. HSG264 Asbestos: the survey guide states that "It is now recognised that even with 'complete' access demolition surveys, all ACMs may not be identified and this only becomes apparent during demolition itself."

1.4 Surveyor Imposed Caveats:

Service duct runs throughout the building forming a chimney, physical access was restricted due to no access points being available without the assistance of power tools to open brick or block walls

Room NBA819A service duct 8th floor, insulating board ceiling panels identified unsure of the absolute extent of the item therefore I recommend further investigative works by way of core hole investigation either side of the room by a licensed contractor to establish the true extent of the item

The survey of the basement plant room was carried out under task lighting due to no power being available on-site

1.5 UKAS Accreditation

Bradley Environmental are accredited by UKAS to both ISO17025 (testing) and ISO17020 (inspections). Please note that the following are outside the scope of UKAS Accreditation:

- Opinions & interpretations;
- Likelihood of disturbance risk assessment;
- Recommendations;
- The sample references cited in section 8.0.

1.6 'Licensable' Abatement

Where an asbestos-containing material is stated as being licensable within section 4 of this report, this is merely a qualified opinion and may not in practice be an absolute fact.

1.7 Extent of ACM Identified

Please note that the extents cited within this report are an approximation only and should not be used for the purposes of quoting asbestos removal works.

1.8 Presumption or Identification of ACMs

Where suspect materials have been located during this investigation, their asbestos content (or otherwise) will have been determined as follows:

A sample of the material will have been taken by the surveyor during the survey. This sample will then have been **analysed using polarised light microscopy** (PLM) to determine its asbestos content.

A material's asbestos content will have been **strongly presumed** where a visual inspection by the lead surveyor indicates the material is visually similar to other items present within the building which have been confirmed to contain asbestos (or otherwise) using PLM.

A material's asbestos content will have been **presumed** where it cannot be accessed or inspected.

2.0 Recommendations

Please note that where a management survey was carried out, individual recommendations related to safe management of each ACM has been cited by the surveyor in section 4.0.

Where a refurbishment or demolition survey was carried out, the recommendation for each item has been defaulted to 'program removal' in line with Regulation 7 of CAR2012.

N/A

Report No.: J102748
Issue Date: 31/10/2018



3.0 Executive Summary

As required by HSG264 Asbestos: The survey guide, the following sections contain an executive summary of the survey findings.

3.1 Executive Summary of Asbestos Containing Materials (ACMs) by Risk

The following pages show an executive summary of the ACMs located during these works ranked in order of risk (i.e. the highest risk item will be at the top of the page).

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002584	Basement	Birmingham City University	NBA02 Plant room	Asbestos Insulation residues to wall	Chrysotile Amosite	Analysis of sample using PLM	24 m ²	B15	Program removal
DU002585	Basement	Birmingham City University	NBA02 Plant room	Asbestos Insulation residues to wall	Chrysotile Amosite	Analysis of sample using PLM	24 m ²	B15	Program removal
DU002587	Basement	Birmingham City University	NBA02 Plant room	Asbestos Insulation residues to wall	Chrysotile Amosite	Analysis of sample using PLM	16 m ²	B15	Program removal
DU002441	4th Floor	Birmingham City University	NBA499C Corridor	Asbestos Insulating board debris	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B14	Program removal
DU002574	Basement	Birmingham City University	NBA02 Plant room	Asbestos Insulation debris	Amosite	Analysis of sample using PLM	2 m ²	B13	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002440	4th Floor	Birmingham City University	NBA499C Corridor	Asbestos Insulating board firebreak	Chrysotile Amosite	Analysis of sample using PLM	2 m ²	B12	Program removal
DU002368	7th Floor	Birmingham City University	NBA799C Corridor	Asbestos Insulating board panel to dry riser	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	B12	Program removal
As DU002497	1st Floor	Birmingham City University	NBA103	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	64 m ²	B11	Program removal
DU002497	1st Floor	Birmingham City University	NBA101	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	14 m ²	C10	Program removal
DU002520	1st Floor	Birmingham City University	NBA113	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	12 m ²	C10	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002463	3rd Floor	Birmingham City University	NBA317 Service duct	Asbestos Cement flue pipe	Chrysotile Crocidolite	Analysis of sample using PLM	4 linear metres	C10	Program removal
DU002401	5th Floor	Birmingham City University	NBA504	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	14 m ²	C10	Program removal
As DU002406	5th Floor	Birmingham City University	NBA510A Plant room	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C10	Program removal
DU002350	8th Floor	Birmingham City University	NBA899B Corridor	Asbestos Insulating board panel to dry riser	Chrysotile Amosite	Analysis of sample using PLM	1 m ²	C10	Program removal
DU002575	E - External	Birmingham City University	NBA903 Roof top plant room	Asbestos Textile rope seal	Chrysotile	Analysis of sample using PLM	4 linear metres	C10	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002576	E - External	Birmingham City University	NBA903 Roof top plant room	Asbestos Textile wrap to ducting	Chrysotile	Analysis of sample using PLM	2 m ²	C10	Program removal
As DU002497	1st Floor	Birmingham City University	NBA102	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	10 m ²	C9	Program removal
As DU002497	1st Floor	Birmingham City University	NBA199A	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	8 m ²	C9	Program removal
As DU002493	2nd Floor	Birmingham City University	NBA299C Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	50 m ²	C9	Program removal
DU002468	3rd Floor	Birmingham City University	NBA314A	Asbestos Cement roof tile packers	Chrysotile	Analysis of sample using PLM	1 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002470	3rd Floor	Birmingham City University	NBA399D Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	60 m ²	C9	Program removal
As DU002470	3rd Floor	Birmingham City University	NBA399F Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	50 m ²	C9	Program removal
DU002535	Ground Floor	Birmingham City University	NBAG28	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	45 m ²	C9	Program removal
DU002537	Ground Floor	Birmingham City University	NBAG03	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C9	Program removal
As DU002537	Ground Floor	Birmingham City University	NBAG05	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	80 m ²	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002540	Ground Floor	Birmingham City University	NBAG04A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	16 m ²	C9	Program removal
DU002553	Ground Floor	Birmingham City University	NBAG11A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	6 m ²	C9	Program removal
DU002557	Ground Floor	Birmingham City University	NBAG20B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	10 m ²	C9	Program removal
DU002560	Ground Floor	Birmingham City University	NBAG99G	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	10 m ²	C9	Program removal
DU002516	1st Floor	Birmingham City University	NBA131	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	36 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002517	1st Floor	Birmingham City University	NBA132	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	24 m ²	C8	Program removal
As DU002514	1st Floor	Birmingham City University	NBA114A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU002514	1st Floor	Birmingham City University	NBA114	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	15 m ²	C8	Program removal
DU002521	1st Floor	Birmingham City University	NBA141	Asbestos Cement flue pipe	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal
DU002528	1st Floor	Birmingham City University	NBA137	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	20 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002530	1st Floor	Birmingham City University	NBA199D	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C8	Program removal
DU002533	1st Floor	Birmingham City University	NBA199G	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	30 m ²	C8	Program removal
DU002473	2nd Floor	Birmingham City University	NBA225	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
DU002479	2nd Floor	Birmingham City University	NBA205	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
DU002488	2nd Floor	Birmingham City University	NBA215 Service duct	Asbestos Cement flue pipe	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002493	2nd Floor	Birmingham City University	NBA299A Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
As DU002493	2nd Floor	Birmingham City University	NBA299B Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	35 m ²	C8	Program removal
DU002443	3rd Floor	Birmingham City University	NBA325	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
DU002444	3rd Floor	Birmingham City University	NBA301	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
DU002448	3rd Floor	Birmingham City University	NBA303	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	35 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002450	3rd Floor	Birmingham City University	NBA323	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
DU002451	3rd Floor	Birmingham City University	NBA305	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	40 m ²	C8	Program removal
DU002452	3rd Floor	Birmingham City University	NBA306	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 units	C8	Program removal
As DU002451	3rd Floor	Birmingham City University	NBA322	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
DU002454	3rd Floor	Birmingham City University	NBA321	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002455	3rd Floor	Birmingham City University	NBA320	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	14 m ²	C8	Program removal
As DU002454	3rd Floor	Birmingham City University	NBA307A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C8	Program removal
As DU002454	3rd Floor	Birmingham City University	NBA307	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	35 m ²	C8	Program removal
As DU002454	3rd Floor	Birmingham City University	NBA308	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C8	Program removal
DU002459	3rd Floor	Birmingham City University	NBA310A	Asbestos Thermoplastic floor tile with bitumen adhesive	Chrysotile	Analysis of sample using PLM	16 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002454	3rd Floor	Birmingham City University	NBA310B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU002470	3rd Floor	Birmingham City University	NBA399E Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	30 m ²	C8	Program removal
DU002422	4th Floor	Birmingham City University	NBA401	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	150 m ²	C8	Program removal
DU002425	4th Floor	Birmingham City University	NBA423	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	80 m ²	C8	Program removal
As DU002430	4th Floor	Birmingham City University	NBA408	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002430	4th Floor	Birmingham City University	NBA409	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU002430	4th Floor	Birmingham City University	NBA410	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C8	Program removal
As DU002430	4th Floor	Birmingham City University	NBA407	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	45 m ²	C8	Program removal
As DU002430	4th Floor	Birmingham City University	NBA411	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C8	Program removal
DU002434	4th Floor	Birmingham City University	NBA417A Service duct	Asbestos Cement flue pipe	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002437	4th Floor	Birmingham City University	NBA499A Corridor	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
As DU002437	4th Floor	Birmingham City University	NBA499B Corridor	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	30 m ²	C8	Program removal
As DU002437	4th Floor	Birmingham City University	NBA499C Corridor	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	40 m ²	C8	Program removal
DU002397	5th Floor	Birmingham City University	NBA502	Asbestos Thermoplastic floor tiles to concrete	Chrysotile	Analysis of sample using PLM	70 m ²	C8	Program removal
As DU002396	5th Floor	Birmingham City University	NBA505	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	75 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002406	5th Floor	Birmingham City University	NBA508	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	100 m ²	C8	Program removal
DU002408	5th Floor	Birmingham City University	NBA522	Asbestos Reinforced plastic cistern	Amosite	Analysis of sample using PLM	2 units	C8	Program removal
As DU002408	5th Floor	Birmingham City University	NBA520	Asbestos Reinforced plastic cistern	Amosite	Strongly presumed	1 unit	C8	Program removal
DU002410	5th Floor	Birmingham City University	NBA519 Service duct	Asbestos Cement flue pipe	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal
As DU002406	5th Floor	Birmingham City University	NBA510	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	50 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002413	5th Floor	Birmingham City University	NBA599B Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	35 m ²	C8	Program removal
DU002415	5th Floor	Birmingham City University	NBA599C Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	30 m ²	C8	Program removal
As DU002415	5th Floor	Birmingham City University	NBA599D Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	45 m ²	C8	Program removal
DU002376	6th Floor	Birmingham City University	NBA617	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
As DU002379	6th Floor	Birmingham City University	NBA607	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	60 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002381	6th Floor	Birmingham City University	NBA605	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	50 m ²	C8	Program removal
DU002384	6th Floor	Birmingham City University	NBA619A Service duct	Asbestos Cement flue pipe	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal
As DU002381	6th Floor	Birmingham City University	NBA603	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	50 m ²	C8	Program removal
DU002391	6th Floor	Birmingham City University	NBA699A Corridor	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
DU002394	6th Floor	Birmingham City University	NBA699C Corridor	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002358	7th Floor	Birmingham City University	NBA721	Asbestos Reinforced plastic cistern	Amosite	Analysis of sample using PLM	2 units	C8	Program removal
As DU002358	7th Floor	Birmingham City University	NBA719	Asbestos Reinforced plastic cistern	Amosite	Strongly presumed	1 unit	C8	Program removal
DU002361	7th Floor	Birmingham City University	NBA719A Service duct	Asbestos Cement flue pipe	Chrysotile	Analysis of sample using PLM	4 linear metres	C8	Program removal
DU002363	7th Floor	Birmingham City University	NBA715 Lecture room	Asbestos Bitumen adhesive to concrete	Chrysotile	Analysis of sample using PLM	25 m ²	C8	Program removal
DU002362	7th Floor	Birmingham City University	NBA715 Lecture room	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	60 m ²	C8	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002367	7th Floor	Birmingham City University	NBA799D Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	60 m ²	C8	Program removal
DU002320	8th Floor	Birmingham City University	NBA814	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	48 m ²	C8	Program removal
As DU002320	8th Floor	Birmingham City University	NBA817	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C8	Program removal
DU002325	8th Floor	Birmingham City University	NBA819A Service duct	Asbestos Insulating board	Chrysotile	Analysis of sample using PLM	4 m ²	C8	Program removal
DU002330	8th Floor	Birmingham City University	NBA822	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	15 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002330	8th Floor	Birmingham City University	NBA821	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
DU002588	Basement	Birmingham City University	NBAB05A Service Duct	Asbestos Compressed fibre gasket	Chrysotile	Analysis of sample using PLM	2 units	C8	Program removal
As DU002535	Ground Floor	Birmingham City University	NBAG26	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
DU002538	Ground Floor	Birmingham City University	NBAG04	Asbestos Vinyl	Chrysotile	Analysis of sample using PLM	16 m ²	C8	Program removal
As DU002538	Ground Floor	Birmingham City University	NBAG06	Asbestos Vinyl	Chrysotile	Strongly presumed	4 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002556	Ground Floor	Birmingham City University	NBAG18	Asbestos Vinyl with bitumen adhesive	Chrysotile	Analysis of sample using PLM	150 m ²	C8	Program removal
DU002558	Ground Floor	Birmingham City University	NBAG23	Asbestos Reinforced plastic cisterns	Amosite	Analysis of sample using PLM	2 units	C8	Program removal
DU002495	1st Floor	Birmingham City University	Attwood walkway	Asbestos Modern vinyl with adhesive	Chrysotile	Analysis of sample using PLM	16 m ²	C7	Program removal
DU002496	1st Floor	Birmingham City University	NBA101	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	4 units	C7	Program removal
As DU002496	1st Floor	Birmingham City University	NBA103	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002496	1st Floor	Birmingham City University	NBA102	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002496	1st Floor	Birmingham City University	NBA199A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
DU002498	1st Floor	Birmingham City University	NBA129A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	3 linear metres	C7	Program removal
As DU002498	1st Floor	Birmingham City University	NBA105	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002496	1st Floor	Birmingham City University	NBA111	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002496	1st Floor	Birmingham City University	NBA110	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002496	1st Floor	Birmingham City University	NBA109	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002496	1st Floor	Birmingham City University	NBA108	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
DU002512	1st Floor	Birmingham City University	NBA107	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	2 units	C7	Program removal
As DU002512	1st Floor	Birmingham City University	NBA106	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002512	1st Floor	Birmingham City University	NBA199B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
DU002514	1st Floor	Birmingham City University	NBA112A	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	10 m ²	C7	Program removal
DU002515	1st Floor	Birmingham City University	NBA112B	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	4 linear metres	C7	Program removal
As DU002512	1st Floor	Birmingham City University	NBA125	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002515	1st Floor	Birmingham City University	NBA124	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	<1 linear metres	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002512	1st Floor	Birmingham City University	NBA116	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002512	1st Floor	Birmingham City University	NBA131	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal
As DU002512	1st Floor	Birmingham City University	NBA132	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002512	1st Floor	Birmingham City University	NBA199C	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002516	1st Floor	Birmingham City University	NBA199C	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	10 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002517	1st Floor	Birmingham City University	NBA199C	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	8 m ²	C7	Program removal
As DU002515	1st Floor	Birmingham City University	NBA114A	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002514	1st Floor	Birmingham City University	NBA114B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	6 m ²	C7	Program removal
As DU002515	1st Floor	Birmingham City University	NBA113	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002522	1st Floor	Birmingham City University	NBA Store	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	2 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002515	1st Floor	Birmingham City University	NBA134A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002525	1st Floor	Birmingham City University	NBA134	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	2 units	C7	Program removal
As DU002525	1st Floor	Birmingham City University	NBA135	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002525	1st Floor	Birmingham City University	NBA136	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
DU002527	1st Floor	Birmingham City University	NBA136	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	10 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002527	1st Floor	Birmingham City University	NBA139	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	8 m ²	C7	Program removal
As DU002525	1st Floor	Birmingham City University	NBA199D	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002525	1st Floor	Birmingham City University	NBA199E	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal
As DU002525	1st Floor	Birmingham City University	NBA199G	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	10 units	C7	Program removal
DU002472	2nd Floor	Birmingham City University	NBA225	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	12 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002472	2nd Floor	Birmingham City University	NBA226	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA201D	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA201A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
DU002474	2nd Floor	Birmingham City University	NBA201A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	18 m ²	C7	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA201C	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	5 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002472	2nd Floor	Birmingham City University	NBA201B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA201	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal
DU002475	2nd Floor	Birmingham City University	NBA201	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	38 m ²	C7	Program removal
DU002476	2nd Floor	Birmingham City University	NBA224A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	3 linear metres	C7	Program removal
DU002477	2nd Floor	Birmingham City University	NBA203	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	18 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002472	2nd Floor	Birmingham City University	NBA203	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002476	2nd Floor	Birmingham City University	NBA203	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002478	2nd Floor	Birmingham City University	NBA224	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C7	Program removal
As DU002477	2nd Floor	Birmingham City University	NBA224	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	40 m ²	C7	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA204A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002477	2nd Floor	Birmingham City University	NBA204A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA204B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002477	2nd Floor	Birmingham City University	NBA204B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA299 Entrance Lobby	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA223	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002472	2nd Floor	Birmingham City University	NBA223B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA205	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	10 units	C7	Program removal
As DU002476	2nd Floor	Birmingham City University	NBA205A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA222	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
DU002481	2nd Floor	Birmingham City University	NBA222	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	25 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002476	2nd Floor	Birmingham City University	NBA221	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002482	2nd Floor	Birmingham City University	NBA221	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C7	Program removal
As DU002482	2nd Floor	Birmingham City University	NBA220	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
As DU002477	2nd Floor	Birmingham City University	NBA219	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
DU002483	2nd Floor	Birmingham City University	NBA206	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002483	2nd Floor	Birmingham City University	NBA207	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	40 m ²	C7	Program removal
As DU002476	2nd Floor	Birmingham City University	NBA210D Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002476	2nd Floor	Birmingham City University	NBA210A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002491	2nd Floor	Birmingham City University	NBA211	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	35 m ²	C7	Program removal
As DU002483	2nd Floor	Birmingham City University	NBA212	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	25 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002446	3rd Floor	Birmingham City University	NBA324A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	3 linear metres	C7	Program removal
As DU002446	3rd Floor	Birmingham City University	NBA303	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002449	3rd Floor	Birmingham City University	NBA324	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	30 m ²	C7	Program removal
As DU002446	3rd Floor	Birmingham City University	NBA306A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002446	3rd Floor	Birmingham City University	NBA312B Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002454	3rd Floor	Birmingham City University	NBA309	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	C7	Program removal
DU002458	3rd Floor	Birmingham City University	NBA309	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	1 m ²	C7	Program removal
As DU002454	3rd Floor	Birmingham City University	NBA399C Corridor	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	3 m ²	C7	Program removal
DU002461	3rd Floor	Birmingham City University	NBA311	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	14 m ²	C7	Program removal
As DU002461	3rd Floor	Birmingham City University	NBA316	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002461	3rd Floor	Birmingham City University	NBA312	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	30 m ²	C7	Program removal
DU002464	3rd Floor	Birmingham City University	NBA315	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	14 m ²	C7	Program removal
As DU002446	3rd Floor	Birmingham City University	NBA312A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002461	3rd Floor	Birmingham City University	NBA313	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	18 m ²	C7	Program removal
As DU002461	3rd Floor	Birmingham City University	NBA313B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002465	3rd Floor	Birmingham City University	NBA313B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	1 linear metres	C7	Program removal
DU002466	3rd Floor	Birmingham City University	NBA313A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	8 m ²	C7	Program removal
DU002469	3rd Floor	Birmingham City University	NBA314	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	25 m ²	C7	Program removal
As DU002422	4th Floor	Birmingham City University	NBA401B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	25 m ²	C7	Program removal
DU002423	4th Floor	Birmingham City University	NBA424A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	3 linear metres	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002423	4th Floor	Birmingham City University	NBA404C	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
DU002424	4th Floor	Birmingham City University	NBA424	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	40 m ²	C7	Program removal
DU002426	4th Floor	Birmingham City University	NBA405	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	40 m ²	C7	Program removal
As DU002423	4th Floor	Birmingham City University	NBA405A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
As DU002426	4th Floor	Birmingham City University	NBA422	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	25 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002426	4th Floor	Birmingham City University	NBA421	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
As DU002426	4th Floor	Birmingham City University	NBA406	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	30 m ²	C7	Program removal
DU002428	4th Floor	Birmingham City University	NBA407A	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	2 units	C7	Program removal
DU002430	4th Floor	Birmingham City University	NBA407A	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	6 m ²	C7	Program removal
As DU002428	4th Floor	Birmingham City University	NBA408	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002428	4th Floor	Birmingham City University	NBA409	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002428	4th Floor	Birmingham City University	NBA410	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002430	4th Floor	Birmingham City University	NBA410A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	8 m ²	C7	Program removal
As DU002428	4th Floor	Birmingham City University	NBA407	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal
As DU002428	4th Floor	Birmingham City University	NBA411	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002423	4th Floor	Birmingham City University	NBA412B Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
DU002436	4th Floor	Birmingham City University	NBA412	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	30 m ²	C7	Program removal
As DU002436	4th Floor	Birmingham City University	NBA417	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
As DU002436	4th Floor	Birmingham City University	NBA416	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	25 m ²	C7	Program removal
As DU002423	4th Floor	Birmingham City University	NBA412A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002436	4th Floor	Birmingham City University	NBA413	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	24 m ²	C7	Program removal
As DU002436	4th Floor	Birmingham City University	NBA414	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	20 m ²	C7	Program removal
As DU002436	4th Floor	Birmingham City University	NBA415	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	25 m ²	C7	Program removal
DU002396	5th Floor	Birmingham City University	NBA529	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	30 m ²	C7	Program removal
As DU002396	5th Floor	Birmingham City University	NBA530	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	18 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002396	5th Floor	Birmingham City University	NBA501	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	25 m ²	C7	Program removal
As DU002400	5th Floor	Birmingham City University	NBA528A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002396	5th Floor	Birmingham City University	NBA527	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	30 m ²	C7	Program removal
DU002402	5th Floor	Birmingham City University	NBA526	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	30 m ²	C7	Program removal
As DU002402	5th Floor	Birmingham City University	NBA526A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	18 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002404	5th Floor	Birmingham City University	NBA524	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	20 m ²	C7	Program removal
DU002405	5th Floor	Birmingham City University	NBA523	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	14 m ²	C7	Program removal
As DU002400	5th Floor	Birmingham City University	NBA510B Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002411	5th Floor	Birmingham City University	NBA518	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C7	Program removal
As DU002406	5th Floor	Birmingham City University	NBA517	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002400	5th Floor	Birmingham City University	NBA510A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002406	5th Floor	Birmingham City University	NBA516	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
As DU002406	5th Floor	Birmingham City University	NBA515	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	20 m ²	C7	Program removal
DU002412	5th Floor	Birmingham City University	NBA514	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	14 m ²	C7	Program removal
As DU002412	5th Floor	Birmingham City University	NBA513	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	20 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002412	5th Floor	Birmingham City University	NBA512	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	22 m ²	C7	Program removal
DU002413	5th Floor	Birmingham City University	NBA599A Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	6 m ²	C7	Program removal
As DU002400	5th Floor	Birmingham City University	NBA505C Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
DU002372	6th Floor	Birmingham City University	NBA613	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	20 m ²	C7	Program removal
As DU002373	6th Floor	Birmingham City University	NBA615A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002375	6th Floor	Birmingham City University	NBA615	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	18 m ²	C7	Program removal
As DU002375	6th Floor	Birmingham City University	NBA616	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	22 m ²	C7	Program removal
As DU002375	6th Floor	Birmingham City University	NBA609	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	20 m ²	C7	Program removal
As DU002373	6th Floor	Birmingham City University	NBA608A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002379	6th Floor	Birmingham City University	NBA619	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002379	6th Floor	Birmingham City University	NBA620	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
DU002381	6th Floor	Birmingham City University	NBA606	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	20 m ²	C7	Program removal
As DU002381	6th Floor	Birmingham City University	NBA613	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	15 m ²	C7	Program removal
As DU002373	6th Floor	Birmingham City University	NBA604A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002388	6th Floor	Birmingham City University	NBA623	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	18 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002373	6th Floor	Birmingham City University	NBA602A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002389	6th Floor	Birmingham City University	NBA602	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	20 m ²	C7	Program removal
As DU002388	6th Floor	Birmingham City University	NBA624	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C7	Program removal
As DU002388	6th Floor	Birmingham City University	NBA625	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C7	Program removal
As DU002389	6th Floor	Birmingham City University	NBA601	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	22 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002391	6th Floor	Birmingham City University	NBA699B Corridor	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	30 m ²	C7	Program removal
DU002345	7th Floor	Birmingham City University	NBA704	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	3 linear metres	C7	Program removal
As DU002345	7th Floor	Birmingham City University	NBA727A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002345	7th Floor	Birmingham City University	NBA707A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002351	7th Floor	Birmingham City University	NBA724	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002351	7th Floor	Birmingham City University	NBA723	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
DU002352	7th Floor	Birmingham City University	NBA722	Asbestos Thermoplastic floor tile to bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C7	Program removal
As DU002345	7th Floor	Birmingham City University	NBA713A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002345	7th Floor	Birmingham City University	NBA714A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002364	7th Floor	Birmingham City University	NBA799A Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	16 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002364	7th Floor	Birmingham City University	NBA799B Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	40 m ²	C7	Program removal
DU002367	7th Floor	Birmingham City University	NBA799C Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	30 m ²	C7	Program removal
As DU002345	7th Floor	Birmingham City University	NBA799C Corridor	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002353	7th Floor	Birmingham City University	NBA799D Corridor	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002320	8th Floor	Birmingham City University	NBA816	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	C7	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002323	8th Floor	Birmingham City University	NBA817B Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	3 linear metres	C7	Program removal
DU002324	8th Floor	Birmingham City University	NBA818	Asbestos Vinyl	Chrysotile	Analysis of sample using PLM	10 m ²	C7	Program removal
As DU002323	8th Floor	Birmingham City University	NBA820E Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002328	8th Floor	Birmingham City University	NBA820D Service duct	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002330	8th Floor	Birmingham City University	NBA821A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	8 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002323	8th Floor	Birmingham City University	NBA809A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002323	8th Floor	Birmingham City University	NBA826C Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002340	8th Floor	Birmingham City University	NBA899A Corridor	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	40 m ²	C7	Program removal
As DU002323	8th Floor	Birmingham City University	NBA899B Corridor	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
DU002342	8th Floor	Birmingham City University	NBA899C Corridor	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	2 linear metres	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002564	Basement	Birmingham City University	NBA02 Plant room	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	10 units	C7	Program removal
DU002567	Basement	Birmingham City University	NBA02 Plant room	Asbestos Compressed fibre gaskets	Chrysotile	Analysis of sample using PLM	16 units	C7	Program removal
DU002569	Basement	Birmingham City University	NBA02 Plant room	Asbestos Compressed fibre gasket	Chrysotile	Analysis of sample using PLM	8 units	C7	Program removal
DU002570	Basement	Birmingham City University	NBA02 Plant room	Asbestos Compressed fibre gasket	Chrysotile	Analysis of sample using PLM	20 units	C7	Program removal
DU002571	Basement	Birmingham City University	NBA02 Plant room	Asbestos Compressed fibre gasket	Chrysotile	Analysis of sample using PLM	10 units	C7	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002564	Basement	Birmingham City University	NBA03 Storage	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002564	Basement	Birmingham City University	NBAB99 Duct	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
As DU002536	Basement	Birmingham City University	NBAB11 Service Duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002578	E - External	Birmingham City University	NBA905 Roof	Asbestos Textile rope seal to metal flue pipe	Chrysotile	Analysis of sample using PLM	1 linear metres	C7	Program removal
DU002580	E - External	Birmingham City University	NBAEXT - External	Asbestos Cement panels	Chrysotile	Analysis of sample using PLM	336 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002581	E - External	Birmingham City University	NBAEXT - External	Asbestos Cement panels	Chrysotile	Analysis of sample using PLM	218 m ²	C7	Program removal
DU002582	E - External	Birmingham City University	NBAEXT - External	Asbestos Cement panels	Chrysotile	Analysis of sample using PLM	308 m ²	C7	Program removal
DU002583	E - External	Birmingham City University	NBAEXT - External	Asbestos Cement panels	Chrysotile	Analysis of sample using PLM	192 m ²	C7	Program removal
DU002534	Ground Floor	Birmingham City University	NBAG28	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	8 units	C7	Program removal
As DU002534	Ground Floor	Birmingham City University	NBAG26	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002536	Ground Floor	Birmingham City University	NBAG32	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	2 linear metres	C7	Program removal
As DU002534	Ground Floor	Birmingham City University	NBAG01	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002534	Ground Floor	Birmingham City University	NBAG03	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal
As DU002534	Ground Floor	Birmingham City University	NBAG05	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	15 units	C7	Action Required
As DU002536	Ground Floor	Birmingham City University	NBAG05	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002534	Ground Floor	Birmingham City University	NBAG04	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
DU002539	Ground Floor	Birmingham City University	NBAG04	Asbestos Bitumen sink pads	Chrysotile	Analysis of sample using PLM	2 units	C7	Program removal
As DU002534	Ground Floor	Birmingham City University	NBAG06	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002536	Ground Floor	Birmingham City University	NBAG30A Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
As DU002534	Ground Floor	Birmingham City University	NBAG99A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002542	Ground Floor	Birmingham City University	NBAG99B	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	30 m ²	C7	Program removal
As DU002536	Ground Floor	Birmingham City University	NBAG99C	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002545	Ground Floor	Birmingham City University	NBAG07D	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	4 m ²	C7	Program removal
As DU002536	Ground Floor	Birmingham City University	NBAG07E Service duct	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
DU002551	Ground Floor	Birmingham City University	NBAG08	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	3 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002536	Ground Floor	Birmingham City University	NBAG08B	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002551	Ground Floor	Birmingham City University	NBAG09A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002551	Ground Floor	Birmingham City University	NBAG09B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002551	Ground Floor	Birmingham City University	NBAG10	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002551	Ground Floor	Birmingham City University	NBAG11A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002551	Ground Floor	Birmingham City University	NBAG18	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal
As DU002536	Ground Floor	Birmingham City University	NBAG34	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	C7	Program removal
As DU002557	Ground Floor	Birmingham City University	NBAG21	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	C7	Program removal
As DU002551	Ground Floor	Birmingham City University	NBAG18D	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002551	Ground Floor	Birmingham City University	NBAG99D	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002500	1st Floor	Birmingham City University	NBA109	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	8 m ²	D6	Program removal
As DU002474	2nd Floor	Birmingham City University	NBA201C	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	D6	Program removal
As DU002474	2nd Floor	Birmingham City University	NBA201B	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	4 m ²	D6	Program removal
As DU002472	2nd Floor	Birmingham City University	NBA202	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002477	2nd Floor	Birmingham City University	NBA299 Entrance Lobby	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	6 m ²	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002477	2nd Floor	Birmingham City University	NBA223B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	D6	Program removal
As DU002477	2nd Floor	Birmingham City University	NBA223A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	6 m ²	D6	Program removal
DU002484	2nd Floor	Birmingham City University	NBA207	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	12 units	D6	Program removal
As DU002484	2nd Floor	Birmingham City University	NBA208	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal
As DU002484	2nd Floor	Birmingham City University	NBA210	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	5 units	D6	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002490	2nd Floor	Birmingham City University	NBA214	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	10 m ²	D6	Program removal
As DU002490	2nd Floor	Birmingham City University	NBA213	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	D6	Program removal
As DU002484	2nd Floor	Birmingham City University	NBA211	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002484	2nd Floor	Birmingham City University	NBA212	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002491	2nd Floor	Birmingham City University	NBA213A	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	10 m ²	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002484	2nd Floor	Birmingham City University	NBA299A Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal
As DU002476	2nd Floor	Birmingham City University	NBA299B Corridor	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	D6	Program removal
As DU002484	2nd Floor	Birmingham City University	NBA299C Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
DU002442	3rd Floor	Birmingham City University	NBA325	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	12 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA325A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002443	3rd Floor	Birmingham City University	NBA325A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	8 m ²	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA326B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA301C	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA301	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	D6	Program removal
DU002445	3rd Floor	Birmingham City University	NBA326A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	4 m ²	D6	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002442	3rd Floor	Birmingham City University	NBA303	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA303B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA303A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA323	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA305	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002446	3rd Floor	Birmingham City University	NBA322	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA307B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA307A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	5 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA307	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA308	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002442	3rd Floor	Birmingham City University	NBA399A Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA399B Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA310A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA399C Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA310B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002442	3rd Floor	Birmingham City University	NBA311	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	5 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA312	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA313	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002461	3rd Floor	Birmingham City University	NBA313C	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA313B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002442	3rd Floor	Birmingham City University	NBA313A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002461	3rd Floor	Birmingham City University	NBA314A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA399D Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	18 units	D6	Program removal
As DU002446	3rd Floor	Birmingham City University	NBA399E Corridor	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	D6	Program removal
As DU002442	3rd Floor	Birmingham City University	NBA399F Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	5 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002421	4th Floor	Birmingham City University	NBA401	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	20 units	D6	Program removal
As DU002421	4th Floor	Birmingham City University	NBA401A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002422	4th Floor	Birmingham City University	NBA401A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	D6	Program removal
As DU002421	4th Floor	Birmingham City University	NBA401B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	9 units	D6	Program removal
As DU002421	4th Floor	Birmingham City University	NBA404C	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002421	4th Floor	Birmingham City University	NBA404A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002421	4th Floor	Birmingham City University	NBA404	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	5 units	D6	Program removal
As DU002421	4th Floor	Birmingham City University	NBA423	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002421	4th Floor	Birmingham City University	NBA405	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002423	4th Floor	Birmingham City University	NBA422	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	D6	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002421	4th Floor	Birmingham City University	NBA406	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
DU002435	4th Floor	Birmingham City University	NBA412	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	3 units	D6	Program removal
As DU002435	4th Floor	Birmingham City University	NBA413	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002435	4th Floor	Birmingham City University	NBA414	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002435	4th Floor	Birmingham City University	NBA499A Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002423	4th Floor	Birmingham City University	NBA499B Corridor	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	D6	Program removal
DU002395	5th Floor	Birmingham City University	NBA529	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	10 units	D6	Program removal
As DU002395	5th Floor	Birmingham City University	NBA530	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002395	5th Floor	Birmingham City University	NBA502	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	D6	Program removal
As DU002395	5th Floor	Birmingham City University	NBA505	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002400	5th Floor	Birmingham City University	NBA504	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	4 linear metres	D6	Program removal
As DU002395	5th Floor	Birmingham City University	NBA505B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002400	5th Floor	Birmingham City University	NBA524	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	D6	Program removal
As DU002395	5th Floor	Birmingham City University	NBA508	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal
As DU002395	5th Floor	Birmingham City University	NBA510	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002395	5th Floor	Birmingham City University	NBA514	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002395	5th Floor	Birmingham City University	NBA512	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002412	5th Floor	Birmingham City University	NBA599A Corridor	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	D6	Program removal
As DU002395	5th Floor	Birmingham City University	NBA599A Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002395	5th Floor	Birmingham City University	NBA599B Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002395	5th Floor	Birmingham City University	NBA599C Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002400	5th Floor	Birmingham City University	NBA599C Corridor	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	D6	Program removal
As DU002395	5th Floor	Birmingham City University	NBA599D Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	5 units	D6	Program removal
DU002370	6th Floor	Birmingham City University	NBA614	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	12 units	D6	Program removal
As DU002370	6th Floor	Birmingham City University	NBA613	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002370	6th Floor	Birmingham City University	NBA612	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	18 units	D6	Program removal
DU002373	6th Floor	Birmingham City University	NBA612	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	3 linear metres	D6	Program removal
As DU002370	6th Floor	Birmingham City University	NBA611	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002370	6th Floor	Birmingham City University	NBA610	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002370	6th Floor	Birmingham City University	NBA615	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002370	6th Floor	Birmingham City University	NBA609A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	D6	Program removal
As DU002370	6th Floor	Birmingham City University	NBA609	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
DU002380	6th Floor	Birmingham City University	NBA607	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	12 units	D6	Program removal
As DU002380	6th Floor	Birmingham City University	NBA605	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	D6	Program removal
DU002387	6th Floor	Birmingham City University	NBA622	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	1 unit	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002386	6th Floor	Birmingham City University	NBA622	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	10 m ²	D6	Program removal
As DU002387	6th Floor	Birmingham City University	NBA603	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal
As DU002387	6th Floor	Birmingham City University	NBA602	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002387	6th Floor	Birmingham City University	NBA699A Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal
As DU002373	6th Floor	Birmingham City University	NBA699B Corridor	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	3 linear metres	D6	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002387	6th Floor	Birmingham City University	NBA699C Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal
DU002343	7th Floor	Birmingham City University	NBA728	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Analysis of sample using PLM	16 units	D6	Program removal
As DU002343	7th Floor	Birmingham City University	NBA702	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal
As DU002343	7th Floor	Birmingham City University	NBA704	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002343	7th Floor	Birmingham City University	NBA704A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002343	7th Floor	Birmingham City University	NBA706	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal
As DU002343	7th Floor	Birmingham City University	NBA707	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
DU002353	7th Floor	Birmingham City University	NBA708	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Analysis of sample using PLM	8 units	D6	Program removal
As DU002353	7th Floor	Birmingham City University	NBA709	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002353	7th Floor	Birmingham City University	NBA710	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002353	7th Floor	Birmingham City University	NBA711	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal
As DU002353	7th Floor	Birmingham City University	NBA713	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	5 units	D6	Program removal
As DU002353	7th Floor	Birmingham City University	NBA714	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
DU002360	7th Floor	Birmingham City University	NBA718	Asbestos Thermoplastic floor tile to bitumen adhesive	Chrysotile	Analysis of sample using PLM	10 m ²	D6	Program removal
As DU002353	7th Floor	Birmingham City University	NBA715 Lecture room	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002353	7th Floor	Birmingham City University	NBA799A Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002353	7th Floor	Birmingham City University	NBA799B Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
DU002319	8th Floor	Birmingham City University	NBA814	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Analysis of sample using PLM	6 units	D6	Program removal
As DU002319	8th Floor	Birmingham City University	NBA813	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
DU002328	8th Floor	Birmingham City University	NBA811	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Analysis of sample using PLM	10 units	D6	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Baker Building, Perry Barr

Report Number: J102748

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002328	8th Floor	Birmingham City University	NBA808A	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002328	8th Floor	Birmingham City University	NBA806A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	10 units	D6	Program removal
DU002334	8th Floor	Birmingham City University	NBA806	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	10 m ²	D6	Program removal
As DU002334	8th Floor	Birmingham City University	NBA806A	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	5 m ²	D6	Program removal
As DU002328	8th Floor	Birmingham City University	NBA805	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002328	8th Floor	Birmingham City University	NBA830	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal
As DU002328	8th Floor	Birmingham City University	NBA830B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002328	8th Floor	Birmingham City University	NBA830A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002328	8th Floor	Birmingham City University	NBA803	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	5 units	D6	Program removal
As DU002328	8th Floor	Birmingham City University	NBA899B Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002328	8th Floor	Birmingham City University	NBA899C Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal
DU002542	Ground Floor	Birmingham City University	NBAG99A	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	8 m ²	D6	Program removal

3.2 Executive Summary of Non-Asbestos Material

The following pages show a summary of non-asbestos materials located during these works.

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002321	8th Floor	Birmingham City University	NBA815	Bitumen adhesive to parquet flooring	No Asbestos Detected	Analysis of sample using PLM	24 m ²	E0	Not applicable
DU002322	8th Floor	Birmingham City University	NBA817B Service duct	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
As DU002322	8th Floor	Birmingham City University	NBA819A Service duct	Insulating board door header	No Asbestos Detected	Strongly presumed	1 m ²	E0	Not applicable
DU002327	8th Floor	Birmingham City University	NBA819	Vinyl	No Asbestos Detected	Analysis of sample using PLM	10 m ²	E0	Not applicable
DU002326	8th Floor	Birmingham City University	NBA819	Textured coating to block wall	No Asbestos Detected	Analysis of sample using PLM	20 m ²	E0	Not applicable
DU002329	8th Floor	Birmingham City University	NBA806A	Bitumen adhesive to parquet flooring	No Asbestos Detected	Analysis of sample using PLM	35 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002329	8th Floor	Birmingham City University	NBA806B	Bitumen adhesive to parquet flooring	No Asbestos Detected	Strongly presumed	12 m ²	E0	Not applicable
As DU002326	8th Floor	Birmingham City University	NBA820	Textured coating to block wall	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
DU002331	8th Floor	Birmingham City University	NBA899 Lifts	Textured coating to blockwork	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable
DU002332	8th Floor	Birmingham City University	NBA825	Vinyl	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable
DU002333	8th Floor	Birmingham City University	NBA800A Stairs	Textured coating to wall	No Asbestos Detected	Analysis of sample using PLM	75 m ²	E0	Not applicable
As DU002322	8th Floor	Birmingham City University	NBA809A Service duct	Insulating board door header	No Asbestos Detected	Strongly presumed	1 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002335	8th Floor	Birmingham City University	NBA805	Bitumen adhesive to parquet flooring	No Asbestos Detected	Analysis of sample using PLM	50 m ²	E0	Not applicable
DU002336	8th Floor	Birmingham City University	NBA827	Textured coating to section of wall timber boxing	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
As DU002322	8th Floor	Birmingham City University	NBA826C Service duct	Insulating board door header	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
DU002337	8th Floor	Birmingham City University	NBA830	Textured coating to block	No Asbestos Detected	Analysis of sample using PLM	90 m ²	E0	Not applicable
As DU002337	8th Floor	Birmingham City University	NBA830B	Textured coating to block	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable
As DU002337	8th Floor	Birmingham City University	NBA830A	Textured coating to block	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002338	8th Floor	Birmingham City University	NBA803	Textured coating to timber boxing	No Asbestos Detected	Analysis of sample using PLM	6 linear metres	E0	Not applicable
DU002339	8th Floor	Birmingham City University	NBA899A	Textured coating to wall and concrete pillars	No Asbestos Detected	Analysis of sample using PLM	30 m ²	E0	Not applicable
DU002341	8th Floor	Birmingham City University	NBA899A	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
As DU002339	8th Floor	Birmingham City University	NBA899B	Textured coating to wall and concrete pillars	No Asbestos Detected	Strongly presumed	10 m ²	E0	Not applicable
As DU002341	8th Floor	Birmingham City University	NBA899B	Insulating board door header	No Asbestos Detected	Strongly presumed	4 m ²	E0	Not applicable
As DU002339	8th Floor	Birmingham City University	NBA899C	Textured coating to wall and concrete pillars	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002341	8th Floor	Birmingham City University	NBA899C Corridor	Insulating board door header	No Asbestos Detected	Strongly presumed	4 m ²	E0	Not applicable
DU002344	7th Floor	Birmingham City University	NBA728	Bitumen adhesive to parquet flooring	No Asbestos Detected	Analysis of sample using PLM	50 m ²	E0	Not applicable
As DU002344	7th Floor	Birmingham City University	NBA701	Bitumen adhesive to parquet flooring	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
As DU002344	7th Floor	Birmingham City University	NBA702	Bitumen adhesive to parquet flooring	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable
As DU002344	7th Floor	Birmingham City University	NBA704	Bitumen adhesive to parquet flooring	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
DU002346	7th Floor	Birmingham City University	NBA727A Service duct	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002347	7th Floor	Birmingham City University	NBA727	Bitumen sink pads	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable
DU002348	7th Floor	Birmingham City University	NBA727	Bitumen adhesive beneath parquet	No Asbestos Detected	Analysis of sample using PLM	20 m ²	E0	Not applicable
As DU002348	7th Floor	Birmingham City University	NBA726	Bitumen adhesive beneath parquet	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
As DU002348	7th Floor	Birmingham City University	NBA706	Bitumen adhesive to parquet flooring	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable
As DU002348	7th Floor	Birmingham City University	NBA725	Bitumen adhesive to rear of parquet	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable
As DU002346	7th Floor	Birmingham City University	NBA707A Service duct	Insulating board door header	No Asbestos Detected	Strongly presumed	1 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002349	7th Floor	Birmingham City University	NBA799 Stairwell	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	50 m ²	E0	Not applicable
As DU002348	7th Floor	Birmingham City University	NBA708	Bitumen adhesive to parquet flooring	No Asbestos Detected	Strongly presumed	25 m ²	E0	Not applicable
As DU002349	7th Floor	Birmingham City University	NBA799A Lift lobby	Textured coating to concrete walls	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable
DU002355	7th Floor	Birmingham City University	NBA709	Bitumen sink pads	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable
DU002354	7th Floor	Birmingham City University	NBA709	Bitumen adhesive beneath parquet	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable
As DU002354	7th Floor	Birmingham City University	NBA711	Bitumen adhesive to parquet flooring	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002354	7th Floor	Birmingham City University	NBA712	Bitumen adhesive to parquet	No Asbestos Detected	Strongly presumed	10 m ²	E0	Not applicable
DU002356	7th Floor	Birmingham City University	NBA712	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable
DU002357	7th Floor	Birmingham City University	NBA713A Service duct	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
As DU002357	7th Floor	Birmingham City University	NBA720B Service duct	Insulating board door header	No Asbestos Detected	Strongly presumed	4 m ²	E0	Not applicable
DU002359	7th Floor	Birmingham City University	NBA721	Textured coating to one wall	No Asbestos Detected	Analysis of sample using PLM	30 m ²	E0	Not applicable
As DU002354	7th Floor	Birmingham City University	NBA713	Bitumen adhesive to parquet flooring	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002354	7th Floor	Birmingham City University	NBA714	Bitumen adhesive to parquet flooring	No Asbestos Detected	Strongly presumed	25 m ²	E0	Not applicable
As DU002357	7th Floor	Birmingham City University	NBA714A Service duct	Insulating board door header	No Asbestos Detected	Strongly presumed	2 m ²	E0	Not applicable
As DU002357	7th Floor	Birmingham City University	NBA715 Lecture room	Insulating board door header	No Asbestos Detected	Strongly presumed	4 m ²	E0	Not applicable
DU002365	7th Floor	Birmingham City University	NBA799A Corridor	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
DU002366	7th Floor	Birmingham City University	NBA799A Corridor	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
As DU002365	7th Floor	Birmingham City University	NBA799B Corridor	Insulating board door header	No Asbestos Detected	Strongly presumed	6 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002366	7th Floor	Birmingham City University	NBA799B Corridor	Textured coating to concrete	No Asbestos Detected	Strongly presumed	10 m ²	E0	Not applicable
DU002369	7th Floor	Birmingham City University	NBA799C Corridor	Insulating board door headers	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
As DU002366	7th Floor	Birmingham City University	NBA799C Corridor	Textured coating to concrete	No Asbestos Detected	Strongly presumed	18 m ²	E0	Not applicable
As DU002365	7th Floor	Birmingham City University	NBA799C Corridor	Insulating board door header	No Asbestos Detected	Strongly presumed	4 m ²	E0	Not applicable
As DU002366	7th Floor	Birmingham City University	NBA799D Corridor	Textured coating to concrete	No Asbestos Detected	Strongly presumed	30 m ²	E0	Not applicable
DU002371	6th Floor	Birmingham City University	NBA614	Bitumen adhesive	No Asbestos Detected	Analysis of sample using PLM	50 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002371	6th Floor	Birmingham City University	NBA612	Bitumen adhesive	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable
As DU002371	6th Floor	Birmingham City University	NBA611	Bitumen adhesive	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
DU002374	6th Floor	Birmingham City University	NBA615A Service duct	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
As DU002371	6th Floor	Birmingham City University	NBA609A	Bitumen adhesive	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable
DU002377	6th Floor	Birmingham City University	NBA608A Service duct	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
DU002378	6th Floor	Birmingham City University	NBA699 Stairwell	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	75 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002378	6th Floor	Birmingham City University	NBA699A Lift lobby	Textured coating to concrete walls	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable
DU002382	6th Floor	Birmingham City University	NBA620A	Textured coating to one wall	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable
DU002383	6th Floor	Birmingham City University	NBA621B Service duct	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
DU002385	6th Floor	Birmingham City University	NBA619A Service duct	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
As DU002385	6th Floor	Birmingham City University	NBA602A Service duct	Insulating board door header	No Asbestos Detected	Strongly presumed	1 m ²	E0	Not applicable
DU002392	6th Floor	Birmingham City University	NBA699A Corridor	Insulating board firebreak	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002390	6th Floor	Birmingham City University	NBA699A Corridor	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	30 m ²	E0	Not applicable
DU002393	6th Floor	Birmingham City University	NBA699B Corridor	Insulating board firebreak	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
As DU002390	6th Floor	Birmingham City University	NBA699B Corridor	Textured coating to concrete	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable
As DU002393	6th Floor	Birmingham City University	NBA699C Corridor	Insulating board firebreak	No Asbestos Detected	Strongly presumed	4 m ²	E0	Not applicable
As DU002390	6th Floor	Birmingham City University	NBA699C Corridor	Textured coating to concrete	No Asbestos Detected	Strongly presumed	30 m ²	E0	Not applicable
DU002398	5th Floor	Birmingham City University	NBA505	Textured coating to block	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002399	5th Floor	Birmingham City University	NBA505	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable
As DU002398	5th Floor	Birmingham City University	NBA526	Textured coating to block	No Asbestos Detected	Strongly presumed	25 m ²	E0	Not applicable
As DU002398	5th Floor	Birmingham City University	NBA599 Stairwell	Textured coating to concrete	No Asbestos Detected	Strongly presumed	100 m ²	E0	Not applicable
DU002403	5th Floor	Birmingham City University	NBA599A Lift lobby	Textured coating to concrete walls	No Asbestos Detected	Analysis of sample using PLM	60 m ²	E0	Not applicable
DU002407	5th Floor	Birmingham City University	NBA510A Plant room	Compressed plasterboard door header	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
DU002409	5th Floor	Birmingham City University	NBA522	Textured coating to one wall	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002414	5th Floor	Birmingham City University	NBA599B Corridor	Textured coating to concrete sections	No Asbestos Detected	Analysis of sample using PLM	20 m ²	E0	Not applicable
As DU002414	5th Floor	Birmingham City University	NBA599C Corridor	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
As DU002414	5th Floor	Birmingham City University	NBA599D Corridor	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	25 m ²	E0	Not applicable
DU002427	4th Floor	Birmingham City University	NBA499 Stairwell	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	80 m ²	E0	Not applicable
As DU002427	4th Floor	Birmingham City University	NBA499 Lift Lobby	Textured coating to concrete	No Asbestos Detected	Strongly presumed	80 m ²	E0	Not applicable
DU002429	4th Floor	Birmingham City University	NBA407A	Fibreboard wall panelling	No Asbestos Detected	Analysis of sample using PLM	16 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002429	4th Floor	Birmingham City University	NBA408	Fibreboard wall panelling	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
As DU002429	4th Floor	Birmingham City University	NBA409	Fibreboard wall panelling	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
As DU002429	4th Floor	Birmingham City University	NBA410	Fibreboard wall panelling	No Asbestos Detected	Strongly presumed	25 m ²	E0	Not applicable
As DU002429	4th Floor	Birmingham City University	NBA410A	Fibreboard wall panelling	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable
As DU002429	4th Floor	Birmingham City University	NBA407	Fibreboard wall panelling	No Asbestos Detected	Strongly presumed	60 m ²	E0	Not applicable
As DU002429	4th Floor	Birmingham City University	NBA411	Fibreboard wall panelling	No Asbestos Detected	Strongly presumed	40 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002431	4th Floor	Birmingham City University	NBA412B Service duct	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
DU002432	4th Floor	Birmingham City University	NBA420A Service duct	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
DU002433	4th Floor	Birmingham City University	NBA418	Textured coating to one wall	No Asbestos Detected	Analysis of sample using PLM	20 m ²	E0	Not applicable
DU002438	4th Floor	Birmingham City University	NBA499A Corridor	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	20 m ²	E0	Not applicable
DU002439	4th Floor	Birmingham City University	NBA499A Corridor	Insulating board wall panelling	No Asbestos Detected	Analysis of sample using PLM	20 m ²	E0	Not applicable
As DU002438	4th Floor	Birmingham City University	NBA499B Corridor	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	18 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002438	4th Floor	Birmingham City University	NBA499C Corridor	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	30 m ²	E0	Not applicable
DU002447	3rd Floor	Birmingham City University	NBA303	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	20 m ²	E0	Not applicable
DU002453	3rd Floor	Birmingham City University	NBA300A Stairwell	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	100 m ²	E0	Not applicable
As DU002453	3rd Floor	Birmingham City University	NBA399 Lift Lobby	Textured coating to concrete	No Asbestos Detected	Strongly presumed	70 m ²	E0	Not applicable
DU002456	3rd Floor	Birmingham City University	NBA319	Textured coating	No Asbestos Detected	Analysis of sample using PLM	45 m ²	E0	Not applicable
DU002457	3rd Floor	Birmingham City University	NBA319	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002460	3rd Floor	Birmingham City University	NBA311	Textured coating to block walls	No Asbestos Detected	Analysis of sample using PLM	64 m ²	E0	Not applicable
As DU002456	3rd Floor	Birmingham City University	NBA318	Textured coating	No Asbestos Detected	Strongly presumed	28 m ²	E0	Not applicable
DU002462	3rd Floor	Birmingham City University	NBA318	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
DU002467	3rd Floor	Birmingham City University	NBA313A	Textured coating to concrete section	No Asbestos Detected	Analysis of sample using PLM	3 m ²	E0	Not applicable
As DU002467	3rd Floor	Birmingham City University	NBA399D Corridor	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
As DU002467	3rd Floor	Birmingham City University	NBA399E Corridor	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	30 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002467	3rd Floor	Birmingham City University	NBA399F Corridor	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	30 m ²	E0	Not applicable
DU002471	2nd Floor	Birmingham City University	To Attwood walkway	Insulating board suspended tiles	No Asbestos Detected	Analysis of sample using PLM	18 m ²	E0	Not applicable
DU002480	2nd Floor	Birmingham City University	NBA200A Stairwell	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	80 m ²	E0	Not applicable
As DU002480	2nd Floor	Birmingham City University	NBA299 Lift Lobby	Textured coating to concrete	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable
DU002485	2nd Floor	Birmingham City University	NBA218	Textured coating	No Asbestos Detected	Analysis of sample using PLM	40 m ²	E0	Not applicable
DU002486	2nd Floor	Birmingham City University	NBA218	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002485	2nd Floor	Birmingham City University	NBA217	Textured coating to blockwork	No Asbestos Detected	Strongly presumed	12 m ²	E0	Not applicable
As DU002485	2nd Floor	Birmingham City University	NBA216	Textured coating	No Asbestos Detected	Strongly presumed	24 m ²	E0	Not applicable
DU002487	2nd Floor	Birmingham City University	NBA216	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
DU002489	2nd Floor	Birmingham City University	NBA210B	Reinforced plastic debris	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
DU002492	2nd Floor	Birmingham City University	NBA299A Corridor	Textured coating to concrete sections	No Asbestos Detected	Analysis of sample using PLM	16 m ²	E0	Not applicable
As DU002492	2nd Floor	Birmingham City University	NBA299B Corridor	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002492	2nd Floor	Birmingham City University	NBA299C Corridor	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	25 m ²	E0	Not applicable
DU002494	1st Floor	Birmingham City University	Attwood walkway	Insulating board door header panel	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
DU002499	1st Floor	Birmingham City University	NBA127	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	1 unit	E0	Not applicable
DU002513	1st Floor	Birmingham City University	NBA199B	Vinyl	No Asbestos Detected	Analysis of sample using PLM	14 m ²	E0	Not applicable
As DU002513	1st Floor	Birmingham City University	NBA116	Vinyl	No Asbestos Detected	Strongly presumed	10 m ²	E0	Not applicable
DU002518	1st Floor	Birmingham City University	NBA100B Stairwell	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	100 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002518	1st Floor	Birmingham City University	NBA199 Lift lobby	Textured coating to concrete	No Asbestos Detected	Strongly presumed	60 m ²	E0	Not applicable
DU002519	1st Floor	Birmingham City University	NBA114B	Textured coating to plaster to block	No Asbestos Detected	Analysis of sample using PLM	16 m ²	E0	Not applicable
DU002523	1st Floor	Birmingham City University	NBA100C Stairwell	Textured coating to concrete walls	No Asbestos Detected	Analysis of sample using PLM	50 m ²	E0	Not applicable
DU002524	1st Floor	Birmingham City University	NBA100C Stairwell	Paper within plastic casing to door	No Asbestos Detected	Analysis of sample using PLM	4 linear metres	E0	Not applicable
DU002526	1st Floor	Birmingham City University	NBA136	Textured coating to walls	No Asbestos Detected	Analysis of sample using PLM	10 m ²	E0	Not applicable
DU002529	1st Floor	Birmingham City University	NBA139	Textured coating to walls	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002531	1st Floor	Birmingham City University	NBA199E	Vinyl	No Asbestos Detected	Analysis of sample using PLM	35 m ²	E0	Not applicable
DU002532	1st Floor	Birmingham City University	NBA199E	Textured coating to concrete sections	No Asbestos Detected	Analysis of sample using PLM	16 m ²	E0	Not applicable
As DU002531	1st Floor	Birmingham City University	NBA199F	Vinyl	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
As DU002532	1st Floor	Birmingham City University	NBA199F	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	30 m ²	E0	Not applicable
As DU002531	1st Floor	Birmingham City University	NBA199G	Vinyl	No Asbestos Detected	Strongly presumed	25 m ²	E0	Not applicable
As DU002532	1st Floor	Birmingham City University	NBA199G	Textured coating to concrete sections	No Asbestos Detected	Strongly presumed	50 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002541	Ground Floor	Birmingham City University	NBAG99A	Insulating board ceiling tile	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
DU002543	Ground Floor	Birmingham City University	NBAG99B	Textured coating to concrete sections	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable
DU002544	Ground Floor	Birmingham City University	NBAG07B	Asphalt	No Asbestos Detected	Analysis of sample using PLM	45 m ²	E0	Not applicable
DU002546	Ground Floor	Birmingham City University	NBAG07D	Textured coating to plaster to walls	No Asbestos Detected	Analysis of sample using PLM	16 m ²	E0	Not applicable
As DU002544	Ground Floor	Birmingham City University	NBAG99E	Asphalt	No Asbestos Detected	Strongly presumed	4 m ²	E0	Not applicable
As DU002544	Ground Floor	Birmingham City University	NBAG07A	Asphalt	No Asbestos Detected	Strongly presumed	30 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002547	Ground Floor	Birmingham City University	NBAG07	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	100 m ²	E0	Not applicable
DU002548	Ground Floor	Birmingham City University	NBAG07	Bitumen adhesive to acoustic tiles	No Asbestos Detected	Analysis of sample using PLM	30 m ²	E0	Not applicable
DU002549	Ground Floor	Birmingham City University	NBAG07	Textured coating to concrete columns	No Asbestos Detected	Analysis of sample using PLM	27 m ²	E0	Not applicable
DU002550	Ground Floor	Birmingham City University	NBAG07	Asphalt	No Asbestos Detected	Analysis of sample using PLM	100 m ²	E0	Not applicable
DU002552	Ground Floor	Birmingham City University	NBAG11A	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable
DU002554	Ground Floor	Birmingham City University	NBAG00 Stairs	Textured coating to concrete walls	No Asbestos Detected	Analysis of sample using PLM	55 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:	
DU002555	Ground Floor	Birmingham City University	NBAG08C	Insulating board panel	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable	
DU002559	Ground Floor	Birmingham City University	NBAG99	Lift lobby	Textured coating to plaster to block wall	No Asbestos Detected	Analysis of sample using PLM	50 m ²	E0	Not applicable
As DU002559	Ground Floor	Birmingham City University	NBAG00A	Stairs	Textured coating to plaster to block wall	No Asbestos Detected	Strongly presumed	100 m ²	E0	Not applicable
As DU002559	Ground Floor	Birmingham City University	NBAG99G		Textured coating to plaster to block wall	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable
DU002561	Basement	Birmingham City University	NBAB99	Corridor	Textured coating to brick and concrete	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable
As DU002561	Basement	Birmingham City University	NBAB07		Textured coating to brick and concrete	No Asbestos Detected	Strongly presumed	35 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002562	Basement	Birmingham City University	NBAB08	Textured coating to brick and concrete	No Asbestos Detected	Analysis of sample using PLM	10 m ²	E0	Not applicable
As DU002562	Basement	Birmingham City University	NBAB09	Textured coating to brick and concrete	No Asbestos Detected	Strongly presumed	10 m ²	E0	Not applicable
As DU002561	Basement	Birmingham City University	NBAB99A Corridor	Textured coating to brick and concrete	No Asbestos Detected	Strongly presumed	20 m ²	E0	Not applicable
As DU002561	Basement	Birmingham City University	NBAB13	Textured coating to brick and concrete	No Asbestos Detected	Strongly presumed	8 m ²	E0	Not applicable
DU002563	Basement	Birmingham City University	NBAB00 Stairs	Textured coating to brick and concrete	No Asbestos Detected	Analysis of sample using PLM	75 m ²	E0	Not applicable
DU002565	Basement	Birmingham City University	NBA02 Plant room	Insulating board to base of boilers	No Asbestos Detected	Analysis of sample using PLM	10 m ²	E0	Not applicable


Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002566	Basement	Birmingham City University	NBA02 Plant room	Textile rope seal to cast iron boilers	No Asbestos Detected	Analysis of sample using PLM	100 linear metres	E0	Not applicable
DU002568	Basement	Birmingham City University	NBA02 Plant room	Compressed fibre gasket	No Asbestos Detected	Analysis of sample using PLM	4 units	E0	Not applicable
DU002572	Basement	Birmingham City University	NBA02 Plant room	Compressed fibre gaskets	No Asbestos Detected	Analysis of sample using PLM	6 units	E0	Not applicable
DU002573	Basement	Birmingham City University	NBA02 Plant room	Insulating board debris	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
DU002577	E - External	Birmingham City University	NBA903 Roof top plant room	Bitumen damp proof course	No Asbestos Detected	Analysis of sample using PLM	16 linear metres	E0	Not applicable
DU002579	E - External	Birmingham City University	NBA905 Roof	Bitumen felt roof covering	No Asbestos Detected	Analysis of sample using PLM	1000 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002586	Basement	Birmingham City University	NBA02 Plant room	Insulation residues to corner pillar	No Asbestos Detected	Analysis of sample using PLM	2 linear metres	E0	Not applicable
DU002589	Ground Floor	Birmingham City University	NBAG00 Sub Station No.3	Insulating board ceiling panels	No Asbestos Detected	Analysis of sample using PLM	30 m ²	E0	Not applicable

4.0 Item Register & Management Report


The following pages show a register of all suspect materials located during this investigation, which includes a photographic record of each item along with individual risk assessment scores.

The section entitled 'Portal Ref No' relates to a corresponding number assigned to each sample for the purpose of identification within the TEAMS online Portal.

Location:	NBA814	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002319	Portal Ref No.:	1	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	[REDACTED]	Extent:	6 units	
Comments: Wall which runs parallel to the corridor				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA814	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002320	Portal Ref No.:	2	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	48 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA815	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002321	Portal Ref No.:	5	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	24 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA816	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002320	Portal Ref No.:	6	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA817B Service duct	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002322	Portal Ref No.:	8	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA817B Service duct	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002323	Portal Ref No.:	9	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA817	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002320	Portal Ref No.:	10	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA818	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002324	Portal Ref No.:	11	
Item:	Asbestos Vinyl			
Asbestos Content:	Result Based on:			
Chrysotile in vinyl only	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	10 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos vinyl)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA819A Service duct	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002325	Portal Ref No.:	12	
Item:	Asbestos Insulating board			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 m ²		
Comments: Where former pipework openings pass through to the roof covering, difficult to determine the extent				

Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos insulating board)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA819A Service duct	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002322	Portal Ref No.:	13	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	1 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA813	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002319	Portal Ref No.:	14	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Wall which runs parallel to the corridor				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA819	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002327	Portal Ref No.:	17	
Item:	Vinyl			
Asbestos Content:		Result Based on:		
No Asbestos Detected in vinyl or adhesive		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	10 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA819	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002326	Portal Ref No.:	18	
Item:	Textured coating to block wall			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA820E Service duct	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002323	Portal Ref No.:	20	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA811	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002328	Portal Ref No.:	23	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	10 units		
Comments: Within concrete structure, beams across room within ceiling				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA808A	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002328	Portal Ref No.:	24	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Within concrete structure, beams across room within ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA820D Service duct	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002328	Portal Ref No.:	25	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA806A	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002329	Portal Ref No.:	26	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	35 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA806A	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002328	Portal Ref No.:	27	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 units	
Comments: Within concrete structure, beams across room within ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA806B	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002329	Portal Ref No.:	28	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA820	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002326	Portal Ref No.:	30	
Item:	Textured coating to block wall			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA822	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002330	Portal Ref No.:	31	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	15 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA821	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002330	Portal Ref No.:	32	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA821A	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002330	Portal Ref No.:	33	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA899 Lifts	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002331	Portal Ref No.:	34	
Item:	Textured coating to blockwork			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments: Behind plasterboard to right and corner of lift lobby				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA825	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002332	Portal Ref No.:	35	
Item:	Vinyl			
Asbestos Content:		Result Based on:		
No Asbestos Detected in vinyl or adhesive		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA800A Stairs	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002333	Portal Ref No.:	37	
Item:	Textured coating to wall			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	75 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA809A Service duct	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002322	Portal Ref No.:	38	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	1 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA809A Service duct	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002323	Portal Ref No.:	39	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA806	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002334	Portal Ref No.:	40	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	10 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA806A	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002334	Portal Ref No.:	41	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA805	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002335	Portal Ref No.:	43	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:			Result Based on:	
No Asbestos Detected in vinyl or adhesive		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA805	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002328	Portal Ref No.:	44	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments: Within concrete structure, beams across room within ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA827	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002336	Portal Ref No.:	47	
Item:	Textured coating to section of wall timber boxing			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 m ²	
Comments: To section of the wall adjacent the external window				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA826C Service duct	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002322	Portal Ref No.:	48	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA826C Service duct	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002323	Portal Ref No.:	49	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA830	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002328	Portal Ref No.:	51	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: Within concrete structure, beams across room within ceiling				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA830	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002337	Portal Ref No.:	52	
Item:	Textured coating to block			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	90 m ²	
Comments: To all external facing walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA830B	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002328	Portal Ref No.:	53	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Within concrete structure, beams across room within ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA830B	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002337	Portal Ref No.:	54	
Item:	Textured coating to block			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: To all external facing walls				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA830A	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002328	Portal Ref No.:	55	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Within concrete structure, beams across room within ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA830A	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002337	Portal Ref No.:	56	
Item:	Textured coating to block			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: To all external facing walls				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA803	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002328	Portal Ref No.:	57	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 units	
Comments: Within concrete structure, beams across room within ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA803	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002338	Portal Ref No.:	58	
Item:	Textured coating to timber boxing			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 linear metres	
Comments: To both timber boxings either side of the room				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA899A Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002339	Portal Ref No.:	60	
Item:	Textured coating to wall and concrete pillars			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	30 m ²	
Comments: The entire wall area of the corridor isn't textured coated				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA899A Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002340	Portal Ref No.:	61	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	40 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA899A Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002341	Portal Ref No.:	62	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Above double doors				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA899B Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002339	Portal Ref No.:	63	
Item:	Textured coating to wall and concrete pillars			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: The entire wall area of the corridor isn't textured coated				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA899B Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002328	Portal Ref No.:	64	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Within concrete structure, beams across room within ceiling				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA899B Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002341	Portal Ref No.:	65	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: Above double doors				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA899B Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002323	Portal Ref No.:	66	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA899C Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002339	Portal Ref No.:	67	
Item:	Textured coating to wall and concrete pillars			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: The entire wall area of the corridor isn't textured coated				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA899C Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002328	Portal Ref No.:	68	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Within concrete structure, beams across room within ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA899C Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	As DU002341	Portal Ref No.:	69	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: Firebreak half way down the corridor				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA899C Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002342	Portal Ref No.:	70	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Chrysotile in tile and adhesive			
Result Based on:	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	2 linear metres	
Comments: Outside stairwell doors NBA800 stairs				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA728	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002343	Portal Ref No.:	71	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	16 units		
Comments: Structural columns				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA728	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002344	Portal Ref No.:	72	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA701	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002344	Portal Ref No.:	74	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: Beneath carpet tiles				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA702	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002343	Portal Ref No.:	76	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: Structural columns				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA702	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002344	Portal Ref No.:	77	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA704	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002343	Portal Ref No.:	79	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA704	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002344	Portal Ref No.:	80	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA704	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002345	Portal Ref No.:	81	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA704A	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002343	Portal Ref No.:	82	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA727A Service duct	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002346	Portal Ref No.:	83	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA727A Service duct	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002345	Portal Ref No.:	84	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA727	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002347	Portal Ref No.:	86	
Item:	Bitumen sink pads			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA727	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002348	Portal Ref No.:	87	
Item:	Bitumen adhesive beneath parquet			
Asbestos Content:			Result Based on:	
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA726	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002348	Portal Ref No.:	89	
Item:	Bitumen adhesive beneath parquet			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA706	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002343	Portal Ref No.:	90	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA706	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002348	Portal Ref No.:	91	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA707	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002343	Portal Ref No.:	92	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA725	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002348	Portal Ref No.:	93	
Item:	Bitumen adhesive to rear of parquet			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA707A Service duct	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002346	Portal Ref No.:	94	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	1 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	


Management Detail

Location:	NBA707A Service duct	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002345	Portal Ref No.:	95	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	


Management Detail

Location:	NBA799 Stairwell	Block:	Birmingham City University		Floor Level: 7th Floor
Sample No.:	DU002349	Portal Ref No.:	96	11/09/2018 13:09:12	
Item:	Textured coating to concrete				
Asbestos Content:		Result Based on:			
No Asbestos Detected		Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²		
Comments:					



Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA899B Corridor	Block:	Birmingham City University	Floor Level: 8th Floor
Sample No.:	DU002350	Portal Ref No.:	97	
Item:	Asbestos Insulating board panel to dry riser			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: Adjacent to stairwell and lift				

Material Assessment Total Score: 6		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA724	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002351	Portal Ref No.:	98	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	12 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA723	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002351	Portal Ref No.:	99	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Beneath carpet tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA722	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002352	Portal Ref No.:	101	
Item:	Asbestos Thermoplastic floor tile to bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	12 m ²		
Comments: Beneath carpet tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA708	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002353	Portal Ref No.:	102	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	8 units	
Comments: Structural columns				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA708	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002348	Portal Ref No.:	103	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA799A Lift lobby	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002349	Portal Ref No.:	104	
Item:	Textured coating to concrete walls			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA709	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002355	Portal Ref No.:	105	
Item:	Bitumen sink pads			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA709	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002354	Portal Ref No.:	106	
Item:	Bitumen adhesive beneath parquet			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA709	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002353	Portal Ref No.:	107	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA710	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002353	Portal Ref No.:	110	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Structural columns				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA711	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002353	Portal Ref No.:	111	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA711	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002354	Portal Ref No.:	112	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA712	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002354	Portal Ref No.:	113	
Item:	Bitumen adhesive to parquet			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA712	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002356	Portal Ref No.:	114	
Item:	Bitumen sink pad			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA713A Service duct	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002345	Portal Ref No.:	115	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA713A Service duct	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002357	Portal Ref No.:	116	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA720B Service duct	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002357	Portal Ref No.:	118	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA721	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002358	Portal Ref No.:	119	
Item:	Asbestos Reinforced plastic cistern			
Asbestos Content:	Result Based on:			
Amosite	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	2 (Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA721	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002359	Portal Ref No.:	120	
Item:	Textured coating to one wall			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	30 m ²	
Comments: Right-hand side on entering				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA719	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002358	Portal Ref No.:	121	
Item:	Asbestos Reinforced plastic cistern			
Asbestos Content:	Result Based on:			
Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	2 (Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA713	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002353	Portal Ref No.:	122	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA713	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002354	Portal Ref No.:	123	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:			Result Based on:	
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA714	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002353	Portal Ref No.:	124	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Structural columns, through ceiling also				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA714	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002354	Portal Ref No.:	125	
Item:	Bitumen adhesive to parquet flooring			
Asbestos Content:			Result Based on:	
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA718	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002360	Portal Ref No.:	126	
Item:	Asbestos Thermoplastic floor tile to bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	10 m ²		
Comments: Beneath carpet tiles				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA719A Service duct	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002361	Portal Ref No.:	127	
Item:	Asbestos Cement flue pipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 linear metres		
Comments: Textile rope present internally to the flue pipe (redundant)				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA714A Service duct	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002345	Portal Ref No.:	128	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA714A Service duct	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002357	Portal Ref No.:	129	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA715 Lecture room	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002353	Portal Ref No.:	130	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA715 Lecture room	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002363	Portal Ref No.:	131	
Item:	Asbestos Bitumen adhesive to concrete			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	25 m ²		
Comments: Beneath carpet, to front section of room				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA715 Lecture room	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002362	Portal Ref No.:	132	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	60 m ²		
Comments: Beneath raised timber floor				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA715 Lecture room	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002357	Portal Ref No.:	133	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA799A Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002364	Portal Ref No.:	134	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	16 m ²		
Comments: Composite sample green and beige				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA799A Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002365	Portal Ref No.:	135	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Above double doors				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA799A Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002353	Portal Ref No.:	136	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA799A Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002366	Portal Ref No.:	137	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 m ²	
Comments: Sections of walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA799B Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002364	Portal Ref No.:	138	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:			Result Based on:	
Chrysotile in tile and adhesive		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	40 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA799B Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002365	Portal Ref No.:	139	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: Above door to NBA719A service duct, also above double doors				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA799B Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002353	Portal Ref No.:	140	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA799B Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002366	Portal Ref No.:	141	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Sections of walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA799C Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002367	Portal Ref No.:	142	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	30 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail


Location:	NBA799C Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002369	Portal Ref No.:	143	
Item:	Insulating board door headers			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	3 m ²	
Comments: Above doors to NBA708, 722 and 723				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail


Location:	NBA799C Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002366	Portal Ref No.:	145	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments: Sections of walls				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	
Management Detail				

Location:	NBA799C Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	DU002368	Portal Ref No.:	146	
Item:	Asbestos Insulating board panel to dry riser			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments:				


Material Assessment Total Score: 8		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B12
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	2 (Local damage)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA799C Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002345	Portal Ref No.:	147	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA799C Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002365	Portal Ref No.:	148	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: Above double doors				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA799D Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002367	Portal Ref No.:	149	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	60 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA799D Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002366	Portal Ref No.:	151	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments: Sections of walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA799D Corridor	Block:	Birmingham City University	Floor Level: 7th Floor
Sample No.:	As DU002353	Portal Ref No.:	153	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Structural columns				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA614	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002370	Portal Ref No.:	154	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Mrs S Williams	Extent:	12 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA614	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002371	Portal Ref No.:	156	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²	
Comments: To underside of timber parquet flooring				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA613	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002370	Portal Ref No.:	157	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA613	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002372	Portal Ref No.:	159	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA612	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002370	Portal Ref No.:	160	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA612	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002371	Portal Ref No.:	162	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments: To underside of timber parquet flooring				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA612	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002373	Portal Ref No.:	163	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	3 linear metres		
Comments: Internally to small opening low level adjacent to entrance door				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA611	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002370	Portal Ref No.:	164	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA611	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002371	Portal Ref No.:	165	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: To underside of timber parquet flooring				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA610	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002370	Portal Ref No.:	166	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA615A Service duct	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002374	Portal Ref No.:	167	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA615A Service duct	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002373	Portal Ref No.:	168	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA615	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002370	Portal Ref No.:	170	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA615	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002375	Portal Ref No.:	171	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	18 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA616	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002375	Portal Ref No.:	174	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	22 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA609A	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002370	Portal Ref No.:	175	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA609A	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002371	Portal Ref No.:	176	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments: To underside of timber parquet flooring				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA617	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002376	Portal Ref No.:	178	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By:	Mrs S Williams	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA609	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002370	Portal Ref No.:	179	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA609	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002375	Portal Ref No.:	180	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA608A Service duct	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002377	Portal Ref No.:	182	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA608A Service duct	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002373	Portal Ref No.:	183	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA699 Stairwell	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002378	Portal Ref No.:	184	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	75 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA619	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002379	Portal Ref No.:	186	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA620	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002379	Portal Ref No.:	187	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA699A Lift lobby	Block:	Birmingham City University		Floor Level: 6th Floor
Sample No.:	As DU002378	Portal Ref No.:	188		
Item:	Textured coating to concrete walls				
Asbestos Content:		Result Based on:			
No Asbestos Detected		Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	50 m ²		
Comments:					

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA607	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002380	Portal Ref No.:	189	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	12 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA607	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002379	Portal Ref No.:	190	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	60 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA606	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002381	Portal Ref No.:	192	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA605	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002380	Portal Ref No.:	193	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA605	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002381	Portal Ref No.:	195	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA620A	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002382	Portal Ref No.:	198	
Item:	Textured coating to one wall			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments: Right-hand side on entering				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA621B Service duct	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002383	Portal Ref No.:	199	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA613	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002381	Portal Ref No.:	200	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	15 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA604A Service duct	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002373	Portal Ref No.:	202	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA619A Service duct	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002384	Portal Ref No.:	204	
Item:	Asbestos Cement flue pipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	4 linear metres	
Comments:				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA619A Service duct	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002385	Portal Ref No.:	205	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA622	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002387	Portal Ref No.:	206	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	1 unit	
Comments: Passes through the ceiling				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA622	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002386	Portal Ref No.:	207	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	10 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA603	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002387	Portal Ref No.:	208	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Passes through the ceiling and wall				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA603	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002381	Portal Ref No.:	209	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA623	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002388	Portal Ref No.:	211	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	18 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA602A Service duct	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002373	Portal Ref No.:	212	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA602A Service duct	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002385	Portal Ref No.:	213	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	1 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA602	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002387	Portal Ref No.:	214	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Passes through the wall				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA602	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002389	Portal Ref No.:	215	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA624	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002388	Portal Ref No.:	216	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA625	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002388	Portal Ref No.:	217	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA601	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002389	Portal Ref No.:	219	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	22 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA699A Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002391	Portal Ref No.:	220	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA699A Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002392	Portal Ref No.:	221	
Item:	Insulating board firebreak			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: See plan for location				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA699A Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002387	Portal Ref No.:	222	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA699A Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002390	Portal Ref No.:	223	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	30 m ²	
Comments: Sections of walls				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA699B Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002391	Portal Ref No.:	224	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA699B Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002393	Portal Ref No.:	225	
Item:	Insulating board firebreak			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Above double doors to corridor 699A				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA699B Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002390	Portal Ref No.:	227	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: Sections of walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA699B Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002373	Portal Ref No.:	228	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments: Internally to timber boxing				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA699C Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	DU002394	Portal Ref No.:	229	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	50 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA699C Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002393	Portal Ref No.:	230	
Item:	Insulating board firebreak			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments: Above double doors				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA699C Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002387	Portal Ref No.:	231	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA699C Corridor	Block:	Birmingham City University	Floor Level: 6th Floor
Sample No.:	As DU002390	Portal Ref No.:	232	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments: Sections of walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA529	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002395	Portal Ref No.:	233	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	10 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA529	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002396	Portal Ref No.:	235	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	30 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA530	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	236	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA530	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002396	Portal Ref No.:	238	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA501	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002396	Portal Ref No.:	241	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA502	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	242	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA502	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002397	Portal Ref No.:	244	
Item:	Asbestos Thermoplastic floor tiles to concrete			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	70 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA505	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	246	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA505	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002396	Portal Ref No.:	247	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	75 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA505	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002398	Portal Ref No.:	248	
Item:	Textured coating to block			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA505	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002399	Portal Ref No.:	249	
Item:	Bitumen sink pad			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA504	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002400	Portal Ref No.:	250	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 linear metres		
Comments: Internally to timber boxing, visible from room NBA502				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA504	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002401	Portal Ref No.:	251	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	14 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 7		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	3 (Routinely disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA505B	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	252	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA528A Service duct	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002400	Portal Ref No.:	254	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA527	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002396	Portal Ref No.:	256	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA526	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002402	Portal Ref No.:	257	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	30 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA526	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002398	Portal Ref No.:	258	
Item:	Textured coating to block			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments: Right-hand wall on entering the room				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA526A	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002402	Portal Ref No.:	259	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA599 Stairwell	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002398	Portal Ref No.:	260	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	100 m ²	
Comments: To all walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA599A Lift lobby	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002403	Portal Ref No.:	261	
Item:	Textured coating to concrete walls			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	60 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA524	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002404	Portal Ref No.:	262	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA524	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002400	Portal Ref No.:	263	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments: Internally to timber boxing				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA523	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002405	Portal Ref No.:	264	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	14 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA508	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	266	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: To structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA508	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002406	Portal Ref No.:	267	 <p>13/09/2018 11:25:04</p>
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	100 m ²		
Comments: To raised seating area of theatre only				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA510A Plant room	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002406	Portal Ref No.:	268	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 7		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	3 (Routinely disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA510A Plant room	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002407	Portal Ref No.:	269	
Item:	Compressed plasterboard door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA510B Service duct	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002400	Portal Ref No.:	270	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA522	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002408	Portal Ref No.:	272	
Item:	Asbestos Reinforced plastic cistern			
Asbestos Content:	Result Based on:			
Amosite	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	2 (Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA522	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002409	Portal Ref No.:	273	
Item:	Textured coating to one wall			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments: Right-hand side on entering				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA520	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002408	Portal Ref No.:	274	
Item:	Asbestos Reinforced plastic cistern			
Asbestos Content:	Result Based on:			
Amosite	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	2 (Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA519 Service duct	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002410	Portal Ref No.:	275	
Item:	Asbestos Cement flue pipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 linear metres		
Comments:				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA518	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002411	Portal Ref No.:	276	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	12 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA517	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002406	Portal Ref No.:	277	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA510	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002406	Portal Ref No.:	278	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA510	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	279	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: To wall which runs alongside the corridor				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA510A Service duct	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002400	Portal Ref No.:	280	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA516	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002406	Portal Ref No.:	281	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA515	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002406	Portal Ref No.:	282	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA514	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002412	Portal Ref No.:	283	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	14 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA514	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	284	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA513	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002412	Portal Ref No.:	285	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA512	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002412	Portal Ref No.:	286	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	22 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA512	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	287	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA599A Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002412	Portal Ref No.:	288	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Floor area outside rooms 15, 14 13 and 12				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA599A Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	290	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA599A Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002413	Portal Ref No.:	291	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	6 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA599B Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	293	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Structural columns				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA599B Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002413	Portal Ref No.:	294	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	35 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA599B Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002414	Portal Ref No.:	295	
Item:	Textured coating to concrete sections			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA599C Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	296	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Structural columns, from service duct				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA599C Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	DU002415	Portal Ref No.:	297	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	30 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA599C Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002414	Portal Ref No.:	298	
Item:	Textured coating to concrete sections			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA599C Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002400	Portal Ref No.:	299	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments: Adjacent to lift				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA505C Service duct	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002400	Portal Ref No.:	300	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA599D Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002395	Portal Ref No.:	301	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 units	
Comments: Structural columns				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA599D Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002415	Portal Ref No.:	302	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	45 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA599D Corridor	Block:	Birmingham City University	Floor Level: 5th Floor
Sample No.:	As DU002414	Portal Ref No.:	303	
Item:	Textured coating to concrete sections			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA401	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002421	Portal Ref No.:	304	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	20 units		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA401	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002422	Portal Ref No.:	306	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	150 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA401A	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002421	Portal Ref No.:	307	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA401A	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002422	Portal Ref No.:	308	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA401B	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002421	Portal Ref No.:	310	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	9 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA401B	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002422	Portal Ref No.:	311	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA424A Service duct	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002423	Portal Ref No.:	313	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	3 linear metres		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA404C	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002421	Portal Ref No.:	314	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA404C	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002423	Portal Ref No.:	316	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA404A	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002421	Portal Ref No.:	317	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA424	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002424	Portal Ref No.:	319	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	40 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA404	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002421	Portal Ref No.:	320	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA423	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002425	Portal Ref No.:	322	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	80 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA423	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002421	Portal Ref No.:	324	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA405	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002426	Portal Ref No.:	325	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	40 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA405	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002421	Portal Ref No.:	327	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA405A Service duct	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002423	Portal Ref No.:	328	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA499 Stairwell	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002427	Portal Ref No.:	329	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	80 m ²	
Comments: To all walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA499 Lift Lobby	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002427	Portal Ref No.:	330	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	80 m ²	
Comments: To all walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA422	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002426	Portal Ref No.:	331	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA422	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002423	Portal Ref No.:	332	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA421	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002426	Portal Ref No.:	333	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA406	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002426	Portal Ref No.:	334	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA406	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002421	Portal Ref No.:	335	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA407A	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002428	Portal Ref No.:	336	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA407A	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002429	Portal Ref No.:	337	
Item:	Fibreboard wall panelling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	16 m ²	
Comments: Extends above and below the ceiling tiles				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA407A	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002430	Portal Ref No.:	338	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	6 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA408	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002428	Portal Ref No.:	339	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA408	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002429	Portal Ref No.:	340	
Item:	Fibreboard wall panelling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: Extends above and below the ceiling tiles				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA408	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002430	Portal Ref No.:	341	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA409	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002428	Portal Ref No.:	342	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA409	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002429	Portal Ref No.:	343	
Item:	Fibreboard wall panelling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: Extends above and below the ceiling tiles				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA409	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002430	Portal Ref No.:	344	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA410	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002428	Portal Ref No.:	345	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA410	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002429	Portal Ref No.:	346	
Item:	Fibreboard wall panelling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments: Extends above and below the ceiling tiles				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA410	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002430	Portal Ref No.:	347	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA410A	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002429	Portal Ref No.:	349	
Item:	Fibreboard wall panelling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: Extends above and below the ceiling tiles				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA410A	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002430	Portal Ref No.:	350	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: 3 x storage cupboards completed as one room				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA407	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002428	Portal Ref No.:	351	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA407	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002429	Portal Ref No.:	352	
Item:	Fibreboard wall panelling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	60 m ²	
Comments: Extends above and below the ceiling tiles, labelled as modern board				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA407	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002430	Portal Ref No.:	353	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	45 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA411	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002428	Portal Ref No.:	354	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA411	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002429	Portal Ref No.:	355	
Item:	Fibreboard wall panelling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	40 m ²	
Comments: Extends above and below the ceiling tiles, labelled as modern board				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA411	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002430	Portal Ref No.:	356	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA412B Service duct	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002431	Portal Ref No.:	357	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA412B Service duct	Block:	Birmingham City University		Floor Level: 4th Floor
Sample No.:	As DU002423	Portal Ref No.:	358		
Item:	Asbestos Reinforced plastic downpipe				
Asbestos Content:	Result Based on:				
Chrysotile	Strongly presumed				
Sample Analysed By:	Not applicable	Extent:	4 linear metres		
Comments:					

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA420A Service duct	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002432	Portal Ref No.:	360	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA418	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002433	Portal Ref No.:	362	
Item:	Textured coating to one wall			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments: Right-hand side on entering				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA417A Service duct	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002434	Portal Ref No.:	363	
Item:	Asbestos Cement flue pipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 linear metres		
Comments: Textile rope seal internally to smaller flue				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA412	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002436	Portal Ref No.:	364	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	30 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA412	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002435	Portal Ref No.:	365	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	3 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA417	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002436	Portal Ref No.:	366	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA416	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002436	Portal Ref No.:	367	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA412A Service duct	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002423	Portal Ref No.:	368	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA413	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002436	Portal Ref No.:	369	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	24 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA413	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002435	Portal Ref No.:	370	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA414	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002436	Portal Ref No.:	371	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA414	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002435	Portal Ref No.:	372	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA415	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002436	Portal Ref No.:	374	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA499A Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002437	Portal Ref No.:	375	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA499A Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002435	Portal Ref No.:	376	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: Structural columns between rooms and corridor, sleeve also seen to pass through the ceiling				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA499A Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002438	Portal Ref No.:	377	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA499A Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002439	Portal Ref No.:	378	
Item:	Insulating board wall panelling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments: Large amount of insulating board to the corner of the corridor above and below the ceiling tile level				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA499B Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002437	Portal Ref No.:	380	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA499B Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002438	Portal Ref No.:	381	
Item:	Textured coating to concrete sections			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments: To concrete sections				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA499B Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002423	Portal Ref No.:	382	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments: Adjacent to lift				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA499C Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002437	Portal Ref No.:	384	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	40 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA499C Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	As DU002438	Portal Ref No.:	385	
Item:	Textured coating to concrete sections			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA499C Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002440	Portal Ref No.:	386	
Item:	Asbestos Insulating board firebreak			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 m ²		
Comments: Within ceiling void adjacent to stairwell NBA400, item in poor condition				


Material Assessment Total Score: 8		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B12
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	2 (Local damage)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA499C Corridor	Block:	Birmingham City University	Floor Level: 4th Floor
Sample No.:	DU002441	Portal Ref No.:	387	
Item:	Asbestos Insulating board debris			
Asbestos Content:	Result Based on:			
Chrysotile Amosite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: Associated debris from badly damaged firebreak				

Material Assessment Total Score: 9		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: B14
Product Type:	2 (Asbestos insulating board)	Location:	2 (Rooms up to 100 sq m)	
Condition:	3 (Significant damage)	Accessibility:	2 (Easily disturbed)	
Surface Treatment:	2 (Unencapsulated asbestos insulating board)			
Asbestos Type:	2 (Chrysotile Amosite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA325	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002442	Portal Ref No.:	388	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	12 units		
Comments: Through the structural concrete				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA325	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002443	Portal Ref No.:	389	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA325A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	390	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA325A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002443	Portal Ref No.:	391	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA326B	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	392	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA301C	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	393	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA301	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	395	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA301	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002444	Portal Ref No.:	396	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA326A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002445	Portal Ref No.:	397	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA324A Service duct	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002446	Portal Ref No.:	398	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	3 linear metres		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA303	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002447	Portal Ref No.:	399	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments: Behind paint to concrete				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA303	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	400	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through the structural concrete				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail


Location:	NBA303	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002446	Portal Ref No.:	401	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail


Location:	NBA303	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002448	Portal Ref No.:	402	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	35 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	
Management Detail				

Location:	NBA303B	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	404	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through the structural concrete				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA303A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	405	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA324	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002449	Portal Ref No.:	406	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	30 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA323	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002450	Portal Ref No.:	407	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA323	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	408	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA305	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	410	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA305	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002451	Portal Ref No.:	412	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	40 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA306	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002452	Portal Ref No.:	414	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	12 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA300A Stairwell	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002453	Portal Ref No.:	415	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	100 m ²	
Comments: To all walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA399 Lift Lobby	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002453	Portal Ref No.:	416	
Item:	Textured coating to concrete			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	70 m ²	
Comments: To all walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA306A Service duct	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002446	Portal Ref No.:	417	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA322	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002446	Portal Ref No.:	418	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments: Through the structural concrete				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA322	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002451	Portal Ref No.:	419	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA321	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002454	Portal Ref No.:	421	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA320	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002455	Portal Ref No.:	423	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA307B	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	424	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through the structural concrete				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA307A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	425	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 units	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA307A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002454	Portal Ref No.:	426	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA319	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002456	Portal Ref No.:	427	
Item:	Textured coating			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	45 m ²		
Comments: All walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA319	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002457	Portal Ref No.:	428	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA312B Service duct	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002446	Portal Ref No.:	433	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA307	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	435	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA307	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002454	Portal Ref No.:	436	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	35 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA308	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	437	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA308	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002454	Portal Ref No.:	438	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA399A Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	439	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Through the structural concrete				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA399B Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	440	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA309	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002454	Portal Ref No.:	442	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA309	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002458	Portal Ref No.:	443	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: Within timber boxing to corner of room				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA310A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	444	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA310A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002459	Portal Ref No.:	445	
Item:	Asbestos Thermoplastic floor tile with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	16 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA399C Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	446	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through the structural concrete				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA399C Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002454	Portal Ref No.:	447	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA310B	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	448	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through the structural concrete, passes through ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA310B	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002454	Portal Ref No.:	449	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA311	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002460	Portal Ref No.:	450	
Item:	Textured coating to block walls			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	64 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA311	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002461	Portal Ref No.:	451	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA311	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	452	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 units	
Comments: Through the structural concrete				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA318	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002456	Portal Ref No.:	453	
Item:	Textured coating			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	28 m ²	
Comments: All walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA318	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002462	Portal Ref No.:	454	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA317 Service duct	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002463	Portal Ref No.:	456	
Item:	Asbestos Cement flue pipe			
Asbestos Content:	Result Based on:			
Chrysotile Crocidolite	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 linear metres		
Comments: Textile rope seal internally to smaller flue, connects to former female WC dispenser unit				

Material Assessment Total Score: 6		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Encapsulated asbestos cement)			
Asbestos Type:	3 (Chrysotile Crocidolite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA316	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002461	Portal Ref No.:	457	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA312	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002461	Portal Ref No.:	458	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA312	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	459	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA315	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002464	Portal Ref No.:	461	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	14 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA312A Service duct	Block:	Birmingham City University		Floor Level: 3rd Floor
Sample No.:	As DU002446	Portal Ref No.:	462		
Item:	Asbestos Reinforced plastic downpipe				
Asbestos Content:	Result Based on:				
Chrysotile	Strongly presumed				
Sample Analysed By:	Not applicable	Extent:	3 linear metres		
Comments:					


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA313	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002461	Portal Ref No.:	463	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments: Sporadic amounts throughout				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA313	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	464	18/09/2018 09:17:39
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:		
Comments: Through the structural concrete, to the corridor wall				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA313C	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002461	Portal Ref No.:	465	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Sporadic amounts throughout				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA313B	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002461	Portal Ref No.:	466	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: Sporadic amounts throughout				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA313B	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002465	Portal Ref No.:	467	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 linear metres	
Comments: To the door opening only				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA313B	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	468	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through the structural concrete, to corridor wall				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA313A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002466	Portal Ref No.:	470	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	8 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA313A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	471	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Through the structural concrete, to corridor wall				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA313A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002467	Portal Ref No.:	472	
Item:	Textured coating to concrete section			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By:	██████████	Extent:	3 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA314A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002461	Portal Ref No.:	473	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA314A	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002468	Portal Ref No.:	474	18/09/2018 09:39:45
Item:	Asbestos Cement roof tile packers			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 m ²		
Comments: To the top of the adjoining wall to room NBA314				

Material Assessment Total Score: 6		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	3 (Significant damage)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA314	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002469	Portal Ref No.:	475	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	25 m ²		
Comments: Throughout all rooms				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA399D Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	DU002470	Portal Ref No.:	476	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	60 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA399D Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002467	Portal Ref No.:	477	
Item:	Textured coating to concrete sections			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments: To concrete sections				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA399D Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	478	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 units	
Comments: Passes through wall section separating the rooms and the corridor				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA399E Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002470	Portal Ref No.:	479	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NBA399E Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002467	Portal Ref No.:	480	
Item:	Textured coating to concrete sections			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments: To concrete sections				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA399E Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002446	Portal Ref No.:	481	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 linear metres	
Comments: Internally to timber boxing				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA399F Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002470	Portal Ref No.:	482	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA399F Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002467	Portal Ref No.:	483	
Item:	Textured coating to concrete sections			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	30 m ²	
Comments: To concrete sections				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA399F Corridor	Block:	Birmingham City University	Floor Level: 3rd Floor
Sample No.:	As DU002442	Portal Ref No.:	484	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 units	
Comments: Passes through wall section separating the rooms and the corridor				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	To Attwood walkway	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002471	Portal Ref No.:	486	
Item:	Insulating board suspended tiles			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	18 m ²	
Comments: Includes firebreak above doors				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NBA225	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002472	Portal Ref No.:	487	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	12 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA225	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002473	Portal Ref No.:	488	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	50 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NBA226	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002472	Portal Ref No.:	489	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA201D	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002472	Portal Ref No.:	490	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NBA201A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002472	Portal Ref No.:	491	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: To structural columns				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail
