

Report No.: J102749
Nature of Work: Demolition Survey
Issue Date: 02/11/2018
Client Name: WYG Engineering Ltd
 Geneva Building, Lake View Drive, Sherwood Business Park,
 Annesley, Nottingham, NG15 0ED
Site Address: Attwood Building, Former City North Campus, Birmingham City
 University, Perry Barr, B42 2US



Order Placed By: Reg 13(1)
Site Contact: Reg 13(1)
Date(s) of Work: 24/08/2018 to 09/10/2018
Technical Manager: Reg 13(1) Reg 13(1)
Assistant Surveyor(s): Reg 13(1)

Lead Surveyor:

Reg 13(1) Reg 13(1) Reg 13(1) Reg 13(1)
 Reg 13(1) Reg 13(1) Reg 13(1) Reg 13(1)
 Reg 13(1) Reg 13(1) Reg 13(1) Reg 13(1)
 Reg 13(1) Reg 13(1) Reg 13(1) Reg 13(1)

Reg 13(1)
 Asbestos Consultant

Authorised Signatory:

Reg 13(1) Reg 13(1) Reg 13(1) Reg 13(1)
 Reg 13(1) Reg 13(1) Reg 13(1) Reg 13(1)
 Reg 13(1) Reg 13(1) Reg 13(1) Reg 13(1)
 Reg 13(1) Reg 13(1) Reg 13(1) Reg 13(1)
 Reg 13(1) Reg 13(1) Reg 13(1) Reg 13(1)

Reg 13(1)
 Deputy Technical manager

2 Nov 2018

*Non-accredited tests are present within this report.

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



Contents

1.0 Introduction & Scope of Work

- 1.1 Aims & Objectives
- 1.2 Caveats, Restrictions & Inaccessible Areas
- 1.3 Pre-agreed Caveats
- 1.4 Surveyor Imposed Caveats
- 1.5 UKAS Accreditation
- 1.6 'Licensable' Abatement
- 1.7 Extent of ACM Identified
- 1.8 Presumption or Identification of ACMs

2.0 Recommendations

3.0 Executive Summary

- 3.1 Asbestos Containing Materials (ACMs) ranked by Risk
- 3.2 Non-Asbestos Materials

4.0 Item Register & Management Report

5.0 Annotated Building Plans

6.0 Room Description Report

7.0 Room Access Report

8.0 Bulk Analysis Results

9.0 Intrusion Photographs

10.0 Risk Assessment Algorithms

- 10.1 Material Assessment
- 10.2 Likelihood of Disturbance Assessment
- 10.3 Overall Risk Category

1.0 Introduction & Scope of Work

A demolition survey in line with HSG264 Asbestos: The Survey Guide was carried out internally and externally to the property.

1.1 Aims & Objectives

The purpose of the survey was to locate, as far as reasonably practicable, the presence and extent of all suspect ACMs prior to demolition.

This survey was conducted for the specific project(s) stated above. Additional or alternative tasks over and above that mentioned will require a supplementary investigation to identify further ACMs that could potentially be disturbed by the task(s) at hand.

1.2 Caveats, Restrictions & Inaccessible Areas

The value and usefulness of a survey can be seriously undermined where either the client or the surveyor imposes restrictions on the survey scope (HSG264).

If any rooms were not accessed during the inspection, they will be indicated on the building plans (in yellow block) in section 5.

Where a room was accessed but specific elements within the room could not be inspected, caveats and their justification will be detailed in section 7.

It is strongly recommended that the client reviews the (general) caveats noted in sections 1.3 and/or 1.4 below, as well as the (room-specific) caveats cited in sections 5 and 7 as soon as possible upon receipt of the report. If the extent of access is less than required, the client should advise the Technical Management Team to arrange additional inspection work as necessary.

1.3 Pre-agreed Caveats:

No safe access was available internally to items of electrically connected plant and equipment. The presence of ACMs internally to such items may therefore have been presumed at the surveyor's discretion.

No access was required beyond ACMs (i.e. into voids or cavities etc) where the services of a licensed asbestos removal contractor would be required to provide safe access.

All land associated with the building such as surrounding grassed verges etc. are not included within the scope of these works and therefore remain unsurveyed.

All incoming services to the building were only investigated above ground level once they had entered the building therefore all sub ground water, gas and electric connections remain un-surveyed.

All outgoing services such as drainage routes were not included within the scope of these works and therefore remain un-surveyed.

All lift shafts will not be accessed as agreed with the client during the pre start period. therefore they will remain unsurveyed at this time

Please note that, although a thorough and methodical survey strategy was adopted, it is possible that further ACMs may be present, and are unreported in this survey. HSG264 Asbestos: the survey guide states that "It is now recognised that even with 'complete' access demolition surveys, all ACMs may not be identified and this only becomes apparent during demolition itself."

1.4 Surveyor Imposed Caveats:

Please note that there were no surveyor imposed caveats noted at the time of the survey.

1.5 UKAS Accreditation

Bradley Environmental are accredited by UKAS to both ISO17025 (testing) and ISO17020 (inspections). Please note that the following are outside the scope of UKAS Accreditation:

- Opinions & interpretations;
- Likelihood of disturbance risk assessment;
- Recommendations;
- The sample references cited in section 8.0.

1.6 'Licensable' Abatement

Where an asbestos-containing material is stated as being licensable within section 4 of this report, this is merely a qualified opinion and may not in practice be an absolute fact.

1.7 Extent of ACM Identified

Please note that the extents cited within this report are an approximation only and should not be used for the purposes of quoting asbestos removal works.

1.8 Presumption or Identification of ACMs

Where suspect materials have been located during this investigation, their asbestos content (or otherwise) will have been determined as follows:

A sample of the material will have been taken by the surveyor during the survey. This sample will then have been **analysed using polarised light microscopy** (PLM) to determine its asbestos content.

A material's asbestos content will have been **strongly presumed** where a visual inspection by the lead surveyor indicates the material is visually similar to other items present within the building which have been confirmed to contain asbestos (or otherwise) using PLM.

A material's asbestos content will have been **presumed** where it cannot be accessed or inspected.

2.0 Recommendations

Please note that where a management survey was carried out, individual recommendations related to safe management of each ACM has been cited by the surveyor in section 4.0.

Where a refurbishment or demolition survey was carried out, the recommendation for each item has been defaulted to 'program removal' in line with Regulation 7 of CAR2012.

N/A

Report No.: J102749
Issue Date: 02/11/2018



3.0 Executive Summary

As required by HSG264 Asbestos: The survey guide, the following sections contain an executive summary of the survey findings.

3.1 Executive Summary of Asbestos Containing Materials (ACMs) by Risk

The following pages show an executive summary of the ACMs located during these works ranked in order of risk (i.e. the highest risk item will be at the top of the page).

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002231	1st Floor	Birmingham City University	NAT134 Service Duct	Asbestos Textile joint seal to metal ducting	Chrysotile	Analysis of sample using PLM	2 linear metres	C10	Program removal
No sample - presumed	1st Floor	Birmingham City University	NAT106A	Asbestos Insulation lining to safe	Crocidolite	Presumed	1 unit	C10	Program removal
DU002246	1st Floor	Birmingham City University	NAT114	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	95 m ²	C9	Program removal
DU002248	1st Floor	Birmingham City University	NAT114A	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	60 m ²	C9	Program removal
DU002196	2nd Floor	Birmingham City University	NAT213A	Asbestos Vinyl	Chrysotile	Analysis of sample using PLM	20 m ²	C9	Program removal
DU002201	2nd Floor	Birmingham City University	NAT223A	Asbestos Textile seal to metal ducting joints	Chrysotile	Analysis of sample using PLM	2 linear metres	C9	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002196	2nd Floor	Birmingham City University	NAT225	Asbestos Vinyl	Chrysotile	Strongly presumed	18 m ²	C9	Program removal
DU002220	2nd Floor	Birmingham City University	NAT299 Corridor	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	100 m ²	C9	Program removal
DU002607	Ground Floor	Birmingham City University	NAT042	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	72 m ²	C9	Program removal
No sample - presumed	Ground Floor	Birmingham City University	NAT007	Asbestos Textile fuse tapes	Chrysotile	Presumed	2 units	C9	Program removal
DU002224	1st Floor	Birmingham City University	NAT101A	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	12 m ²	C8	Program removal
As DU002224	1st Floor	Birmingham City University	NAT101	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002224	1st Floor	Birmingham City University	NAT102	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
As DU002224	1st Floor	Birmingham City University	NAT103	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C8	Program removal
DU002230	1st Floor	Birmingham City University	NAT134 Service Duct	Asbestos Cement flue	Chrysotile	Analysis of sample using PLM	1 linear metres	C8	Program removal
DU002240	1st Floor	Birmingham City University	NAT121	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	14 m ²	C8	Program removal
DU002242	1st Floor	Birmingham City University	NAT111	Asbestos Vinyl tiles with bitumen adhesive to concrete	Chrysotile	Analysis of sample using PLM	8 m ²	C8	Program removal
DU002251	1st Floor	Birmingham City University	NAT199A	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	32 linear metres	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002197	2nd Floor	Birmingham City University	NAT203	Asbestos Vinyl floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	64 m ²	C8	Program removal
DU002200	2nd Floor	Birmingham City University	NAT223A	Asbestos Cement flue pipe	Chrysotile	Analysis of sample using PLM	1 linear metres	C8	Program removal
As DU002199	2nd Floor	Birmingham City University	NAT222	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	84 m ²	C8	Program removal
As DU002204	2nd Floor	Birmingham City University	NAT219	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	84 m ²	C8	Program removal
As DU002197	2nd Floor	Birmingham City University	NAT209	Asbestos Vinyl floor tiles with bitumen adhesive	Chrysotile	Strongly presumed	45 m ²	C8	Program removal
DU002213	2nd Floor	Birmingham City University	NAT207A	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	18 m ²	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002215	2nd Floor	Birmingham City University	NAT213	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	72 m ²	C8	Program removal
As DU002215	2nd Floor	Birmingham City University	NAT212	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	50 m ²	C8	Program removal
DU002217	2nd Floor	Birmingham City University	NAT211A	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	72 m ²	C8	Program removal
DU002218	2nd Floor	Birmingham City University	NAT210B	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	50 m ²	C8	Program removal
DU002221	2nd Floor	Birmingham City University	NAT299 Corridor	Asbestos Reinforced plastic downpipes	Chrysotile	Analysis of sample using PLM	36 linear metres	C8	Program removal
DU002610	Ground Floor	Birmingham City University	NAT036	Asbestos Compressed fibre gasket	Chrysotile	Analysis of sample using PLM	6 units	C8	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002627	Ground Floor	Birmingham City University	NAT023	Asbestos Reinforced plastic downpipes	Chrysotile	Analysis of sample using PLM	12 linear metres	C8	Program removal
As DU002627	Ground Floor	Birmingham City University	NAT099K	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	12 linear metres	C8	Program removal
As DU002627	Ground Floor	Birmingham City University	NAT099D	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	16 linear metres	C8	Program removal
DU002223	1st Floor	Birmingham City University	NAT101A	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	1 unit	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT101	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT102	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002223	1st Floor	Birmingham City University	NAT103	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT104A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT104B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT138	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
DU002226	1st Floor	Birmingham City University	NAT138	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	18 m ²	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT105D	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002223	1st Floor	Birmingham City University	NAT105	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002226	1st Floor	Birmingham City University	NAT105	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	20 m ²	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT105B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT105A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT137	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
DU002227	1st Floor	Birmingham City University	NAT137	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile	Analysis of sample using PLM	21 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002223	1st Floor	Birmingham City University	NAT136	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
DU002229	1st Floor	Birmingham City University	NAT136	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	21 m ²	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT135	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002229	1st Floor	Birmingham City University	NAT135	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT134B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002229	1st Floor	Birmingham City University	NAT134B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002223	1st Floor	Birmingham City University	NAT134A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002229	1st Floor	Birmingham City University	NAT134A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal
As DU002223	1st Floor	Birmingham City University	NAT106	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
DU002232	1st Floor	Birmingham City University	NAT106A	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	10 units	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT107A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
DU002233	1st Floor	Birmingham City University	NAT107	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	20 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002232	1st Floor	Birmingham City University	NAT107	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal
As DU002233	1st Floor	Birmingham City University	NAT107B	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	16 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT107B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002233	1st Floor	Birmingham City University	NAT105C	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	22 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT105C	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002229	1st Floor	Birmingham City University	NAT133	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002229	1st Floor	Birmingham City University	NAT132	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT132	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002229	1st Floor	Birmingham City University	NAT131	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal
As DU002229	1st Floor	Birmingham City University	NAT130	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT130	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
DU002234	1st Floor	Birmingham City University	NAT129	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	14 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002235	1st Floor	Birmingham City University	NAT128	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	14 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT128	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002235	1st Floor	Birmingham City University	NAT127B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT127B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
As DU002235	1st Floor	Birmingham City University	NAT127A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT127A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002232	1st Floor	Birmingham City University	NAT199D	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT110B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002237	1st Floor	Birmingham City University	NAT112	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	45 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT112	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
As DU002237	1st Floor	Birmingham City University	NAT126	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	14 m ²	C7	Program removal
DU002238	1st Floor	Birmingham City University	NAT125	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	21 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002232	1st Floor	Birmingham City University	NAT125	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002237	1st Floor	Birmingham City University	NAT110A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT110A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002238	1st Floor	Birmingham City University	NAT137	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	21 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT137	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
DU002239	1st Floor	Birmingham City University	NAT123	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	21 m ²	C7	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Attwood Building, Perry Barr

Report Number: J102749

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002232	1st Floor	Birmingham City University	NAT123	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002238	1st Floor	Birmingham City University	NAT110	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	45 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT110	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
As DU002238	1st Floor	Birmingham City University	NAT122	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	21 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT122	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT121	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002238	1st Floor	Birmingham City University	NAT111	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	45 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT111	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
As DU002238	1st Floor	Birmingham City University	NAT113A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	32 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT113A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
DU002244	1st Floor	Birmingham City University	NAT113B	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	25 m ²	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT113B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	7 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002232	1st Floor	Birmingham City University	NAT113H	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT116B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT116A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
As DU002232	1st Floor	Birmingham City University	NAT115A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
DU002245	1st Floor	Birmingham City University	NAT115	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	4 units	C7	Program removal
As DU002245	1st Floor	Birmingham City University	NAT114	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002245	1st Floor	Birmingham City University	NAT116	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
DU002247	1st Floor	Birmingham City University	NAT116	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	4 linear metres	C7	Program removal
As DU002245	1st Floor	Birmingham City University	NAT114A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002245	1st Floor	Birmingham City University	NAT113G	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002247	1st Floor	Birmingham City University	NAT113G	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
DU002249	1st Floor	Birmingham City University	NAT113G	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	6 m ²	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002245	1st Floor	Birmingham City University	NAT113F	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002249	1st Floor	Birmingham City University	NAT113F	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	10 m ²	C7	Program removal
As DU002245	1st Floor	Birmingham City University	NAT113E	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
As DU002249	1st Floor	Birmingham City University	NAT113E	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	8 m ²	C7	Program removal
As DU002245	1st Floor	Birmingham City University	NAT113D	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002249	1st Floor	Birmingham City University	NAT113D	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	6 m ²	C7	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Attwood Building, Perry Barr

Report Number: J102749

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002245	1st Floor	Birmingham City University	NAT113C	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002249	1st Floor	Birmingham City University	NAT113C	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	4 m ²	C7	Program removal
As DU002249	1st Floor	Birmingham City University	NAT199H	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	5 m ²	C7	Program removal
As DU002247	1st Floor	Birmingham City University	NAT199H	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
As DU002245	1st Floor	Birmingham City University	NAT199H	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	C7	Program removal
As DU002245	1st Floor	Birmingham City University	NAT199A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	16 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002250	1st Floor	Birmingham City University	NAT199A	Asbestos Textile rope seal to metal ducting	Chrysotile	Analysis of sample using PLM	4 linear metres	C7	Program removal
As DU002250	1st Floor	Birmingham City University	NAT199A	Asbestos Textile rope seal to metal ducting	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
DU002191	2nd Floor	Birmingham City University	NAT201	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	9 units	C7	Program removal
As DU002191	2nd Floor	Birmingham City University	NAT202	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	7 units	C7	Program removal
DU002194	2nd Floor	Birmingham City University	NAT202	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	50 m ²	C7	Program removal
As DU002191	2nd Floor	Birmingham City University	NAT202A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002191	2nd Floor	Birmingham City University	NAT203	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal
As DU002191	2nd Floor	Birmingham City University	NAT224	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal
As DU002191	2nd Floor	Birmingham City University	NAT203A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal
DU002199	2nd Floor	Birmingham City University	NAT203A	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	25 m ²	C7	Program removal
As DU002199	2nd Floor	Birmingham City University	NAT221	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	20 m ²	C7	Program removal
As DU002191	2nd Floor	Birmingham City University	NAT204	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002202	2nd Floor	Birmingham City University	NAT204	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	84 m ²	C7	Program removal
As DU002191	2nd Floor	Birmingham City University	NAT210A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	C7	Program removal
As DU002191	2nd Floor	Birmingham City University	NAT206	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
DU002204	2nd Floor	Birmingham City University	NAT220	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	18 m ²	C7	Program removal
As DU002191	2nd Floor	Birmingham City University	NAT216	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	C7	Program removal
As DU002191	2nd Floor	Birmingham City University	NAT207	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002206	2nd Floor	Birmingham City University	NAT208	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	12 units	C7	Program removal
DU002207	2nd Floor	Birmingham City University	NAT208	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	60 m ²	C7	Program removal
As DU002206	2nd Floor	Birmingham City University	NAT217	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	9 units	C7	Program removal
As DU002206	2nd Floor	Birmingham City University	NAT208A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
As DU002206	2nd Floor	Birmingham City University	NAT209	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
As DU002206	2nd Floor	Birmingham City University	NAT207A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002204	2nd Floor	Birmingham City University	NAT205A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	C7	Program removal
As DU002204	2nd Floor	Birmingham City University	NAT205	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	20 m ²	C7	Program removal
DU002214	2nd Floor	Birmingham City University	NAT205	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Analysis of sample using PLM	3 units	C7	Program removal
As DU002214	2nd Floor	Birmingham City University	NAT213	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	12 units	C7	Program removal
As DU002214	2nd Floor	Birmingham City University	NAT212	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
As DU002214	2nd Floor	Birmingham City University	NAT211B	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	4 units	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002197	2nd Floor	Birmingham City University	NAT211B	Asbestos Vinyl floor tiles	Chrysotile	Strongly presumed	16 m ²	C7	Program removal
As DU002214	2nd Floor	Birmingham City University	NAT211A	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
As DU002214	2nd Floor	Birmingham City University	NAT210B	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Strongly presumed	8 units	C7	Program removal
DU002219	2nd Floor	Birmingham City University	NAT210B	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	4 linear metres	C7	Program removal
As DU002214	2nd Floor	Birmingham City University	NAT299 Corridor	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	25 units	C7	Program removal
DU002616	Ground Floor	Birmingham City University	NAT009	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	4 linear metres	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002605	Ground Floor	Birmingham City University	NAT012A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	C7	Program removal
DU002624	Ground Floor	Birmingham City University	NAT025B	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	3 linear metres	C7	Program removal
As DU002624	Ground Floor	Birmingham City University	NAT014	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
As DU002624	Ground Floor	Birmingham City University	NAT017	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
As DU002627	Ground Floor	Birmingham City University	NAT019A	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal
As DU002627	Ground Floor	Birmingham City University	NAT099J	Asbestos Reinforced plastic downpipe	Chrysotile	Strongly presumed	4 linear metres	C7	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002222	1st Floor	Birmingham City University	NAT199B	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	4 linear metres	D6	Program removal
As DU002226	1st Floor	Birmingham City University	NAT105B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	4 m ²	D6	Program removal
As DU002226	1st Floor	Birmingham City University	NAT105A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	8 m ²	D6	Program removal
As DU002229	1st Floor	Birmingham City University	NAT106C	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	6 m ²	D6	Program removal
As DU002229	1st Floor	Birmingham City University	NAT107A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	6 m ²	D6	Program removal
DU002236	1st Floor	Birmingham City University	NAT199D	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	10 m ²	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002237	1st Floor	Birmingham City University	NAT110B	Asbestos Bitumen adhesive	Chrysotile	Analysis of sample using PLM	10 m ²	D6	Program removal
As DU002237	1st Floor	Birmingham City University	NAT108A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	8 m ²	D6	Program removal
As DU002237	1st Floor	Birmingham City University	NAT108B	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	10 m ²	D6	Program removal
As DU002244	1st Floor	Birmingham City University	NAT113H	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	8 m ²	D6	Program removal
DU002190	2nd Floor	Birmingham City University	NAT200	Asbestos Reinforced plastic soil pipe	Chrysotile	Analysis of sample using PLM	4 linear metres	D6	Program removal
As DU002199	2nd Floor	Birmingham City University	NAT210A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	18 m ²	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002199	2nd Floor	Birmingham City University	NAT206	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	12 m ²	D6	Program removal
As DU002199	2nd Floor	Birmingham City University	NAT216	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	18 m ²	D6	Program removal
As DU002199	2nd Floor	Birmingham City University	NAT207	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	40 m ²	D6	Program removal
As DU002207	2nd Floor	Birmingham City University	NAT208A	Asbestos Bitumen adhesive	Chrysotile	Strongly presumed	16 m ²	D6	Program removal
DU002605	Ground Floor	Birmingham City University	NAT040A	Asbestos Reinforced plastic sleeve	Chrysotile	Analysis of sample using PLM	2 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT045	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002605	Ground Floor	Birmingham City University	NAT042	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT040	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT039	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT043	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT043A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT036	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002609	Ground Floor	Birmingham City University	NAT036	Asbestos Reinforced plastic downpipe	Chrysotile	Analysis of sample using PLM	4 linear metres	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT044	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT033	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT002	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT00B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT007	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002605	Ground Floor	Birmingham City University	NAT006	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT032	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	5 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT032A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT009	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	10 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT031A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT031D	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002605	Ground Floor	Birmingham City University	NAT031	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT030	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	5 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT029	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT010	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT012	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal
DU002623	Ground Floor	Birmingham City University	NAT012E	Asbestos Thermoplastic floor tiles	Chrysotile	Analysis of sample using PLM	10 m ²	D6	Program removal

**Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk**

Attwood Building, Perry Barr

Report Number: J102749

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002605	Ground Floor	Birmingham City University	NAT027A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT028B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT028	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT027	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT026	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT025A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002605	Ground Floor	Birmingham City University	NAT025	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT025B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT014	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT014B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT014D	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT015	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002605	Ground Floor	Birmingham City University	NAT016	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT024A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT024	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT023	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	16 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT022	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT021A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	1 unit	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002605	Ground Floor	Birmingham City University	NAT021B	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT020	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT019A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT016A	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	4 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT099H	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT019	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002605	Ground Floor	Birmingham City University	NAT099J	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	2 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT099K	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	18 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT099L	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	3 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT099D	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	8 units	D6	Program removal
As DU002605	Ground Floor	Birmingham City University	NAT099C	Asbestos Reinforced plastic sleeve	Chrysotile	Strongly presumed	6 units	D6	Program removal
As DU002194	2nd Floor	Birmingham City University	NAT202A	Asbestos Thermoplastic floor tiles	Chrysotile	Strongly presumed	6 m ²	D5	Program removal

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002632	E - External	Birmingham City University	NAT EXT	Asbestos Cement cowl	Chrysotile	Analysis of sample using PLM	1 unit	D5	Program removal

3.2 Executive Summary of Non-Asbestos Material

The following pages show a summary of non-asbestos materials located during these works.

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002192	2nd Floor	Birmingham City University	NAT201	Bitumen adhesive	No Asbestos Detected	Analysis of sample using PLM	72 m ²	E0	Not applicable
DU002193	2nd Floor	Birmingham City University	NAT299E	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
DU002195	2nd Floor	Birmingham City University	NAT213A	Textured coating to blockwork	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable
As DU002192	2nd Floor	Birmingham City University	NAT224	Bitumen adhesive	No Asbestos Detected	Strongly presumed	70 m ²	E0	Not applicable
DU002198	2nd Floor	Birmingham City University	NAT203A	Insulating board upstand	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
DU002203	2nd Floor	Birmingham City University	NAT204	Bitumen sink pads	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002205	2nd Floor	Birmingham City University	NAT220	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	1 m ²	E0	Not applicable
DU002208	2nd Floor	Birmingham City University	NAT217	Vinyl	No Asbestos Detected	Analysis of sample using PLM	16 m ²	E0	Not applicable
DU002209	2nd Floor	Birmingham City University	NAT225	Textured coating to blockwork	No Asbestos Detected	Analysis of sample using PLM	40 m ²	E0	Not applicable
DU002210	2nd Floor	Birmingham City University	NAT299A	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	8 m ²	E0	Not applicable
DU002211	2nd Floor	Birmingham City University	NAT209	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	2 units	E0	Not applicable
DU002212	2nd Floor	Birmingham City University	NAT299A	Textured coating to door wall	No Asbestos Detected	Analysis of sample using PLM	12 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002216	2nd Floor	Birmingham City University	NAT213	Bitumen sink pads	No Asbestos Detected	Analysis of sample using PLM	6 units	E0	Not applicable
As DU002216	2nd Floor	Birmingham City University	NAT212	Bitumen sink pads	No Asbestos Detected	Strongly presumed	6 units	E0	Not applicable
As DU002216	2nd Floor	Birmingham City University	NAT211B	Bitumen sink pads	No Asbestos Detected	Strongly presumed	2 units	E0	Not applicable
DU002225	1st Floor	Birmingham City University	NAT104B	Bitumen adhesive to parquet	No Asbestos Detected	Analysis of sample using PLM	25 m ²	E0	Not applicable
DU002241	1st Floor	Birmingham City University	NAT121	Textured coating to blockwork	No Asbestos Detected	Analysis of sample using PLM	20 m ²	E0	Not applicable
DU002243	1st Floor	Birmingham City University	NAT118B	Textured coating	No Asbestos Detected	Analysis of sample using PLM	12 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002603	Ground Floor	Birmingham City University	NAT041B	Insulating board ceiling tiles	No Asbestos Detected	Analysis of sample using PLM	6 m ²	E0	Not applicable
As DU002603	Ground Floor	Birmingham City University	NAT041A	Insulating board ceiling tiles	No Asbestos Detected	Strongly presumed	18 m ²	E0	Not applicable
DU002604	Ground Floor	Birmingham City University	NAT041C	Insulating board ceiling tiles	No Asbestos Detected	Analysis of sample using PLM	112 m ²	E0	Not applicable
DU002606	Ground Floor	Birmingham City University	NAT047	Insulating board ceiling tiles	No Asbestos Detected	Analysis of sample using PLM	18 m ²	E0	Not applicable
As DU002606	Ground Floor	Birmingham City University	NAT047A	Insulating board ceiling tiles	No Asbestos Detected	Strongly presumed	6 m ²	E0	Not applicable
DU002608	Ground Floor	Birmingham City University	NAT036	Textured coating to plaster to block wall	No Asbestos Detected	Analysis of sample using PLM	16 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002611	Ground Floor	Birmingham City University	NATG00A	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
DU002612	Ground Floor	Birmingham City University	NAT044	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable
DU002613	Ground Floor	Birmingham City University	NAT044	Bitumen adhesive	No Asbestos Detected	Analysis of sample using PLM	80 m ²	E0	Not applicable
DU002614	Ground Floor	Birmingham City University	NAT002	Textured coating to concrete	No Asbestos Detected	Analysis of sample using PLM	3 linear metres	E0	Not applicable
DU002615	Ground Floor	Birmingham City University	NAT00B	Modern vinyl to bitumen adhesive	No Asbestos Detected	Analysis of sample using PLM	16 m ²	E0	Not applicable
DU002617	Ground Floor	Birmingham City University	NAT009	Textured coating to concrete pillar	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002618	Ground Floor	Birmingham City University	NAT009	Bitumen adhesive	No Asbestos Detected	Analysis of sample using PLM	160 m ²	E0	Not applicable
As DU002617	Ground Floor	Birmingham City University	NAT009C	Textured coating to concrete pillar	No Asbestos Detected	Strongly presumed	4 m ²	E0	Not applicable
As DU002618	Ground Floor	Birmingham City University	NAT009C	Bitumen adhesive	No Asbestos Detected	Strongly presumed	28 m ²	E0	Not applicable
As DU002618	Ground Floor	Birmingham City University	NAT009B	Bitumen adhesive	No Asbestos Detected	Strongly presumed	12 m ²	E0	Not applicable
As DU002618	Ground Floor	Birmingham City University	NAT009A	Bitumen adhesive	No Asbestos Detected	Strongly presumed	6 m ²	E0	Not applicable
DU002619	Ground Floor	Birmingham City University	NAT029	Bitumen adhesive	No Asbestos Detected	Analysis of sample using PLM	48 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002621	Ground Floor	Birmingham City University	NAT010	Bitumen adhesive	No Asbestos Detected	Analysis of sample using PLM	84 m ²	E0	Not applicable
DU002620	Ground Floor	Birmingham City University	NAT010	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	5 units	E0	Not applicable
As DU002621	Ground Floor	Birmingham City University	NAT010A	Bitumen adhesive	No Asbestos Detected	Strongly presumed	15 m ²	E0	Not applicable
DU002622	Ground Floor	Birmingham City University	NAT012	Bitumen sink pad	No Asbestos Detected	Analysis of sample using PLM	5 units	E0	Not applicable
As DU002622	Ground Floor	Birmingham City University	NAT012B	Bitumen sink pad	No Asbestos Detected	Strongly presumed	2 units	E0	Not applicable
As DU002621	Ground Floor	Birmingham City University	NAT012A	Bitumen adhesive	No Asbestos Detected	Strongly presumed	12 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
As DU002613	Ground Floor	Birmingham City University	NAT027	Bitumen adhesive	No Asbestos Detected	Strongly presumed	16 m ²	E0	Not applicable
As DU002613	Ground Floor	Birmingham City University	NAT026A	Bitumen adhesive	No Asbestos Detected	Strongly presumed	6 m ²	E0	Not applicable
As DU002613	Ground Floor	Birmingham City University	NAT026	Bitumen adhesive	No Asbestos Detected	Strongly presumed	8 m ²	E0	Not applicable
As DU002613	Ground Floor	Birmingham City University	NAT025A	Bitumen adhesive	No Asbestos Detected	Strongly presumed	12 m ²	E0	Not applicable
As DU002613	Ground Floor	Birmingham City University	NAT025	Bitumen adhesive	No Asbestos Detected	Strongly presumed	25 m ²	E0	Not applicable
DU002625	Ground Floor	Birmingham City University	NAT015	Bitumen adhesive	No Asbestos Detected	Analysis of sample using PLM	8 m ²	E0	Not applicable


Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002626	Ground Floor	Birmingham City University	NAT016	Thermoplastic floor tiles	No Asbestos Detected	Analysis of sample using PLM	18 m ²	E0	Not applicable
DU002628	Ground Floor	Birmingham City University	NAT099K	Thermoplastic floor tiles	No Asbestos Detected	Analysis of sample using PLM	18 m ²	E0	Not applicable
As DU002613	Ground Floor	Birmingham City University	NAT099L	Bitumen adhesive	No Asbestos Detected	Strongly presumed	18 m ²	E0	Not applicable
As DU002628	Ground Floor	Birmingham City University	NAT099D	Thermoplastic floor tiles	No Asbestos Detected	Strongly presumed	38 m ²	E0	Not applicable
DU002629	Ground Floor	Birmingham City University	NAT099D	Insulating board upstand and ceiling	No Asbestos Detected	Analysis of sample using PLM	4 m ²	E0	Not applicable
DU002630	E - External	Birmingham City University	NAT EXT	Insulating board door header	No Asbestos Detected	Analysis of sample using PLM	2 m ²	E0	Not applicable

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
DU002631	Ground Floor	Birmingham City University	NAT002A	Insulating board ceiling panels	No Asbestos Detected	Analysis of sample using PLM	6 m ²	E0	Not applicable

4.0 Item Register & Management Report


The following pages show a register of all suspect materials located during this investigation, which includes a photographic record of each item along with individual risk assessment scores.

The section entitled 'Portal Ref No' relates to a corresponding number assigned to each sample for the purpose of identification within the TEAMS online Portal.

Location:	NAT200	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002190	Portal Ref No.:	1	
Item:	Asbestos Reinforced plastic soil pipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	4 linear metres	
Comments: Within riser				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT201	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002191	Portal Ref No.:	3	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Chrysotile			
Result Based on:	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	9 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT201	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002192	Portal Ref No.:	4	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	72 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT299E	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002193	Portal Ref No.:	5	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments: To link corridor to Baker building, including debris panel				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT202	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002191	Portal Ref No.:	6	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	7 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT202	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002194	Portal Ref No.:	7	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT202A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002191	Portal Ref No.:	8	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT202A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002194	Portal Ref No.:	9	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D5
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT213A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002195	Portal Ref No.:	12	
Item:	Textured coating to blockwork			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments: To one half of the room, behind plaster to one side exposed on the other				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT213A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002196	Portal Ref No.:	13	
Item:	Asbestos Vinyl			
Asbestos Content:	Result Based on:			
Chrysotile in bitumen adhesive only		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 7		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos vinyl)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	3 (Routinely disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT203	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002191	Portal Ref No.:	15	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT203	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002197	Portal Ref No.:	16	
Item:	Asbestos Vinyl floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in bitumen adhesive only		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	64 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos vinyl)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT224	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002191	Portal Ref No.:	17	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT224	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002192	Portal Ref No.:	18	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	70 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT203A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002191	Portal Ref No.:	19	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT203A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002199	Portal Ref No.:	20	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT203A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002198	Portal Ref No.:	21	
Item:	Insulating board upstand			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Within ceiling void above partition walls				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT223A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002200	Portal Ref No.:	24	
Item:	Asbestos Cement flue pipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 linear metres		
Comments: Embedded within concrete floor				


Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT223A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002201	Portal Ref No.:	25	
Item:	Asbestos Textile seal to metal ducting joints			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 linear metres		
Comments: To bolted joint section only				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	2 (Asbestos textile)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Enclosed textile/paper)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT222	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002199	Portal Ref No.:	27	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	84 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT221	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002199	Portal Ref No.:	29	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT204	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002191	Portal Ref No.:	30	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT204	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002202	Portal Ref No.:	31	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Chrysotile in tile and adhesive			
Result Based on:	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	84 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT204	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002203	Portal Ref No.:	32	
Item:	Bitumen sink pads			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments: Sink and drainer				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT210A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002191	Portal Ref No.:	33	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT210A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002199	Portal Ref No.:	34	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT206	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002191	Portal Ref No.:	35	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:			Result Based on:	
Chrysotile			Strongly presumed	
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT206	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002199	Portal Ref No.:	36	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT220	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002204	Portal Ref No.:	37	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	18 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT220	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002205	Portal Ref No.:	39	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	1 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT219	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002204	Portal Ref No.:	40	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	84 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT216	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002191	Portal Ref No.:	41	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT216	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002199	Portal Ref No.:	42	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT207	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002191	Portal Ref No.:	43	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT207	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002199	Portal Ref No.:	44	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	40 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT208	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002206	Portal Ref No.:	45	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	12 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT208	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002207	Portal Ref No.:	46	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	60 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT217	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002206	Portal Ref No.:	47	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	9 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT217	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002208	Portal Ref No.:	48	
Item:	Vinyl			
Asbestos Content:		Result Based on:		
No Asbestos Detected in vinyl or adhesive		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	16 m ²	
Comments: To bottom section of room				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT225	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002209	Portal Ref No.:	49	
Item:	Textured coating to blockwork			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	40 m ²	
Comments: To both sides of room				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT225	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002196	Portal Ref No.:	50	
Item:	Asbestos Vinyl			
Asbestos Content:	Result Based on:			
Chrysotile in bitumen adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 7		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos vinyl)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	3 (Routinely disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT208A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002206	Portal Ref No.:	51	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT208A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002207	Portal Ref No.:	52	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT299A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002210	Portal Ref No.:	53	
Item:	Textured coating to concrete			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	8 m ²		
Comments: To timber wall of built in cupboard				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT209	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002206	Portal Ref No.:	54	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT209	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002197	Portal Ref No.:	55	
Item:	Asbestos Vinyl floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in bitumen adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	45 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos vinyl)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT209	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002211	Portal Ref No.:	56	
Item:	Bitumen sink pad			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 units	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT299A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002212	Portal Ref No.:	57	
Item:	Textured coating to door wall			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	12 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT207A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002206	Portal Ref No.:	58	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT207A	Block:	Birmingham City University		Floor Level: 2nd Floor
Sample No.:	DU002213	Portal Ref No.:	59		
Item:	Asbestos Bitumen adhesive				
Asbestos Content:	Result Based on:				
Chrysotile	Analysis of sample using PLM				
Sample Analysed By:	Reg 13(1)	Extent:	18 m ²		
Comments:					


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail


Location:	NAT205A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002204	Portal Ref No.:	60	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail


Location:	NAT205	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002204	Portal Ref No.:	61	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	
Management Detail				

Location:	NAT205	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002214	Portal Ref No.:	62	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	3 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT213	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002215	Portal Ref No.:	63	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	72 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT213	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002214	Portal Ref No.:	64	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:			Result Based on:	
Chrysotile			Strongly presumed	
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT213	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002216	Portal Ref No.:	65	
Item:	Bitumen sink pads			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 units	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT212	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002215	Portal Ref No.:	66	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	50 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT212	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002214	Portal Ref No.:	67	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void, this sleeve is sealed in				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT212	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002216	Portal Ref No.:	68	
Item:	Bitumen sink pads			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT211B	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002214	Portal Ref No.:	71	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:			Result Based on:	
Chrysotile			Strongly presumed	
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT211B	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002216	Portal Ref No.:	72	
Item:	Bitumen sink pads			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT211B	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002197	Portal Ref No.:	73	
Item:	Asbestos Vinyl floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in bitumen adhesive only	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos vinyl)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT211A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002217	Portal Ref No.:	74	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	72 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT211A	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002214	Portal Ref No.:	75	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:			Result Based on:	
Chrysotile			Strongly presumed	
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT210B	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002218	Portal Ref No.:	77	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Chrysotile			
Result Based on:	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	50 m ²	
Comments:				

Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT210B	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002214	Portal Ref No.:	78	
Item:	Asbestos Reinforced plastic pipe sleeve			
Asbestos Content:			Result Based on:	
Chrysotile			Strongly presumed	
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through structural concrete various points within ceiling void items run parallel generally throughout the ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT210B	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002219	Portal Ref No.:	79	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT299 Corridor	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	As DU002214	Portal Ref No.:	80	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	25 units	
Comments: Top section of corridor within ceiling void, then again throughout the corridor through the structural concrete				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT299 Corridor	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002220	Portal Ref No.:	81	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	100 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT299 Corridor	Block:	Birmingham City University	Floor Level: 2nd Floor
Sample No.:	DU002221	Portal Ref No.:	82	
Item:	Asbestos Reinforced plastic downpipes			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	36 linear metres		
Comments: 9 pipes within risers throughout this corridor see plan for location				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT199B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002222	Portal Ref No.:	90	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Chrysotile			
Result Based on:	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	4 linear metres	
Comments: Adjacent to link corridor doors				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT101A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002223	Portal Ref No.:	91	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 unit		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT101A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002224	Portal Ref No.:	92	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT101	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	93	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT101	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002224	Portal Ref No.:	94	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	
Management Detail				

Location:	NAT102	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	95	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT102	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002224	Portal Ref No.:	96	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT103	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	97	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT103	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002224	Portal Ref No.:	98	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT104A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	99	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT104B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	100	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT104B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002225	Portal Ref No.:	101	
Item:	Bitumen adhesive to parquet			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	25 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT138	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	104	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT138	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002226	Portal Ref No.:	105	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	18 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT105D	Block:	Birmingham City University		Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	106		
Item:	Asbestos Reinforced plastic sleeve				
Asbestos Content:	Result Based on:				
Chrysotile	Strongly presumed				
Sample Analysed By:	Not applicable	Extent:	2 units		
Comments:					

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT105	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	107	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT105	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002226	Portal Ref No.:	108	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	20 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT105B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	110	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT105B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002226	Portal Ref No.:	111	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT105A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	112	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT105A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002226	Portal Ref No.:	113	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT137	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	114	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT137	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002227	Portal Ref No.:	115	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	21 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT136	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	116	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT136	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002229	Portal Ref No.:	117	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	21 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT135	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	119	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT135	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002229	Portal Ref No.:	120	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT134B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	121	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT134B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002229	Portal Ref No.:	122	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT134A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	123	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT134A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002229	Portal Ref No.:	124	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT134 Service Duct	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002230	Portal Ref No.:	125	
Item:	Asbestos Cement flue			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	1 linear metres		
Comments: Foam sealed, continues through the floor slab				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos cement)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Enclosed asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT134 Service Duct	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002231	Portal Ref No.:	126	
Item:	Asbestos Textile joint seal to metal ducting			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 linear metres		
Comments: To both metal ductings				


Material Assessment Total Score: 6		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	2 (Asbestos textile)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	2 (Unencapsulated textile/paper)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT106	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002223	Portal Ref No.:	127	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT106A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002232	Portal Ref No.:	129	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	10 units		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT106A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	No sample - presumed	Portal Ref No.:	131	
Item:	Asbestos Insulation lining to safe			
Asbestos Content:	Result Based on:			
Crocidolite	Presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: No sample - presumed due to no physical access available				


Material Assessment Total Score: 7		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: Yes Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C10
Product Type:	3 (Asbestos Insulation/Coating)	Location:	2 (Rooms up to 100 sq m)	
Condition:	0 (Perfect)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	1 (Enclosed insulation)			
Asbestos Type:	3 (Crocidolite)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT106C	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002229	Portal Ref No.:	133	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT107A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002229	Portal Ref No.:	134	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT107A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	135	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT107	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002233	Portal Ref No.:	136	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	20 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT107	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	137	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT107B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002233	Portal Ref No.:	138	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT107B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	139	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT105C	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002233	Portal Ref No.:	140	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	22 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT105C	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	141	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT133	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002229	Portal Ref No.:	143	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments: Lifted elsewhere				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT132	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002229	Portal Ref No.:	144	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT132	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	145	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT131	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002229	Portal Ref No.:	146	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT130	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002229	Portal Ref No.:	147	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT130	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	148	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT129	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002234	Portal Ref No.:	149	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	14 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT128	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002235	Portal Ref No.:	150	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	14 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT128	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	151	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Also passes through the ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT127B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002235	Portal Ref No.:	153	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT127B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	154	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Passes through the ceiling				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT127A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002235	Portal Ref No.:	155	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT127A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	156	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Passes through the ceiling				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT199D	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002236	Portal Ref No.:	157	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	10 m ²		
Comments: Beneath carpet				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT199D	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	158	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Passes through the ceiling				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT110B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002237	Portal Ref No.:	159	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	10 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT110B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	160	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT108A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002237	Portal Ref No.:	161	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT108B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002237	Portal Ref No.:	162	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT112	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002237	Portal Ref No.:	163	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	45 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT112	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	164	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT126	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002237	Portal Ref No.:	165	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT125	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002238	Portal Ref No.:	166	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	21 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT125	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	167	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through ceiling also where rooms join				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT110A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002237	Portal Ref No.:	168	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT110A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	169	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through ceiling also where rooms join				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT137	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002238	Portal Ref No.:	170	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	21 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT137	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	171	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through ceiling also where rooms join				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT123	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002239	Portal Ref No.:	172	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	21 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT123	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	173	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT110	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002238	Portal Ref No.:	174	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	45 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT110	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	175	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT122	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002238	Portal Ref No.:	176	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	21 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT122	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	177	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT121	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002240	Portal Ref No.:	178	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	14 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT121	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002241	Portal Ref No.:	179	
Item:	Textured coating to blockwork			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	20 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT121	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	180	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT111	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002238	Portal Ref No.:	181	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	45 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT111	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	182	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT111	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002242	Portal Ref No.:	183	
Item:	Vinyl tiles with bitumen adhesive to concrete			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	8 m ²		
Comments: Kitchen area only				


Material Assessment Total Score: 2		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	0 (Bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	3 (Routinely disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT118B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002243	Portal Ref No.:	184	
Item:	Textured coating			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	12 m ²	
Comments: To walls of cleaners cupboard				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT113A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002238	Portal Ref No.:	185	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	32 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT113A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	186	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002244	Portal Ref No.:	187	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	25 m ²		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT113B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	188	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	7 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113H	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002244	Portal Ref No.:	189	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113H	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	190	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT116B	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	195	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT116A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	196	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT115A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002232	Portal Ref No.:	197	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT115	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002245	Portal Ref No.:	198	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 units		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT114	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002245	Portal Ref No.:	199	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT114	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002246	Portal Ref No.:	200	
Item:	Asbestos Bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	95 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos bitumen)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT116	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002245	Portal Ref No.:	201	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT116	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002247	Portal Ref No.:	202	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 linear metres		
Comments: Black pipe within timber boxing				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT114A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002245	Portal Ref No.:	203	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT114A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002248	Portal Ref No.:	204	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	60 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT113G	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002245	Portal Ref No.:	205	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113G	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002247	Portal Ref No.:	206	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments: Black pipe within timber boxing				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113G	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002249	Portal Ref No.:	207	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	6 m ²		
Comments: Beneath raised timber flooring				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113F	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002245	Portal Ref No.:	208	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113F	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002249	Portal Ref No.:	210	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 m ²	
Comments: Beneath raised timber flooring				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113E	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002245	Portal Ref No.:	211	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113E	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002249	Portal Ref No.:	212	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113D	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002245	Portal Ref No.:	214	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113D	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002249	Portal Ref No.:	215	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113C	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002245	Portal Ref No.:	216	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT113C	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002249	Portal Ref No.:	217	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT199H	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002249	Portal Ref No.:	218	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 m ²	
Comments: Corridor section outside room NAT113				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT199H	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002247	Portal Ref No.:	219	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments: Black pipe within timber boxing				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT199H	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002245	Portal Ref No.:	220	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT199A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002251	Portal Ref No.:	222	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	32 linear metres		
Comments: Black pipe within timber boxing to risers 8 in total				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT199A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002245	Portal Ref No.:	223	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: Estimated amount of sleeves				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT199A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	DU002250	Portal Ref No.:	224	
Item:	Asbestos Textile rope seal to metal ducting			
Asbestos Content:	Chrysotile			
Result Based on:	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	4 linear metres	
Comments: Within timber boxing				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 2		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	2 (Asbestos textile)	Location:	1 (Large rooms or well-ventilated areas)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	1 (Enclosed textile/paper)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT199A	Block:	Birmingham City University	Floor Level: 1st Floor
Sample No.:	As DU002250	Portal Ref No.:	225	
Item:	Asbestos Textile rope seal to metal ducting			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments: Within timber boxing / riser adjacent double doors				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 2		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	2 (Asbestos textile)	Location:	1 (Large rooms or well-ventilated areas)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	1 (Enclosed textile/paper)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT041B	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002603	Portal Ref No.:	226	
Item:	Insulating board ceiling tiles			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 m ²	
<p>Comments: No access could be made beyond the insulating board ceiling panels at the time of the survey therefore the presence of further reinforced plastic sleeves should be considered in this void. it is recommended that BECL re visit these areas prior to demolition to determine the possible location and extent of these materials.</p>				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		<p>Management Assessment</p> <p>Licensable: Yes</p> <p>Recommendations: Not Applicable</p> <p>Reinspection Interval: Not Applicable</p> <p>Overall Risk Category: E0</p>
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT041A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002603	Portal Ref No.:	227	
Item:	Insulating board ceiling tiles			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	18 m ²	
<p>Comments: No access could be made beyond the insulating board ceiling panels at the time of the survey therefore the presence of further reinforced plastic sleeves should be considered in this void. it is recommended that BECL re visit these areas prior to demolition to determine the possible location and extent of these materials.</p>				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		<p>Management Assessment</p> <p>Licensable: Yes</p> <p>Recommendations: Not Applicable</p> <p>Reinspection Interval: Not Applicable</p> <p>Overall Risk Category: E0</p>
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT041C	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002604	Portal Ref No.:	229	
Item:	Insulating board ceiling tiles			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	112 m ²	
<p>Comments: No access could be made beyond the insulating board ceiling panels at the time of the survey therefore the presence of further reinforced plastic sleeves should be considered in this void. it is recommended that BECL re visit these areas prior to demolition to determine the possible location and extent of these materials.</p>				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		<p>Management Assessment</p> <p>Licensable: Yes</p> <p>Recommendations: Not Applicable</p> <p>Reinspection Interval: Not Applicable</p> <p>Overall Risk Category: E0</p>
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT040A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002605	Portal Ref No.:	231	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	2 units		
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT047	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002606	Portal Ref No.:	232	
Item:	Insulating board ceiling tiles			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	18 m ²	
Comments: No access above AIB ceiling tiles without assistance of a licensed contractor				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT047A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002606	Portal Ref No.:	234	
Item:	Insulating board ceiling tiles			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	6 m ²	
<p>Comments: No access could be made beyond the insulating board ceiling panels at the time of the survey therefore the presence of further reinforced plastic sleeves should be considered in this void. it is recommended that BECL re visit these areas prior to demolition to determine the possible location and extent of these materials.</p>				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		<p>Management Assessment</p> <p>Licensable: Yes</p> <p>Recommendations: Not Applicable</p> <p>Reinspection Interval: Not Applicable</p> <p>Overall Risk Category: E0</p>
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT045	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	235	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT042	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	236	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT042	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002607	Portal Ref No.:	237	
Item:	Asbestos Thermoplastic floor tiles with bitumen adhesive			
Asbestos Content:	Result Based on:			
Chrysotile in adhesive only	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	72 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 6		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	3 (>50 sq m or >50m pipe run)	

Management Detail

Location:	NAT040	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	238	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT039	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	239	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT043	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	240	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT043A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	241	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT036	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	242	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT036	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002608	Portal Ref No.:	243	
Item:	Textured coating to plaster to block wall			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	16 m ²	
Comments: To one wall to stairwell				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT036	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002609	Portal Ref No.:	244	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 linear metres		
Comments: Internally to timber boxing				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT036	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002610	Portal Ref No.:	245	
Item:	Asbestos Compressed fibre gasket			
Asbestos Content:	Chrysotile			
Result Based on:	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	6 units	
Comments: Local to stairwell within ceiling void				

Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	2 (Compressed asbestos fibre)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	1 (Enclosed textile/paper)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NATG00A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002611	Portal Ref No.:	246	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments: To external door				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT044	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	247	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT044	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002612	Portal Ref No.:	248	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT044	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002613	Portal Ref No.:	249	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	80 m ²	
Comments: To the rear of the parquet flooring				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT033	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	250	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT002	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	253	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT002	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002614	Portal Ref No.:	254	
Item:	Textured coating to concrete			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	3 linear metres		
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT00B	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	255	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT00B	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002615	Portal Ref No.:	256	
Item:	Modern vinyl to bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	16 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT007	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	257	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT007	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	No sample - presumed	Portal Ref No.:	258	
Item:	Asbestos Textile fuse tapes			
Asbestos Content:	Result Based on:			
Chrysotile	Presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Asbestos content presumed as they remained live and connected and no isolation certificate was available.				


Material Assessment Total Score: 5		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C9
Product Type:	2 (Asbestos Textiles/Paper)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	1 (Enclosed textile/paper)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT006	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	259	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT032	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	260	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT032A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	261	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT009	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	262	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	10 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT009	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002616	Portal Ref No.:	263	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	4 linear metres		
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT009	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002617	Portal Ref No.:	264	
Item:	Textured coating to concrete pillar			
Asbestos Content:	Result Based on:			
No Asbestos Detected	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT009	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002618	Portal Ref No.:	265	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	160 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT009C	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002617	Portal Ref No.:	268	
Item:	Textured coating to concrete pillar			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	4 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT009C	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002618	Portal Ref No.:	269	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	28 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT009B	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002618	Portal Ref No.:	271	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT009A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002618	Portal Ref No.:	272	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT031A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	273	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT031D	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	274	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT031	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	275	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT030	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	277	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	5 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT029	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	278	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT029	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002619	Portal Ref No.:	279	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	48 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT010	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002621	Portal Ref No.:	280	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	84 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT010	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002620	Portal Ref No.:	281	
Item:	Bitumen sink pad			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	5 units	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT010	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	282	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT010A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002621	Portal Ref No.:	283	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	15 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT012	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002622	Portal Ref No.:	285	
Item:	Bitumen sink pad			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	5 units	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT012	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	286	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT012E	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002623	Portal Ref No.:	287	
Item:	Asbestos Thermoplastic floor tiles			
Asbestos Content:	Result Based on:			
Chrysotile in tile and adhesive	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	10 m ²		
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos thermoplastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT012B	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002622	Portal Ref No.:	289	
Item:	Bitumen sink pad			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT012A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	290	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT012A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002621	Portal Ref No.:	291	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT027A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	292	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT028B	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	293	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT028	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	294	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT027	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	295	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT027	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002613	Portal Ref No.:	296	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	16 m ²	
Comments: To the rear of the parquet flooring				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT026A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002613	Portal Ref No.:	298	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	6 m ²	
Comments: To the rear of the parquet flooring				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT026	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	299	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT026	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002613	Portal Ref No.:	300	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	8 m ²	
Comments: To the rear of the parquet flooring				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT025A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	301	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT025A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002613	Portal Ref No.:	302	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	12 m ²	
Comments: To the rear of the parquet flooring				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT025	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	303	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT025	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002613	Portal Ref No.:	304	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	25 m ²	
Comments: To the rear of the parquet flooring				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT025B	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	307	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT025B	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002624	Portal Ref No.:	308	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	3 linear metres		
Comments: To left handside of sink units				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT014	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	309	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail


Location:	NAT014	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002624	Portal Ref No.:	310	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	
Management Detail				

Location:	NAT014B	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	311	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT014D	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	312	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT017	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002624	Portal Ref No.:	313	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments:				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT015	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	314	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT015	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002625	Portal Ref No.:	315	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	8 m ²	
Comments: Beneath modern vinyl				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT016	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	316	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT016	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002626	Portal Ref No.:	317	
Item:	Thermoplastic floor tiles			
Asbestos Content:		Result Based on:		
No Asbestos Detected in tile no adhesive present		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	18 m ²	
Comments:				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT024A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	318	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT024	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	319	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT023	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	320	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 units	
Comments: Through concrete structure, throughout ceiling void				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT023	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002627	Portal Ref No.:	321	
Item:	Asbestos Reinforced plastic downpipes			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By: Reg 13(1)	Extent:	12 linear metres		
Comments: 3 x no downpipes see plan for locations				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT022	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	324	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT021A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	325	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	1 unit	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT021B	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	326	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT020	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	327	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT019A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	328	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Through concrete structure				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT019A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002627	Portal Ref No.:	329	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments: Within plasterboard boxing				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT016A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	330	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT099H	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	331	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure, core holes have been filled				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT019	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	332	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT099J	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	333	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	2 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT099J	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002627	Portal Ref No.:	334	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	4 linear metres	
Comments: Within timber boxing				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 4		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C7
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT099K	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	335	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	18 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT099K	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002627	Portal Ref No.:	336	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	12 linear metres	
Comments: Within timber boxing, 3No				

Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT099K	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002628	Portal Ref No.:	338	
Item:	Thermoplastic floor tiles			
Asbestos Content:		Result Based on:		
No Asbestos Detected in tile or adhesive		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	18 m ²	
Comments: Blue, to section of floor to corridor				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT099L	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	340	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	3 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT099L	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002613	Portal Ref No.:	341	
Item:	Bitumen adhesive			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	18 m ²	
Comments: To the rear of the parquet flooring				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT099D	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	342	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	8 units	
Comments: Through concrete structure				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT099D	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002627	Portal Ref No.:	343	
Item:	Asbestos Reinforced plastic downpipe			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	16 linear metres	
Comments: Within timber boxing 4No				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 5		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: C8
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	1 (Occasionally likely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	2 (>10 - <50 sq m or >10m - <50m pipe run)	

Management Detail

Location:	NAT099D	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002628	Portal Ref No.:	345	
Item:	Thermoplastic floor tiles			
Asbestos Content:		Result Based on:		
No Asbestos Detected in tile or adhesive		Strongly presumed		
Sample Analysed By:	Not applicable	Extent:	38 m ²	
Comments: Blue, to section of floor to corridor				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: No Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT099D	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002629	Portal Ref No.:	346	
Item:	Insulating board upstand and ceiling			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	4 m ²	
Comments: Local to double doors				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT099C	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	As DU002605	Portal Ref No.:	347	
Item:	Asbestos Reinforced plastic sleeve			
Asbestos Content:	Result Based on:			
Chrysotile	Strongly presumed			
Sample Analysed By:	Not applicable	Extent:	6 units	
Comments: Through concrete structure, within corridor section only				


Material Assessment Total Score: 3		Likelihood of Disturbance Assessment Total Score: 3		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D6
Product Type:	1 (Asbestos reinforced plastic)	Location:	2 (Rooms up to 100 sq m)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	0 (Composite material)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Location:	NAT EXT	Block:	Birmingham City University	Floor Level: E - External
Sample No.:	DU002630	Portal Ref No.:	348	
Item:	Insulating board door header			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	2 m ²	
Comments:				


Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT002A	Block:	Birmingham City University	Floor Level: Ground Floor
Sample No.:	DU002631	Portal Ref No.:	351	
Item:	Insulating board ceiling panels			
Asbestos Content:		Result Based on:		
No Asbestos Detected		Analysis of sample using PLM		
Sample Analysed By:	Reg 13(1)	Extent:	6 m ²	
Comments: Damaged				

Material Assessment Total Score: 0		Likelihood of Disturbance Assessment Total Score: 0		Management Assessment Licensable: Yes Recommendations: Not Applicable Reinspection Interval: Not Applicable Overall Risk Category: E0
Product Type:	0 Not Applicable	Location:	0 Not Applicable	
Condition:	0 Not Applicable	Accessibility:	0 Not Applicable	
Surface Treatment:	0 Not Applicable			
Asbestos Type:	0 Not Applicable	Extent Score:	0 Not Applicable	

Management Detail

Location:	NAT EXT	Block:	Birmingham City University	Floor Level: E - External
Sample No.:	DU002632	Portal Ref No.:	352	
Item:	Asbestos Cement cowl			
Asbestos Content:	Result Based on:			
Chrysotile	Analysis of sample using PLM			
Sample Analysed By:	Reg 13(1)	Extent:	1 unit	
Comments: To rear section of the roof right of centre				

Material Assessment Total Score: 4		Likelihood of Disturbance Assessment Total Score: 1		Management Assessment Licensable: No Recommendations: Program removal Reinspection Interval: Not Applicable Overall Risk Category: D5
Product Type:	1 (Asbestos cement)	Location:	0 (Outdoors)	
Condition:	1 (Minor scratches)	Accessibility:	0 (Usually inaccessible or unlikely to be disturbed)	
Surface Treatment:	1 (Unencapsulated asbestos cement)			
Asbestos Type:	1 (Chrysotile)	Extent Score:	1 (<10 sq m or 10m pipe run)	

Management Detail

Report No.: J102749
Issue Date: 02/11/2018




5.0 Annotated Building Plans

Diagrams included:


Plan(s) supplied by client, additional plans drawn by Bradley Environmental Consultants Ltd.

- J102749/01 - Ground Floor Plan - Item Location(s)
- J102749/02 - Ground Floor Plan - Item Location(s)
- J102749/03 - Ground Floor Plan - Intrusion Location(s)
- J102749/04 - Ground Floor Plan - Intrusion Location(s)
- J102749/05 - First Floor Plan - Item Location(s)
- J102749/06 - First Floor Plan - Item Location(s)
- J102749/07 - First Floor Plan - Intrusion Location(s)
- J102749/08 - First Floor Plan - Intrusion Location(s)
- J102749/09 - Second Floor Plan - Item Location(s)
- J102749/10 - Second Floor Plan - Item Location(s)
- J102749/11 - Second Floor Plan - Intrusion Location(s)
- J102749/12 - Second Floor Plan - Intrusion Location(s)



PLAN OVERVIEW

NAT External



- KEY**
- ?????? ASBESTOS ITEM LOCATION
 - ?????? NON-ASBESTOS ITEM LOCATION
 - ??? ROOM NO
 - AREA/FEATURES NOT ACCESSED
 - Ext EXTERNAL ITEM
 - REMOVED ITEM LOCATION
 - AREA DEPICTED BELOW

This diagram is only to be reproduced in colour.

- Plan Abbreviations:**
- AC - Asbestos Cement
 - AIB - Asbestos Insulating Board
 - AT - Asbestos Textile
 - AI - Asbestos Insulation
 - ATC - Asbestos Textured Coating
 - AB - Asbestos Bitumen
 - ACF - Asbestos Compressed Fibre
 - ATP - Asbestos Thermoplastic Floor Tiles

Drawing title:
Asbestos Survey Plan (J102749/01)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Ground Floor

This drawing is to be read in conjunction with survey report number: J102749


Date of work: 24/08/2018 - 09/10/2018

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk




PLAN OVERVIEW

KEY

- ????? ASBESTOS ITEM LOCATION
- ????? NON-ASBESTOS ITEM LOCATION
- ?? ROOM NO
- AREA/FEATURES NOT ACCESSED
- Ext EXTERNAL ITEM
- REMOVED ITEM LOCATION
- AREA DEPICTED BELOW

This diagram is only to be reproduced in colour.

- Plan Abbreviations:
- AC - Asbestos Cement
 - AIB - Asbestos Insulating Board
 - AT - Asbestos Textile
 - AI - Asbestos Insulation
 - ATC- Asbestos Textured Coating
 - AB - Asbestos Bitumen
 - ACF- Asbestos Compressed Fibre
 - ATP- Asbestos Thermoplastic Floor Tiles



Drawing title:
Asbestos Survey Plan (J102749/02)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Ground Floor

This drawing is to be read in conjunction with survey report number: J102749


Date of work: 24/08/2018 - 09/10/2018

Lead surveyor: Reg 13(1)


Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk



PLAN OVERVIEW



KEY

- ⊘ INTRUSION LOCATIONS
- ??? ROOM NO
- AREA/FEATURES NOT ACCESSED
- Ext EXTERNAL ITEM
- ⊘ AREA DEPICTED BELOW

This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC- Asbestos Textured Coating
- AB - Asbestos Bitumen
- ACF- Asbestos Compressed Fibre
- ATP- Asbestos Thermoplastic Floor Tiles

Drawing title:
Asbestos Survey Plan (J102749/03)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Ground Floor

This drawing is to be read in conjunction with survey report number: J102749


Date of work: 24/08/2018 - 09/10/2018

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk



PLAN OVERVIEW

KEY

- ⊘?? INTRUSION LOCATIONS
- ??? ROOM NO
- AREA/FEATURES NOT ACCESSED
- Ext EXTERNAL ITEM
- ▨ AREA DEPICTED BELOW

This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC - Asbestos Textured Coating
- AB - Asbestos Bitumen
- ACF - Asbestos Compressed Fibre
- ATP - Asbestos Thermoplastic Floor Tiles

Drawing title:
Asbestos Survey Plan (J102749/04)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Ground Floor

This drawing is to be read in conjunction with survey report number: J102749

Date of work: 24/08/2018 - 09/10/2018


Lead surveyor: [REDACTED]


Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk


NAT External





PLAN OVERVIEW

NAT External



KEY

- ?????? ASBESTOS ITEM LOCATION
- ?????? NON-ASBESTOS ITEM LOCATION
- ??? ROOM NO
- AREA/FEATURES NOT ACCESSED
- Ext EXTERNAL ITEM
- REMOVED ITEM LOCATION
- AREA DEPICTED BELOW
- DU002251

This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC - Asbestos Textured Coating
- AB - Asbestos Bitumen
- ACF - Asbestos Compressed Fibre
- ATP - Asbestos Thermoplastic Floor Tiles

Drawing title:
Asbestos Survey Plan (J102749/05)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): First Floor

This drawing is to be read in conjunction with survey report number: J102749


Date of work: 24/08/2018 - 09/10/2018

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk



NAT External

PLAN OVERVIEW

KEY

- ?????? ASBESTOS ITEM LOCATION
- ?????? NON-ASBESTOS ITEM LOCATION
- ??? ROOM NO
- AREA/FEATURES NOT ACCESSED
- Ext EXTERNAL ITEM
- REMOVED ITEM LOCATION
- AREA DEPICTED BELOW
- DU002251

This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC - Asbestos Textured Coating
- AB - Asbestos Bitumen
- ACF - Asbestos Compressed Fibre
- ATP - Asbestos Thermoplastic Floor Tiles

Drawing title:
Asbestos Survey Plan (J102749/06)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): First Floor


This drawing is to be read in conjunction with survey report number: J102749


Date of work: 24/08/2018 - 09/10/2018
Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.




Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk





PLAN OVERVIEW

NAT External



KEY

- ⊘?? INTRUSION LOCATIONS
- ??? ROOM NO
- AREA/FEATURES NOT ACCESSED
- Ext EXTERNAL ITEM
- ▨ AREA DEPICTED BELOW

This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC - Asbestos Textured Coating
- AB - Asbestos Bitumen
- ACF - Asbestos Compressed Fibre
- ATP - Asbestos Thermoplastic Floor Tiles

Drawing title:
Asbestos Survey Plan (J102749/07)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): First Floor


This drawing is to be read in conjunction with survey report number: J102749

Date of work: 24/08/2018 - 09/10/2018
Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk



PLAN OVERVIEW

NAT External

KEY

- ⊘ INTRUSION LOCATIONS
- ??? ROOM NO
- AREA/FEATURES NOT ACCESSED
- Ext EXTERNAL ITEM
- ▨ AREA DEPICTED BELOW

This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC - Asbestos Textured Coating
- AB - Asbestos Bitumen
- ACF - Asbestos Compressed Fibre
- ATP - Asbestos Thermoplastic Floor Tiles

Drawing title:
Asbestos Survey Plan (J102749/08)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): First Floor

This drawing is to be read in conjunction with survey report number: J102749


Date of work: 24/08/2018 - 09/10/2018

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk



KEY

- ?????? ASBESTOS ITEM LOCATION
- ?????? NON-ASBESTOS ITEM LOCATION
- ??? ROOM NO
- AREA/FEATURES NOT ACCESSED
- Ext EXTERNAL ITEM
- REMOVED ITEM LOCATION
- AREA DEPICTED BELOW
- DU002221

This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC - Asbestos Textured Coating
- AB - Asbestos Bitumen
- ACF - Asbestos Compressed Fibre
- ATP - Asbestos Thermoplastic Floor Tiles

Drawing title: Asbestos Survey Plan (J102749/09)

Site address: Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Second Floor

This drawing is to be read in conjunction with survey report number: J102749

Date of work: 24/08/2018 - 09/10/2018


Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.





Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk

PLAN OVERVIEW



NAT External






PLAN OVERVIEW

NAT External

- KEY**
- ?????? ASBESTOS ITEM LOCATION
 - ?????? NON-ASBESTOS ITEM LOCATION
 - ??? ROOM NO
 - AREA/FEATURES NOT ACCESSED
 - Ext EXTERNAL ITEM
 - REMOVED ITEM LOCATION
 - AREA DEPICTED BELOW
 - DU002221

This diagram is only to be reproduced in colour.

- Plan Abbreviations:**
- AC - Asbestos Cement
 - AIB - Asbestos Insulating Board
 - AT - Asbestos Textile
 - AI - Asbestos Insulation
 - ATC - Asbestos Textured Coating
 - AB - Asbestos Bitumen
 - ACF - Asbestos Compressed Fibre
 - ATP - Asbestos Thermoplastic Floor Tiles



DU002190

DU002191

Drawing title:
Asbestos Survey Plan (J102749/10)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Second Floor

This drawing is to be read in conjunction with survey report number: J102749


Date of work: 24/08/2018 - 09/10/2018

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.




Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk



PLAN OVERVIEW

NAT External



KEY

- ⊘ INTRUSION LOCATIONS
- ??? ROOM NO
- AREA/FEATURES NOT ACCESSED
- Ext EXTERNAL ITEM
- ▨ AREA DEPICTED BELOW

This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC - Asbestos Textured Coating
- AB - Asbestos Bitumen
- ACF - Asbestos Compressed Fibre
- ATP - Asbestos Thermoplastic Floor Tiles

Drawing title:
Asbestos Survey Plan (J102749/11)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Second Floor


This drawing is to be read in conjunction with survey report number: J102749

Date of work: 24/08/2018 - 09/10/2018
Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.




Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk



PLAN OVERVIEW

NAT External



KEY

- ⊘?? INTRUSION LOCATIONS
- ??? ROOM NO
- AREA/FEATURES NOT ACCESSED
- Ext EXTERNAL ITEM
- ⊘⊘⊘ AREA DEPICTED BELOW

This diagram is only to be reproduced in colour.

Plan Abbreviations:

- AC - Asbestos Cement
- AIB - Asbestos Insulating Board
- AT - Asbestos Textile
- AI - Asbestos Insulation
- ATC- Asbestos Textured Coating
- AB - Asbestos Bitumen
- ACF- Asbestos Compressed Fibre
- ATP- Asbestos Thermoplastic Floor Tiles

Drawing title:
Asbestos Survey Plan (J102749/12)

Site address:
Attwood Building
Former City North Campus
Birmingham City University
Perry Barr
B42 2US

Floor level(s): Second Floor

This drawing is to be read in conjunction with survey report number: J102749

Date of work: 24/08/2018 - 09/10/2018

Lead surveyor: Reg 13(1)

Please note: this drawing is NOT TO SCALE.



Bradley Environmental Consultants Limited
20 Stourbridge Road
Halesowen, West Midlands B63 3US
Tel: 0121 550 0224 Fax: 0121 550 0641
email: info@bradley-enviro.co.uk

6.0 Room Description Report

Please note that this section of the survey report documents the general building materials recorded on a room by room basis by the surveyor while undertaking the inspection in line with our ISO17020 UKAS Accreditation. It has not been designed to use as a register for asbestos materials. Please refer to the asbestos register and/or summary section of this report for details of the ACMs located during this investigation.

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT002	Ground Floor	Compressed fibre suspended ceiling tiles	Plaster to blockwork, ceramic tile, textured coating to concrete pillar	Modern vinyl to concrete	Metal and plastic pipework, plastic cisterns, reinforced plastic sleeve, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT002A	Ground Floor	Insulating board panels to corrugated metal	Plasterboard to brickwork	Concrete	Modern electrics
Birmingham City University	NAT002B	Ground Floor	Corrugated metal	Brickwork	Concrete	Modern electrics
Birmingham City University	NAT005	Ground Floor	Compressed fibre suspended ceiling tiles	Plaster to plasterboard, brickwork, blockwork, ceramic tile	Modern vinyl to concrete	Metal and plastic pipework, plastic cisterns

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT006	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Metal pipework, plastic trunking, reinforced plastic sleeve, timber door header
Birmingham City University	NAT007	Ground Floor	Concrete	Blockwork, brickwork	Concrete	Textile fuse tapes to lift isolator, reinforced plastic sleeve, modern electrics
Birmingham City University	NAT008	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Plastic trunking, timber boxing to metal pipework, metal ducting
Birmingham City University	NAT009	Ground Floor	Compressed glassfibre insulation suspended ceiling tiles to concrete	Painted block, textured coating to concrete	Modern vinyl to bitumen adhesive to concrete	Reinforced plastic sleeve, reinforced plastic downpipe, metal trunking, timber door header

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT009A	Ground Floor	Concrete	Timber door header, plaster to plasterboard	Carpet tiles to cork vinyl to bitumen adhesive to concrete	Quarry tile window sill, metal pipework
Birmingham City University	NAT009B	Ground Floor	Concrete	Painted block, plaster to plasterboard	Carpet tiles to cork vinyl to bitumen adhesive to concrete	Quarry tile window sill, metal pipework
Birmingham City University	NAT009C	Ground Floor	Concrete	Painted block, textured coating to concrete, timber wall panels	Modern vinyl to bitumen adhesive to concrete	Quarry tile window sill
Birmingham City University	NAT00B	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork	Carpet tiles to vinyl floor tiles with bitumen adhesive to concrete	Timber door headers, metal pipework, metal cable tray, reinforced plastic sleeve

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT00C	Ground Floor	Concrete	Plaster to blockwork	Modern vinyl to concrete	Rubber stair nosing, timber door header, quarry tile sill, metal pipework
Birmingham City University	NAT010	Ground Floor	Concrete	Painted block, plaster to plasterboard	Modern vinyl tiles to bitumen adhesive	Quarry tile window sill, metal pipework, bitumen sink pads, reinforced plastic sleeve, plastic pipework, metal ducting
Birmingham City University	NAT010A	Ground Floor	Concrete, plaster to plasterboard to concrete	Block, plaster to plasterboard	Modern vinyl tiles to bitumen adhesive	Quarry tile window sill, metal pipework, plastic pipework, metal conduit, glass fibre insulation to metal pipework
Birmingham City University	NAT012	Ground Floor	Concrete	Block, plaster to plasterboard, timber panels, brick work	Modern vinyl tiles to concrete	Quarry tile window sill, metal pipework, bitumen sink pads, reinforced plastic sleeve, plastic pipework, metal ducting, glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT012A	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Brick, plaster to block	Carpet tiles to bitumen adhesive to concrete	Metal pipework and ducting, reinforced plastic sleeve
Birmingham City University	NAT012B	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Brick, plaster to block	Modern vinyl to concrete	Metal pipework and ducting, bitumen sink pad
Birmingham City University	NAT012C	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Brick, plaster to plasterboard	Carpet tiles to concrete	Quarry tile window sill, metal pipework
Birmingham City University	NAT012D	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Quarry tile window sill, metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT012E	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block, plaster to plasterboard, timber panels, brick work	Carpet tiles to thermoplastic floor tiles to concrete	Quarry tile window sill, glass fibre insulation to metal pipework
Birmingham City University	NAT014	Ground Floor	Concrete	Block and brick	Concrete	Reinforced plastic sleeve, timber door headers, foil faced glass fibre insulation to metal pipework, reinforced plastic downpipe
Birmingham City University	NAT014A	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Glass fibre insulation to metal pipework
Birmingham City University	NAT014B	Ground Floor	Concrete	Block, plaster to plasterboard	Concrete	Reinforced plastic sleeve, timber door headers, metal trunking

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT014C	Ground Floor	Concrete	Block, plaster to plasterboard	Concrete	Modern bitumen sink pad, metal ducting, metal and plastic pipework
Birmingham City University	NAT014D	Ground Floor	Compressed fibre suspended tiles to concrete	Block, plaster to plasterboard	Modern vinyl to concrete	Foil faced glass fibre insulation to metal pipework, metal ducting, metal and plastic pipework, reinforced plastic sleeve, ceramic cistern
Birmingham City University	NAT015	Ground Floor	Compressed fibre suspended tiles to concrete	Block, plaster to plasterboard	Modern vinyl to bitumen to concrete	Foil faced glass fibre insulation to metal pipework, metal ducting, metal and plastic pipework, reinforced plastic sleeve
Birmingham City University	NAT016	Ground Floor	Compressed fibre suspended tiles to concrete	Block, plaster to plasterboard	Thermoplastic floor tiles to concrete	Foil faced glass fibre insulation to metal pipework, metal ducting, metal and plastic pipework, reinforced plastic sleeve, timber door header

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT016A	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, reinforced plastic sleeve, timber panels
Birmingham City University	NAT017	Ground Floor	Concrete	Block, plaster to plasterboard	Concrete	Glass fibre insulation to metal pipework, metal ducting, metal pipework, reinforced plastic downpipe, plastic conduit
Birmingham City University	NAT018	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT019	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, reinforced plastic sleeve, metal ducting

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT019A	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, reinforced plastic sleeve, reinforced plastic downpipe, metal ducting, modern electrics
Birmingham City University	NAT020	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, reinforced plastic sleeve
Birmingham City University	NAT020A	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand
Birmingham City University	NAT021	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to painted concrete	Plasterboard upstands

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT021A	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, reinforced plastic sleeve
Birmingham City University	NAT021B	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, reinforced plastic sleeve
Birmingham City University	NAT022	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, reinforced plastic sleeve
Birmingham City University	NAT023	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, reinforced plastic sleeve, foil faced and glass fibre insulated metal pipework, plastic downpipe, modern electrics

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT024	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, reinforced plastic sleeve
Birmingham City University	NAT024A	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, plaster to plasterboard	Modern vinyl to concrete	Modern electrics, metal and plastic pipework, reinforced plastic sleeve
Birmingham City University	NAT024B	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to concrete	Modern electrics, metal trunking
Birmingham City University	NAT025	Ground Floor	Compressed fibre suspended tiles to concrete	Plaster to plasterboard, block	Carpet tiles to screed to parquet to bitumen adhesive to concrete	Reinforced plastic sleeve, glass fibre insulation to metal pipework, timber panel to modern electrics

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT025A	Ground Floor	Compressed fibre suspended tiles to concrete	Plaster to plasterboard, block	Carpet tiles to screed to parquet to bitumen adhesive to concrete	Reinforced plastic sleeve, glass fibre insulation to metal pipework
Birmingham City University	NAT025B	Ground Floor	Compressed fibre suspended tiles to concrete	Plaster to block, block, ceramic tile	Modern vinyl to quarry tile	Reinforced plastic sleeve, glass fibre insulation to metal pipework, metal and plastic pipework, plastic cistern, reinforced plastic downpipe, ceramic cistern
Birmingham City University	NAT025C	Ground Floor	Compressed fibre suspended tiles to concrete	Plaster to block, block, ceramic tile	Modern vinyl to quarry tile	Glass fibre insulation to metal pipework, metal and plastic pipework, ceramic cistern
Birmingham City University	NAT025D	Ground Floor	Concrete	Blockwork	Concrete	Not Applicable

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT026	Ground Floor	Compressed fibre suspended tiles to concrete	Plaster to plasterboard, block	Carpet tiles to screed to parquet to bitumen adhesive to concrete	Reinforced plastic sleeve, glass fibre insulation to metal pipework
Birmingham City University	NAT026A	Ground Floor	Compressed fibre suspended tiles to concrete	Plaster to plasterboard, plaster to block	Carpet tiles to screed to parquet to bitumen adhesive to concrete	Glass fibre insulation, modern electrics
Birmingham City University	NAT027	Ground Floor	Compressed fibre suspended tiles to concrete	Plaster to plasterboard, block	Carpet tiles to screed to parquet to bitumen adhesive to concrete	Reinforced plastic sleeve, glass fibre insulation to metal pipework
Birmingham City University	NAT027A	Ground Floor	Concrete	Plaster to block, plaster to plasterboard	Concrete	Modern electrics, timber door header, timber panels to steel, reinforced plastic sleeve

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT028	Ground Floor	Compressed fibre suspended tiles to concrete	Plaster to plasterboard, block	Carpet tiles to concrete	Reinforced plastic sleeve, glass fibre insulation to metal pipework
Birmingham City University	NAT028A	Ground Floor	Plaster to plasterboard to concrete	Plaster to plasterboard, block	Carpet tiles to concrete	Not Applicable
Birmingham City University	NAT028B	Ground Floor	Compressed fibre suspended tiles to concrete	Plaster to plasterboard, block	Carpet tiles to concrete	Reinforced plastic sleeve, glass fibre insulation to metal pipework
Birmingham City University	NAT029	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block, plaster to block	Modern vinyl to ply wood to parquet flooring to bitumen adhesive to concrete	Redundant metal ducting, reinforced plastic sleeve

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT030	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block, plaster to block	Carpet tiles to concrete	Redundant metal ducting, reinforced plastic sleeve
Birmingham City University	NAT031	Ground Floor	Plasterboard suspended tiles to concrete	Block, plaster to block	Modern vinyl to concrete	Quarry tile window sill, metal pipework, reinforced plastic sleeve, timber panel to walls
Birmingham City University	NAT031A	Ground Floor	Plasterboard suspended tiles to concrete	Block, plaster to block	Modern vinyl to concrete	Quarry tile window sill, metal pipework, reinforced plastic sleeve, timber panel to walls
Birmingham City University	NAT031D	Ground Floor	Plasterboard suspended tiles to concrete	Ceramic tiles to plaster to block	Modern vinyl to concrete	Quarry tile window sill, metal pipework, reinforced plastic sleeve, ceramic cistern

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT032	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Metal pipework glass fibre insulation, plastic trunking, reinforced plastic sleeve, timber door header
Birmingham City University	NAT032A	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Redundant metal ducting, reinforced plastic sleeve
Birmingham City University	NAT033	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Metal pipework, plastic trunking, reinforced plastic sleeve, timber door header
Birmingham City University	NAT034	Ground Floor	Concrete	Block, plaster to plasterboard	Concrete	Modern electrics, foil faced glass fibre insulation to metal pipework, timber boxing to steel, plastic pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT036	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, textured coating to plaster to block	Carpet tiles to concrete	Metal pipework, plastic trunking, reinforced plastic sleeve, reinforced plastic downpipe to timber boxing, cloth wrap glass fibre insulation to metal pipework, glass fibre insulation firebreak, compressed fibre gasket
Birmingham City University	NAT039	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, block	Carpet tiles to concrete	Metal pipework, plastic trunking, quarry tile window sill, reinforced plastic sleeve, timber boxing to plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT040	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block	Carpet tiles to raised timber flooring to concrete	Metal pipework, plastic trunking, timber window sill, reinforced plastic sleeve, timber boxing to plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework, rubber stair nosing
Birmingham City University	NAT040A	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Ceramic tiles to plaster to blockwork	Modern vinyl to concrete	Ceramic cistern, foil faced glass fibre insulation to metal pipework, plastic pipework internally to timber boxing, reinforced plastic sleeve

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT040B	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Ceramic tiles to plaster to blockwork	Modern vinyl to concrete	Ceramic cistern, foil faced glass fibre insulation to metal pipework, plastic pipework
Birmingham City University	NAT040C	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Ceramic tiles to plaster to blockwork	Modern vinyl to concrete	Ceramic cistern, foil faced glass fibre insulation to metal pipework, plastic pipework
Birmingham City University	NAT041A	Ground Floor	Compressed fibre suspended ceiling tiles to insulating board ceiling tiles	Plaster to plasterboard, brickwork	Carpet tiles to concrete	Metal pipework, timber boxing to plastic pipework
Birmingham City University	NAT041B	Ground Floor	Compressed fibre suspended ceiling tiles to insulating board ceiling tiles	Plaster to plasterboard, brickwork, blockwork	Carpet tiles to concrete	Metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT041C	Ground Floor	Compressed fibre suspended ceiling tiles to insulating board ceiling tiles	Plaster to plasterboard, brickwork	Carpet tiles to concrete	Metal pipework, timber boxing to plastic pipework
Birmingham City University	NAT042	Ground Floor	Compressed fibre suspended ceiling tiles to concrete, timber	Plaster to plasterboard, block	Carpet tiles to thermoplastic floor tiles to concrete	Metal pipework, plastic trunking, timber window sill, reinforced plastic sleeve, timber boxing to plastic pipework, modern electrics, metal ducting
Birmingham City University	NAT043	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, block, plaster to plasterboard	Carpet tiles to concrete	Metal pipework, plastic trunking, quarry tile window sill, reinforced plastic sleeve, timber boxing to plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework, cloth wrap to glass fibre insulation to metal pipework
Birmingham City University	NAT043A	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Block, plaster to plasterboard	Carpet tiles to concrete	Metal pipework, plastic trunking, reinforced plastic sleeve

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT044	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Painted block	Carpet tiles to parquet flooring to bitumen adhesive to concrete	Metal pipework, timber window sill, insulating board door header, metal conduit, modern electrics
Birmingham City University	NAT045	Ground Floor	Compressed fibre suspended ceiling tiles to concrete, timber	Plaster to plasterboard, block	Carpet tiles to modern vinyl floor tiles to concrete	Metal pipework, plastic trunking, timber window sill, reinforced plastic sleeve
Birmingham City University	NAT046	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to plasterboard, block	Carpet tiles to modern vinyl floor tiles to concrete	Metal pipework, plastic trunking, timber window sill
Birmingham City University	NAT047	Ground Floor	Compressed fibre suspended ceiling tiles to insulating board ceiling tiles	Plaster to plasterboard, brickwork	Carpet tiles to concrete	Metal pipework, plastic trunking

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT047A	Ground Floor	Compressed fibre suspended ceiling tiles to insulating board ceiling tiles	Plaster to plasterboard, brickwork, block	Carpet tiles to concrete	Metal pipework, plastic trunking
Birmingham City University	NAT099B	Ground Floor	Concrete	Plaster to plasterboard, block	Modern vinyl to concrete	Metal pipework, plastic trunking, rubber stair nosing
Birmingham City University	NAT099C	Ground Floor	Compressed fibre suspended ceiling tiles to concrete, compressed fibre straw board	Blockwork, plaster to blockwork	Carpet tiles to concrete	Timber door header, reinforced plastic sleeve, glass fibre insulation to metal pipework, modern electrics, plastic pipework to boxing, loose glass fibre insulation fire break
Birmingham City University	NAT099D	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, timber panels	Carpet tiles to thermoplastic floor tiles to concrete	Timber door header, reinforced plastic sleeve, glass fibre insulation to metal pipework, modern electrics, reinforced plastic downpipe, metal pipework internally to timber and block boxing, cork expansion joint to concrete sections, plastic pipework to boxing, loose glass fibre insulation fire break

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT099E	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, brickwork, blockwork	Modern vinyl to concrete	Metal pipework, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT099H	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Plasterboard upstand, reinforced plastic sleeve, foil faced glass fibre insulation to metal pipework, modern electrics
Birmingham City University	NAT099J	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plaster to plasterboard	Carpet tiles to concrete	Timber door header, reinforced plastic sleeve, glass fibre insulation to metal pipework, modern electrics, reinforced plastic downpipe
Birmingham City University	NAT099K	Ground Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, timber panels	Carpet tiles to thermoplastic floor tiles to concrete	Timber door header, reinforced plastic sleeve, glass fibre insulation to metal pipework, modern electrics, reinforced plastic downpipe, metal pipework internally to timber and block boxing, cork expansion joint to concrete sections, plastic pipework to boxing, loose glass fibre insulation fire break

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT099L	Ground Floor	Compressed fibre suspended tiles to concrete	Plaster to plasterboard, block	Carpet tiles to screed to parquet to bitumen adhesive to concrete	Reinforced plastic sleeve, glass fibre insulation to metal pipework, modern bitumen sink pad
Birmingham City University	NATG00A	Ground Floor	Concrete	Plaster to blockwork	Carpet tiles to concrete	Insulating board door header, timber door header, rubber stair nosing
Birmingham City University	NAT101	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework
Birmingham City University	NAT101A	1st Floor	Compressed fibre suspended ceiling tiles to concrete, plaster to mesh to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT102	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework
Birmingham City University	NAT102A	1st Floor	Concrete	Concrete, blockwork	Concrete	Foil faced and cloth wrap glass fibre insulation to metal pipework, timber doorheader, plastic pipework
Birmingham City University	NAT103	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, foil faced glass fibre insulation to metal pipework, glass door header
Birmingham City University	NAT104A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, block	Carpet tiles to concrete	Reinforced plastic sleeve, metal pipework, glass door header

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT104B	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, block	Carpet tiles to timber parquet with bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass door header, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT105	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, block	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass door header, foil faced glass fibre insulation to metal pipework, plasterboard and timber boxing to metal ducting
Birmingham City University	NAT105A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, block	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass partition
Birmingham City University	NAT105B	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, block, brick	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT105C	1st Floor	Compressed fibre suspended ceiling tiles to glass fibre insulation to concrete	Plaster to block	Carpet tiles to thermoplastic floor tiles to concrete	Reinforced plastic sleeve, cloth wrap to glass fibre insulation to metal pipework, timber boxing to metal pipework
Birmingham City University	NAT105D	1st Floor	Concrete	Brick and block	Carpet tiles to concrete	Metal ducting, foil faced glass fibre insulation to metal pipework, modern electrics, glass door header, reinforced plastic sleeve
Birmingham City University	NAT106	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plasterboard to blockwork	Carpet tiles to concrete	Reinforced plastic sleeve, metal pipework, foil faced glass fibre insulation to metal pipework, timber door header
Birmingham City University	NAT106A	1st Floor	Compressed fibre suspended ceiling tiles to concrete, plaster to plasterboard to concrete	Plasterboard to blockwork, plaster to block	Carpet tiles to concrete	Reinforced plastic sleeve, metal pipework, foil faced glass fibre insulation to metal pipework, timber door header, insulation to safe

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT106C	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, glass partition, plasterboard	Carpet tiles to bitumen adhesive to concrete	Cloth wrap to glass fibre insulation to metal pipework, timber boxing to metal pipework
Birmingham City University	NAT107	1st Floor	Compressed fibre suspended ceiling tiles to concrete, plaster to plasterboard to concrete	Plaster to block, plasterboard to block	Carpet tiles to thermoplastic floor tiles to concrete	Reinforced plastic sleeve, cloth wrap to glass fibre insulation to metal pipework
Birmingham City University	NAT107A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, glass partition, plasterboard	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, cloth wrap to glass fibre insulation to metal pipework, timber boxing to metal pipework
Birmingham City University	NAT107B	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block	Carpet tiles to thermoplastic floor tiles to concrete	Reinforced plastic sleeve, cloth wrap to glass fibre insulation to metal pipework, timber boxing to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT108A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, blockwork	Carpet tiles to bitumen adhesive to concrete	Metal pipework and plastic pipework, modern electrics, timber boxing to metal ducting
Birmingham City University	NAT108B	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, blockwork	Carpet tiles to bitumen adhesive to concrete	Metal pipework and plastic pipework, modern electrics, timber boxing to metal ducting, cloth wrap to glass fibre insulation to metal pipework
Birmingham City University	NAT110	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT110A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, cloth wrap glass fibre insulation to metal pipework, timber and glass door header

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT110B	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, blockwork	Modern vinyl to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, modern bitumen sink pad, metal ducting
Birmingham City University	NAT111	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete, vinyl tiles with bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework, modern bitumen sink pads
Birmingham City University	NAT112	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics
Birmingham City University	NAT113A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, block	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, cloth wrap to glass fibre insulation to metal pipework, foam insulated metal pipework internally to timber boxing

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT113B	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, brick external wall, plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT113C	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard	Carpet tiles to thermoplastic floor tiles raised timber floor to thermoplastic floor tiles to concrete	Modern electrics, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve, cloth wrap glass fibre insulation to metal pipework, timber boxing to metal pipework
Birmingham City University	NAT113D	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard	Carpet tiles to thermoplastic floor tiles raised timber floor to thermoplastic floor tiles to concrete	Modern electrics, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve, cloth wrap glass fibre insulation to metal pipework, timber boxing to metal pipework
Birmingham City University	NAT113E	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block	Carpet tiles to thermoplastic floor tiles raised timber floor to thermoplastic floor tiles to concrete	Modern electrics, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve, cloth wrap glass fibre insulation to metal pipework, timber boxing to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT113F	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block	Carpet tiles to thermoplastic floor tiles raised timber floor to thermoplastic floor tiles to concrete	Modern electrics, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve, timber boxing to reinforced plastic downpipe, chicken wire to cloth wrap glass fibre insulation to metal pipework
Birmingham City University	NAT113G	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block	Carpet tiles to thermoplastic floor tiles raised timber floor to thermoplastic floor tiles to concrete	Modern electrics, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve, timber boxing to reinforced plastic downpipe, chicken wire to cloth wrap glass fibre insulation to metal pipework
Birmingham City University	NAT113H	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork, plasterboard partition	Carpet tiles to thermoplastic floor tiles to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT114	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard glass fibre insulation cavity	Carpet tiles to bitumen adhesive to concrete	Modern electrics, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve, plastic pipework, foil faced glass fibre insulation to metal ducting

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT114A	1st Floor	Concrete	Plaster to block	Carpet tiles to thermoplastic floor tile to concrete	Modern electrics, plastic conduit, metal ducting, reinforced plastic sleeve, plastic pipework, foil faced glass fibre insulation to metal ducting, timber sills to quarry tile
Birmingham City University	NAT115	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard glass fibre insulation cavity	Carpet tiles to concrete	Modern electrics, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve, plastic pipework
Birmingham City University	NAT115A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard glass fibre insulation cavity	Carpet tiles to concrete	Modern electrics, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve, plastic pipework
Birmingham City University	NAT116	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard glass fibre insulation cavity	Carpet tiles to concrete	Modern electrics, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve, timber boxing to reinforced plastic downpipe, metal cable tray housing armoured cable, timber partition within ceiling void, cloth wrap glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT116A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard glass fibre insulation cavity	Carpet tiles to concrete	Modern electrics, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve
Birmingham City University	NAT116B	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard glass fibre insulation cavity	Carpet tiles to concrete	Modern electrics, foil faced glass fibre insulation to metal pipework, flexible ducting, plastic conduit, metal ducting, reinforced plastic sleeve
Birmingham City University	NAT117	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard glass fibre insulation cavity	Carpet tiles to concrete	Chicken wire to glass fibre insulation to metal pipework, modern electrics, foil faced glass fibre insulation to metal pipework, flexible ducting, plastic conduit, metal ducting
Birmingham City University	NAT117A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard glass fibre insulation cavity	Carpet tiles to concrete	Chicken wire to glass fibre insulation to metal pipework, modern electrics, foil faced glass fibre insulation to metal pipework, flexible ducting, plastic conduit, metal ducting

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT118	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to block, plaster to plasterboard glass fibre insulation cavity	Carpet tiles to concrete	Modern electrics, foil faced glass fibre insulation to metal pipework, flexible ducting, plastic conduit, metal ducting, thick ply wood door
Birmingham City University	NAT118B	1st Floor	Reinforced glass	Timber, concrete	Modern vinyl tiles to concrete	Not Applicable
Birmingham City University	NAT121	1st Floor	Compressed fibre suspended ceiling tiles	Blockwork, textured coating to blockwork to rear of WC's	Modern vinyl to bitumen adhesive to concrete	Plastic cisterns, quarry tile window sill, reinforced plastic sleeve, metal and plastic pipework
Birmingham City University	NAT122	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT123	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to thermoplastic floor tiles to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT125	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT126	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT127A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT127B	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework, polystyrene expansion joints
Birmingham City University	NAT128	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework, cork and polystyrene expansion joints
Birmingham City University	NAT129	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to thermoplastic floor tile to concrete	Metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT130	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT131	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT132	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT133	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT134 Service Duct	1st Floor	Concrete	Blockwork	Concrete	Cement flue, textile seal to metal ducting joints

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT134A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT134B	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT135	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT136	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework, polystyrene expansion joint, cork expansion

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT137	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to thermoplastic floor tiles	Reinforced plastic sleeve, metal pipework, glass and timber door header, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT137	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework and plastic pipework, modern electrics, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT138	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, metal pipework, glass door header, foil faced glass fibre insulation to metal pipework
Birmingham City University	NAT139	1st Floor	Compressed fibre suspended tiles to concrete	Timber partition to blockwork	Modern vinyl to concrete	Foil faced glass fibre insulation to metal pipework, plastic pipework, ceramic cisterns

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT139A	1st Floor	Compressed fibre suspended tiles to concrete	Timber partition to blockwork	Modern vinyl to concrete	Foil faced glass fibre insulation to metal pipework, plastic pipework, ceramic cistern
Birmingham City University	NAT199A	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, plasterboard within void	Carpet tiles to concrete	Foil faced glass fibre insulation to metal pipework, plastic pipework, metal cable tray, modern electrics, reinforced plastic downpipe, reinforced plastic sleeve, foil faced glass fibre insulation to metal pipework, plastic pipework to timber boxing, timber door headers, textile rope seal to metal ducting, cork expansion joint, plastic pipework to timber boxing / riser, glass fibre firebreak
Birmingham City University	NAT199B	1st Floor	Concrete	Plaster to blockwork, blockwork	Carpet tiles to concrete	Quarry tile window sill, modern stair nosing, timber boxing to reinforced plastic downpipe, timber header to link corridor doors, cloth wrap glass fibre insulation to metal pipework
Birmingham City University	NAT199D	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plasterboard to blockwork	Carpet to thermoplastic floor tiles to concrete	Reinforced plastic sleeve, metal pipework, glass and timber door header, plastic pipework, modern electrics

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT199G	1st Floor	Concrete	Blockwork, concrete	Modern vinyl tiles to concrete	Textured timber partition walls of cleaners cupboard
Birmingham City University	NAT199H	1st Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, plasterboard within void	Carpet tiles to concrete, carpet tiles to thermoplastic floor tiles	Cloth wrap glass fibre insulation to metal pipework, plastic pipework, metal cable tray, modern electrics, reinforced plastic downpipe, reinforced plastic sleeve, foil faced glass fibre insulation to metal pipework, plastic pipework to timber boxing
Birmingham City University	NAT200	2nd Floor	Compressed fibre suspended ceiling tiles to timber frame to concrete	Plaster to blockwork	Modern vinyl to concrete	Reinforced plastic soil pipe within riser, foil faced glass fibre insulation to metal pipework, plastic pipework, metal trunking, modern bitumen sink pads, quarry tile window sills
Birmingham City University	NAT201	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Foil faced glass fibre insulation to metal pipework, plastic pipework, metal trunking, plastic upvc to timber windows sills, reinforced plastic sleeve through concrete structure sections, plasterboard upstands to external wall, flexible ventilation ducting, timber boxing to pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT202	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, block, brick	Carpet tiles to thermoplastic floor tiles	Plastic pipework, metal trunking, plastic upvc to timber windows sills, reinforced plastic sleeve through concrete structure sections, plasterboard upstands to external wall, flexible ventilation ducting, metal ducting non suspect ducting, timber door headers
Birmingham City University	NAT202A	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, plaster to plasterboard partition	Carpet tiles to thermoplastic floor tiles	Plastic upvc to timber windows sills, reinforced plastic sleeve through concrete structure sections, plasterboard upstands to external wall, flexible ventilation ducting, timber door header, timber panels within void
Birmingham City University	NAT203	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to vinyl floor tiles	Plastic pipework, plastic conduit, plastic upvc to timber windows sills, reinforced plastic sleeve through concrete structure sections, plasterboard upstands to external wall, timber door headers, metal pipework, modern electrics, polystyrene packing joints
Birmingham City University	NAT203A	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, timber partition	Carpet tiles to bitumen adhesive to concrete	Plastic pipework, plastic conduit, plastic upvc to timber windows sills, reinforced plastic sleeve through concrete structure sections, plasterboard upstands to external wall, timber door headers, metal pipework, modern electrics, insulating board upstands, flexible ducting, foil faced glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT204	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, block, brick	Carpet tiles to thermoplastic floor tiles	Plastic pipework, metal trunking, plastic upvc to timber windows sills, reinforced plastic sleeve through concrete structure sections, plasterboard upstands to external wall, flexible ventilation ducting, metal ducting non suspect ducting mastic, timber door headers, foil faced glass fibre insulation to metal pipework, bitumen sink pad
Birmingham City University	NAT205	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, timber partitions	Carpet tiles to bitumen adhesive to concrete	Metal pipework, plastic conduit, reinforced plastic pipe sleeve, quarry tile window sill
Birmingham City University	NAT205A	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, timber partitions	Carpet tiles to bitumen adhesive to concrete	Timber upstands to roof light opening, flexible ducting, reinforced glass, metal pipework, plastic conduit
Birmingham City University	NAT206	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Plastic pipework, metal trunking, reinforced plastic sleeve through concrete structure sections, modern electrics, metal ducting

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT207	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Plastic pipework, metal trunking, reinforced plastic sleeve through concrete structure sections, modern electrics, metal ducting, cloth wrap glass fibre insulation to metal pipework, foil faced glass fibre insulation to metal pipework, upvc to timber window sill
Birmingham City University	NAT207A	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Plastic conduit, plastic upvc to timber windows sills, reinforced plastic sleeve through concrete structure sections, modern electrics, timber door header
Birmingham City University	NAT208	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, plaster to plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Plastic pipework, metal trunking, reinforced plastic sleeve through concrete structure sections, modern electrics, metal ducting, foil faced glass fibre insulation to metal pipework, upvc to timber window sill
Birmingham City University	NAT208A	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, plaster to plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Plastic pipework, metal trunking, reinforced plastic sleeve through concrete structure sections, modern electrics, metal ducting, foil faced glass fibre insulation to metal pipework, upvc to timber window sill

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT209	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Blockwork	Vinyl floor tiles	Plastic pipework, plastic conduit, plastic upvc to timber windows sills, reinforced plastic sleeve through concrete structure sections, plasterboard upstands to external wall, timber door headers, metal pipework, modern electrics, foil faced glass fibre insulation to metal pipework, bitumen sink pad
Birmingham City University	NAT210A	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Plastic pipework, metal trunking, plastic upvc to timber windows sills, reinforced plastic sleeve through concrete structure sections, plasterboard upstands to external wall, modern electrics
Birmingham City University	NAT210B	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal pipework, plastic conduit, reinforced plastic pipe sleeve, upvc to timber window sill, metal trunking, modern electrics, plastic pipework, foil faced glass fibre insulation to metal pipework, metal pipework, timber boxing to reinforced plastic soil pipe
Birmingham City University	NAT211A	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal pipework, plastic conduit, reinforced plastic pipe sleeve, quarry tile window sill and upvc to timber window sill, metal trunking, modern electrics, plastic pipework, foil faced glass fibre insulation to metal ducting, plasterboard upstands above external windows

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT211B	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Vinyl floor tiles to concrete	Metal pipework, plastic conduit, reinforced plastic pipe sleeve, quarry tile window sill, metal trunking, modern electrics, bitumen sink pads, plastic pipework, metal ducting, foil faced glass fibre insulation to metal ducting
Birmingham City University	NAT212	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal pipework, plastic conduit, reinforced plastic pipe sleeve, quarry tile window sill, metal trunking, modern electrics, bitumen sink pads, plastic pipework, timber access panels to riser, metal ducting, foil faced glass fibre insulation to metal ducting
Birmingham City University	NAT213	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal pipework, plastic conduit, reinforced plastic pipe sleeve, quarry tile window sill, metal trunking, modern electrics, bitumen sink pads, plastic pipework
Birmingham City University	NAT213A	2nd Floor	Compressed fibre suspended ceiling tiles to fibreboard panels to timber frame to concrete	Plaster to blockwork, plaster to textured coating blockwork	Vinyl to concrete	Quarry tile window sill, metal ducting, metal and plastic pipework, plastic cisterns, timber door header

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT216	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Plastic pipework, metal trunking, reinforced plastic sleeve through concrete structure sections, modern electrics, metal ducting
Birmingham City University	NAT217	2nd Floor	Compressed fibre suspended ceiling tiles to glass fibre insulation to concrete	Plaster to blockwork	Carpet tiles to vinyl to concrete, carpet tiles to raised timber floor	Plastic pipework, metal trunking, reinforced plastic sleeve through concrete structure sections, modern electrics, quarry tile window sill, fibreboard
Birmingham City University	NAT219	2nd Floor	Compressed fibre suspended ceiling tiles to timber frame to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal conduit, plastic trunking, plastic conduit, quarry tile window sill to concrete
Birmingham City University	NAT220	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, plaster to plasterboard partition	Carpet tiles to bitumen adhesive to concrete	Metal conduit, plastic trunking, plastic conduit, quarry tile window sill to concrete, plasterboard and timber upstands to window wall, insulating board door header

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT221	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal conduit, plastic trunking, plastic conduit, quarry tile window sill to concrete, plasterboard and timber upstands to window wall
Birmingham City University	NAT222	2nd Floor	Compressed fibre suspended ceiling tiles to timber frame to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal conduit, plastic trunking, plastic conduit, quarry tile window sill to concrete
Birmingham City University	NAT223	2nd Floor	Compressed fibre suspended ceiling tiles to timber frame to concrete	Plaster to blockwork	Modern vinyl to concrete	Modern electrics, metal conduit, quarry tile window sill to concrete
Birmingham City University	NAT223A	2nd Floor	Concrete	Blockwork	Concrete	Cement flue pipe, textile seal to metal ducting

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT224	2nd Floor	Compressed fibre suspended ceiling tiles to timber frame to concrete	Plaster to blockwork	Carpet tiles to bitumen adhesive to concrete	Metal conduit, reinforced plastic sleeve through concrete structure sections, plasterboard upstands to external wall, timber boxing to external wall to radiator, plastic trunking
Birmingham City University	NAT225	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to blockwork, textured coating blockwork	Vinyl to concrete	Quarry tile window sill, metal ducting, metal and plastic pipework, plastic cisterns, timber door header
Birmingham City University	NAT225A	2nd Floor	Concrete	Blockwork, concrete	Concrete	Foil faced glass fibre insulation to metal pipework, plastic pipework, metal cable tray, timber doorheader
Birmingham City University	NAT299 Corridor	2nd Floor	Compressed fibre suspended ceiling tiles to concrete	Plaster to brickwork	Carpet tiles to bitumen adhesive to concrete	Reinforced plastic sleeve, plastic pipework metal ducting, reinforced plastic and metal pipework downpipes internally to risers throughout, timber door headers, foil faced glass fibre insulated metal pipework, metal cable tray, modern electrics, reinforced plastic downpipe, foil faced glass fibre insulation to metal pipework

Block:	Room:	Floor Level:	Ceiling:	Walls:	Floor:	Other:
Birmingham City University	NAT299A	2nd Floor	Concrete	Concrete, textured coating to concrete	Modern vinyl tiles to concrete	Plastic pipework, reinforced glazing, rubber stair nosing, timber built in cupboard
Birmingham City University	NAT299E	2nd Floor	Concrete	Blockwork, concrete	Carpet tiles to concrete	Plastic pipework within boxing, insulating board door header to link corridor, quarry tile window sill, timber boxing to link corridor door surround, rubber stair nosing
Birmingham City University	NAT EXT	E - External	Modern roof covering	Brickwork	Not Applicable	Timber panels to external windows surrounding vents, metal encased foam under external windows to the rear, plastic pipework, timber canopy, insulating board door header, timber door header and surround, modern ventilation units, rubber and glass fibre insulation to metal ducting

Report No.: J102749
Issue Date: 02/11/2018



7.0 Room Access Report

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT002	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT002A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT002B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT005	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT006	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT007	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT008	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT009	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT009A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT009B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT009C	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT00B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT00C	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT010	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT010A	Ground Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT012	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT012A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT012B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT012C	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT012D	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT012E	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT014	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT014A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT014B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT014C	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT014D	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT015	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT016	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT016A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT017	Ground Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT018	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT019	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT019A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT020	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT020A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT021	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT021A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT021B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT022	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT023	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT024	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT024A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT024B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT025	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT025A	Ground Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT025B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT025C	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT025D	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT026	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT026A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT027	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT027A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT028	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT028A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT028B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT029	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT030	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT031	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT031A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT031D	Ground Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT032	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT032A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT033	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT034	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT036	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT039	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT040	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT040A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT040B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT040C	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT041A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT041B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT041C	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT042	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT043	Ground Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT043A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT044	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT045	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT046	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT047	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT047A	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT099B	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT099C	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT099D	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT099E	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT099H	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT099J	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT099K	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NAT099L	Ground Floor	Accessed	None	Not Applicable
Birmingham City University	NATG00A	Ground Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT101	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT101A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT102	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT102A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT103	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT104A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT104B	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT105	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT105A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT105B	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT105C	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT105D	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT106	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT106A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT106C	1st Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT107	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT107A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT107B	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT108A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT108B	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT110	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT110A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT110B	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT111	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT112	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT113A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT113B	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT113C	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT113D	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT113E	1st Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT113F	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT113G	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT113H	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT114	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT114A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT115	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT115A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT116	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT116A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT116B	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT117	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT117A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT118	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT118B	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT121	1st Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT122	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT123	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT125	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT126	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT127A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT127B	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT128	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT129	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT130	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT131	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT132	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT133	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT134 Service Duct	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT134A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT134B	1st Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT135	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT136	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT137	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT138	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT139	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT139A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT199A	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT199B	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT199D	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT199G	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT199H	1st Floor	Accessed	None	Not Applicable
Birmingham City University	NAT200	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT201	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT202	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT202A	2nd Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT203	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT203A	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT204	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT205	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT205A	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT206	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT207	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT207A	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT208	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT208A	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT209	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT210A	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT210B	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT211A	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT211B	2nd Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT212	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT213	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT213A	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT216	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT217	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT219	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT220	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT221	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT222	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT223	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT223A	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT224	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT225	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT225A	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT299 Corridor	2nd Floor	Accessed	None	Not Applicable

Block:	Room:	Floor Level:	Surveyed:	Areas Not Accessed:	Reason For No Access:
Birmingham City University	NAT299A	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT299E	2nd Floor	Accessed	None	Not Applicable
Birmingham City University	NAT EXT	E - External	Accessed	None	Not Applicable

8.0 Bulk Analysis Results

CERTIFICATE OF ANALYSIS

Asbestos Fibre Identification in Bulk Sample

Client WYG Engineering Ltd
Address: Geneva Building
 Lake View Drive
 Sherwood Business Park
 Annesley
 Nottingham
 NG15 0ED

Site Attwood Building
Address: Former City North Campus
 Birmingham City University
 Perry Barr
 B42 2US

Samples Received: 11/10/2018

Issue Date: 17/10/2018

Order Placed By: [Redacted]

Sampled By: [Redacted]

Analysed on: 05/10/2018 –17/10/2018

Authorised Signatory: Reg 13(1)Reg 13(1)Reg 13(1)
 Reg 13(1)Reg 13(1)Reg 13(1)

Job Title: Laboratory Analyst

Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation					
Report No.: J102749					
Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU002190	-	NAT200	Asbestos Reinforced plastic soil pipe	Chrysotile	Reg 13(1)
DU002191	-	NAT201	Asbestos Reinforced plastic sleeve	Chrysotile	Reg 13(1)
DU002192	-	NAT201	Bitumen adhesive	No Asbestos Detected	Reg 13(1)
DU002193	-	NAT299E	Insulating board door header	No Asbestos Detected	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J102749

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU002194	-	NAT202	Asbestos Thermoplastic floor tiles	Chrysotile in tile and adhesive	Reg 13(1)
DU002195	-	NAT213A	Textured coating to blockwork	No Asbestos Detected	Reg 13(1)
DU002196	-	NAT213A	Asbestos Vinyl	Chrysotile in bitumen adhesive only	Reg 13(1)
DU002197	-	NAT203	Asbestos Vinyl floor tiles with bitumen adhesive	Chrysotile in bitumen adhesive only	Reg 13(1)
DU002198	-	NAT203A	Insulating board upstand	No Asbestos Detected	Reg 13(1)
DU002199	-	NAT203A	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002200	-	NAT223A	Asbestos Cement flue pipe	Chrysotile	Reg 13(1)
DU002201	-	NAT223A	Asbestos Textile seal to metal ducting joints	Chrysotile	Reg 13(1)
DU002202	-	NAT204	Asbestos Thermoplastic floor tiles	Chrysotile in tile and adhesive	Reg 13(1)
DU002203	-	NAT204	Bitumen sink pads	No Asbestos Detected	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
20 Stourbridge Road,
Halesowen, West Midlands
B63 3US

Tel: 0121 550 0224 Fax: 0121 550 0641
Email: sales@bradley-enviro.co.uk



Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J102749

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU002204	-	NAT220	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002205	-	NAT220	Insulating board door header	No Asbestos Detected	Reg 13(1)
DU002206	-	NAT208	Asbestos Reinforced plastic sleeve	Chrysotile	Reg 13(1)
DU002207	-	NAT208	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002208	-	NAT217	Vinyl	No Asbestos Detected in vinyl or adhesive	Reg 13(1)
DU002209	-	NAT225	Textured coating to blockwork	No Asbestos Detected	Reg 13(1)
DU002210	-	NAT299A	Textured coating to concrete	No Asbestos Detected	Reg 13(1)
DU002211	-	NAT209	Bitumen sink pad	No Asbestos Detected	Reg 13(1)
DU002212	-	NAT299A	Textured coating to door wall	No Asbestos Detected	Reg 13(1)
DU002213	-	NAT207A	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J102749

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU002214	-	NAT205	Asbestos Reinforced plastic pipe sleeve	Chrysotile	Reg 13(1)
DU002215	-	NAT213	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002216	-	NAT213	Bitumen sink pads	No Asbestos Detected	Reg 13(1)
DU002217	-	NAT211A	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002218	-	NAT210B	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002219	-	NAT210B	Asbestos Reinforced plastic downpipe	Chrysotile	Reg 13(1)
DU002220	-	NAT299 Corridor	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002221	-	NAT299 Corridor	Asbestos Reinforced plastic downpipes	Chrysotile	Reg 13(1)
DU002222	-	NAT199B	Asbestos Reinforced plastic downpipe	Chrysotile	Reg 13(1)
DU002223	-	NAT101A	Asbestos Reinforced plastic sleeve	Chrysotile	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J102749

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU002224	-	NAT101A	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002225	-	NAT104B	Bitumen adhesive to parquet	No Asbestos Detected	Reg 13(1)
DU002226	-	NAT138	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002227	-	NAT137	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in tile and adhesive	Reg 13(1)
DU002229	-	NAT136	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002230	-	NAT134 Service Duct	Asbestos Cement flue	Chrysotile	Reg 13(1)
DU002231	-	NAT134 Service Duct	Asbestos Textile joint seal to metal ducting	Chrysotile	Reg 13(1)
DU002232	-	NAT106A	Asbestos Reinforced plastic sleeve	Chrysotile	Reg 13(1)
DU002233	-	NAT107	Asbestos Thermoplastic floor tiles	Chrysotile in tile and adhesive	Reg 13(1)
DU002234	-	NAT129	Asbestos Thermoplastic floor tiles	Chrysotile in tile and adhesive	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J102749

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU002235	-	NAT128	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002236	-	NAT199D	Asbestos Thermoplastic floor tiles	Chrysotile in tile and adhesive	Reg 13(1)
DU002237	-	NAT110B	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002238	-	NAT125	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002239	-	NAT123	Asbestos Thermoplastic floor tiles	Chrysotile in tile and adhesive	Reg 13(1)
DU002240	-	NAT121	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002241	-	NAT121	Textured coating to blockwork	No Asbestos Detected	Reg 13(1)
DU002242	-	NAT111	Asbestos Vinyl tiles with bitumen adhesive to concrete	Chrysotile	Reg 13(1)
DU002243	-	NAT118B	Textured coating	No Asbestos Detected	Reg 13(1)
DU002244	-	NAT113B	Asbestos Thermoplastic floor tiles	Chrysotile in tile and adhesive	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J102749

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU002245	-	NAT115	Asbestos Reinforced plastic sleeve	Chrysotile	Reg 13(1)
DU002246	-	NAT114	Asbestos Bitumen adhesive	Chrysotile	Reg 13(1)
DU002247	-	NAT116	Asbestos Reinforced plastic downpipe	Chrysotile	Reg 13(1)
DU002248	-	NAT114A	Asbestos Thermoplastic floor tiles	Chrysotile in tile and adhesive	Reg 13(1)
DU002249	-	NAT113G	Asbestos Thermoplastic floor tiles	Chrysotile in tile and adhesive	Reg 13(1)
DU002250	-	NAT199A	Asbestos Textile rope seal to metal ducting	Chrysotile	Reg 13(1)
DU002251	-	NAT199A	Asbestos Reinforced plastic downpipe	Chrysotile	Reg 13(1)
DU002603	-	NAT041B	Insulating board ceiling tiles	No Asbestos Detected	Reg 13(1)
DU002604	-	NAT041C	Insulating board ceiling tiles	No Asbestos Detected	Reg 13(1)
DU002605	-	NAT040A	Asbestos Reinforced plastic sleeve	Chrysotile	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J102749

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU002606	-	NAT047	Insulating board ceiling tiles	No Asbestos Detected	Reg 13(1)
DU002607	-	NAT042	Asbestos Thermoplastic floor tiles with bitumen adhesive	Chrysotile in adhesive only	Reg 13(1)
DU002608	-	NAT036	Textured coating to plaster to block wall	No Asbestos Detected	Reg 13(1)
DU002609	-	NAT036	Asbestos Reinforced plastic downpipe	Chrysotile	Reg 13(1)
DU002610	-	NAT036	Asbestos Compressed fibre gasket	Chrysotile	Reg 13(1)
DU002611	-	NATG00A	Insulating board door header	No Asbestos Detected	Reg 13(1)
DU002612	-	NAT044	Insulating board door header	No Asbestos Detected	Reg 13(1)
DU002613	-	NAT044	Bitumen adhesive	No Asbestos Detected	Reg 13(1)
DU002614	-	NAT002	Textured coating to concrete	No Asbestos Detected	Reg 13(1)
DU002615	-	NAT00B	Modern vinyl to bitumen adhesive	No Asbestos Detected	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J102749

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU002616	-	NAT009	Asbestos Reinforced plastic downpipe	Chrysotile	Reg 13(1)
DU002617	-	NAT009	Textured coating to concrete pillar	No Asbestos Detected	Reg 13(1)
DU002618	-	NAT009	Bitumen adhesive	No Asbestos Detected	Reg 13(1)
DU002619	-	NAT029	Bitumen adhesive	No Asbestos Detected	Reg 13(1)
DU002620	-	NAT010	Bitumen sink pad	No Asbestos Detected	Reg 13(1)
DU002621	-	NAT010	Bitumen adhesive	No Asbestos Detected	Reg 13(1)
DU002622	-	NAT012	Bitumen sink pad	No Asbestos Detected	Reg 13(1)
DU002623	-	NAT012E	Asbestos Thermoplastic floor tiles	Chrysotile in tile and adhesive	Reg 13(1)
DU002624	-	NAT025B	Asbestos Reinforced plastic downpipe	Chrysotile	Reg 13(1)
DU002625	-	NAT015	Bitumen adhesive	No Asbestos Detected	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
 20 Stourbridge Road,
 Halesowen, West Midlands
 B63 3US
 Tel: 0121 550 0224 Fax: 0121 550 0641
 Email: sales@bradley-enviro.co.uk



Opinions and interpretations including the sample reference are outside the scope of UKAS accreditation

Report No.: J102749

Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
DU002626	-	NAT016	Thermoplastic floor tiles	No Asbestos Detected in tile no adhesive present	Reg 13(1)
DU002627	-	NAT023	Asbestos Reinforced plastic downpipes	Chrysotile	Reg 13(1)
DU002628	-	NAT099K	Thermoplastic floor tiles	No Asbestos Detected in tile or adhesive	Reg 13(1)
DU002629	-	NAT099D	Insulating board upstand and ceiling	No Asbestos Detected	Reg 13(1)
DU002630	-	NAT EXT	Insulating board door header	No Asbestos Detected	Reg 13(1)
DU002631	-	NAT002A	Insulating board ceiling panels	No Asbestos Detected	Reg 13(1)
DU002632	-	NAT EXT	Asbestos Cement cowl	Chrysotile	Reg 13(1)

TEST NOTES: The test method is as described in the in-house method (Appendix 7, Quality Manual), based on HSG248. "Crocidolite", "Amosite" and "Chrysotile" are more commonly known as "blue", "brown" and "white" asbestos respectively. "Actinolite", "Anthophyllite" and "Tremolite" are other rarer forms of asbestos. Bradley Environmental Consultants Limited is not responsible for sampling errors where the sample is provided by yourselves. Materials that have been referred to as Asbestos Insulating Board or Asbestos Cement are based on their asbestos content and visual appearance alone (these opinions are not covered by our UKAS accreditation), water absorption tests have not been carried out unless otherwise stated. The report should not be reproduced except in full, without written approval of the laboratory.

Analysed at:

Head Office:
20 Stourbridge Road,
Halesowen, West Midlands
B63 3US

Tel: 0121 550 0224 Fax: 0121 550 0641

Email: sales@bradley-enviro.co.uk

END OF REPORT



Report No.: J102749
Issue Date: 02/11/2018



9.0 Intrusion Photographs

Please note that the intrusion numbers in this section may not run consecutively.

Intrusion 01 - Foil tape glass fibre insulation to copper pipework




Intrusion 02



Intrusion 03



Intrusion 04



Intrusion 05




Intrusion 06



Intrusion 07 - Plasterboard surround to service duct



Intrusion 08



Intrusion 09 - Ceiling void



Intrusion 10 - Riser



Intrusion 11 - Ceiling void




Intrusion 12



Intrusion 13




Intrusion 14



Intrusion 15 - Timber panel above link corridor doors



Intrusion 16



Intrusion 17



Intrusion 18 - Plasterboard boxing to metal ducting



Intrusion 19 - Cork expansion joint to external wall



Intrusion 20



Intrusion 21



Intrusion 22



Intrusion 23 - Cork expansion joint



Intrusion 24 - Chicken wire to glass fibre insulation to metal pipework



Intrusion 25 - Carpet tiles to concrete




Intrusion 26 - Plywood thick set door



Intrusion 27



Intrusion 28 - Timber boxing to plastic pipework



Intrusion 29 - Insulating board ceiling tiles to straw board



Intrusion 30



Intrusion 31



Intrusion 32 - Cement flue pipe removed sampled to floor above



Intrusion 33



Intrusion 34



Intrusion 35 - Timber panel to modern electrics



Intrusion 36



Intrusion 37



Intrusion 38 - Cork expansion joint




Intrusion 39



Intrusion 40 - Metal panels to foam to underside of external windows



Intrusion 41



10.0 Risk Assessment Algorithms

Once an asbestos item has been identified, Regulation 4 of CAR2012 requires that a risk assessment be undertaken on the material. The risk assessment contained within this report is based on the **material assessment algorithm**, as defined in HSG264, and the **likelihood of disturbance algorithm** which is *part* of the priority assessment as defined in HSG227.

The score for each assessment is added together to provide an **overall risk rating** based on the material's ability to release airborne fibre *and* the risk of it being disturbed. This overall risk category is shown in section 10.3.

10.1 Material Assessment

The material assessment algorithm provides a numerical indication of the ability of an ACM to release airborne asbestos fibre, if disturbed. A risk category score of between 2 and 12 is assigned to each ACM as shown below:

- < 5 Very low hazard
- 5 & 6 Low hazard
- 7 - 9 Medium hazard
- > 9 High hazard

The table below shows how the individual material assessment scores are calculated:

	SCORE 0	SCORE 1	SCORE 2	SCORE 3
Product type		Composite materials, reinforced plastics, felts, textured coating and asbestos cement (AC) products	Low density boards (i.e. AIB), gaskets, textiles	Sprays, insulation, loose asbestos, mattresses and packing
Extent of damage/deterioration	Good condition: no visible damage	Low damage: a few scratches or damaged edges	Medium damage: significant breakage of materials or several small areas of damage revealing loose fibres	High damage or delamination of materials, sprays and insulation. Visible asbestos debris
Surface treatment	Composite materials, reinforced plastics, textured coating, felts etc	Painted, encapsulated AIB & AC. Enclosed AIB, AC, sprays & lagging, Unencapsulated AC	Unencapsulated AIB. Encapsulated sprays and insulation	Unencapsulated sprays and insulation
Asbestos type		Chrysotile	Amphibole asbestos excluding crocidolite	Crocidolite

10.2 Likelihood of Disturbance Assessment

The likelihood of disturbance algorithm provides a numerical value which helps assess how likely an ACM is to be disturbed.

The following table has been extracted from HSG227 (A comprehensive guide to Managing Asbestos in premises):

SAMPLE VARIABLE	SCORE	EXAMPLES OF SCORES
LOCATION	0	Outdoors
	1	Large rooms or well ventilated areas
	2	Rooms up to 100 sq. m
	3	Confined spaces
ACCESSIBILITY	0	Usually inaccessible or unlikely to be disturbed
	1	Occasionally likely to be disturbed
	2	Easily disturbed
	3	Routinely disturbed
EXTENT/AMOUNT	0	Small amounts or items (i.e. strings, gaskets etc)
	1	<10 sq m or < 10 linear metre pipe run
	2	>10 - <50 sq m or >10m - <50 linear metre pipe run
	3	>50 sq m or >50 linear metre pipe run

10.3 Overall Risk Category

It is recommended that where practicable to do so, the Dutyholder aims to reduce the risk associated with all ACMs to a grade C (low) or D (very low).

Risk Category	Risk	Score Range	Comments and Recommendations
A	High	16+	<p>It is very likely that crumbly loose asbestos may be disturbed releasing a significant quantity of fibres.</p> <p>Plans for urgent remedial work, including possible removal, are required and access to the area should be limited to adequately trained personnel.</p>
B	Medium	11-15	<p>Fibres may be released if the material is further damaged or disturbed.</p> <p>A programme of remedial work (which may include removal) should be planned. Until then, some emergency repairs may be required.</p> <p>The material's condition should be monitored periodically.</p>
C	Low	7-10	<p>Little likelihood of fibres being released under normal conditions, either because of the location of the materials or because the type of material present will only release very low levels of fibres.</p> <p>Immediate work is not needed and any removal can be planned with a suitable timescale. The material should be inspected and assessed at suitable intervals (at least annually).</p>
D	Very Low	<7	<p>Little likelihood that fibres will be released. The material will only need removal if serious damage/deterioration is detected in the future.</p> <p>The material should be inspected and assessed at suitable intervals (at least annually).</p>
E	No asbestos detected	0	No asbestos detected

DISCLAIMER

Bradley Environmental Consultants Ltd have undertaken surveying, sampling and analysis following in-house documented methods, which involve systematic access, inspection and reporting. It is not possible to guarantee that all asbestos will be located within a specified site and we accept no financial or other responsibility for remedial works or disruption to programmes which may occur as a result of asbestos materials being located which are *outside the scope of this survey*.

The survey report should not be reproduced except in full without the approval of the client and Bradley Environmental Consultants Ltd.

Bradley Environmental - Additional Services

Since 1991, Bradley Environmental Consultants have provided a full range of asbestos management services to a wide range of clients including local authorities, hospital trusts and large commercial businesses. A summary of the asbestos related services we are able to offer include the following:

- Management asbestos surveys;
- Refurbishment & demolition asbestos surveys;
- Preparation of Asbestos Management Plans;
- Labelling programmes;
- Cost-effective remedial advice;
- Preparation of removal specifications;
- Evaluation & selection of licensed asbestos removal contractors;
- Preparation of tender documentation;
- Assessment and critical evaluation of method statements;
- Air monitoring during asbestos removal projects;
- Issuing certificates of re-occupation following asbestos removal works;
- Annual re-inspection of ACMs to update the asbestos register;
- Asbestos removal project management.

If you would like any further information regarding your survey, the implementation of a suitable management plan, or any other asbestos-related issue, please do not hesitate to contact us.

Birmingham: (Head Office)	0121 550 0224	Reg 13(1)Reg 13(1)Reg 13(1)Reg 13(1)
Wakefield: (Northern Office)	01924 274 777	Reg 13(1)
Blackpool: (North West Office)	01253 405 396	Reg 13(1)Reg 13(1)
St Asaph: (North Wales Office)	01745 585 587	Reg 13(1)