## **ACCIDENT**

Aircraft Type and Registration: Jodel DR250/160, G-BUVM

**No & Type of Engines:** 1 Lycoming O-320-D2A piston engine

**Year of Manufacture:** 1966 (Serial no: 54)

**Date & Time (UTC):** 11 August 2020 at 1900 hrs

**Location:** Crosland Moor Airfield, Huddersfield, West

Yorkshire

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - 1

**Injuries:** Crew - 1 (Serious) Passengers - None

Nature of Damage: Extensive damage

Commander's Licence: Other

Commander's Age: 59 years

**Commander's Flying Experience:** 464 hours (of which 159 were on type)

Last 90 days - 3 hours Last 28 days - 2 hours

**Information Source:** Aircraft Accident Report Form submitted by the

pilot

The pilot was flying this tail-dragger aircraft with its co-owner to increase his currency and proficiency after a period of reduced flying activity due to public health restrictions. The flight had been uneventful, and the choice of Runway 25 for landing considered a 5 kt tailwind, upslope, and a hedge before the threshold of the reciprocal runway.

The pilot reported that they encountered buffeting and windshear at about 50 ft, which he attributed to an adjacent quarry¹. He thought that the flare was normal, but the aircraft slewed left in the turbulent air and he overcorrected using right rudder. He reported that "subsequent oscillations required full rudder deflection with braking" and the aircraft departed the right side of the runway onto the grass. The right wing struck a metal gate post approximately eight feet from a raised embankment at the airfield perimeter, and the aircraft came to rest inverted. The passenger sustained serious injuries, but both occupants were able to exit through the left cockpit window, which had broken.

The pilot cited that the tail wind conditions during the approach, along with the local topography, combined with the lack of recent flying practice were factors that led to the accident.

## Footnote

Pooleys Flight Guide 2019 includes a warning to expect turbulence on approach to Runway 25 from quarry working to the north of the airfield.