October 2023



# Air Quality and Dust Monitoring Monthly Report - October 2023

London Borough of Camden

© HS2 Ltd. gov.uk/hs2



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2021, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/ version/2 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Printed in Great Britain on paper containing at least 75% recycled fibre.

# **Monthly Summary**

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in the London Borough of Camden (LBC) during September 2023 and October 2023 respectively.
- 1.1.2 Figure 1 to Figure 5 in Appendix A present the current worksites together with air quality and dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from <a href="www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2">www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2</a>, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites, as presented in Appendix A, Figure 1 to Figure 5, include:

# Skanska Costain Strabag Joint Venture (SCSjv)

## Adelaide Road Vent Shaft

- Piling operations; and
- Groundworks.

# **Euston Scissor Cut**

- Limited groundworks;
- Piling operations; and
- Materials management.

#### **Euston Throat Retained Cut**

- Limited groundworks;
- Piling operations; and
- Materials management.

## Hampstead Road Bridge

Utilities diversion works.

### **Euston Cavern**

- Limited groundworks; and
- Materials management.

## **Mace Dragados Joint Venture (MDjv)**

#### TSS

- Roof access hatches install
- Kemwell riser works began
- Riser 1 completed
- Hammerhead completed
- Screeded all major rooms completed
- Only stair landings remaining
- Byrne bros scabbling and making good on the slipform finish

#### Maria Fidelis

- Completed handover of CSC to Camden all external & internal works completed including tarmac, hoarding and fitout
- Continue MEP 1<sup>st</sup> & 2<sup>nd</sup> fix L1-5
- Continue tape & joint L1-5
- Continue doors install L1-5
- Continue flooring works L1 & L2

# Maria Fidelis Old School

- Continue asbestos removal set up
- Continue lighting install

#### Utilities

- MH11 completed excavation works and precast segment rings construction; poured concrete base slab; fixed supporting needle beams and TBM breakthrough on October 31
- MH10 1500mm tunnel drive
- MH9 commenced excavation and exposure of the crown of the existing egg-shaped brick sewer
- MH5-MH8 (Cobourg Street) excavation and DN1000 &250PE pipes install
- MH3 excavation and TW ground support install


# <u>ITR</u>


- Emico electrical testing & maintenance.
- Emico signage set up adjustments to new positions.
- Delta Install anti bug screens to all canopy gaps EPDM & brushes.
- Delta canopy inspection covers & signage fit anti blast tethers.
- Blu3 Stephenson way excavate damaged cobbles & subbase prep.
- Blu3 Upper Woburn place TM set up for VMS NAL socket install.
- Stephenson way base blinding & cobbles reinstatement.
- Stephenson way hydroblasting old road markings & repaint & clear TM.
- Melton Street remove paving & prep for new tarmac walkway.
- Melton Street lay tarmac base followed day after with wear coat to complete new footpath route.


- 1.1.5 Twenty-Two (22) dust monitors are installed around these worksites, where works are underway. These sites returned a medium to high dust risk rating.
- 1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor in Figure 6. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.7 The trigger level for  $PM_{10}$  concentrations of 190  $\mu$ g/m<sup>3</sup>, over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018)' has been applied.
- 1.1.8 Details of the trigger alerts investigations and remediations are presented in Appendix B, Table 2.
- 1.1.9 Data capture was below 90% for multiple monitors. AQ054 had power loss to the CCTV column on which the monitor is mounted. AQ012 had a blockage in the monitor. There was a power failure at the lamppost which supplies power to the AQ007 monitor. AQ021 had a possible fault with the monitor, this is being investigated.
- 1.1.10 Diffusion tube monitoring of Nitrogen Dioxide (NO<sub>2</sub>) is undertaken at sixty-four (64) locations around highways within the LBC as part of the management of air quality where significant effects may occur as a result of the scheme.
- 1.1.11 Diffusion tube monitoring results are as provided from the laboratory analysis, and therefore still require various analysis and adjustments to be undertaken. Final corrected results will be presented and described in the annual report. However, based on the results to date, no unexpected values were recorded during the monitoring period.
- 1.1.12 NO<sub>2</sub> monitoring locations and results are presented in Appendix C, Table 3, together with the 2023 running mean.
- 1.1.13 There were no (0) complaints received during the reporting period (October 2023).


# **Appendix A - Worksites and Monitoring Locations**


Figure 1 to Figure 5: Worksites and monitoring locations within the LBC











# **Appendix B - Dust Monitoring Results**


Table 1: Dust Monitoring Locations and Results


Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM <sub>10</sub> concentration (μg/m³)	Minimum 1- hour PM <sub>10</sub> concentration (μg/m³)	Maximum 1- hour PM <sub>10</sub> concentration (μg/m³)	Number of 1- hour periods exceeding trigger level of 190 µg/m³	Data capture (%)
AQ001	529016, 183049	Junction of Park Village East, Stanhope Street and Granby Terrace	М	Yes	N	11.9	0.9	60.0	0	100.0
AQ002	528924, 183130	Park Village East	М	Yes	N	10.4	0.7	95.4	0.0	100.0
AQ003	529273, 182698	St James' Gardens	М	Yes	N/A	7.6	0.8	117.8	0	100.0
AQ004	529533, 182519	Melton Street	Н	Yes	N/A	5.6	0.4	27.2	0	100.0
AQ005	529498, 182502	Stephenson Way	Н	Yes	N/A	24.1	0.5	471.0	1	100.0
AQ006	529388, 182524	Euston Street	Н	Yes	N/A	6.3	0.5	32.3	0	100.0
AQ007	529361, 182574	Drummond Street	Н	Yes	N/A	8.8	0.6	39.4	0	71.5
AQ008	529372, 182657	Cobourg Street	Н	Yes	N/A	19.7	1.1	600.5	1	99.6
AQ009	529707, 182730	Eversholt Street	Н	Yes	N/A	12.2	0.9	184.7	0	100.0
AQ010	529223, 182746	Hampstead Road South	М	Yes	N/A	12.9	1.2	60.7	0	100.0
AQ011	529176, 182922	Hampstead Road	М	Yes	N	12.8	0.1	85.5	0	91.5


Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM <sub>10</sub> concentration (μg/m³)	Minimum 1- hour PM <sub>10</sub> concentration (μg/m³)	Maximum 1- hour PM <sub>10</sub> concentration (µg/m³)	Number of 1- hour periods exceeding trigger level of 190 µg/m³	Data capture (%)
AQ012	529144, 182941	Rear of Coniston House	М	Yes	N	12.6	2.0	65.1	0	84.9
AQ013	529066, 182990	Regents Park Estate	М	Yes	N	9.3	0.7	43.0	0	100.0
AQ016	528820, 183498	Mornington Terrace North	М	Yes	N	9.9	1.2	44.7	0	100.0
AQ017	528962, 183274	Mornington Terrace South	М	Yes	N	9.0	0.6	41.7	0	100.0
AQ018	529192, 183071	Hampstead Road North	М	Yes	N	10.1	0.9	49.8	0	100.0
AQ019	528689, 183500	Park Village East (North)	М	Yes	N	11.1	1.0	131.2	0	99.9
AQ020	529109, 182605	Netley School	n/a	Yes	N/A	12.2	1.0	56.3	0	100.0
AQ021	529136, 183086	Site compound at the Junction of Hampstead Road & Granby Terrace Bridge	М	Yes	N	23.2	0.5	95.9	0	85.2
AQ044	527725, 184369	Adelaide Road 1	М	Yes	N	16.1	1.3	134.9	0	100.0
AQ045	527826, 184375	Adelaide Road 2	М	Yes	N	18.5	1.3	131.1	0	99.9
AQ054	529266, 183076	Ampthill Estate, Hampstead Road	М	Yes	N	No data	No data	No data	No data	No data


Table 2: Summary of exceedances during period (October 2023)


Monitoring site ID	Period exceeding trigger level	Investigation	Outcomes / Resolution / Remedial measures implemented
AQ005	27/10/2023 20:00 – 20:59; 471.0 μg/m³	Hydroblasting was undertaken directly underneath the air quality monitor to remove the line markings on the street.	Equipment will not be used in this area again.  Mitigation was also implemented prior to the activity being undertaken to help minimise dust emissions, i.e. cleaning of the area.
AQ008	09/10/2023 08:00 – 08:59; 600.5 μg/m <sup>3</sup>	Produced by Utilities works, excavating the area adjacent to the monitor for the water main installation.	The activity was stopped and water suppression was implemented before continuing with the works. No further exceedances were monitored at this monitor for these works after this action was taken.














# **Appendix C - Air Quality Monitoring Results**

Table 3: NO₂ monitoring locations around highways, NO₂ concentrations and monthly monitoring results with running mean for 2023 (µg/m³)

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
HS2- 000020BM5	Junction of St Chad's Street and Grays Inn Road	530436, 182929	45	46	37	40	36	36	30	35	42				39
HS2- 000020BM7	Chalton Street	529894, 182702	50	53	48	41	36	30	33	31	45				41
HS2- 000020BM8	Junction of Euston Square and Grafton Place	529737, 182641	48	62	41	Tube Missing	42	43	38	37	50				45
HS2- 000020BM9	Junction of Endsleigh Gardens and Upper Woburn Place	529785, 182529	43	50	25	47	49	46	31	36	49				42
HS2- 000020BMA	Junction of Euston Road and Gower Street	529429, 182375	51	59	37	Tube Missing	37	34	34	32	46				41
HS2- 000020BMB	Whitfield Street	529273, 182114	38	43	33	33	29	30	21	24	32				31
HS2- 000020BMC	Hampstead Road	529232, 182511	56	69	63	52	52	53	47	44	69				56
HS2- 000020BMF	Junction of Polygon Road and Ossulston Street	529715, 183123	36	34	24	28	30	Tube Missing	18	18	33				28
HS2- 000020BMH	Nash Street	528861, 182717	37	30	24	24	21	20	21	21	30				25

<sup>&</sup>lt;sup>1</sup> Note: to aid interpretation and conform with best practice, the monthly measurements in this table are reported rounded to the nearest whole number. The annual mean presented here is calculated based on laboratory data to 4 significant figures, rounded to a whole number, and therefore may differ slightly to a mean derived from averaging the rounded monthly measurements in the table.

Monitoring	Location	Coordinates	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
Site ID	description	(X, Y)	Juli	100	IVIGI	Aþi	way	Juli	Jui	Aug	ЗСР	Oct	1404	Dec	Wican
HS2- 000020BMJ	Junction on Robert Street and Stanhope Street	529080, 182698	37	37	14	29	25	25	20	20	42				27
HS2- 000020BMK	Junction of Plender Street and Bayham Street	529196, 183546	47	52	38	40	38	38	34	38	37				40
HS2- 000020BML	Junction of Arlington Road and Mornington Crescent	529093, 183356	35	37	Tube Missing	26	25	25	18	21	28				27
HS2- 000020BMM	Junction of Bayham Street and Pratt Street	529084, 183722	57	59	35	39	32	48	38	39	49				44
HS2- 000020BMN	Junction of Delancey Street and Albert Street	528850, 183573	41	46	23	24	21	24	25	24	31				29
HS2- 000020BMQ	Junction of Parkway and Delancey Street	528662, 183604	42	42	30	Tube Missing	35	34	26	28	45				35
HS2- 000020BMR	Junction of Oval Road and Jamestown Road	528548, 183967	32	38	27	28	25	24	18	21	28				27
HS2- 000020BMS	Junction of Chalk Farm Road and Castlehaven Road	528685, 184188	43	45	36	35	38	35	30	32	43				37
HS2- 000020BMT	Junction of Camden Road and Camden Street	529079, 184043	48	50	31	38	40	34	28	29	40				38
HS2- 000020BMU	Junction of Southampton Road and Fleet Road	527783, 185407	44	45	38	36	33	35	27	29	41				36
HS2- 000020BMV	Primrose Hill Road	527538, 184250	35	44	29	25	25	25	17	20	27				27

Monitoring	Location	Coordinates	la	r.b	M				11		C	0-4	New	Des	1
Site ID	description	(X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
HS2- 000020BMW	Junction of Finchley Road and Hilgrove Road	526619, 184081	Tube Missing	50	33	41	42	43	34	40	66				44
HS2- 000020BMZ	Junction of Finchley Road and Hendon Way	525102, 186042	71	67	53	62	53	60	40	49	62				57
HS2- 000020BNA	Junction of Regent's Park Road and Rothwell Street	527884, 183980	36	37	25	25	19	19	16	21	30				25
HS2- 000020BNC	Junction of Outer Circle and Gloucester Gate	528528, 183443	27	27	21	21	21	21	Tube Missing	16	22				22
HS2- 000020BNH	Junction of Parkway and Albert Street	528763, 183720	32	40	30	29	27	Tube Missing	20	21	30				29
HS2- 000020BNN	Lincoln's Inn Fields	530744, 181308	36	36	24	Tube Missing	21	20	23	23	31				27
HS2- 000020BNQ	Camley Street	529735, 183737	25	41	26	29	24	23	21	20	32				27
HS2- 000020BNY	Junction of Mill Lane and Hillfield Road	524839, 185136	35	32	Tube Missing	32	Tube Missing	Tube Missing	25	30	38				32
HS2- 000020BNZ	Mansfield Road	528050, 185508	40	44	27	23	19	25	28	25	34				29
HS2- 000020BP0	Junction of Camden Road and Torriano Avenue	529708, 184871	46	56	42	43	40	40	36	40	50				44
HS2- 000020BP2	Junction of Grays Inn Road and Holborn	531149, 181616	41	40	32	30	27	25	25	28	33				31
HS2- 000020BPB	Camden High Street	528966, 183735	60	65	40	49	50	47	47	Tube Missing	64				53
HS2- 000020BPC	Castlehaven Road	528788, 184591	39	39	30	26	21	Tube Missing	Tube Missing	22	27				29

Monitoring	Location	Coordinates								•		0.1			1
Site ID	description	(X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
HS2- 000020BPD	Prince of Wales Road	528571, 184683	31	35	16	27	19	17	14	17	23				22
HS2- 000020BPE	Haverstock Hill	527710, 184749	36	39	27	24	22	Tube Missing	24	25	36				29
HS2- 000020BPF	Junction of Primrose Gardens and England's Lane	527549, 184640	42	42	33	27	25	27	22	24	35				31
HS2- 000020BPU	Junction of Gower Street and Grafton Way	529476, 182267	51	47	36	Tube Missing	34	30	29	31	39				37
HS2- 000020BPW	Junction of Delancey Street and Arlington Road	528939, 183637	40	45	30	28	26	28	23	25	34				31
HS2- 000020BPX	Netley Street	529177, 182625	32	Tube Missing	21	31	30	27	18	20	33				27
HS2- 000020BPY	Stanhope Street	529060, 182947	31	37	19	25	19	19	Tube Missing	16	20				23
HS2- 000020BPZ	Albany Street	528790, 182923	27	40	25	27	25	22	18	22	33				26
HS2- 000020BQ0	Werrington Street	529493, 183113	34	35	19	24	20	19	16	18	Tube Missing				23
HS2- 000020BQ1	Polygon Road	529574, 183045	30	36	22	25	23	19	17	19	28				24
HS2- 000020BQ2	Alexandra Place	526320, 183980	32	35	23	24	20	22	16	20	25				24
HS2- 000020BQ3	Harrington Square	529228, 183172	42	38	26	33	41	31	24	28	38				33
HS2- 000020BQ4	Junction of North Gower Street and Starcross Street	529290, 182572	43	41	28	26	27	23	21	20	30				29
HS2- 000020BQ5	Adelaide Road	527713, 184392	35	41	17	Tube Missing	25	23	24	23	30				27
HS2- 000020BQ6	Mornington Terrace	528836, 183474	34	34	26	25	22	21	18	18	27				25

Monitoring	Location	Coordinates	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
Site ID	description	(X, Y)	Jan	ren	IVIAI	Aþi	iviay	Juli	Jui	Aug	Sep	OCT	INOV	Dec	Weari
HS2- 000020BQ7	Arlington Road	529009, 183479	33	35	24	25	Tube Missing	Tube Missing	16	16	22				24
HS2- 000020BQ8	Clarkson Row	529024, 183213	39	39	25	25	Tube Missing	20	17	18	27				26
HS2- 000020BQ9	Park Village East	528923, 183121	30	33	17	22	20	18	17	19	26				22
HS2- 000020BQA	Eversholt Street	529386, 183132	52	45	34	38	35	37	35	36	46				40
HS2- 000020BQB	Junction of Harrington Street and Varndell Street	529147, 182816	30	34	27	24	21	21	16	17	25				24
HS2- 000020BQC	Junction of Robert Street and Hampstead Road	529199, 182704	40	40	33	25	34	27	21	22	32				30
HS2- 000020BQD	Drummond Crescent	529648, 182856	38	33	Tube Missing	Tube Missing	31	30	24	23	36				31
HS2- 000020BQJ	Grafton Way	529380, 182225	56	56	38	34	36	33	36	34	38				40
HS2- 000020BQL	Delancey Street	528768, 183581	46	50	Tube Missing	34	31	39	22	26	40				36
HS2- 000020BQR	Lamp post on Park Village East	528682, 183505	36	40	26	29	Tube Missing	Tube Missing	Tube Missing	Tube Missing	Tube Missing				33
HS2- 000020BQS	Opposite Maria fidelis school on Phoenix Road	529670, 182982	37	36	25	26	23	23	17	Tube Missing	29				27
HS2- 000020BQT	Drummond Street	529385, 182581	42	46	29	31	28	25	19	23	32				30
HS2- 000020BQX	Lamp post on Brunswick Square	530344, 182236	44	46	32	30	24	21	23	25	30				31
HS2- 000020BP4	Triplicate site on Finchley Road next to Swiss Cottage kerbside automatic monitoring station	526633, 184392	51	54	45	42	47	40	32	38	47				44

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>1</sup>
HS2- 000020BP5	Triplicate site next to the Euston Road roadside automatic monitoring stations	529895, 182657	46	64	59	Tubes Missing	59	59	53	49	72				58
HS2- 000020BP9	Triplicate site in Russell Square next to Bloomsbury urban background automatic monitoring station	530120, 182034	39	40	30	30	27	21	16	19	26				28