Product Safety Report

Shimano Hollowtech 11 speed Crank Arms for bicycles	
Aspect	Details
Images	Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image: Window Stress Image:
Alert Number	2309-0122
Product	Hobby / sports equipment - Bicycle cranksets
Туре	Brand: Shimano DURA ACE and ULTEGRA
Product Identifiers	Affected models: FC-6800 – ULTEGRA, FC-9000 - DURA-ACE, FC-R8000 - ULTEGRA, FC-R9100 - DURA-ACE, FC-R9100P - DURA-ACE Sales period: 2012 to 30 June 2019 Affected production codes: KF, KG, KH, KI, KJ, KK, KL, LA, LB, LC, LD, LE, LF, LG, LH, LI, LJ, LK, LL, MA, MB, MC, MD, ME, MF, MG, MH, MI, MJ, MK, ML, NA, NB, NC, ND, NE, NF, NG, NH, NI, NJ, NK, NL, OA, OB, OC, OD, OE, OF, OG, OH, OI, OJ, OK, OL, PA, PB, PC, PD, PE, PF, PG, PH, PI, PJ, PK, PL, QA, QB, QC, QD, QE, QF, QG, QH, QI, QJ, QK, QL, RA, RB, RC, RD, RE and RF
Product Description	Five models of bicycle crank arms.
Country of Origin	Japan
Counterfeit	Genuine
Risk Type	Injuries
Risk Level	Medium
Risk Description	The product presents a risk of injuries as it has been identified that the outer cover of the crank arm may start to separate from the main crank arm body, posing potential fall and injury hazards to consumers. The affected products do not meet the requirements of the General Product Safety Regulations 2005.
Corrective Measures	Modification programme. Owners of affected bicycles should immediately stop using the product and contact an authorised Shimano dealer for the product to be inspected. Shimano Europe has established an inspection and replacement programme. If a crank arm fails inspection, Shimano Europe will provide a replacement of





	equal or greater value than the previous crank arm, at Shimano Europe's sole expense. Users should consult the consumer notice to check whether the inspection programme applies to their crank set. Further information on the corrective action can be found in the consumer notice at the following link: <u>https://bike.shimano.com/en-EU/information/customer-services/corrective-actions/important-safety-notice-11-speed-hollowtech-road-cranksets-inspection-program.html</u>
Online Marketplace	N/A
Notifier	Office for Product Safety and Standards.