July 2024



Air Quality and Dust Monitoring Monthly Report - July 2024

London Borough of Camden

© HS2 Ltd. gov.uk/hs2



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2024, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/ version/2 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in the London Borough of Camden (LBC) during June 2024 and July 2024 respectively.
- 1.1.2 Figure 1 to Figure 5 in Appendix A present the current worksites together with air quality and dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites, as presented in Appendix A, Figure 1 to Figure 5, include:

Skanska Costain Strabag Joint Venture (SCSjv)

Adelaide Road Vent Shaft

Works currently paused until April 2025.

Euston Scissor Cut

- Limited groundworks;
- Concrete works; and
- Materials management.

Euston Throat Retained Cut

- Limited groundworks;
- Concrete works; and
- Materials management.

Hampstead Road Bridge

Utilities diversion works.

Euston Cavern

- Limited groundworks;
- Concrete works; and
- Materials management.

Mace Dragados Joint Venture (MDjv)

NTH De-mob

• MWU park extension works.

TSS - Delatim

- Back of House works:
- Installing stair nosing to stairs in 4/792.
- 4/986: Gantry and handrails snagging and painting.
- BOH: Blockwork to wall N2
- B3 4/986: Installing durbar plate to ramp. Ramp screed.

TSS - Various locations

- Kemwell works around services.
- Fire stopping around services.
- Core drilling for leaky feeder.
- Installation of permanent fire doors thresholds.
- Installation of permanent signage.
- Stair 1 and Stair 2: Floor painting.
- Stair 1 and Stair 2: Installation of stair nosing.

Byrne Bros

• Stair 1 Level 1: Works for relocation of stairs.

GKR

Scaffolding Tracker works.

Utilities

- Completed TSS duct trench excavation and DOYMA plate was installed
- Completed TSS Gas & Water Main DI1000 combined trench MH11 to MH8 excavation
- External Sites Hampstead Road ongoing cross connection works; ongoing Ph1b (re)commissioning at Robert St & Cumberland Market
- Maria Fidelis MH04 excavation and backfill
- Commenced UKPN trench excavation MH3 area towards MH5.

MF Building

Internal snagging works.

MF Old School

- Continue window install, all floors.
- TEP entrance area, begin groundworks
- Continue fire protection soffit boarding and penetrations.
- Continue roof plant install works.
- Complete riser works, installing lintels and pad stones.

• Begin internal M&E fit out.

ITR


- Set up HARAS slot barriers to accommodate footpath through site
- Strip down cycle racks & remove canopy from south area
- Load cycle racks & canopy components for removal from site & load on the night shift
- Adapt barriers to accommodate slot blocks water ballast tanks
- Pedestrian ramp from road to path level
- Railings being cut off & removed as per design
- Stack & remove railings from site
- Break out cycle rack concrete bases on day & night shift
- Night shift to remove material from south area for muck away
- Break out south path
- Column removal & dig out column bases
- Topsoil delivery to be moved on a night shift after walkway closed
- Excavate a jointing pit for UKPN to spike cables for future RMU removal
- Earthing cable issue as red line drawing & onsite exposure do not match.
- 1.1.5 Twenty-Two (22) dust monitors are installed around these worksites, where works are underway. These sites returned a medium to high dust risk rating.
- 1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor in Figure 6. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.7 The trigger level for PM_{10} concentrations of 190 μ g/m³, over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018)' has been applied.
- 1.1.8 Details of the trigger alerts investigations and remediations are presented in Appendix B, Table 2.
- 1.1.9 Data capture was below 90% for AQ044 due to a fault with the monitor. This has subsequently been repaired.
- 1.1.10 Data recorded as AQ005 was abnormally low during this monitoring period and has therefore been deemed unreliable. The cause of this issue is currently being investigated. In response to this, a new unit has been installed on site.


Air Quality and Dust Monitoring Summary Report, July 2024 London Borough of Camden


- 1.1.11 Diffusion tube monitoring of Nitrogen Dioxide (NO₂) is undertaken at sixty-four (64) locations around highways within the LBC as part of the management of air quality where significant effects may occur as a result of the scheme.
- 1.1.12 Diffusion tube monitoring results are as provided from the laboratory analysis, and therefore still require various analysis and adjustments to be undertaken. Final corrected results will be presented and described in the annual report. However, based on the results to date, no unexpected values were recorded during the monitoring period.
- 1.1.13 NO₂ monitoring locations and results are presented in Appendix C, Table 3, together with the 2024 running mean.
- 1.1.14 There were no (0) complaints received during the reporting period (July 2024).


Appendix A - Worksites and Monitoring Locations


Figure 1 to Figure 5: Worksites and monitoring locations within the LBC











Appendix B - Dust Monitoring Results


Table 1: Dust Monitoring Locations and Results


Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (μg/m³)	Minimum 1- hour PM ₁₀ concentration (μg/m³)	Maximum 1- hour PM ₁₀ concentration (μg/m³)	Number of 1- hour periods exceeding trigger level of 190 µg/m³	Data capture (%)
AQ001	529016, 183049	Junction of Park Village East, Stanhope Street and Granby Terrace	М	Yes	N	8.5	1.7	33.2	0	100.0
AQ002	528924, 183130	Park Village East	М	Yes	N	7.8	1.6	23.1	0	100.0
AQ003	529273, 182698	St James' Gardens	М	Yes	N/A	4.8	0.7	48.8	0	98.0
AQ004	529533, 182519	Melton Street	Н	Yes	N/A	12.7	2.4	96.4	0	100.0
AQ005	529498, 182502	Stephenson Way	Н	Yes	N/A	-	-	-	-	0
AQ006	529388, 182524	Euston Street	Н	Yes	N/A	7.8	1.5	29.1	0	100.0
AQ007	529361, 182574	Drummond Street	Н	Yes	N/A	4.7	0.8	36.7	0	100.0
AQ008	529372, 182657	Cobourg Street	Н	Yes	N/A	11.0	1.3	97.7	0	94.5
AQ009	529707, 182730	Eversholt Street	Н	Yes	N/A	17.4	3.3	51.3	0	94.8
AQ010	529223, 182746	Hampstead Road South	М	Yes	N/A	11.3	2.4	62.4	0	94.6
AQ011	529176, 182922	Hampstead Road	М	Yes	N	13.7	2.5	238.4	1	100.0


Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (μg/m³)	Minimum 1- hour PM ₁₀ concentration (µg/m³)	Maximum 1- hour PM ₁₀ concentration (µg/m³)	Number of 1- hour periods exceeding trigger level of 190 µg/m³	Data capture (%)
AQ012	529144, 182941	Rear of Coniston House	М	Yes	N	7.7	1.5	54.5	0	100.0
AQ013	529066, 182990	Regents Park Estate	М	Yes	N	6.7	1.2	22.5	0	99.9
AQ016	528820, 183498	Mornington Terrace North	М	Yes	N	7.6	1.3	77.0	0	100.0
AQ017	528962, 183274	Mornington Terrace South	М	Yes	N	8.5	0.4	283.8	1	98.9
AQ018	529192, 183071	Hampstead Road North	М	Yes	N	7.0	1.4	45.2	0	100.0
AQ019	528689, 183500	Park Village East (North)	М	Yes	N	6.3	1.1	24.8	0	100.0
AQ020	529109, 182605	Netley School	n/a	Yes	N/A	7.1	1.5	17.7	0	100.0
AQ021	529136, 183086	Site compound at the Junction of Hampstead Road & Granby Terrace Bridge	М	Yes	N	8.8	1.6	313.8	1	100.0
AQ044	527725, 184369	Adelaide Road 1	М	Yes	N	6.2	1.2	14.4	0	87.2
AQ045	527826, 184375	Adelaide Road 2	М	Yes	N	7.3	1.5	22.6	0	100.0
AQ054	529266, 183076	Ampthill Estate, Hampstead Road	М	Yes	N	8.5	1.6	22.2	0.0	100.0


Table 2: Summary of exceedances during period (July 2024)


Monitoring site ID	Period exceeding trigger level	Investigation	Outcomes / Resolution / Remedial measures implemented
AQ011	24/07/2024 14:01 – 15:00; 238.4 μg/m ³	At the time of the trigger alert from dust monitor (AQ011), which is located on the southern boundary of the Euston Throat Retained Cut (ETRC) between Cartmel House and Coniston House there was limited material backfilling works underway at a nearby large excavation. The area had been damped down as part of normal activities before the trigger and no excessive dust was observed at the time. Works had already stopped on receipt of the trigger. Over the same period the nearby monitor, AQ012 at the rear of Coniston House, measured no elevated levels.	Dust suppression, using a high-pressure hose was deployed at the time of works and will continue to be available and deployed in the area for the remainder of the works.
AQ017	02/07/2024 08:01 – 09:00; 283.8 μg/m ³	At the time of the exceedance there were no dusty site works taking place near the monitoring location. No notable HS2 works, or Network Rail works on the Mornington Crescent side of the tracks were taking place at that time of the morning. It is considered trigger was false due to a piece of loose debris in the inlet following cleaning.	N/A
AQ021	08/07/2024 09:01 – 10:00; 313.8 μg/m ³	At the time of the exceedance subcontractors were nearby but only limited work below the surface and not dusty. The monitor was serviced and the previous week. It is considered trigger was false due to a piece of loose debris in the inlet following the service	The monitor was serviced and calibrated late June.














Appendix C - Air Quality Monitoring Results

Table 3: NO₂ monitoring locations around highways, NO₂ concentrations and monthly monitoring results with running mean for 2024 (µg/m³)

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹²
HS2- 000020BM5	Junction of St Chad's Street and Grays Inn Road	530436, 182929	44	43	Tube Missing	Tube Missing	26	42							39
HS2- 000020BM7	Chalton Street	529894, 182702	Tube Missing	45	42	31	38	Tube Missing							39
HS2- 000020BM8	Junction of Euston Square and Grafton Place	529737, 182641	Tube Missing	39	35	31	46	43							39
HS2- 000020BM9	Junction of Endsleigh Gardens and Upper Woburn Place	529785, 182529	44	Tube Missing	Tube Missing	Tube Missing	44	33							40
HS2- 000020BMA	Junction of Euston Road and Gower Street	529429, 182375	56	50	37	Tube Missing	Tube Missing	41							46
HS2- 000020BMB	Whitfield Street	529273, 182114	39	35	23	23	30	21							29
HS2- 000020BMC	Hampstead Road	529232, 182511	55	62	57	48	54	47							54
HS2- 000020BMF	Junction of Polygon Road and Ossulston Street	529715, 183123	32	27	29	Tube Missing	24	17							26
HS2- 000020BMH	Nash Street	528861, 182717	34	27	18	18	Tube Missing	20							23

¹ Note: to aid interpretation and conform with best practice, the monthly measurements in this table are reported rounded to the nearest whole number. The annual mean presented here is calculated based on laboratory data to 4 significant figures, rounded to a whole number, and therefore may differ slightly to a mean derived from averaging the rounded monthly measurements in the table.

² The annual mean for diffusion tubes presented in the table above still require various analysis and adjustments to be undertaken before comparison to the Air Quality Objectives. The final corrected annual mean will be presented in the HS2 Annual Air Quality Report.

Monitoring	Location	Coordinates	lan	Feb	Ман	Апи	May	lum	lul.	Aug	Con	Oct	Nov	Dos	Mean ¹²
Site ID	description	(X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	NOV	Dec	wean
HS2- 000020BMJ	Junction on Robert Street and Stanhope Street	529080, 182698	31	31	27	19	25	20							25
HS2- 000020BMK	Junction of Plender Street and Bayham Street	529196, 183546	45	42	37	32	38	33							38
HS2- 000020BML	Junction of Arlington Road and Mornington Crescent	529093, 183356	36	30	25	20	23	18							25
HS2- 000020BMM	Junction of Bayham Street and Pratt Street	529084, 183722	39	Tube Missing	Tube Missing	Tube Missing	41	42							41
HS2- 000020BMN	Junction of Delancey Street and Albert Street	528850, 183573	34	32	29	23	Tube Missing	23							28
HS2- 000020BMQ	Junction of Parkway and Delancey Street	528662, 183604	38	36	39	20	33	29							32
HS2- 000020BMR	Junction of Oval Road and Jamestown Road	528548, 183967	30	28	21	22	23	19							24
HS2- 000020BMS	Junction of Chalk Farm Road and Castlehaven Road	528685, 184188	43	41	Tube Missing	Tube Missing	40	35							40
HS2- 000020BMT	Junction of Camden Road and Camden Street	529079, 184043	46	41	37	31	37	29							37
HS2- 000020BMU	Junction of Southampton Road and Fleet Road	527783, 185407	40	30	34	27	32	31							32
HS2- 000020BMV	Primrose Hill Road	527538, 184250	Tube Missing	31	28	21	24	19							24

Monitoring	Location	Coordinates	la	e.b		0	Mari		11		6	0-4	New	D	Mean ¹²
Site ID	description	(X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	wean.
HS2- 000020BMW	Junction of Finchley Road and Hilgrove Road	526619, 184081	43	45	39	28	41	36							39
HS2- 000020BMZ	Junction of Finchley Road and Hendon Way	525102, 186042	54	54	53	42	57	50							52
HS2- 000020BNA	Junction of Regent's Park Road and Rothwell Street	527884, 183980	29	29	22	18	20	19							23
HS2- 000020BNC	Junction of Outer Circle and Gloucester Gate	528528, 183443	29	22	19	14	20	15							20
HS2- 000020BNH	Junction of Parkway and Albert Street	528763, 183720	33	30	24	23	27	24							27
HS2- 000020BNN	Lincoln's Inn Fields	530744, 181308	23	33	30	21	24	19							25
HS2- 000020BNQ	Camley Street	529735, 183737	38	36	21	23	Tube Missing	23							28
HS2- 000020BNY	Junction of Mill Lane and Hillfield Road	524839, 185136	42	39	29	29	Tube Missing	28							33
HS2- 000020BNZ	Mansfield Road	528050, 185508	35	31	23	23	Tube Missing	24							27
HS2- 000020BP0	Junction of Camden Road and Torriano Avenue	529708, 184871	45	51	40	35	40	35							41
HS2- 000020BP2	Junction of Grays Inn Road and Holborn	531149, 181616	36	35	32	25	36	26							32
HS2- 000020BPB	Camden High Street	528966, 183735	59	52	48	Tube Missing	58	57							55
HS2- 000020BPC	Castlehaven Road	528788, 184591	29	27	23	Tube Missing	22	21							24

Monitoring	Location	Coordinates	la.	e.b		A			test		6	0-4	New	D	B.4 12
Site ID	description	(X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹²
HS2- 000020BPD	Prince of Wales Road	528571, 184683	26	26	21	16	20	19							21
HS2- 000020BPE	Haverstock Hill	527710, 184749	40	39	29	23	28	24							30
HS2- 000020BPF	Junction of Primrose Gardens and England's Lane	527549, 184640	41	37	21	22	27	23							29
HS2- 000020BPU	Junction of Gower Street and Grafton Way	529476, 182267	43	42	38	Tube Missing	35	28							37
HS2- 000020BPW	Junction of Delancey Street and Arlington Road	528939, 183637	27	28	30	23	29	26							27
HS2- 000020BPX	Netley Street	529177, 182625	36	30	31	22	20	19							26
HS2- 000020BPY	Stanhope Street	529060, 182947	Tube Missing	26	22	14	20	14							19
HS2- 000020BPZ	Albany Street	528790, 182923	34	25	26	18	26	24							26
HS2- 000020BQ0	Werrington Street	529493, 183113	35	26	27	18	22	17							24
HS2- 000020BQ1	Polygon Road	529574, 183045	27	33	Tube Missing	Tube Missing	Tube Missing	Tube Missing							30
HS2- 000020BQ2	Alexandra Place	526320, 183980	29	29	Tube Missing	15	20	17							22
HS2- 000020BQ3	Harrington Square	529228, 183172	43	37	34	28	32	24							33
HS2- 000020BQ4	Junction of North Gower Street and Starcross Street	529290, 182572	33	33	28	21	17	19							25
HS2- 000020BQ5	Adelaide Road	527713, 184392	32	34	25	19	25	22							26
HS2- 000020BQ6	Mornington Terrace	528836, 183474	30	26	23	8	21	19							21

Monitoring	Location	Coordinates	la	F-16	M				test		6	0-4	New	D	Mean ¹²
Site ID	description	(X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean'-
HS2- 000020BQ7	Arlington Road	529009, 183479	27	26	26	14	20	16							22
HS2- 000020BQ8	Clarkson Row	529024, 183213	32	26	28	Tube Missing	20	16							25
HS2- 000020BQ9	Park Village East	528923, 183121	30	24	23	15	19	18							21
HS2- 000020BQA	Eversholt Street	529386, 183132	43	28	33	26	Tube Missing	Tube Missing							32
HS2- 000020BQB	Junction of Harrington Street and Varndell Street	529147, 182816	32	28	24	17	21	16							23
HS2- 000020BQC	Junction of Robert Street and Hampstead Road	529199, 182704	40	35	30	23	32	20							30
HS2- 000020BQD	Drummond Crescent	529648, 182856	39	36	38	22	28	21							31
HS2- 000020BQJ	Grafton Way	529380, 182225	40	47	32	30	24	32							34
HS2- 000020BQL	Delancey Street	528768, 183581	36	29	35	Tube Missing	32	29							32
HS2- 000020BQR	Lamp post on Park Village East	528682, 183505	33	22	23	17	Tube Missing	Tube Missing							23
HS2- 000020BQS	Opposite Maria fidelis school on Phoenix Road	529670, 182982	34	32	26	26	21	17							26
HS2- 000020BQT	Drummond Street	529385, 182581	27	33	Tube Missing	Tube Missing	22	22							26
HS2- 000020BQX	Lamp post on Brunswick Square	530344, 182236	36	39	31	31	28	23							31
HS2- 000020BP4	Triplicate site on Finchley Road next to Swiss Cottage kerbside automatic monitoring station	526633, 184392	49	40	41	37	45	38							42

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹²
HS2- 000020BP5	Triplicate site next to the Euston Road roadside automatic monitoring stations	529895, 182657	57	Tube Missing	Tube Missing	Tube Missing	58	52							56
HS2- 000020BP9	Triplicate site in Russell Square next to Bloomsbury urban background automatic monitoring station	530120, 182034	34	30	Tube Missing	24	26	19							26