

## Air Quality and Dust Monitoring Monthly Report – November 2024

London Borough of Camden



## Department for Transport

High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited,  
Two Snowhill  
Snow Hill Queensway  
Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: [HS2enquiries@hs2.org.uk](mailto:HS2enquiries@hs2.org.uk)

Website: [www.gov.uk/hs2](http://www.gov.uk/hs2)

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2024, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit [www.nationalarchives.gov.uk/doc/open-government-licence/version/2](http://www.nationalarchives.gov.uk/doc/open-government-licence/version/2) **OGI** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: [psi@nationalarchives.gsi.gov.uk](mailto:psi@nationalarchives.gsi.gov.uk). Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



# Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in the London Borough of Camden (LBC) during October 2024 and November 2024 respectively.
- 1.1.2 Figure 1 to Figure 5 in Appendix A present the current worksites together with air quality and dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from [www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2](http://www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2), which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites, as presented in Appendix A, Figure 1 to Figure 5, include:

## **Skanska Costain Strabag Joint Venture (SCSjv)**

### Adelaide Road Vent Shaft

- Works currently paused until April 2025.

### Euston Scissor Cut

- Limited groundworks;
- Concrete works; and
- Materials management.

### Euston Throat Retained Cut

- Limited groundworks;
- Concrete works; and
- Materials management.

### Hampstead Road Bridge

- Utilities diversion works.

### Euston Cavern

- Limited concrete;
- Groundworks; and
- Materials management.

## **Mace Dragados Joint Venture (MDjv)**

### TSS

- Installation of permanent signage CMS (96% completed)
- Earthing strips installed around the box
- Concrete repair works to walls and floor
- Kemwell alteration works
- Fire stopping around door frames and services
- Installation and snagging of permanent fire doors and thresholds
- Ongoing CMS and wiring installation to the whole of the building
- Ongoing commissioning of the building
- Completion of external painting of TSS
- Ironmongery installation complete.

### Wingate

- Re-routing cables and maintenance works.

### GKR

- Scaffolding Tracker works.

### Clipfine

- Assisting contractors with movement of materials and floor protection
- General housekeeping
- Various carpentry works
- Lifting operations via access hatches (carried out by Plant Movement)
- Hoarding adjustment.

### MF building

- Internal snagging and painting works.

### MF Old School

- Continue window install, all floors
- TEP entrance area, begin groundworks
- Continue fire protection – soffit boarding and penetrations
- Continue roof plant install works
- Complete riser works, installing lintels and pad stones
- Internal M&E fit out
- Phase 1 TEP Rooms 1-7 handed over to Client (although additional works instructed for Client through HS2)
- Phase 2 Gym floor sanded and stained.

### MWU Hampstead Road

- Ongoing NTH MWU Park construction

- 7nr Trial Pits excavation
- The Podium Piazza pavement remedial works.

#### Zone 5

- SCS utilizing CLD compound for training area.

#### Maria Fidelis Old School

- Completion of TEP Sports Hall including corridor
- Completion TEP Entrance slab
- Commencement of TEP entrance roof joists install.
- Completion of Blockwork with 2nd lift brickwork complete this week.
- Completion of Main building roof final connections.

#### Utilities

- Commenced MH1 at Hampstead Road/Cardington Street excavation
- Cumberland Market backfill
- TSS combined trench excavation; installed water DI1000/250PE and 80mm gas pipes
- Exposed 42' water main connection at MF MH3 Area
- Ongoing UKPN trench excavation at Cobourg Street – MH5 area towards MH8
- Completed excavation for gas main between MH10-11 at TSS site and 36' gas pipe fusion
- Works for commissioning of 4-point connection at Melton Street
- 42' pressure tests and remedial works.


- 1.1.5 Twenty-Two (22) dust monitors are installed around these worksites, where works are underway. These sites returned a medium to high dust risk rating.
- 1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor in Figure 6. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.7 The trigger level for PM<sub>10</sub> concentrations of 190 µg/m<sup>3</sup>, over a 1-hour period, in accordance with the updated guidance document '*Guidance on Monitoring in the Vicinity of Demolition and Construction Sites – (October 2018)*' has been applied.
- 1.1.8 Details of the trigger alerts investigations and remediations are presented in Appendix B, Table 2.
- 1.1.9 Data capture was below 90% for the AQ044 monitor due to a fault with the monitor which was subsequently replaced.

- 1.1.10 Diffusion tube monitoring of Nitrogen Dioxide (NO<sub>2</sub>) is undertaken at sixty-four (64) locations around highways within the LBC as part of the management of air quality where significant effects may occur as a result of the scheme.
- 1.1.11 Diffusion tube monitoring results are as provided from the laboratory analysis, and therefore still require various analysis and adjustments to be undertaken. Final corrected results will be presented and described in the annual report. However, based on the results to date, no unexpected values were recorded during the monitoring period.
- 1.1.12 NO<sub>2</sub> monitoring locations and results are presented in Appendix C, Table 3, together with the 2024 running mean.
- 1.1.13 There were no (0) complaints received during the reporting period (November 2024).

# Appendix A – Worksites and Monitoring Locations

Figure 1 to Figure 5: Worksites and monitoring locations within the LBC





**Legend**  
 Diffusion Tube  
 District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number  
 Map Name  
**Monitoring Locations  
 In LBC (Sheet 1)**  
 London Borough of Camden

**hs2**  
 HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.


Registered in England. Registration number 06791686.  
 Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

© Crown copyright and database rights 2022.  
 Ordnance Survey Licence Number 100049190.

Scale at A3: 1:10,000

Doc Number: Date: 25/10/22





**Legend**  
■ Diffusion Tube ■ Worksite  
● Dust Monitor  District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number  
 Map Name  
**Worksite and Monitoring Locations  
 In LBC (Sheet 2)**  
 London Borough of Camden


**hs2**  
 Registered in England. Registration number 06791686.  
 Registered office: 2 Snowhill, Queensway,  
 Birmingham B4 6GA.

Scale at A3: 1:7,000

© Crown copyright and database rights 2022.  
 Ordnance Survey Licence Number 100049190.

Doc Number: Date: 25/10/22






**Legend**  
 ● Dust Monitor □ District Borough Unitary Boundaries  
 ■ Worksite


Map Number  
 Map Name  
**Worksite & Monitoring Locations  
 In LBC (Sheet 3)**

London Borough of Camden


 HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.  
 Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

Scale at A3: 1:7,000



 Metres

© Crown copyright and database rights 2023.  
 Ordnance Survey Licence Number 100049190.

Doc Number: Date: 18/05/23

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community






**Legend**  
■ Diffusion Tube  District Borough Unitary Boundaries  
 Worksite


Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number  
 Map Name  
**Worksite & Monitoring Locations  
 In LBC (Sheet 4)**  
 London Borough of Camden


 HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.


Registered in England. Registration number 06791686.  
 Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

© Crown copyright and database rights 2023.  
 Ordnance Survey Licence Number 100049190.

Scale at A3: 1:7,000  


Doc Number: Date: 18/05/23







**Legend**  
 ■ Diffusion Tube  
 □ District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community


Map Number  
 Map Name  
**Worksite and Monitoring Locations  
 In LBC (Sheet 5)**  
 London Borough of Camden


 HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.



Registered in England. Registration number 06791686.  
 Registered office: 2 Snowhill, Queensway,  
 Birmingham B4 6GA.

© Crown copyright and database rights 2022.  
 Ordnance Survey Licence Number 100049190.

Scale at A3: 1:4,000  


Doc Number: \_\_\_\_\_ Date: 25/10/22



## Appendix B – Dust Monitoring Results

Table 1: Dust Monitoring Locations and Results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Minimum 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Maximum 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Number of 1- hour periods exceeding trigger level of 190 µg/m <sup>3</sup>	Data capture (%)
AQ001	529016, 183049	Junction of Park Village East, Stanhope Street and Granby Terrace	M	Yes	N	13.4	0.7	50.1	0	100.0
AQ002	528924, 183130	Park Village East	M	Yes	N	12.1	0.5	48.4	0	100.0
AQ003	529273, 182698	St James' Gardens	M	Yes	N/A	7.5	0.3	31.7	0	100.0
AQ004	529533, 182519	Melton Street	H	Yes	N/A	12.9	0.5	129.7	0	100.0
AQ005	529498, 182502	Stephenson Way	H	Yes	N/A	21.9	1.2	323.6	1	100.0
AQ006	529388, 182524	Euston Street	H	Yes	N/A	11.9	0.7	38.4	0	100.0
AQ007	529361, 182574	Drummond Street	H	Yes	N/A	30.8	1.0	231.9	3	100.0
AQ008	529372, 182657	Cobourg Street	H	Yes	N/A	13.6	0.6	83.5	0	100.0
AQ009	529707, 182730	Eversholt Street	H	Yes	N/A	46.9	1.5	296.6	6	100.0
AQ010	529223, 182746	Hampstead Road South	M	Yes	N/A	21.7	0.8	560.2	8	100.0
AQ011	529176, 182922	Hampstead Road	M	Yes	N	2.4	0.1	16.0	0	99.0

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Minimum 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Maximum 1-hour PM <sub>10</sub> concentration (µg/m <sup>3</sup> )	Number of 1- hour periods exceeding trigger level of 190 µg/m <sup>3</sup>	Data capture (%)
AQ012	529144, 182941	Rear of Coniston House	M	Yes	N	13.8	0.7	45.8	0	100.0
AQ013	529066, 182990	Regents Park Estate	M	Yes	N	11.7	0.6	55.9	0	99.9
AQ016	528820, 183498	Mornington Terrace North	M	Yes	N	12.7	0.7	48.3	0	100.0
AQ017	528962, 183274	Mornington Terrace South	M	Yes	N	5.5	0.1	22.9	0	100.0
AQ018	529192, 183071	Hampstead Road North	M	Yes	N	12.1	0.6	49.3	0	100.0
AQ019	528689, 183500	Park Village East (North)	M	Yes	N	10.1	0.5	72.0	0	100.0
AQ020	529109, 182605	Netley School	N/A	Yes	N/A	11.1	0.4	52.3	0	100.0
AQ021	529136, 183086	Site compound at the Junction of Hampstead Road & Granby Terrace Bridge	M	Yes	N	14.7	0.9	407.4	1	100.0
AQ044	527725, 184369	Adelaide Road 1	M	Yes	N	15.3	0.8	56.2	0	85.8
AQ045	527826, 184375	Adelaide Road 2	M	Yes	N	13.9	0.9	59.8	0	99.9
AQ054	529266, 183076	Ampthill Estate, Hampstead Road	M	Yes	N	22.1	1.6	69.2	0	100.0


Table 2: Summary of exceedances during period (November 2024)





Monitoring site ID	Period exceeding trigger level	Investigation	Outcomes / Resolution / Remedial measures implemented
AQ005	28/11/2024 13:01 – 14:00; 323.6 µg/m <sup>3</sup>	There were no HS2 works or vehicle/ machine movements related to HS2 occurring in the vicinity of this unit during the period where the trigger level was exceeded.  No further exceedances at this monitor were recorded during this monitoring period.	MDJV will continue to ensure all the activities being undertaken have appropriate mitigation measures applied (in line with the CoCP).  Any further exceedances at this monitor will continue to be investigated to confirm whether the exceedance is caused by HS2 activities.
AQ007	06/11/2024 03:01 – 04:00; 231.9 µg/m <sup>3</sup> 04:01 – 05:00; 219.5 µg/m <sup>3</sup> 05:01 – 06:00; 210.0 µg/m <sup>3</sup>	There were no HS2 works or vehicle/ machine movements related to HS2 occurring in the vicinity of this unit during the period where the trigger level was exceeded.  Given the date and time of the exceedance alerts, it is instead thought that the exceedances were related to bonfire night celebrations in the wider area as an increase in concentrations across all the monitors was observed during this period.	MDJV will continue to ensure all the activities being undertaken have appropriate mitigation measures applied (in line with the CoCP).  Any further exceedances at this monitor will continue to be investigated to confirm whether the exceedance is caused by HS2 activities.
AQ009	06/11/2024 02:01 – 03:00; 218.2 µg/m <sup>3</sup> 03:01 – 04:00; 238.1 µg/m <sup>3</sup> 04:01 – 05:00; 294.5 µg/m <sup>3</sup> 05:01 – 06:00; 296.6 µg/m <sup>3</sup> 06:01 – 07:00; 236.4 µg/m <sup>3</sup> 07:01 – 08:00; 196.4 µg/m <sup>3</sup>	There were no HS2 works or vehicle/ machine movements related to HS2 occurring in the vicinity of this unit during the period where the trigger level was exceeded.  Given the date and time of the exceedance alerts, it is instead thought that the exceedances were related to bonfire night celebrations in the wider area as an increase in concentrations across all the monitors was observed during this period.	MDJV will continue to ensure all the activities being undertaken have appropriate mitigation measures applied (in line with the CoCP).  Any further exceedances at this monitor will continue to be investigated to confirm whether the exceedance is caused by HS2 activities.
AQ010	08/11/2024 16:01 – 17:00; 271.0 µg/m <sup>3</sup> 21:01 – 22:00; 463.8 µg/m <sup>3</sup>	There were no HS2 works or vehicle/ machine movements related to HS2 occurring in the vicinity of this unit during the periods where the trigger level was exceeded.	MDJV will continue to ensure all the activities being undertaken have appropriate mitigation measures applied (in line with the CoCP).  Any further exceedances at this monitor will continue to be investigated to confirm whether the exceedance is caused by HS2 activities.
	14/11/2024 16:01 – 17:00; 293.6 µg/m <sup>3</sup>  15/11/2024 10:01 – 11:00; 313.0 µg/m <sup>3</sup>	The breaking of a layer of concrete for the Utility Diversion was being undertaken close to the monitor (within 3 metres of the monitor) when these trigger level exceedances were recorded. However, Best Practicable Means were being implemented	The duration and frequency of dust mitigation was increased at the worksite. The sampling and alert reporting interval across all dust monitors was also reduced from 1 hour to 15 minutes so that site operatives





	<p>11:01 – 12:00; 560.2 µg/m<sup>3</sup>                  12:01 – 13:00; 246.5 µg/m<sup>3</sup>                  13:01 – 14:00; 244.5 µg/m<sup>3</sup></p> <p>16/11/2024                  11:01 – 12:00; 220.1 µg/m<sup>3</sup></p>	<p>during the works. This included localised dust suppression with a water bowser.</p>	<p>will be alerted sooner when there are elevated concentrations. This will allow additional mitigation measures to be actioned more quickly. A handheld dust monitor (Dust Canary), which provides real-time alert and feedback to the site team, will also be used.</p>
AQ021	<p>28/11/2024                  13:01 – 14:00; 407.4 µg/m<sup>3</sup></p>	<p>At the time of the exceedance there were no dusty works taking place in the vicinity of the monitor. There was waterproofing works to the Granby Terrace Bridge quite a distance away but this was a wet operation. It is considered that the trigger was false, especially given the very high reading, probably due to a tiny piece of debris dislodged in the monitor's inlet tube.</p>	<p>Monitor was subsequently serviced.</p>







Figure 6: Construction dust 1-hour mean indicative PM<sub>10</sub> concentration for all dust monitors














AQ019




AQ020




AQ021




AQ044



AQ045



AQ054



## Appendix C – Air Quality Monitoring Results

Table 3: NO<sub>2</sub> monitoring locations around highways, NO<sub>2</sub> concentrations and monthly monitoring results with running mean for 2024 (µg/m<sup>3</sup>)

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>12</sup>
HS2-000020BM5	Junction of St Chad's Street and Grays Inn Road	530436, 182929	44	43	Tube Missing	Tube Missing	26	42	29	32	38	Tube Missing			36
HS2-000020BM7	Chalton Street	529894, 182702	Tube Missing	45	42	31	38	Tube Missing	15	35	34	36			35
HS2-000020BM8	Junction of Euston Square and Grafton Place	529737, 182641	Tube Missing	39	35	31	46	43	44	46	45	Tube Missing			41
HS2-000020BM9	Junction of Endsleigh Gardens and Upper Woburn Place	529785, 182529	44	Tube Missing	Tube Missing	Tube Missing	44	33	32	36	40	44			39
HS2-000020BMA	Junction of Euston Road and Gower Street	529429, 182375	56	50	37	Tube Missing	Tube Missing	41	33	37	32	44			41
HS2-000020BMB	Whitfield Street	529273, 182114	39	35	23	23	30	21	20	24	27	35			28
HS2-000020BMC	Hampstead Road	529232, 182511	55	62	57	48	54	47	48	Tube Missing	37	61			52
HS2-000020BMF	Junction of Polygon Road and Ossulston Street	529715, 183123	32	27	29	Tube Missing	24	17	Tube Missing	18	23	30			25

<sup>1</sup> Note: to aid interpretation and conform with best practice, the monthly measurements in this table are reported rounded to the nearest whole number. The annual mean presented here is calculated based on laboratory data to 4 significant figures, rounded to a whole number, and therefore may differ slightly to a mean derived from averaging the rounded monthly measurements in the table.

<sup>2</sup> The annual mean for diffusion tubes presented in the table above still require various analysis and adjustments to be undertaken before comparison to the Air Quality Objectives. The final corrected annual mean will be presented in the HS2 Annual Air Quality Report.

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>12</sup>
HS2-000020BMH	Nash Street	528861, 182717	34	27	18	18	Tube Missing	20	20	21	20	32			23
HS2-000020BMJ	Junction on Robert Street and Stanhope Street	529080, 182698	31	31	27	19	25	20	21	21	26	32			25
HS2-000020BMK	Junction of Plender Street and Bayham Street	529196, 183546	45	42	37	32	38	33	32	32	34	39			36
HS2-000020BML	Junction of Arlington Road and Mornington Crescent	529093, 183356	36	30	25	20	23	18	17	18	25	Tube Missing			24
HS2-000020BMM	Junction of Bayham Street and Pratt Street	529084, 183722	39	Tube Missing	Tube Missing	Tube Missing	41	42	40	39	34	47			40
HS2-000020BMN	Junction of Delancey Street and Albert Street	528850, 183573	34	32	29	23	Tube Missing	23	21	23	29	30			27
HS2-000020BMQ	Junction of Parkway and Delancey Street	528662, 183604	38	36	39	20	33	29	Tube Missing	Tube Missing	34	39			33
HS2-000020BMR	Junction of Oval Road and Jamestown Road	528548, 183967	30	28	21	22	23	19	17	19	21	30			23
HS2-000020BMS	Junction of Chalk Farm Road and Castlehaven Road	528685, 184188	43	41	Tube Missing	Tube Missing	40	35	31	32	36	41			37
HS2-000020BMT	Junction of Camden Road and Camden Street	529079, 184043	46	41	37	31	37	29	28	30	36	40			36
HS2-000020BMU	Junction of Southampton Road and Fleet Road	527783, 185407	40	30	34	27	32	31	28	29	34	36			32

Air Quality and Dust Monitoring Summary Report, November 2024  
London Borough of Camden

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>12</sup>
HS2-000020BMV	Primrose Hill Road	527538, 184250	Tube Missing	31	28	21	24	19	18	19	23	12			22
HS2-000020BMW	Junction of Finchley Road and Hilgrove Road	526619, 184081	43	45	39	28	41	36	34	25	40	41			37
HS2-000020BMZ	Junction of Finchley Road and Hendon Way	525102, 186042	54	54	53	42	57	50	45	51	53	52			51
HS2-000020BNA	Junction of Regent's Park Road and Rothwell Street	527884, 183980	29	29	22	18	20	19	17	17	18	32			22
HS2-000020BNC	Junction of Outer Circle and Gloucester Gate	528528, 183443	29	22	19	14	20	15	12	16	21	23			19
HS2-000020BNH	Junction of Parkway and Albert Street	528763, 183720	33	30	24	23	27	24	23	24	26	34			27
HS2-000020BNN	Lincoln's Inn Fields	530744, 181308	23	33	30	21	24	19	21	22	21	Tube Missing			24
HS2-000020BNQ	Camley Street	529735, 183737	38	36	21	23	Tube Missing	23	21	23	15	Tube Missing			25
HS2-000020BNY	Junction of Mill Lane and Hillfield Road	524839, 185136	42	39	29	29	Tube Missing	28	22	25	33	27			31
HS2-000020BNZ	Mansfield Road	528050, 185508	35	31	23	23	Tube Missing	24	23	29	28	29			27
HS2-000020BP0	Junction of Camden Road and Torriano Avenue	529708, 184871	45	51	40	35	40	35	37	35	37	35			39
HS2-000020BP2	Junction of Grays Inn Road and Holborn	531149, 181616	36	35	32	25	36	26	21	Tube Missing	27	34			30
HS2-000020BPB	Camden High Street	528966, 183735	59	52	48	Tube Missing	58	57	50	45	38	52			51

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>12</sup>
HS2-000020BPC	Castlehaven Road	528788, 184591	29	27	23	Tube Missing	22	21	13	18	22	25			22
HS2-000020BPD	Prince of Wales Road	528571, 184683	26	26	21	16	20	19	14	16	18	29			20
HS2-000020BPE	Haverstock Hill	527710, 184749	40	39	29	23	28	24	23	27	26	32			29
HS2-000020BPF	Junction of Primrose Gardens and England's Lane	527549, 184640	41	37	21	22	27	23	19	26	30	31			28
HS2-000020BPU	Junction of Gower Street and Grafton Way	529476, 182267	43	42	38	Tube Missing	35	28	24	22	19	39			32
HS2-000020BPW	Junction of Delancey Street and Arlington Road	528939, 183637	27	28	30	23	29	26	19	25	Tube Missing	39			27
HS2-000020BPX	Netley Street	529177, 182625	36	30	31	22	20	19	13	21	27	35			25
HS2-000020BPY	Stanhope Street	529060, 182947	Tube Missing	26	22	14	20	14	22	15	19	28			20
HS2-000020BPZ	Albany Street	528790, 182923	34	25	26	18	26	24	16	23	35	30			26
HS2-000020BQ0	Werrington Street	529493, 183113	35	26	27	18	22	17	15	19	21	31			23
HS2-000020BQ1	Polygon Road	529574, 183045	27	33	Tube Missing	Tube Missing	Tube Missing	Tube Missing	24	19	24	34			27
HS2-000020BQ2	Alexandra Place	526320, 183980	29	29	Tube Missing	15	20	17	24	17	18	29			22
HS2-000020BQ3	Harrington Square	529228, 183172	43	37	34	28	32	24	20	26	29	33			30
HS2-000020BQ4	Junction of North Gower Street and Starcross Street	529290, 182572	33	33	28	21	17	19	17	22	24	33			25
HS2-000020BQ5	Adelaide Road	527713, 184392	32	34	25	19	25	22	14	20	23	30			24



Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>12</sup>
HS2-000020BQ6	Mornington Terrace	528836, 183474	30	26	23	8	21	19	15	16	20	27			20
HS2-000020BQ7	Arlington Road	529009, 183479	27	26	26	14	20	16	16	17	22	26			21
HS2-000020BQ8	Clarkson Row	529024, 183213	32	26	28	Tube Missing	20	16	15	20	21	24			23
HS2-000020BQ9	Park Village East	528923, 183121	30	24	23	15	19	18	16	18	22	30			21
HS2-000020BQA	Eversholt Street	529386, 183132	43	28	33	26	Tube Missing	Tube Missing	14	35	42	44			33
HS2-000020BQB	Junction of Harrington Street and Varndell Street	529147, 182816	32	28	24	17	21	16	21	16	20	25			22
HS2-000020BQC	Junction of Robert Street and Hampstead Road	529199, 182704	40	35	30	23	32	20	22	23	28	Tube Missing			28
HS2-000020BQD	Drummond Crescent	529648, 182856	39	36	38	22	28	21	18	24	23	35			28
HS2-000020BQJ	Grafton Way	529380, 182225	40	47	32	30	24	32	Tube Missing	34	38	42			35
HS2-000020BQL	Delancey Street	528768, 183581	36	29	35	Tube Missing	32	29	27	9	30	37			29
HS2-000020BQR	Lamp post on Park Village East	528682, 183505	33	22	23	17	Tube Missing	Tube Missing	16	16	14	30			21
HS2-000020BQS	Opposite Maria fidelis school on Phoenix Road	529670, 182982	34	32	26	26	21	17	19	19	23	Tube Missing			24
HS2-000020BQT	Drummond Street	529385, 182581	27	33	Tube Missing	Tube Missing	22	22	36	20	23	32			27
HS2-000020BQX	Lamp post on Brunswick Square	530344, 182236	36	39	31	31	28	23	21	26	28	33			30

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean <sup>12</sup>
HS2-000020BP4	Triplicate site on Finchley Road next to Swiss Cottage kerbside automatic monitoring station	526633, 184392	49	40	41	37	45	38	36	36	41	44			41
HS2-000020BP5	Triplicate site next to the Euston Road roadside automatic monitoring stations	529895, 182657	57	Tube Missing	Tube Missing	Tube Missing	58	52	51	55	53	53			54
HS2-000020BP9	Triplicate site in Russell Square next to Bloomsbury urban background automatic monitoring station	530120, 182034	34	30	Tube Missing	24	26	19	18	Tube Missing	24	33			26