June 2025



# Air Quality and Dust Monitoring Monthly Report - June 2025

London Borough of Hillingdon



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2025, except where otherwise stated. Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v3.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/ version/3 or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



### **Monthly Summary**

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in the London Borough of Hillingdon (LBH) during May 2025 and June 2025 respectively.
- 1.1.2 Figure 1 to Figure 4 in Appendix A present the current worksites together with air quality monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from <a href="www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2">www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2</a>, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites, as presented in Appendix A, Figure 1 to Figure 4, include:
  - Gatemead and West Ruislip Embankment, Breakspear Road South and River Pinn Underbridge, concreting, groundworks and materials management.
  - Harvil Road realignment groundworks, materials management, concreting and shuttering works at Copthall North.
  - West Ruislip Portal materials management (tunnel boring machine arisings).
  - South Ruislip vent shaft and headhouse construction, ground works, concrete works and materials management.
  - Northern Sustainable Placement Area (NSPA) landscaping, seeding and planting.
  - Southern Sustainable Placement Area (SSPA) seeding, planting and demobilisation.

#### **CVV Dews Lane**

- North Moorhall Compound: operation;
- HOAC Compound: operation;
- Haul Road Maintenance: haul road maintenance;
- ATFS: ATFS permanent drainage, soiling and seeding, ATFS access road construction, Slab removal;
- Pumping Water Management: pumping water management;
- Satellite Welfares;
- South Abutment: drainage works, South Abutment construction stage 2 earthworks, yard supporting activities, soiling and seeding works, launching girder platform removal:
- Environmental Maintenance;
- Stockpiling Activity HOAC: stockpile management;
- Deck Finishes Logistics: preparation and operation of storage yards and installation of below deck access provision, traffic management on the deck surface, delivery of parapets, noise barriers, troughs, pipes, steel works and other minor material to the

- storage yards and deck, installation of access at the top of the deck (HAKI stairs) and finishes support plant;
- Deck Finishes On-deck Construction: construction of robust kerbs, installation of parapets, construction of concrete stitch, filling of voids and top openings, verge deck waterproofing, trough installation, noise barrier installation, deck waterproofing, SFRC slab construction, north Embankment and south embankment noise barriers and foundations, noise barrier and concrete panel installation at north embankment and masking wall installation at north embankment and south embankment;
- Deck Finishes In-deck Construction: concrete works within the deck, drainage works within the deck, steel works within the deck, and structural health monitoring;
- Landscaping (pier 57 Pier 1): advanced works including removal of cofferdams, initial ground drainage including manhole chamber, hardstanding removal, tree removal & vegetation clearance, earthworks cut & fill, landscaping (subsoil, topsoil, cultivating, seeding, planting) and streetworks bellmouth road construction;
- Jetty Removal and associated earthworks: cutting tubular piles, sheet piles and steelworks; and
- General Works.


#### **CVV Moorhall Road**


- North Moorhall Compound: operation;
- HOAC Compound: operation;
- Haul Road Maintenance: haul road maintenance;
- ATFS: ATFS permanent drainage, soiling and seeding, ATFS access road construction,
   Slab removal;
- Pumping Water Management: pumping water management;
- Satellite Welfares;
- South Abutment: drainage works, South Abutment construction stage 2 earthworks, yard supporting activities, soiling and seeding works, launching girder platform removal;
- Environmental Maintenance;
- Stockpiling Activity HOAC: stockpile management;
- Deck Finishes Logistics: preparation and operation of storage yards and installation of below deck access provision, traffic management on the deck surface, delivery of parapets, noise barriers, troughs, pipes, steel works and other minor material to the storage yards and deck, installation of access at the top of the deck (HAKI stairs) and finishes support plant;
- Deck Finishes On-deck Construction: construction of robust kerbs, installation of parapets, construction of concrete stitch, filling of voids and top openings, verge deck waterproofing, trough installation, noise barrier installation, deck waterproofing, SFRC slab construction, North Embankment and south embankment noise barriers and foundations, noise barrier and concrete panel installation at north embankment and masking wall installation at north embankment and south embankment;
- Deck Finishes In-deck Construction: concrete works within the deck, drainage works within the deck, steel works within the deck, and structural health monitoring;


- Landscaping (pier 57 Pier 1): advanced works including removal of cofferdams, initial
  ground drainage including manhole chamber, hardstanding removal, tree removal &
  vegetation clearance, earthworks cut & fill, landscaping (subsoil, topsoil, cultivating,
  seeding, planting) and streetworks bellmouth road construction;
- Jetty Removal and associated earthworks: cutting tubular piles, sheet piles and steelworks; and
- General Works.
- 1.1.5 Eleven (11) dust monitors are installed around these worksites, where works are underway. These sites returned a low to medium dust risk rating.
- 1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor in Figure 5. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.7 The trigger level for  $PM_{10}$  concentrations of  $190\mu g/m^3$ , over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018)' has been applied.
- 1.1.8 Details of the trigger alert investigations and remediations are presented in Appendix B, Table 3.
- 1.1.9 Data capture was below 90% for multiple monitors due to:
  - Data capture for monitor AQ033 was below 90% due to the monitor running out of hydrogen gas, subsequently recharged.
  - Data capture for AQ041 was below 90% originally due to a loss of power. Power was subsequently restored on the 1<sup>st</sup> July but the monitor displayed a fault or blockage despite continuing to operate.
- 1.1.10 Diffusion tube monitoring of Nitrogen Dioxide (NO<sub>2</sub>) is undertaken at eleven (11) locations around highways within the LBH as part of the management of air quality where significant effects may occur as a result of the scheme.
- 1.1.11 Diffusion tube monitoring results are as provided from the laboratory analysis, and therefore still require various analysis and adjustments to be undertaken. Final corrected results will be presented and described in the annual report. However, based on results to date, no unexpected values were recorded during the monitoring period.
- 1.1.12 NO<sub>2</sub> monitoring locations and results are presented in Appendix C, Table 2, together with the 2025 running mean.


## **Appendix A – Worksites and Monitoring Locations**

Figure 1 to Figure 4: Current monitoring locations within the LBH









## **Appendix B - Dust Monitoring Results**

Table 1: Dust Monitoring Locations and Results


| Monitoring site ID | Coordinate<br>s (X,Y) | Location<br>description                      | Dust<br>risk<br>rating<br>for<br>site | Monitoring<br>site active<br>during<br>period | Change to<br>site since<br>previous<br>period<br>report | Mean 1-hour PM <sub>10</sub><br>concentration<br>(μg/m³) | Minimum 1-<br>hour PM <sub>10</sub><br>concentration<br>(µg/m³) | Maximum 1-<br>hour PM <sub>10</sub><br>concentration<br>(μg/m³) | Number of<br>1- hour<br>periods<br>exceeding<br>trigger level<br>of 190 µg/m³ | Data capture<br>(%) |  |
|--------------------|-----------------------|--|---------------------------------------|---|---|--|---|---|---|---------------------|--|
| AQ033              | 507045,<br>187352     | Breakspear<br>Road South                     | М                                     | Yes   | N   | 19.8   | 2.6   | 180.7   | 0   | 42.1                |  |
| AQ034              | 506608,<br>187592     | Copthall<br>Cutting                          | L                                     | Yes   | N   | 21.2   | 3.2   | 215.0   | 2   | 100.0               |  |
| AQ040              | 508328,<br>186880     | West Ruislip<br>Golf Course                  | М                                     | Yes   | N   | 13.7   | 1.0   | 73.2  | 0   | 100.0               |  |
| AQ041              | 507942,<br>187028     | West Ruislip<br>Portal                       | М                                     | Yes   | N   | 11.9   | 2.7   | 103.0   | 0   | 76.1                |  |
| AQ049              | 506531,<br>187865     | Copthall North,<br>Ancient<br>Woodland       | М                                     | Yes   | N   | 15.6   | 1.5   | 210.4   | 1   | 99.6                |  |
| AQ050              | 506399,<br>187166     | Copthall South<br>Compound                   | М                                     | Yes   | N   | 10.8   | 2.6   | 57.8  | 0   | 100.0               |  |
| AQ052              | 506433,<br>186725     | Southern<br>Sustainable<br>Placement<br>Area | М                                     | Yes   | N   | 17.4   | 7.0   | 45.0  | 0   | 100.0               |  |
| AQ056              | 506494,<br>186432     | Southern<br>Sustainable<br>Placement<br>Area | М                                     | Yes   | N   | 14.6   | 4.0   | 51.0  | 0   | 100.0               |  |
| AQ057              | 506739,<br>186359     | Southern<br>Sustainable<br>Placement<br>Area | М                                     | Yes   | N   | 16.2   | 6.0   | 48.0  | 0   | 100.0               |  |


| Monitoring site ID | Coordinate<br>s (X,Y) | Location<br>description                               | Dust<br>risk<br>rating<br>for<br>site | Monitoring<br>site active<br>during<br>period | Change to site since previous period report | Mean 1-hour PM <sub>10</sub><br>concentration<br>(μg/m³) | Minimum 1-<br>hour PM <sub>10</sub><br>concentration<br>(µg/m³) | Maximum 1-<br>hour PM <sub>10</sub><br>concentration<br>(μg/m³) | Number of<br>1- hour<br>periods<br>exceeding<br>trigger level<br>of 190 µg/m³ | Data capture<br>(%) |
|--------------------|-----------------------|---|---------------------------------------|---|---|--|---|---|---|---------------------|
| CVV-AQMP4          | 505589,<br>187793     | On the western<br>boundary of<br>HOAC at Dews<br>Lane | М                                     | Yes   | Y   | 6.1  | 1.0   | 56.0  | 0   | 100.0               |


Table 2: Summary of exceedances during period (June 2025)

| Monitoring site ID | Period exceeding trigger level   | Investigation   | Outcomes / Resolution / Remedial measures implemented  |
|--------------------|--|---|--|
| AQ034              | 02/06/2025<br>13:01 – 14:00; 194.1 μg/m <sup>3</sup><br>30/06/2025<br>13:01 – 14:00; 215.0 μg/m <sup>3</sup> | At the times of the trigger alerts from monitor AQ034 which is located at the south-eastern boundary of the ancient woodland on the North Copthall site adjacent to the internal haul road there was the same daily regular movements of dump trucks and other large machinery.  The haulage road is regularly damped down throughout each day with regular circuits of the driven water bowsers.  However, it is considered that the haul road experienced a brief drying out in that location on each occasion and it is considered this was the cause of the trigger alerts. | With the dry, warm weather the on-site bowsers will continue to maintain circuits of all the internal haul routes throughout each day. There is also a dust cannon at this location too. |
| AQ049              | 06/06/2025<br>16:01 – 17:00; 210.4 μg/m <sup>3</sup>   | At the time of the trigger alerts from monitor AQ049 which is located at the western boundary of the ancient woodland on the North Copthall site adjacent to the internal haul road there was the same daily regular movements of dump trucks and other large machinery.  The haulage road is regularly damped down throughout each day with regular circuits of the driven water bowsers.  However, it is considered that the haul road experienced a brief drying out in that location on this occasion and it is considered this was the cause of the trigger alerts.        | With the dry, warm weather the on-site bowsers will continue to maintain circuits of all the internal haul routes throughout each day.   |

Figure 5: Construction dust 1-hour mean indicative PM<sub>10</sub> concentration for all dust monitors







## **Appendix C - Air Quality Monitoring Results**

Table 3: NO₂ monitoring locations around highways, NO₂ concentrations and monthly monitoring results with running mean for 2025 (µg/m³)

| Monitoring Site | Location description   | Coordinates (X, Y) | Jan | Feb | Mar             | Apr | May             | Jun | Jul | Aug | Sep | Oct | Nov | Dec | Mean <sup>12</sup> |
|-----------------|--|--------------------|-----|-----|-----------------|-----|-----------------|-----|-----|-----|-----|-----|-----|-----|--------------------|
| HS2-000020BNT   | Lamp post on<br>Pembroke Road  | 509678, 187214     | 32  | 25  | 33              | 19  | 12              |     |     |     |     |     |     |     | 24                 |
| HS2-000020BNU   | Cowley Road<br>sign post at<br>junction with<br>Hillingdon Road                  | 505492, 183926     | 44  | 34  | Tube<br>Missing | 36  | 28              |     |     |     |     |     |     |     | 36                 |
| HS2-000020BNV   | High Street sign<br>post at junction<br>with Pembroke<br>Road                    | 509439, 187117     | 47  | 33  | 42              | 35  | Tube<br>Missing |     |     |     |     |     |     |     | 39                 |
| HS2-000020BNW   | Signpost on<br>A4020 Uxbridge<br>Road at<br>junction with<br>Long Lane           | 507365, 182687     | 38  | 43  | Tube<br>Missing | 45  | 25              |     |     |     |     |     |     |     | 38                 |
| HS2-000020BPK   | Lamp post in crescent off Swakeleys Road   | 506542, 186037     | 34  | 32  | 36              | 25  | 22              |     |     |     |     |     |     |     | 30                 |
| HS2-000020BPL   | Warren Road<br>sign post on<br>corner of<br>Swakeleys Road<br>and Warren<br>Road | 506240, 185660     | 43  | 20  | 12              | 26  | 22              |     |     |     |     |     |     |     | 24                 |

<sup>&</sup>lt;sup>1</sup> Note: to aid interpretation and conform with best practice, the monthly measurements in this table are reported rounded to the nearest whole number. The annual mean presented here is calculated based on laboratory data to 4 significant figures, rounded to a whole number, and therefore may differ slightly to a mean derived from averaging the rounded monthly measurements in the table.

<sup>&</sup>lt;sup>2</sup> The annual mean for diffusion tubes presented in the table above still require various analysis and adjustments to be undertaken before comparison to the Air Quality Objectives. The final corrected annual mean will be presented in the HS2 Annual Air Quality Report.

| Monitoring Site | Location description  | Coordinates (X, Y) | Jan | Feb | Mar             | Apr | May | Jun | Jul | Aug | Sep | Oct | Nov | Dec | Mean <sup>12</sup> |
|-----------------|---|--------------------|-----|-----|-----------------|-----|-----|-----|-----|-----|-----|-----|-----|-----|--------------------|
| HS2-000020BPN   | Lamp post on<br>B467  | 506767, 186224     | 41  | 38  | Tube<br>Missing | 32  | 19  |     |     |     |     |     |     |     | 32                 |
| HS2-000020BQH   | Lamp post on<br>High Road<br>Ickenham   | 508451, 186879     | 37  | 36  | 42              | 37  | 4   |     |     |     |     |     |     |     | 31                 |
| HS2-000020BQN   | Lamp post on<br>Park Road   | 506176, 185444     | 50  | 37  | 63              | 39  | 26  |     |     |     |     |     |     |     | 43                 |
| HS2-000020BQP   | Sign post on<br>Long Lane   | 507614, 184663     | 44  | 42  | Tube<br>Missing | 39  | 24  |     |     |     |     |     |     |     | 37                 |
| HS2-000020BP8   | Triplicate site at<br>South Ruislip<br>roadside<br>automatic<br>monitoring<br>station | 510858, 184916     | 34  | 30  | 45              | 30  | 21  |     |     |     |     |     |     |     | 32                 |