YAK-50, RA44541

AAIB Bulletin No: 11/2000 Ref: EW/G2000/05/04 Category: 1.3

Aircraft Type and Registration:	YAK-50, RA44541
No & Type of Engines:	1 Ivchenko M14P piston engine
Year of Manufacture:	1984
Date & Time (UTC):	4 May 2000 at 1513 hrs
Location:	White Waltham Airfield, Berkshire
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Damage to propeller and underside of aircraft
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	31 years
Commander's Flying Experience:	6,800 hours (less than one on type) Last 90 days - 240 hours Last 28 days - 75 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot

The pilot was making his first landing in his newly purchased aircraft on the grass Runway 07 at White Waltham airfield. The pilot omitted to select the landing gear down prior to touchdown.