April 2017 Scouting

ASC Area 6/8

Process: Deliver Service

Title: Electrical Scout Sheet

Mandatory	HA Process
Generic	
Contract Specific	HA4
Guidance	

Works Order No.		
Road:		A11
Date:		02/05/2017
Name:		[redacted]

c = consecutive	Direction	Position
S = Sequential	NB = North Bound, SB =South Bo	L1=Lane1, CR= Central reserve
	EB = East Bound, WB West Boun	LV=Left Verge, RV=Right Verge

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	RTA	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out: Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
											THICKTHORN						
	NO NUM							NB			ON RAB WESTSIDE						
126								NB	RV		BULK HEAD LIGHT UNDER A47						
TT021								NB	RV		BULK HEAD LIGHT UNDER A47						
TT034								NB	LV		1ST COL APPROACHING RAB						
TT063								NB	LV								
	NO NUM							NB	CR		SERVICE ROAD BOLLARD						
111								SB	LV		BULK HEAD LIGHT UNDER A47						
110								SB	LV		BULK HEAD LIGHT UNDER A47						
	NO NUM							SB			ON RAB NORTHSIDE						
	NO NUM							NB			ON RAB EASTSIDE						
TT005								SB	LV								
	NO NUM							WB	LV		SIGN AT ROAD TO SERVICES JNCT						
	NO NUM							SB	LV		LAST SIGN LEAVING RAB NATIONAL SPEED LIMIT						
TT006								SB	LV								
											TUTLES LANE						
TU005								SB	RV		ONSLIP						
	233							SB	RV		ON COL TU005						
TU014								NB	RV		OFF SLIP						
											MULBARTON						
	61							SB	RV		OFFSLIP						
											SPOONER ROW						
	NO NUM							NB	RV		OFFSLIP						
											ATTLEBOROUGH STAG						
AT020								EB	LV		AT CORNER OF SERVICE ROAD WROC LANE						
	NO NUM							SB	CR								
	NO NUM							SB	CR		BOLLARD						
	NO NUM							NB	CR		BOLLARD NORTH SIDE OF RAB						
AT007								SB	LV	1	LONDON ROAD JNCT DCP COL						
AT006											LONDON ROAD JNCT						
											STONE CROSS						
NO NUM								EB			BRIDGE LIGHT						
											SNETTERTON						
	NO NUM							SB	LV		OFFSLIP						
	NO NUM							NB	CR		BOLLARD OFFSLIP						
											ROUGHAM UNDERPASS						
NO NUM											3 X LIGHT SHADES MISSING						
											KILVERSTONE RAB (TESCO)						
WA016								NB	CR		NEW LANTERN REQ						
WA019								NB	CR								
WA003								NB	CR		1ST COL LEAVING RAB						
	NO NUM							WB	LV		KILVERSTONE SIDE OF RAB						
	NO NUM							EB	CR		BOLLARD SPLITTER ISLAND WATTON SIDE						
NO NUM									CR		WATTON SIDE						
											MUNDFORD RAB						
NO NUM								WB	LV		A1066 JNCT						
	NO NUM										BOLLARD NORTH SPLITTER ISLAND						
	NO NUM										BOLLARD SOUTH SPLITTER ISLAND						
	NO NUM										BOLLARD EAST SPLITTER ISLAND						
	351							EB	LV		CLEARWAY SIGN						
	NO NUM							EB	RV		CLEARWAY SIGN						
26	21				Totals					1							

COL Ref:		MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position		Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out: Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
											MUNDFORD RAB						
MU007								SB	LV	1	DCP						
											BRANDON						
	NO NUM								LV		BRANDON ROAD APPROACH						
	NO NUM								RV		BRANDON ROAD APPROACH						
	NO NUM								CR		A134 BOLLARD						
	NO NUM								CR		A134 SIGN						
	NO NUM							EB	LV		CLEARWAY SIGN						
	NO NUM							EB	RV		CLEARWAY SIGN						
BR002								SB	LV								
											THETFORD SAINSBURYS RAB						
	NO NUM							SB	CR		BOLLARD SPLITTER ISLAND LONDON R/BA/5						
											BARTON MILLS						

	01 12							NB	LV		NO CABLE IN POST						
	01 01										ON RAB						
27A								SB	LV								
	NO NUM							EB	LV		EAST APPROACH TO RAB						
	NO NUM							EB	RV		EAST APPROACH TO RAB						
31								SB	LV		AFTER RAB 50MPH SECTION						
34								SB	LV		AFTER RAB 50MPH SECTION						
40								NB	LV		CABLE FAULT						
41								NB	LV		CABLE FAULT						
42								NB	LV		CABLE FAULT						
	NO NUM							NB	LV		CABLE FAULT						
46								NB	LV		CABLE FAULT						
26								SB	LV		CABLE FAULT						
32								SB	LV		CABLE FAULT						
33								SB	LV		CABLE FAULT						
35								SB	LV		CABLE FAULT						
13	12		3		Totals					1							

ASC Area 6/8

Process: Deliver Service

Title: Electrical Scout Sheet

Mandatory	HA Process
Generic	HA4
Contract Specific	
Guidance	

Works Order No.		
Road:		A11
Date:		27.2.17
Name:		

c = consecutive	Direction	Position
S = Sequential	NB = North Bound, SB =South Bound	L1=Lane1, CR= Central reserve
	EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out: Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
										THICKTHORN						
	NO NUM							NB		ON RAB WESTSIDE						
128								NB	RV	BULK HEAD LIGHT UNDER A47						
NO NUM								NB	RV	BULK HEAD LIGHT UNDER A47						
NO NUM								NB	LV	1ST COL APPROACHING RAB						
NO NUM								SB	LV	NEXT TO TRAFFIC LIGHT 13						
	NO NUM							NB	CR	SERVICE ROAD BOLLARD						
111								SB	LV	BULK HEAD LIGHT UNDER A47						
110								SB	LV	BULK HEAD LIGHT UNDER A47						
	NO NUM							SB		ON RAB NORTHSIDE						
	NO NUM							NB		ON RAB EASTSIDE						
NO NUM								NB	LV	AT RAB BETWEEN A47 EB OFFSLIP AND SERVICE ROAD						
	NO NUM							WB	LV	SIGN AT ROAD TO SERVICES JNCT						
	NO NUM							SB	LV	LAST SIGN LEAVING RAB NATIONAL SPEED LIMIT						
										TUTLES LANE						
TU005								SB	RV	ONSLIP						
	233							SB	RV	ON COL TU005						
										MULBARTON						
	91							SB	RV	OFFSLIP						
										SPOONER ROW						
	NO NUM							NB	RV	OFFSLIP						
										ATTLEBOROUGH STAG						
AT020								EB	LV	AT CORNER OF SERVICE ROAD WROO LANE						
	NO NUM							SB	CR							
	NO NUM							SB	CR	BOLLARD						
	NO NUM							NB	CR	BOLLARD NORTH SIDE OF RAB						
AT007								SB	LV	LONDON ROAD JNCT DCP COL						
AT006										LONDON ROAD JNCT						
										STONE CROSS						
NO NUM								EB		BRIDGE LIGHT						
										SNETTERTON						
SN004								SB	RV	ONSLIP 2ND COL						
	NO NUM							SB	LV	OFFSLIP						
	NO NUM							NB	CR	BOLLARD OFFSLIP						
										ROUGHAM UNDERPASS						
NO NUM										3 X LIGHT SHADES MISSING						
										KILVERSTONE RAB						
NO NUM								SB	LV	COLUMN SPLITTER ISLAND NO LANTERN						
NO NUM								SB	LV	COLUMN NEXT TO FEED PILLAR						
NO NUM								NB	CR	1ST COL LEAVING RAB						
	NO NUM							WB	LV	KILVERSTONE SIDE OF RAB						
	NO NUM							EB	CR	BOLLARD SPLITTER ISLAND WATTON SIDE						
NO NUM									CR	WATTON SIDE						
										MUNDFORD RAB						
NO NUM								WB	LV	A1066 JNCT						
	NO NUM									BOLLARD NORTH SPLITTER ISLAND						
	NO NUM									BOLLARD SOUTH SPLITTER ISLAND						
	NO NUM									BOLLARD EAST SPLITTER ISLAND						
	381							EB	LV	CLEARWAY SIGN						
	NO NUM							EB	RV	CLEARWAY SIGN						
					Totals											

COL Ref:		MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out					
											Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
										BRANDON						
	NO NUM								LV	BRANDON ROAD APPROACH						
	NO NUM								RV	BRANDON ROAD APPROACH						
	NO NUM								CR	A134 BOLLARD						
	NO NUM								CR	A134 SIGN						
	NO NUM							EB	LV	CLEARWAY SIGN						
	NO NUM							EB	RV	CLEARWAY SIGN						
NO NUM								SB	LV	DCP						
										THETFORD SAINSBURYS RAB						
	NO NUM							SB	CR	BOLLARD SPLITTER ISLAND LONDON ROAD						
										BARTON MILLS						
	01 12							NB	LV	NO CABLE IN POST						
	01 01									ON RAB						
27A								SB	LV							
	NO NUM							EB	LV	EAST APPROACH TO RAB						
	NO NUM							EB	RV	EAST APPROACH TO RAB						
31								SB	LV	AFTER RAB 50MPH SECTION						
34								SB	LV	AFTER RAB 50MPH SECTION						
40								NB	LV	CABLE FAULT						
41								NB	LV	CABLE FAULT						
42								NB	LV	CABLE FAULT						
	NO NUM							NB	LV	NEXT TO 42						
26					Totals											

ASC Area 6/8

Process: Deliver Service

Title: Electrical Scout Sheet

Mandatory	HA Process
Generic	HA4
Contract Specific	
Guidance	

Works Order No.		
Road:		A11
Date:		23.1.17
Name:		

	Direction	Position
c = consecutive		
S = Sequential	NB = North Bound, SB =South Bound	L1=Lane1, CR= Central reserve
	EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out: Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
										THICKTHORN						
	NO NUM							NB		ON RAB WESTSIDE						
128								NB	RV	BULK HEAD LIGHT UNDER A47						
NO NUM								NB	RV	BULK HEAD LIGHT UNDER A47						
NO NUM								NB	LV	1ST COL APPROACHING RAB						
NO NUM								SB	LV	NEXT TO TRAFFIC LIGHT 13						
	NO NUM							NB	CR	SERVICE ROAD BOLLARD						
111								SB	LV	BULK HEAD LIGHT UNDER A47						
	NO NUM							SB		ON RAB NORTHSIDE						
	NO NUM.							NB		ON RAB EASTSIDE						
NO NUM								NB	LV	AT RAB BETWEEN A47 EB OFFSLIP AND SERVICE ROAD						
	NO NUM							WB	LV	SIGN AT ROAD TO SERVICES JNCT						
	NO NUM							SB	LV	LAST SIGN LEAVING RAB NATIONAL SPEED LIMIT						
										TUTLES LANE						
899								SB	RV	ONSLIP						
	233							SB	RV	ON COL 899						
NO NUM								NB	RV	OFFSLIP 1ST COL						
										MULBARTON						
	61							SB	RV	OFFSLIP						
										SPOONER ROW						
	NO NUM							NB	RV	OFFSLIP						
										ATTLEBOROUGH STAG						
NO NUM								EB	LV	AT CORNER OF SERVICE ROAD WROO LANE						
NO NUM								NB	LV	1ST COL APPROACH TO RAB						
	NO NUM							SB	CR							
	NO NUM							SB	CR	BOLLARD						
	NO NUM							NB	CR	BOLLARD NORTH SIDE OF RAB						
NO NUM								SB	LV	LONDON ROAD JNCT DCP COL						
										STONE CROSS						
NO NUM								EB		BRIDGE LIGHT						
										SNETTERTON						
NO NUM								SB	RV	ONSLIP 2ND COL						
	NO NUM							SB	LV	OFFSLIP						
	NO NUM							NB	CR	BOLLARD OFFSLIP						
										ROUGHAM UNDERPASS						
NO NUM										3 X LIGHT SHADES MISSING						
										KILVERSTONE RAB						
NO NUM								SB	LV	COLUMN SPLITTER ISLAND DCP						
16J								NB	CR	1ST COL LEAVING RAB						
	NO NUM							WB	LV	KILVERSTONE SIDE OF RAB						
	NO NUM							EB	CR	BOLLARD SPLITTER ISLAND WATTON SIDE						
NO NUM									CR	WATTON SIDE						
										MUNDFORD RAB						
NO NUM								WB	LV	A1066 JNCT						
	NO NUM									BOLLARD NORTH SPLITTER ISLAND						
	NO NUM									BOLLARD SOUTH SPLITTER ISLAND						
	NO NUM									BOLLARD EAST SPLITTER ISLAND						
	351							EB	LV	CLEARWAY SIGN						
	NO NUM							EB	RV	CLEARWAY SIGN						
					Totals											

COL Ref.		MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out					
											Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
										BRANDON						
	NO NUM								LV	BRANDON ROAD APPROACH						
	NO NUM								RV	BRANDON ROAD APPROACH						
	NO NUM								CR	A134 BOLLARD						
	NO NUM								CR	A134 SIGN						
	NO NUM							EB	LV	CLEARWAY SIGN						
	NO NUM							EB	RV	CLEARWAY SIGN						
NO NUM								SB	LV	DCP						
										THETFORD SAINSBURYS RAB						
	NO NUM							SB	CR	BOLLARD SPLITTER ISLAND LONDON ROAD						
										BARTON MILLS						
	01 12							NB	LV	NO CABLE IN POST						
	01 01									ON RAB						
27A								SB	LV							
	NO NUM							EB	LV	EAST APPROACH TO RAB						
	NO NUM							EB	RV	EAST APPROACH TO RAB						
31								SB	LV	AFTER RAB 50MPH SECTION						
34								SB	LV	AFTER RAB 50MPH SECTION						
40								NB	LV	CABLE FAULT						
41								NB	LV	CABLE FAULT						
42								NB	LV	CABLE FAULT						
	NO NUM							NB	LV	NEXT TO 42						
					Totals											

ASC Area 6/8

Process: Deliver Service

Title: Electrical Scout Sheet

Mandatory	HA Process
Generic	
Contract Specific	HA4
Guidance	

Works Order No.		
Road:		A11
Date:		24.11.16
Name:		

	Direction	Position
c = consecutive		
S = Sequential	NB = North Bound, SB =South Bound	L1=Lane1, CR= Central reserve
	EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out: Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
										THICKTHORN						
	NO NUM							NB		ON RAB WESTSIDE						
128								NB	RV	BULK HEAD LIGHT UNDER A47						
NO NUM								NB	LV	1ST COL APPROACHING RAB						
NO NUM								SB	LV	NEXT TO TRAFFIC LIGHT 13						
	NO NUM							NB	CR	SERVICE ROAD BOLLARD						
111								SB	LV	BULK HEAD LIGHT UNDER A47						
	NO NUM							SB		ON RAB NORTHSIDE						
	NO NUM							NB		ON RAB EASTSIDE						
NO NUM								NB	LV	AT RAB BETWEEN A47 EB OFFSLIP AND SERVICE ROAD						
	NO NUM							WB	LV	SIGN AT ROAD TO SERVICES JNCT						
	NO NUM							SB	LV	LAST SIGN LEAVING RAB NATIONAL SPEED LIMIT						
										TUTLES LANE						
899								SB	RV	ONSLIP						
	233							SB	RV	ON COL 899						
NO NUM								NB	RV	OFFSLIP 1ST COL						
										MULBARTON						
	61							SB	RV	OFFSLIP						
	NO NUM							NB	LV	ONSLIP						
	NO NUM							NB	RV	ONSLIP						
										SPOONER ROW						
	NO NUM							NB	RV	OFFSLIP						
										ATTLEBOROUGH STAG						
NO NUM								EB	LV	AT CORNER OF SERVICE ROAD WROO LANE						
NO NUM								NB	LV	1ST COL APPROACH TO RAB						
	NO NUM							SB	CR							
	NO NUM							SB	CR	BOLLARD						
	NO NUM							NB	CR	BOLLARD NORTH SIDE OF RAB						
	NO NUM							EB	LV	LONDON ROAD JNCT						
	NO NUM							EB	RV	LONDON ROAD JNCT						
	NO NUM									4X SIGNS OUT ON RAB DCP						
NO NUM								SB	LV	LONDON ROAD JNCT DCP COL						
										STONE CROSS						
NO NUM								EB		BRIDGE LIGHT						
										SNETTERTON						
	NO NUM							SB	LV	ONSLIP						
	NO NUM							SB	RV	ONSLIP						
										ROUGHAM UNDERPASS						
NO NUM										3 X LIGHT SHADES MISSING						
										KILVERSTONE RAB						
	NO NUM							SB	LV	BOLLARD SPLITTER ISLAND						
NO NUM								SB	LV	COLUMN SPLITTER ISLAND DCP						
15J								NB	CR	1ST COL LEAVING RAB						
	NO NUM							WB	LV	KILVERSTONE SIDE OF RAB						
	NO NUM							EB	CR	BOLLARD SPLITTER ISLAND WATTON SIDE						
										MUNDFORD RAB						
NO NUM								WB	LV	A1066 JNCT						
	NO NUM									BOLLARD NORTH SPLITTER ISLAND						
	NO NUM									BOLLARD SOUTH SPLITTER ISLAND						
	NO NUM									BOLLARD EAST SPLITTER ISLAND						
	351							EB	LV	CLEARWAY SIGN						
	NO NUM							EB	RV	CLEARWAY SIGN						
					Totals											

											Repair Carried out					
COL Ref:		MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
										BRANDON						
	NO NUM								LV	BRANDON ROAD APPROACH						
	NO NUM								RV	BRANDON ROAD APPROACH						
	NO NUM								CR	A134 BOLLARD						
	NO NUM								CR	A134 SIGN						
	NO NUM							EB	LV	CLEARWAY SIGN						
	NO NUM							EB	RV	CLEARWAY SIGN						
NO NUM								SB	LV	DCP						
										THETFORD SAINSBURYS RAB						
	NO NUM							SB	CR	BOLLARD SPLITTER ISLAND LONDON ROAD						
										BARTON MILLS						
	01 12							NB	LV	NO CABLE IN POST						
	01 01									ON RAB						
27A								SB	LV							
	NO NUM							EB	LV	EAST APPROACH TO RAB						
	NO NUM							EB	RV	EAST APPROACH TO RAB						
31								SB	LV	AFTER RAB 50MPH SECTION						
34								SB	LV	AFTER RAB 50MPH SECTION						
40								NB	LV	CABLE FAULT						
41								NB	LV	CABLE FAULT						
42								NB	LV	CABLE FAULT						
	NO NUM							NB	LV	NEXT TO 42						
										RED LODGE						
	NO NUM							NB	RV	ONSLIP						
	NO NUM							SB	LV	ONSLIP						
					Totals											

ASC Area 6/8

Process: Deliver Service

Title: Electrical Scout Sheet

Mandatory	HA Process
Generic	HA4
Guidance	

Works Order No.		
Road:		A11
Date:		27-10-16
Name:		[redacted]

C = consecutive	Direction	Position
S = Sequential	NB = North Bound, SB = South Bound	L1=Lane1, CR= Central reserve
	EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct.	Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
										Thickthorn						
	NO Num									westside on RAB						
128								N	R	bridge light						
NO Num								N	L	1st col approach to RAB						
"								S	L	Next to traffic light 13						
	NO Num							N	CR	Service Rd bollard						
126										west side bridge light						
										Tuttles lane						
899								S	R	on slip						
NO Num								N	R	offslip 1st col						
										Stone cross						
NO Num								E		bridge light						
										Walton RAB						
	NO Num							E	L	splitter Island bollard						
163								N	CR	1st col leaving RAB						
										Mundford RAB						
NO Num																
								W	L	A1066 Jnct						
										Brandon						
	NO Num								L	brandon Rd approach						
	"								R	" "						
	"								CR	A134 bollard						
	"								"	" Sign						
	"							E	LV	clearway Sign						
	"							E	RV	"						
										Sainsburys RAB						
	NO Num								CR	bollard on splitter island						
										Barton Mills						
	01-12							N	L	No cable						
34								S	L	50mph section						
	NO Num							E	L	east approach						
	"							E	R	" "						
40								NB	LV	fault						
41								"	"	↓						
42								"	"							
						Totals										

Spooner Row - 1x Sign NB offslip

Attleborough Stag RAB 1x 12m col 1x 10m col 1x Sign

Brandon Rd RAB 1x 12m col

ASC Area 6/8

Process: Deliver Service

Title: Electrical Scout Sheet

Mandatory	HA Process
Generic	HA4
Contract Specific	
Guidance	

Works Order No.		
Road:		A11
Date:		18 - 3 - 16
Name:		[redacted]

c = consecutive	Direction	Position
S = Sequential	NB = North Bound, SB =South Bound	L1=Lane1, CR= Central reserve
	EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out: Lamp Type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
										Thetford						
	No Num									west side on RAB						
128								NB	RV	bridge light						
No Num								NB	LV	first col approach to RAB						
"								SB	LV	next to traffic light 13						
	No Num							NB	CR	Service Rd bollard						
126																
128										west bridge lights						
										Tuttles Lane						
899								SB	RV	onslip						
										Stone Cross						
No Num								EB		bridge light						
										Walton RAB						
	No Num							EB	LV	splitter island bollard						
165								NB	CR	14 col leaving RAB						
										Muckfield RAB						
No Num								WB	LV	A1066 spur						
										Brandon						
	No Num								LV	Brandon Rd approach						
	"								RV	" "						
	"								CR	A134 bollard						
	"									" sign						
	"									clearway sign						
	"									" "						
	"									uplighter A134 side RAB						
										Swaffham RAB						
	No Num							SB	CR	bollard on splitter London Rd						
										Barton Mills						
	01-12							NB	LV	~~No Number~~ No cable						
34								SB	LV	50 mph section						
	No Num							EB	LV	exit approach						
	"							"	RV	" "						
40			✓					NB	LV	fault						
41			✓													
42			✓													
43			✓													
44			✓													
45			✓													
46			✓													
					Totals											

Spooner Row: No Num - Sign NB offslip

Attleborough Sting RAB: No Num 12M col, No Num 10M col, Sign - No Num

Brandon Rd RAB: No Num - 12M col

Barton Mills: Sign No Number

COL Ref:	SIGN Bollard Ref:	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct,	Repair Carried out					
											Lamp /type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
32										Marks Tey						
24								EB	LV							
42								"	"							
74								"	"							
52								"	"							
48								"	"							
15								"	"							
7								WB	LV							
	NO NUM								CR	centre island london rd RAB						
	NO NUM							EB	LV	40 mph signs station rd						
	NO NUM							EB	RV	" "						
NO NUM									CR	Ped crossing opp bus stop						
14								EB	LV	on second RAB						
T47										Ardleigh crown RAB						
	S197								LV	RAB						
	S22								LV	"						
									LV	"						
	B1									Markey street						
	B2							EB	LV							
								"	"							
HC4										Horsley cross						
7									CR	approach to RAB						
15									LV	RAB						
9									LV	RAB						
	NO NUM							EB	LV	.						
	NO NUM								CR							
R1										Ramsey						
R3								EB	LV							
R10								↓	↓							
R11								↓	↓							
R12								↓	↓							
R13								↓	↓							
R14								↓	↓							
R15								↓	↓							
R16								↓	↓							
R17								↓	↓							
R21								WB	LV							
R23								↓	↓							
	S12								CR	Church hill exit						
	108							WB	LV	" "						
P38										Parkstone						
39									LV	RAB						
15			✓						LV	"						
	NO NUM		✓						CR	"						
									CR	"						
					Totals											