Accident

Aircraft Type and Registration:	EMB-145EP, G-SAJE
No & Type of Engines:	2 Allison Ae 3007/A1/1 turbofan engines
Year of Manufacture:	2001 (Serial no: 145442)
Date & Time (UTC):	10 December 2024 at 0930 hrs
Location:	During initial climb out from Edinburgh Airport
Type of Flight:	Commercial Air Transport (Passenger)
Persons on Board:	Crew - 3 Passengers - 20
Injuries:	Crew - 1 (Serious) 2 (None) Passengers - None
Nature of Damage:	None
Commander's Licence:	Airline Transport Pilot's Licence
Commander's Age:	26 years
Commander's Flying Experience:	3,045 hours (of which 1,903 were on type) Last 90 days - 193 hours Last 28 days - 47 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot

After departure from Edinburgh, the cabin crew member was released to commence duties but hurt an ankle after slipping on what is believed to be de-icing fluid on the floor near the front of the aircraft.

Following a discussion with the commander, the cabin crew member was relieved from performing the in-flight drinks service but was still able to perform safety duties, albeit with some discomfort. Upon later examination at hospital, the ankle was found to be fractured.

© Crown copyright 2025