Product Safety Report

Giant Momentum Vida E+ Bicycle

Aspect	Details
Images	2022 Vida E+ Low -Step 2022 Vida E+ Mid -Step
PSD Number	2507-0146
Product Type	Hobby/sports equipment - Cycles (Powered)
Product Identifiers	Brand: Momentum (Giant UK Limited) Model year: 2022 Please access Annex 1 to establish if your bicycle is affected.
Product Description	A two-wheeled electric bicycle sold in black, white, red and yellow colours. The frame number is engraved in the lower left rear dropout or underneath the top tube on a barcode sticker.
Country of Origin	China
Counterfeit	No
Risk Level	Not provided
Risk Type	Injuries
Risk Description	Affected bicycles present a risk of injuries as it is possible for the steering tube on the front fork of the bike to fracture. If this happened during use, it could result in the user losing control of the bicycle and receiving injuries. The affected products do not meet the requirements of the General Product Safety Regulations 2005.
Corrective Measures	Modification programme. Consumers who own a 2022 Momentum Vida E+ Bicycle should check their frame number to determine whether their bicycle needs to be inspected and if necessary, have the fork replaced. To arrange an inspection, consumers are advised to contact the authorised Giant/Momentum retailer from which the bike was purchased. For further details, please access the Momentum notice here: https://www.momentum-biking.com/gb/community/safety-recall-notice.html.
Online Marketplace	N/A
Notifier	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts

Product Safety Report

Annex 1 – Affected or potentially affected products

Bikes with a frame number in which the third character is **E or F are not affected** and require no action.

Frame number third character	Action required
G	Fork requires inspection
H	Affected – Fork requires replacing
J	Affected – Fork requires replacing
K	Affected – Fork requires replacing

Fork number first character	Action required
M	Affected – Fork requires replacing UNLESS there is a rivet on the back of the fork crown

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: https://www.gov.uk/guidance/product-recalls-and-alerts