




Yamaha Drive 2 AC and Drive 2 AC Li Golf Cars	
Aspect	Details
Images	
PSD Number	2604-0136
Product Type	Motor vehicles (including spare parts) - Utility Task Vehicles (UTVs)/ Recreational Off-Road Vehicles (ROVs)
Product Identifiers	Brand: Yamaha Please access Annex A for further details on the affected products.
Product Description	DR2E Golf utility vehicles with model year 2021 and 2022.
Country of Origin	United States
Counterfeit	No
Risk Level	Not provided
Risk Type	Injuries
Risk Description	<p>The affected golf cars present a risk of injuries as the cable brake is incorrectly routed meaning there is a sharp bend which creates a stress point. As a result, the cable brake could fail unexpectedly whilst in use and the user may not be able to stop the vehicle as intended.</p> <p>The affected products do not meet the requirements of the Supply of Machinery (Safety) Regulations 2008.</p>
Corrective Measures	<p>Recall of the product from end users. Yamaha have launched a modification programme to inspect and replace the brake cable.</p> <p>Consumers who own an affected golf car should contact their local Authorised Yamaha Dealer, quoting the machine's chassis number to arrange a convenient appointment for the necessary work to be carried out by a Yamaha trained technician. Please access the following link to locate your nearest dealer: https://www.yamahamotor.eu/gb/en/dealer-locator/.</p> <p>For further details, please access the access the Yamaha Motor recall page at the following link: https://www.yamaha-motor.eu/gb/en/service-support/recall/golf/. For further questions, please contact Yamaha Motor UK customer support team on: +44 (0)114 553 3099, or via emailing customersupport@yamahamotor.co.uk.</p>
Online Marketplace	N/A
Lead Authority	Local Authority Trading Standards



Office for Product
Safety & Standards

Product Recall

Annex A – Affected golf cars

Model	Frame number
JOJ5 (2021)	Between: JOJ 410201-414900
JOJ6 (2022)	Between: JOJ 500101-505608
J5B1 (2022)	Between: J5B 000101-000300