



Hidrostan Out/Permarmor (UK) Limited Ethylene Propylene Diene Monomer (EPDM) Membrane HIDROSTAN OUT, 0.75mm Ethylene Propylene Diene Monomer (EPDM) façade membrane, fire rating Class B, (also referred to as ‘CLASS B FR HIDROSTAN 0,75’ and Permarmor EPDM material)

Aspect	Details
Images	
PSD Number	2606-0245
Product Type	Construction product - EPDM (Ethylene Propylene Diene Monomer) façade membrane
Product Identifiers	Brand: Hidrostan Out/Permarmor (UK) Limited Product thickness: 0.75mm
Product Description	EPDM (Ethylene Propylene Diene Monomer) façade membrane, fire classification B, 0,75mm thickness, known as ‘Hidrostan Out’ and ‘Permarmor EPDM material’. Affected product were available on the market between 31 October 2024 and 24 September 2025. All batches within the dates specified were affected.
Country of Origin	Spain
Counterfeit	No
Risk Level	Not provided
Risk Type	Non-compliance
Risk Description	The product is marketed as Euroclass B, but there is no evidence that it could consistently achieve Euroclass B for reaction to fire performance. The product therefore may not perform with the declared reaction to fire performance required or be suitable for its original desired application. The product does not meet the requirements of EU Construction Products Regulation 305/2011 as they apply in the UK.
Corrective Measures	Permarmor (UK) Limited, importer of the EPDM façade membrane, with declared performance of Euroclass B for fire performance, notified the two distributors in its supply chain of the product not meeting its declared fire



	performance. Distributors Dorteck Direct Limited and BuildmasterUK Limited have notified their affected customers directly. Businesses who may have purchased this product and not been contacted by Dorteck Direct Limited and BuildmasterUK Limited should contact the distributor directly. The potential impact of lower performance of a product in relation to reaction to fire and building safety will vary on a project-by-project basis and will depend on factors unique to each building. Where already incorporated, building owners should seek advice from their building safety officer, an independent inspector, fire safety officer or a relevant building control authority, as appropriate, and consider reviewing the building's fire strategy if necessary.
Online Marketplace	N/A
Notifier	Office for Product Safety and Standards