



3M Peltor Comtac VIII Headset	
Aspect	Details
Images	
PSD Number	2607-0161
Product Type	Personal protective equipment (PPE) - Hearing Protection - Powered
Product Identifiers	Brand: 3M For a full list of identifiers and how to locate them, please see Annex A.
Product Description	Over the ear hearing protection and communications headset designed for military and civil defence personnel. Recall is applicable to headsets manufactured between November 27, 2025 and February 6, 2026 with the model/type and printed circuit board assembly numbers listed in Annex A.
Country of Origin	Sweden
Counterfeit	No
Risk Level	Serious
Risk Type	Risk of hearing loss
Risk Description	The product presents a serious risk of hearing loss because affected batches may emit feedback noise (measured up to 106 dBA) through the headset speakers. The likelihood of occurrence of this issue can be increased in cold ambient temperatures and with a depleted battery state. The product does not meet the requirements of the Regulation (EU) 2016/425 on Personal Protective Equipment and the applicable standards: EN 352-1:2020, EN 352-4:2020, EN 352-6:2020.
Corrective Measures	The product has been recalled from distributors by 3M United Kingdom PLC. A Stop Use Notification has been issued. For more information, or to check whether your product is affected, please contact your distributor.
Online Marketplace	N/A
Notifier	Health and Safety Executive



Annex A

Model/Type

MT14H418A-02
MT14H418A-35
MT14H418A-38
MT14H418A-86
MT14H418A-87
MT14H418A-90

Identifying Impacted Products

Step 1: To determine if your headset model is affected, locate the Model ID printed on the outside of the cup (see Figure 1a) or the box label (See Figure 1b or 1c). Compare the Model ID on the cup to the list above. If the Model ID matches any in the table, continue to Step 2. If they do not match any number in the table, your product is not affected by this Notice.

Figure 1a



Figure 1b



Figure 1c



Step 2: Locate the manufacturing date (YYYY/MM) printed on the outside of the cup (see Figure 2a) or the box label (See Figure 2b or 2c). If the headset manufacture date is during or between 2025/11 (11th month 2025) and 2026/02 (2nd month 2026), your product may be affected. Continue to Step 3

Figure 2a



Figure 2b



Figure 2c



Step 3: Locate the first 9-digits of the manufacturing identification number printed on the The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: <https://www.gov.uk/guidance/product-recalls-and-alerts>



Office for Product Safety & Standards

Product Recall

outside of the cup (see Figure 3a) or the box label (See Figure 3b or 3c). If the headset identification number matches an ID in Table A, your product is affected.

Figure 3a



Figure 3b



Figure 3c



Table A:

108775721	109144338	109192458	109233313	109279617	109360936	109456621
108863341	109145831	109192862	109239367	109285367	109365614	109458072
109077741	109150424	109197373	109244468	109287901	109365615	109460871
109082396	109174022	109198474	109248672	109298189	109370555	109462455
109109939	109174023	109207131	109248673	109302476	109375025	109462457
109124149	109178217	109209709	109259266	109308224	109411650	
109125200	109178218	109224666	109259267	109312449	109433818	
109139789	109183911	109224667	109270474	109331229	109438243	
109139793	109183912	109229134	109270477	109339849	109451206	
109144337		109229138	109270479	109342506		



Product Recall


Alternative Identification Method - Printed Circuit Board Assembly (PCBA) batch numbers:

Affected products will have the following Printed Circuit Board Assembly batch numbers: 2547, 2549, 2550 and 2552.

Step 1: To remove sealing ring from the left cup (boom mic/keypad side), grab the ring as shown in the picture and pull the ring outwards.



Step 2: When the ring is removed from the cup, also remove the foam that is placed inside the cup.



In the example shown to the left, the batch of the PCBA is "2524" representing manufacturing year 2025 and week 24.