

In support of objection submitted by Great Hallingbury Neighbours Association



Figure -1



Figure-2



Figure 3




Figure -4




Figure 5



Figure 6



Figures 1 & 2 are photos of a pot hole on the bend close to the entrance to the fishing lake, particularly dangerous as cars pull onto the wrong side of the road (on a bend) to avoid it. Approx. 27" (69cm) across and 5" (12cm) deep. It is on the side of the road heading from Latchmore Bank towards B1256

Figures 3 & 4 are photos of a pot hole between the entrance to the fishing lake and Captains. Approx. 33" (84cm) across and 3" (7.5cm) deep. It is on the side of the road heading from Latchmore Bank towards B1256

Figures 5 & 6 are photos of a pot hole between the entrance to the Harps Farm opposite the farm cottages. Approx. 68" (173cm) across and 6.5" (16cm) deep. It is on the side of the road heading from B1256 heading towards Latchmore Bank.

The last 6 photos are of three different drains on the road heading from Latchmore Bank towards B1256 close to the entrance to Bedlars Green and show sunken drains.