(Revised Feb 19)

PPQ = 1

MDS Reporting

- 1. Historic aircraft are subject to MDS reporting, information from the front page of F707Bs is captured on a database managed by the BBMF PT. Sheet 1 of the MOD Form 707B(ADP) or photocopies of the front sheet of the MOD Form 707B(IS) are to be forwarded at least quarterly upon completion to the PT for entry on to the database. Completed MOD Forms 707A, 707B(ADP)/original 707B(IS) card copies, are to be retained at the Unit for the <u>life of the aircraft, plus 2 years.</u>
- 2. Refer to MOD Form 799/5A(ADP) for reporting requirements.
 - a. For all instances where work is undertaken on an SSI, the SSI number is to be recorded in the 'Management Aid' field.
 - b. Removed item condition should be provided if applicable and available, and "Y" annotated on the MOD Form 731 Equipment Conditioning Label 'MDS Reportable' field.