



Home Office

Room No: R10a/B10, Scientific Development Branch, Sandridge, St Albans, Herts, AL4 9HQ
Fax 01727 816473 Direct Line 01727 816391
E-mail ian.humphrey@homeoffice.gsi.gov.uk www.homeoffice.gov.uk

Simon Griffiths
Technical Director
RedSpeed International Ltd
Unit 21, Birchen Coppice Trading Estate
Stourport Rd, Kidderminster
Worcs DY11 7QY

Our Ref **CFP 7/10/1234**
Your Ref **HO/A/10/016**
Date **5th January 2011**

cc: T Hall
S Lewis
S Jegede

Re: Replacement Colour Camera in the RedFusion Head

In your letter dated 9th December 2010, you requested authorisation for a change to the approved colour camera in the RedFusion head, due to component obsolescence.

We are pleased to inform you that this change is acceptable, and no testing will be required before the amendment can be used. It is understood that there will be no other changes in the approved hardware or software.

The existing camera is a Dalsa Genie C1410 v 1.31.151 with firmware v27719 (RedSpeed part number 800-020). The replacement camera is a Dalsa Genie C1410 v 1.70.220 with firmware v54858 (RedSpeed part number 800-036). We require that all new builds use the new parts, but you may use old stock to repair existing units.

Our records will be amended to incorporate this change.

Ian Humphrey

