

ACCIDENT

Aircraft Type and Registration:	Montgomerie-Bensen B8MR, G-CBSV
No & Type of Engines:	1 Rotax 912-UL piston engine
Year of Manufacture:	2002
Date & Time (UTC):	19 November 2009 at 1200 hrs
Location:	Damyns Hall Aerodrome, Upminster, London
Type of Flight:	Private
Persons on Board:	Crew - 1 Passengers - None
Injuries:	Crew - None Passengers - N/A
Nature of Damage:	Damage to rotor and propeller
Commander's Licence:	Private Pilot's Licence (Gyroplane)
Commander's Age:	62 years
Commander's Flying Experience:	Not provided
Information Source:	Aircraft Accident Report Form submitted by the pilot

The pilot was practising flying circuits with tight left turns and short landing rolls. On the accident circuit the autogyro had insufficient height to complete the final

turn and it touched down with right slip, causing it to roll onto its side. The pilot was uninjured.