

No: 8/86

Ref: 1b

Aircraft type and registration: Grumman AA1 G-BCIL

No & Type of engines: 1 Lycoming 0-235-C2C piston engine

Year of Manufacture: 1974

Date and time (UTC): 14 June 1986 at 1415 hrs

Location: Lambs Hillock, Ellen, Aberdeenshire

Type of flight: Private (pleasure)

Persons on board: Crew — 1 Passengers — 1

Injuries: Crew — 1 (Minor) Passengers — 1 (Minor)

Nature of damage: Damage to propeller, engine cowl, canopy and fin

Commander's Licence: Private Pilot's Licence

Commander's Age: 38 years

Commander's Total Flying Experience: 66 hours (of which 2 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot.

The aircraft was on a low approach to land, into wind (10 knots), in a field. When it was crossing a track at the field boundary it contacted a wire fence and was pitched nose down. It struck the ground and came to rest inverted. The occupants received minor injuries.