No: 2/85 Ref: EW/G84/12/07

Aircraft type and registration: Jodel D117 G-BDIH (light single engine fixed wing aircraft)

Year of Manufacture: 1958

Date and time (GMT): 9 December 1984 at 1200 hrs

Location: Rydinghurst Farm, Cranleigh

Type of flight: Private (Pleasure)

Persons on board: Crew -1 Passengers -1

Injuries: Crew — None Passengers — None

Nature of damage: Damage to undercarriage legs and mountings and also engine cowling.

Propeller broken

Commander's Licence: Airline Transport Pilot's Licence

Commander's Age: 37 years

Commander's total flying

experience 3,337 hours (of which 50 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot

The pilot was attempting to land on a farm strip with a light tailwind component but misjudged the approach. As a result the aircraft touched down heavily in very soft ground approximately 6 metres short of the runway threshold. The undercarriage sank into the ground causing the aircraft to tip forward on to its nose. It skidded to a halt in about 8 metres, and both occupants escaped without suffering any injuries.