

ACCIDENT

Aircraft Type and Registration:	Cessna 120, G-BUJM	
No & Type of Engines:	1 Continental Motors Corp C85-12F piston engine	
Year of Manufacture:	1946	
Date & Time (UTC):	30 July 2011 at 1105 hrs	
Location:	Yeovilton Airfield, Somerset	
Type of Flight:	Training	
Persons on Board:	Crew - 2	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Left mainwheel, tailwheel mounting, right landing gear mounting	
Commander's Licence:	Airline Transport Pilot's Licence	
Commander's Age:	60 years	
Commander's Flying Experience:	9,870 hours (of which 3 were on type) Last 90 days - 55 hours Last 28 days - 10 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

After a normal approach and touchdown in a headwind of 8-10 kt, considered normal by the pilot, the aircraft yawed to the right. The pilot and instructor applied full left rudder and left brake but the aircraft continued to

yaw right, stopping after approximately 270° of right yaw. Both occupants were wearing a lap and diagonal harness and were uninjured.