

No: 2/90

Ref: EW/G89/11/09

Category: 1c

**Aircraft Type and Registration:** Piper Warrior II PA 28-161, G-BNJT

**No & Type of Engines:** 1 Lycoming O-320-D3G piston engine

**Year of Manufacture:** 1981

**Date and Time (UTC):** 6 November 1989 at 1115 hrs

**Location:** Wycombe Air Park, Buckinghamshire

**Type of Flight:** Private (pleasure)

**Persons on Board:** Crew - 1 Passengers - 2

**Injuries:** Crew - None Passengers - None

**Nature of Damage:** Leading edge of the right wing dented

**Commander's Licence:** Private Pilot's Licence

**Commander's Age:** 25 years

**Commander's Total Flying Experience:** 74 hours (of which 10 were on type)

**Information Source:** Aircraft Accident Report Form submitted by the pilot

The aircraft was travelling along the taxiway between the rear of some parked aircraft and the Air Centre clubhouse when it struck an unattended parked vehicle. The pilot immediately switched off the engine and all the aircraft systems and the occupants disembarked.

The pilot has since stated that his vision to the right was partially obscured by the passenger in the right front seat of the aircraft.