

ACCIDENT

Aircraft Type and Registration:	Jabiru UL-450, G-BZSZ	
No & Type of Engines:	1 Jabiru Aircraft PTY 2200A piston engine	
Year of Manufacture:	2001	
Date & Time (UTC):	6 September 2009 at 1300 hrs	
Location:	Clipgate Farm, Barham, Kent	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Damage to wings, wing strut, propeller and nose gear leg	
Commander's Licence:	National Private Pilot's Licence	
Commander's Age:	60 years	
Commander's Flying Experience:	312 hours (of which 237 were on type) Last 90 days - 4 hours Last 28 days - 1 hour	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

After returning from a local flight the pilot lined up for an approach to Runway 20 (grass). He reported that the wind was from 200° at 8 to 10 kt. Just prior to touchdown, while the pilot was reducing power, the aircraft was struck by a gust of wind from the right. The

pilot reported that he had insufficient time to stop the aircraft from drifting to the left. After touchdown the left wing clipped some hedges and spun the aircraft around until it came to rest. The pilot was uninjured.