Cessna 150M, G-BFLM

AAIB Bulletin No: 3/97 Ref: EW/G97/01/03 Category: 1.3

Aircraft Type and Registration:	Cessna 150M, G-BFLM
No & Type of Engines:	1 Continental O-200-A piston engine
Year of Manufacture:	1974
Date & Time (UTC):	14 January 1997 at 1225 hrs
Location:	Bodmin Airfield, Cornwall
Type of Flight:	Private
Persons on Board:	Crew - 1 - Passengers - None
Injuries:	Crew - 1 (Minor) - Passengers - N/A
Nature of Damage:	Aircraft destroyed
Commander's Licence:	Private Pilot's Licence
Commander's Age:	69 years
Commander's Flying Experience:	164 hours (of which 152 were on type)
	Last 90 days - 4 hours
	Last 28 days - 2 hours
Information Source:	Aircraft Accident Report Form submitted by the pilot
	and further enquiries by the AAIB

The pilot had intended to fly circuits at Bodmin Airfield wherethe runway in use was Runway 14 with a right hand circuit. Theweather conditions included a surface wind of 140°/10 ktand a visibility on the airfield of 8 to 10 km but with some patchy, light mist in the area.

After take off, at a height of 500 feet, the pilot commenced aright turn onto the crosswind leg and then realised that the visibilitywas poor when flying towards the sun. He therefore decided tocomplete a low level circuit and land as soon as possible. Hebegan the downwind checks but had difficulty in finding the airfieldand was further distracted when another aircraft called that itwas approaching finals. Because he could not see this aircraft pilot decided to complete a left hand orbit on the downwindleg after which he briefly spotted the runway and repositionedfor a landing. Shortly afterwards the aircraft struck the groundfirmly and bounced over a hedge and stone wall before coming torest in the next field; the pilot remembered hearing the stallwarning immediately

prior to impact. The aircraft had suffered substantial damage to the propeller, the engine, the undercarriage and the fuse lage and the door had fallen off but the aircraft had remained upright throughout. The pilot, who was wearing alap strap and diagonal harness, stepped out of the aircraft unaided. The aircraft had crashed half a mile north-west of the threshold of Runway 14.