ACCIDENT

Aircraft Type and Registration: Pegasus Quik, G-CDMZ

No & Type of Engines: 1 Rotax 912-UL piston engine

Year of Manufacture: 2005

Date & Time (UTC): 5 July 2009 at 1700 hrs

Location: Herridge Court Farmstrip, Kent

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Nose landing gear, fuselage pod and wing

Commander's Licence: Private Pilot's Licence

Commander's Age: 64 years

Commander's Flying Experience: 232 hours (of which 67 were on type)

Last 90 days - 4 hours Last 28 days - 2 hours

Information Source: Aircraft Accident Report Form submitted by the pilot

During the final stages of the approach, in mildly turbulent conditions, the pilot moved the wing to initiate the flare. The aircraft failed to respond to the change in attitude of the wing and landed heavily. It became briefly airborne again before landing on its nosewheel, which

collapsed, causing the aircraft to become inverted. The pilot was uninjured. The pilot attributed the accident to encountering turbulence or wind shear during the later stages of the approach.

© Crown copyright 2009 165