## Airbus A300B4-622R, F-OIHA

AAIB Bulletin No: 5/99 Ref: EW/G99/03/03 Category: 1.1

**Aircraft Type and Registration:** Airbus A300B4-622R, F-OIHA

No & Type of Engines: 2 General Electric CF6-50C2 turbofan engines

Year of Manufacture: 1989

**Date & Time (UTC):** 7 March 1999 at 1910 hrs

**Location:** London Heathrow Airport

**Type of Flight:** Public Transport

**Persons on Board:** Crew - 10 - Passengers - 140

**Injuries:** Crew - None - Passengers - None

Nature of Damage: Forward fuselage punctured

**Commander's Licence:** Airline Transport Pilot's Licence

**Commander's Age:** 50 years

**Commander's Flying Experience:** 14,600 hours (of which 1,050 were on type)

Last 90 days - 210 hours

Last 28 days - 60 hours

**Information Source:** Aircraft Accident Report Form submitted by the pilot

As the aircraft was being pushed back from Stand H5, the nose struck an air starter trolley. The Commander stated that the area was very congested and that the push back was very fast.