

Yakovlev YAK-50, G-YAKA

AAIB Bulletin No: 5/2002	Ref: EW/G2002/03/12	Category: 1.3
Aircraft Type and Registration:	Yakovlev YAK-50, G-YAKA	
No & Type of Engines:	1 Ivchenko Vedeneyev M-14PF piston engine	
Year of Manufacture:	1982	
Date & Time (UTC):	12 March 2002 at 1500 hrs	
Location:	Brighton Aerodrome, North Yorkshire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Damage to propeller and oil cooler cowling	
Commander's Licence:	Private Pilots Licence	
Commander's Age:	44 years	
Commander's Flying Experience:	1,400 hours (of which 2 were on type)	
	Last 90 days - 80 hours	
	Last 28 days - 15 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

In a very concise report about the accident, the pilot indicated that he had made an error and landed the aircraft at Brighton Aerodrome with the landing gear still retracted after a short local flight.