## **Boeing 737-46B, G-OBMN, 5 April 1996**

AAIB Bulletin No: 6/96 Ref: EW/G96/04/22Category: 1.1

Aircraft Type and Registration: Boeing 737-46B, G-OBMN

No & Type of Engines: 2 CFM56-3C1 turbofan engines

Year of Manufacture: 1989

**Date & Time (UTC):**5 April 1996 at 1940 hrs

Location: In cruise 20 nm from Wallasey VOR

Type of Flight: Public Transport

**Persons on Board:**Crew - 7 Passengers - 157

**Injuries:**Crew - None Passengers - None

Nature of Damage: None

Commander's Licence: Airline Transport Pilot's Licence

Commander's Age:54 years

Commander's Flying Experience: 19,000 hours (of which 4000 were on type)

Last 90 days - 574 hours

Last 28 days - 159 hours

**Information Source:** Aircraft Accident Report Form submitted by the pilot

The commander was undergoing a line check on a scheduled flightfrom London Heathrow Airport to Belfast Airport. In the cruise, at FL 310, the check captain "slumped" in his seat; the commander, who at first thought he may be feigning incapacitationas part of the check, pushed him back in the seat and locked theharness. Almost immediately the check captain began to vomit; the commander called a steward to the flight deck to assist himand continued the flight to Belfast, with the steward occupyingthe jump seat. Subsequently the check captain was found to havebeen suffering from a gastric disorder.