

ACCIDENT

Aircraft Type and Registration:	Rans S6-ESD (Modified) Coyote II, G-MYLF	
No & Type of Engines:	1 Rotax 912-UL piston engine	
Year of Manufacture:	1993	
Date & Time (UTC):	26 June 2010 at 1100 hrs	
Location:	Wharf Farm, Market Bosworth, Leicestershire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - 1
Injuries:	Crew - None	Passengers - None
Nature of Damage:	Damage to nose gear leg and propeller	
Commander's Licence:	National Private Pilot's Licence	
Commander's Age:	69 years	
Commander's Flying Experience:	119 hours (of which 100 were on type) Last 90 days - 12 hours Last 28 days - 4 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The aircraft was landing on Runway 20 at Wharf Farm when it touched down heavily and then bounced. The nose gear collapsed during the subsequent touchdown

and the propeller was damaged. The pilot and passenger exited the aircraft without injury after it had slid to a stop.