

**ACCIDENT**

<b>Aircraft Type and Registration:</b>	Tanarg/Ixess 15 912S(1), G-CEBH	
<b>No &amp; Type of Engines:</b>	1 Rotax 912ULS piston engine	
<b>Year of Manufacture:</b>	2006	
<b>Date &amp; Time (UTC):</b>	19 March 2011 at 1600 hrs	
<b>Location:</b>	Palmer Moor Farm, Doveridge, Derbyshire	
<b>Type of Flight:</b>	Private	
<b>Persons on Board:</b>	Crew - 1	Passengers - None
<b>Injuries:</b>	Crew - None	Passengers - N/A
<b>Nature of Damage:</b>	Propeller, left suspension leg and fairings damaged	
<b>Commander's Licence:</b>	National Private Pilot's Licence	
<b>Commander's Age:</b>	63 years	
<b>Commander's Flying Experience:</b>	169 hours (of which n/k were on type) Last 90 days - 8 hours Last 28 days - 4 hours	
<b>Information Source:</b>	Aircraft Accident Report Form submitted by the pilot	

During the approach to Runway 27 at Palmer Moor Farm, the aircraft experienced an area of sink. The pilot attempted to correct this, but the aircraft clipped a fence, veered to the left and struck a chicken wire fence that

ran alongside the runway. Damage was sustained to the left suspension leg, fibre glass fairings and the propeller. The pilot was uninjured.