

ACCIDENT

Aircraft Type and Registration:	Savannah VG Jabiru (2), G-CCSV	
No & Type of Engines:	1 Jabiru Aircraft PTY 2200 piston engine	
Year of Manufacture:	2004	
Date & Time (UTC):	9 September 2010 at 1005 hrs	
Location:	Inglenook Farm, Maydensole, Dover	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Damage to wings, landing gear and propeller; third party damage to boundary fence	
Commander's Licence:	National Private Pilot's Licence	
Commander's Age:	77 years	
Commander's Flying Experience:	288 hours (of which 174 were on type) Last 90 days - 9 hours Last 28 days - 2 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The pilot reported that he applied excessive rudder to correct a swing as the aircraft approached lift off speed.

The right wingtip touched a hedge and the aircraft then ground looped into the boundary fence.