

ACCIDENT

Aircraft Type and Registration:	Jabiru UL-450, G-TYKE	
No & Type of Engines:	1 Jabiru Aircraft Pty 2200A piston engine	
Year of Manufacture:	2001 (Serial no: PFA 274A-13739)	
Date & Time (UTC):	31 March 2013 at 1230 hrs	
Location:	Charterhall Airfield, Berwickshire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - 1
Injuries:	Crew - None	Passengers - None
Nature of Damage:	Damage to landing gear and propeller	
Commander's Licence:	National Private Pilot's Licence	
Commander's Age:	56 years	
Commander's Flying Experience:	146 hours (of which 77 were on type) Last 90 days - 18 hours Last 28 days - 3 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The aircraft was landing on Runway 07 at Charterhall Airfield after a local flight. The weather was fine but with a strong and gusting south-easterly wind. During the landing roll, the pilot had difficulty keeping the aircraft on the paved surface. He braked heavily and the aircraft slowed considerably but he was unable to

prevent it leaving the runway on the left, downwind side. The nose landing gear dug into the soft ground and the propeller struck the surface. The main landing gear was damaged and the aircraft settled onto its underside. Neither occupant was injured.