

No: 6/87

Ref: 1c

Aircraft type and registration: DHC-1 Chipmunk 22 (Lycoming) G-AOUO

No & Type of engines: 1 Lycoming 0-360-AIA piston engine

Year of Manufacture: 1950

Date and time (UTC): 18 February 1987 at 1525 hrs

Location: Bicester Airfield, Oxon

Type of flight: Glider towing

Persons on board: Crew — 1 Passengers — None

Injuries: Crew — None Passengers — N/A

Nature of damage: Starboard wing leading edge damaged, forward wing spar attachment bracket fractured and wing fairing panels buckled

Commander's Licence: Commercial Pilot's Licence

Commander's Age: 43 years

Commander's Total Flying Experience: 11201 hours

Information Source: Aircraft Accident Report Form submitted by RAFGSA.

The aircraft was taxiing at normal speed on the aircraft manoeuvring area when a car drove into its starboard wing.