

ACCIDENT

Aircraft Type and Registration:	Renegade Spirit UK, G-MYFM	
No & Type of Engines:	1 Rotax 582 piston engine	
Year of Manufacture:	1993	
Date & Time (UTC):	1 November 2010 at 1500 hrs	
Location:	Farm strip, London Colney, Hertfordshire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Damage to landing gear and wings	
Commander's Licence:	National Private Pilot's Licence	
Commander's Age:	47 years	
Commander's Flying Experience:	419 hours (of which n/k were on type) Last 90 days - Not known Last 28 days - Not known	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The Renegade Spirit is a three-axis microlight aircraft with a biplane and tailwheel configuration. During an attempted landing on a 325-metre grass strip the pilot overshot the runway and initiated a go-around. During

the go-around the landing gear clipped the top of a hedge, causing the aircraft to hit the ground in the field beyond. In his written report the pilot assessed the cause of the accident as "pilot error".