Ref: EW/G84/08/02 No: 10/84

Nord NC 858S G-BPZD (single light engined, fixed wing aircraft) Aircraft type and registration:

11 August 1984 at 1812 hrs Date and time (GMT):

Shoreham Airport, Sussex Location:

Type of flight:

Passengers - 1 Persons on board: Crew - 1

Crew - Nil

Private

1950

Damage to propeller tip, and to left undercarriage, wing strut, door and Nature of damage:

Passengers - Nil

windscreen

Commander's Licence: Private Pilot's Licence

Commander's Age: 53 years

Commander's total flying

Year of Manufacture:

Injuries:

452 hours (of which 6 were on type) experience:

Aircraft Accident Report Pro-forma completed by pilot. Information Source:

The aircraft had just become airborne from the grass runway 25 at Shoreham when, from an estimated height of 20 feet, it stalled. Before the pilot could take recovery action, it hit the ground in a flat attitude and bounced once before coming to rest with the left undercarriage collapsed.