

Douglas DC-9-82 MD 82, OH-LMT

AAIB Bulletin No: 10/98 **Ref:** EW/G98/07/33 **Category:** 1.1

Aircraft Type and Registration: Douglas DC-9-82 MD 82, OH-LMT

No & Type of Engines: 2 Pratt & Whitney PW JT8D-219 turbofan engine

Year of Manufacture: 1989

Date & Time (UTC): 25 July 1998 at 0850 hrs

Location: London Heathrow Airport

Type of Flight: Public Transport (Passenger)

Persons on Board: Crew - 7 - Passengers - None

Injuries: Crew - None - Passengers - N/A

Nature of Damage: Substantial to left wingtip

Commander's Licence: Airline Transport Pilot's Licence

Commander's Age: 49 years

Commander's Flying Experience: 14,500 hours (of which 5,400 were on type)
Last 90 days - 210 hours
Last 28 days - N/K

Information Source: Aircraft Accident Report Form submitted by the pilot

The aircraft was parked on Stand B27R when a water replenishment vehicle collided with its left wingtip.