

Aircraft type and registration: Piper PA-38-112 G-BKMK

No & Type of engines: 1 Lycoming O-235-L2C piston engine

Year of Manufacture: 1980

Date and time (UTC): 9 April 1987 at 1740 hrs

Location: Glasgow Airport

Type of flight: Training

Persons on board: Crew — 2 Passengers — None

Injuries: Crew — None Passengers — N/A

Nature of damage: Right landing gear leg collapsed and right wing spars bent

Commander's Licence: Private Pilot's Licence

Commander's Age: 27 years

Commander's Total Flying Experience: 1480 hours (of which 800 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot

The aircraft was engaged on dual instruction. After a heavy, flat landing and a bounce, the instructor took control and relanded the aircraft. During the ground roll the right wing dropped slightly and, suspecting that the right tyre had burst, the instructor turned the aircraft left to clear the runway. During the turn the right landing gear leg collapsed.