

# Europa, G-BYJI

**AAIB Bulletin No:** 7/2001    **Ref:** EW/ G2001/04/14    **Category:** 1.3

**Aircraft Type and Registration:** Europa, G-BYJI

**No & Type of Engines:** 1 Rotax 912-UL piston engine

**Year of Manufacture:** 1996

**Date & Time (UTC):** 21 April 2001 at 1645 hrs

**Location:** Wolverhampton Business Airport

**Type of Flight:** Private

**Persons on Board:** Crew - 1 - Passengers - None

**Injuries:** Crew - None - Passengers - N/A

**Nature of Damage:** Damage to propeller

**Commander's Licence:** Private Pilot's Licence with IMC Rating

**Commander's Age:** 53 years

**Commander's Flying Experience:** 297 hours ( of which 20 were on type)

Last 90 days - 4 hours

Last 28 days - 3 hours

**Information Source:** Aircraft Accident Report Form submitted by the pilot

The aircraft landed on Runway 28, the wind was calm. In the final stage of the landing roll the aircraft veered off the runway to the left and came to rest on the grass. The propeller struck the runway edge during this event.