

INCIDENT

Aircraft Type and Registration: Douglas DC-9-82, OH-LMT

No & Type of Engines: 2 Pratt & Whitney JT8D-219 turbofan engines

Year of Manufacture: 1989

Date & Time (UTC): 13 April 1994 at 1550 hrs

Location: London Heathrow Airport

Type of Flight: Public Transport

Persons on Board: Crew - 8 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Minor damage to cargo bay door frame and fuselage skin

Commander's Licence: Finnish Airline Transport Pilot's Licence with Night Rating

Commander's Age: 43 years

Commander's Flying Experience: 12,000 hours
Last 90 days - N/K
Last 28 days - N/K

Information Source: Aircraft Accident Report Form submitted by the pilot

The aircraft was parked on Stand C26 at London Heathrow Airport and was being turned round and reloaded for a return flight to Helsinki. During this procedure a loading vehicle struck the No 1 cargo bay door frame causing minor damage to the door frame doubler and fuselage skin. The aircraft was withdrawn from service and the necessary repairs were carried out before it departed for Helsinki.