

AAIB Bulletin No: 2/95

Ref: EW/G94/08/22

Category: 1.3

Aircraft Type and Registration: Cessna 172N Skyhawk, G-BUOJ

No & Type of Engines: 1 Lycoming O-320-H2AD piston engine

Year of Manufacture: 1978

Date & Time (UTC): 20 August 1994 at 1029 hrs

Location: Stapleford Tawney Airfield, Essex

Type of Flight: Private

Persons on Board: Crew - 1 Passengers - 3

Injuries: Crew - None Passengers - None

Nature of Damage: Substantial to landing gear and engine bearers

Commander's Licence: Private Pilot's Licence

Commander's Age: 39 years

Commander's Flying Experience: 92 hours (of which 25 were on type)
Last 90 days - 8 hours
Last 28 days - 6 hours

Information Source: Aircraft Accident Report Form submitted by the pilot

The aircraft landed heavily on Runway 22 with a surface wind of 260°/15 kt. Normal after landing checks were completed and the aircraft taxied to its usual parking position, whereupon the damage was noted.