

Reims Cessna F172K, G-BFPH

AAIB Bulletin No: 3/97 Ref: EW/G96/10/24 Category: 1.3

Aircraft Type and Registration:	Reims Cessna F172K, G-BFPH
No & Type of Engines:	1 Rolls-Royce O-300-D Continental piston engine
Year of Manufacture:	1971
Date & Time (UTC):	19 October 1996 at 1130 hrs
Location:	North Coates Airfield, Humberside
Type of Flight:	Private
Persons on Board:	Crew - 2 - Passengers - None
Injuries:	Crew - None - Passengers - N/A
Nature of Damage:	Extensive damage to left wing
Commander's Licence:	Private Pilot's Licence
Commander's Age:	66 years
Commander's Flying Experience:	209 hours (All were on type) Last 90 days - None Last 28 days - None
Information Source:	Aircraft Accident Report Form submitted by the pilot and further enquiries by the AAIB

The accident occurred at the conclusion of a flight from Sturgateto North Coates. After landing on Runway 24 the aircraft wastaxied clear at the second intersection. As the aircraft wasturned to the right from this taxiway onto the main perimetertrack, the pilot became distracted by another aircraft which waslanding at the time and allowed the aircraft to swing wide inthe turn and hit the airfield perimeter fence.