

ACCIDENT

Aircraft Type and Registration:	Rotorsport Cavalon, G-CIAT	
No & Type of Engines:	1 Rotax 914 UL piston engine	
Year of Manufacture:	2013 (Serial no: 003)	
Date & Time (UTC):	11 June 2013 at 1515 hrs	
Location:	Chiltern Air Park, Oxfordshire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Damage to rotor	
Commander's Licence:	Student Pilot	
Commander's Age:	59 years	
Commander's Flying Experience:	70 hours (of which 25 were on type) Last 90 days - 33 hours Last 28 days - 25 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

The gyroplane veered left after landing and rolled over onto its right side. The student pilot attributed the accident to inputting left rudder and putting the stick

forward too quickly, and hence not allowing the energy to dissipate. There were no injuries.