

No: 9/88

Ref: EW/G88/07/02

Category: 1c

Aircraft Type and Registration: Piper PA-28-151, G-BELP

No & Type of Engines: 1 Lycoming O-320-E3D piston engine

Year of Manufacture: 1978

Date and Time (UTC): 2 July 1988 at 1525 hrs

Location: Cranfield Airport, Bedford

Type of Flight: Private (pleasure)

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Minor

Commander's Licence: Private Pilot's Licence

Commander's Age: 39 years

Commander's Total Flying Experience: 347 hours (of which 95 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot

Whilst taxiing between two rows of parked aircraft the left wing tip struck the rudder of a stationary aircraft. There was no damage to the taxiing aircraft but the rudder of the parked aircraft was dented.