

Aircraft Type and Registration:	Jabiru UL-450, G-DJAY	
No & Type of Engines:	1 Jabiru Aircraft Pty 2200A piston engine	
Year of Manufacture:	2001	
Date & Time (UTC):	8 June 2005 at 1305 hrs	
Location:	Wycombe Air Park, Buckinghamshire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Propeller tips and nose wheel	
Commander's Licence:	Private Pilot's Licence	
Commander's Age:	76 years	
Commander's Flying Experience:	609 hours (of which 78 were on type) Last 90 days - 4 hours Last 28 days - 2 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

Following a private flight from Popham to Wycombe Air Park, the pilot prepared the aircraft for a landing on Runway 24 Right. The weather at the time was good with the wind from 180°/2 kt. On landing, the aircraft bounced which resulted in damage to the nose wheel rubber shock absorber, collapse of the nose wheel and damage to the tips of the propeller. The pilot, who was wearing a lap strap and diagonal harness, was uninjured and exited the aircraft normally.