

To our customers and users of the Dräger Oxylog 2000 disposable ventilation hoses Ventstar 2M86791

May 2014

Important safety notice!!

Disposable ventilation hoses Ventstar for the Dräger emergency breathing device Batch numbers 330384.001 - 331661.002

Dear Sir or Madam,

During our market and product monitoring we became aware of three cases where prior to the use of the Oxylog 2000 disposable ventilation hoses Ventstar adhesive residue the size of a finger nail was found loose in the hose or the packaging around the hose. Had the hose been used with the residue in place, it may have entered the patient's lungs.

Our investigations showed that the adhesive residue originated from the glueing of the angled connector to the hose. Further investigations indicated that during the time between January 2013 and April 2014 too much adhesive may have been applied and then pushed to the outside when joining the components. After the adhesive hardened, excessive adhesive could detach and move within the packaging.

The following batches may be affected:

	Part number	Batch number (from – to)
Packaging box set	2M86841	330384.001 - 331661.002
Hose packaging	2M86791	330384.001 - 331661.002

Our records indicated that you received Disposable ventilation hoses Ventstar from an affected batch. Please check your stock in accordance with the batch number stated on the packaging label. An illustration of the packaging label with batch number is shown in appendix 1 of this letter.

Dräger Medical GmbH Moislinger Allee 53-55 23558 Lübeck, Germany Correspondence address: 23542 Lübeck, Germany Tel. +49 451 882-0 Fax +49 451 882-2080 info@draeger.com www.draeger.com VAT no. DE813745277

Bank connections: Commerzbank AG, Lübeck Account no. 014 679 500 Sort code 230 400 22 IBAN DE95 2304 0022 0014 6795 00 SWIFT code COBADEFF230

Sparkasse Lübeck Account no. 1 071 117 Sort code 230 501 01 IBAN DE15 2305 0101 0001 0711 17 Managing Director: SWIFT code NOLADE21SPL

Corporate head office: Lübeck Commercial register: Municipal court Lübeck HRB 4358 HL Anton Schrofner

Chair of the supervisory board: Professor Dr. Nikolaus Schweickart

Stefan Dräger (chair) Dr. Herbert Fehrecke Andreas Frahm Gert-Hartwig Lescow



Page 2 / 3

To prevent complications during the use of an affected hose we highly recommend that you check for the presence of residue inside the hose prior to use. Since potential residue can generally move freely within the hose, the residue can be removed by holding the hose vertical with the opening facing down.

If in doubt, do not use the hose system from the batches mentioned. For the free of charge replacement of unopened packaging units please contact your Dräger representative.

We apologise for the inconvenience to you during this action but consider the action necessary as a preventative measure for increasing patient safety.

If you have any questions or need any additional information please do not hesitate to contact your local Dräger representative who would be happy to answer any queries.

With best regards,

Martin Döring Head of Key Application Field Hospital Consumables & Accessories



Appendix 1

Illustration of the label on the packaging box set 2M86841:



Affected batch number: 330384.001 - 331661.002

Illustration of the label on the packaging of the disposable hose 2M86791



Affected batch numbers: 330384.001 - 331661.002