

No: 6/88

Ref: EW/G88/04/09

Category: 1c

Aircraft Type and Registration: Piper Cub series L21B, G-SCUB

No & Type of Engines: 1 Lycoming O-290-D2 piston engine

Year of Manufacture: 1954

Date and Time (UTC): 1 April 1988 at 1840 hrs

Location: Leicester Airport

Type of Flight: Private (pleasure)

Persons on Board: Crew - 1 Passengers - None

Injuries: Crew - None Passengers - N/A

Nature of Damage: Propeller bent, starboard undercarriage axle bent and starboard wing tip fabric torn

Commander's Licence: Private Pilot's Licence

Commander's Age: 40 years

Commander's Total Flying Experience: 276 hours (of which 36 were on type)

Information Source: Aircraft Accident Report Form submitted by the pilot

Following a normal approach, a landing was made at Leicester Airport. The wind was from 210° and gusting to 15 kt. During the landing roll, the aircraft swung to the left and ground looped. There was no fire.