

Recommendation(s) Status: Fire on prototype tram 611 at Blackpool




This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of implementation of the recommendations, as reported to us, has been divided into six categories:

Key to Recommendation Status

Implemented:	All actions to deliver the recommendation have been completed.
Implemented by alternative means:	The intent of the recommendation has been satisfied in a way that was not identified by the RAIB during the investigation.
Implementation ongoing:	Work to deliver the intent of the recommendation has been agreed and is in the process of being delivered.
In-progress:	The relevant safety authority has yet to be satisfied that an appropriate plan, with timescales, is in place to implement the recommendation; and work is in progress to provide this.
Non-implementation:	Regulation 12(2)(b)(iii) = recommendation considered and no implementation action to be taken.
Awaiting response:	Awaiting initial report from the relevant safety authority or public body on the status of the recommendation.

RAIB concerns on actions taken by organisations in response to recommendations are reflected in this report and are indicated by one of the following.

-  The red triangle shows recommendations where the RAIB has concerns that no actions have been taken in response to a recommendation.
-  The blue triangle shows recommendations where the RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.
-  The white triangle shows recommendations where the RAIB notes substantive actions have been reported, but the RAIB still has concerns.

Note: The tables which follow, report the status of recommendations on 31 December 2015. In some other cases the end implementer has already sent information to the relevant safety authority about the actions it has taken, or proposes to take and the safety authority is considering whether it is satisfied that those actions and the associated timescales are accepted.

Number/ Date/ Report No/ Inv Title / Current Status	Safety Recommendation	Summary of current status (based on latest report from the relevant safety authority or public body)
<p>1 24/01/2007 41/2007</p> <p>Fire on prototype tram 611 at Blackpool</p> <p>Status: Implemented</p>	<p>Blackpool Transport Services should develop vehicle acceptance procedures and integrate these into the "management of change" procedure within the Safety Management System</p>	<p>BTS has reported that it has taken actions in response to this recommendation.</p> <p>ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate.</p>
<p>2 24/01/2007 41/2007</p> <p>Fire on prototype tram 611 at Blackpool</p> <p>Status: Implemented</p>	<p>Trampower Ltd should carry out an appropriate risk assessment relating to the design, construction and operation of the vehicle with reference to Regulation 3 of the Management of Health and Safety at Work Regulations. Part of this assessment should consider whether components and systems are appropriately constructed and installed in a way that is fit for their intended use. This risk assessment, and related currently-applicable technical documentation, should be provided to the operators of any network where the vehicle is used.</p>	<p>ORR has reported that actions were taken in response to this recommendation. However, the RAIB has not been provided with information about these actions and is unable to judge whether the intent of the recommendation has been met.</p>