## Recommendation(s) Status: Fatal accident at Norbreck, Blackpool


This report is based on information provided to the RAIB by the relevant safety authority or public body.

The status of implementation of the recommendations, as reported to us, has been divided into six categories:

Key to Recommendation Status		
Implemented:	All actions to deliver the recommendation have been completed.	
Implemented by alternative	The intent of the recommendation has been satisfied in a way that was not identified by the RAIB	
means:	during the investigation.	
Implementation ongoing:	Work to deliver the intent of the recommendation has been agreed and is in the process of being	
	delivered.	
In-progress:	The relevant safety authority has yet to be satisfied that an appropriate plan, with timescales, is	
	in place to implement the recommendation; and work is in progress to provide this.	

Awaiting response:	Awaiting initial report from the relevant safety authority or public body on the status of the	
	recommendation.	

RAIB concerns on actions taken by organisations in response to recommendations are reflected in this report and are indicated by one of the following:





The blue triangle shows recommendations where the RAIB has concerns that the actions taken, or proposed, are inappropriate or insufficient to address the risk identified during the investigation.

The white triangle shows recommendations where the RAIB notes substantive actions have been reported, but the RAIB still has concerns.

Note: The tables which follow, report the status of recommendations on 31 December 2015. In some other cases the end implementer has already sent information to the relevant safety authority about the actions it has taken, or proposes to take and the safety authority is considering whether it is satisfied that those actions and the associated timescales are accepted.

Number/ Date/ Report No/ Inv Title / Current Status	Safety Recommendation	Summary of current status (based on latest report from the relevant safety authority or public body)
1 05/08/2009 09/2010 Fatal accident at Norbreck, Blackpool Status: Implemented	BTS management should develop and document a company- wide policy for the determination and application of speed limits throughout the network. This should include a maximum speed for non-stopping trams through tram-stops. They should also develop, document, train and brief a speed limit signage policy. The purpose of this recommendation is to introduce a universal speed limit policy, agreed by all parts of BTS and a corresponding speed limit signage policy. These should both be documented. Derivation of any timetables should fully take account of the speed limits applied.	Blackpool Transport Services has reported that it has reviewed speed limits and associated signage (including at level crossings). ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate.
2 05/08/2009 09/2010 Fatal accident at Norbreck, Blackpool Status: Implemented	BTS should develop and document an effective and consistent system to monitor compliance with speed limits among tram drivers, and adjust BTS recruitment, training and compliance procedures as necessary to increase levels of compliance. The purpose of this recommendation is to improve the measurement of levels of non-compliance with speed limits and bring about improved levels.	Blackpool Transport Services has reported that it has taken actions in response to this recommendation. ORR proposes to take no further action unless they become aware that the information provided becomes inaccurate.